

Records of Messenger and Co. Ltd

Deposited in T80/8 via Leicestershire Museums, Art Galleries and Records Service.

Thomas Goode Messenger is recorded as having a plumber's, glazier's and glassfitter's business in High Street, Loughborough as early as 1855. In 1858 he formed his own company of Messenger and Co. and by 1863 is listed as a plumber and hydraulic engineer. By 1877 the firm is described as "horticultural builders and hot water apparatus manufacturers". In 1874, Walter Chapman Burder purchased the company and in 1884 the business was moved from the High Street premises to Cumberland Road, off Ashby Road. A foundry was then built and further extensions in 1895 led to the complete closure of the High Street Branch. The firm was famous, particularly in the Victorian and Edwardian period, for making greenhouses, verandahs, summer houses, cucumber frames, melon pits, mushroom beds, orchid stages, vineries and peach houses. As the demand declined from the 1930s, the company began to concentrate more on the manufacture of heating equipment and became an engineering firm. It was also known by the name Midland Horticultural Company.

The Collection contains contract files for buildings erected in Great Britain and overseas. Many records for Leicestershire were retained by the Records Office of Leicestershire, Leicester and Rutland.

The Records Office for Leicestershire, Leicester and Rutland also holds records relating to Messenger and Co. The material held there contains financial records, purchase and estimate books, contract books, order books, contract files, plans etc 1866-1973 [Reference DE 2121]

The catalogue is arranged by the following counties:

Bedfordshire	Gloucestershire	Middlesex	Sussex
Berkshire	Hampshire	Norfolk	Warwickshire
Buckinghamshire	Herefordshire	Northamptonshire	West Midlands
Cambridgeshire	Hertfordshire	Northumberland and Co. Durham	Wiltshire
Cheshire	Isles of Wight and Man	Nottinghamshire	Worcestershire
Cornwall	Kent	Oxfordshire	Yorkshire
Cumbria	Lancashire	Rutlandshire	Scotland
Derbyshire	Leicestershire	Shropshire	Ireland
Devon	Lincolnshire	Somerset	Wales
Dorset	London	Staffordshire	Overseas
Essex	Merseyside	Suffolk	

NB: Current county boundaries may differ from those given in the records

Records for Messenger and Co. in Numerical Order

TR MES AD1/67	Structure: Vinery Location: 10 The Village, Meads, Eastbourne, Sussex Client: Latter Parsons and Co.	1892
TR MES AD1/68	Structure: Plant house Location: Seacroft, Leeds, West Yorkshire Client: Leeds City Hospital	1904
TR MES AD1/69	Structure: Greenhouses Location: Kilvrough, Park Mill RSO, Glamorganshire, Wales Client: Admiral Sir Algernon Lyons	1902
TR MES AD1/70	Structure: Plant house Location: Hartfield, Roehampton Lane, London Client: W. Austin Leigh	1900
TR MES AD1/71	Structure: Peach house; Plant house Location: Westbury House, Petersfield, Hampshire Client: Col. H. Le Roy Lewis, DSO	1900; 1908
TR MES AD1/72	Structure: Conservatory Location: Henshall Hall, Congleton, Cheshire Client: John Lewis [Architect]	1891
TR MES AD1/75	Structure: Plant House Location: Loddon Vicarage, Norfolk Client: Rev. C.B. Mayhew	1889
TR MES AD1/77	Structure: Glasshouse Location: Benwell House, Woodchester, Gloucestershire Client: Mrs Mostyn	1906
TR MES AD1/78	Structure: Conservatory Location: Flaghead, Canford Cliffs, Bournemouth, Dorset Client: Col. Charles Mercier	1895
TR MES AD1/80	Structure: Plant house Location: Lynford Hall, Mundford, Norfolk Client: F.J.C. Montague	1905
TR MES AD1/81	Structure: Heating apparatus Location: The Hut, Birchington-on-sea, Kent Client: W. Macnamara	1898
TR MES AD1/82	Structure: Vinery Location: Leftwich Grange, Northwich, Cheshire Client: W.H. Moreton	1892
TR MES AD1/83	Structure: Heating to shop and office Location: Post Office, Worcester Park, Surrey Client: Millward and Son	1895
TR MES AD1/86	Structure: Orchid house Location: 10 Radnor Park West, Folkestone, Kent Client: E. Sutcliffe per J.A. Mitchell [Florist]	1904
TR MES AD1/89	Structure: Conservatory Location: Drissaig, Kilchrenan, Argyll, Scotland Client: Dr McDougall per James Wilding [Architect]	1905
TR MES AD1/90	Structure: Conservatory; Greenhouse Location: Marlborough College, Marlborough, Wiltshire Client: Mr J. Gibson Bulmer	1904; 1913
TR MES AD1/91	Structure: Glass house Location: Chase Cliffe, Whatstandwell, Derbyshire Client: His honourable judge, H.R. Mansel-Jones	1906

TR MES AD1/92	Structure: Boiler Location: Bloomsgrave Works, Nottingham, Nottinghamshire Client: Manlove, Alliott and Co., LTD	1891
TR MES AD1/93	Structure: Greenhouse/Conservatory Location: Clarence Lodge, Lucknow Road, Nottingham, Nottinghamshire Client: T. Moody	1904
TR MES AD1/94	Structure: Boiler and fittings Location: Market Place, Blandford, Dorset Client: J. Marshall	1905
TR MES AD1/96	Structure: Greenhouse Location: Park Villa, Bolton, Yorkshire Client: R. Maisland	1904
TR MES AD1/97	Structure: Greenhouse; Peach House Location: Tapton House, Chesterfield, Derbyshire Client: Mrs Markham	1896; 1899
TR MES AD1/99	Structure: Greenhouse Location: Sunnyside, Potters Bar, Hertfordshire Client: A. Marshall	1893
TR MES AD1/100	Structure: Peach House; Heating apparatus Location: Ruddington Hall, Nottingham, Nottinghamshire Client: Philo and Mills	1903; 1905
TR MES AD1/101	Structure: Greenhouse/Conservatory Location: Balliol College, Oxford, Oxfordshire Client: Sir W. Markby	1893
TR MES AD1/103	Structure: Greenhouse Location: The Gate House, Mere Vale, Atherstone, Warwickshire Client: P.H. Parry Mitchell	1896
TR MES AD1/104 [2 packets]	Structure: Painting to greenhouses Location: Sulby Hall near Rugby, Warwickshire Client: Major Guy Paget	1930
TR MES AD1/104	Structure: Vinery, Azalea house and other glasshouses Location: Sulby Hall, Rugby, Warwickshire Client: Miss Mansell, Major E.D. Mansell	1899-1902
TR MES AD1/105	Structure: Heating apparatus Location: Drill Hall, Seaford, Sussex Client: B.A. Miller [Civil Engineer]	1896
TR MES AD1/106	Structure: Conservatory Location: Oxted, Surrey Client: Mr Money Marsland per Ellis Marsland [Architect]	1893
TR MES AD1/107	Structure: Greenhouse Location: Bassett Down House, near Swindon, Wiltshire Client: Mrs Maskelyne	1889
TR MES AD1/108	Structure: Heating apparatus Location: Catholic Church, Hucknall Torkard, Nottinghamshire Client: Rev. John R. McDonnell	1892
TR MES AD1/109	Structure: Heating apparatus alterations Location: Raddington House, Nottingham, Nottinghamshire Client: W. Forster Mills	1901

TR MES AD1/110	Structure: Conservatory Location: Rectory Farm, Streatley, Goring-on-Thames, Oxfordshire Client: Capt. C.L. Marks DSO	1903
TR MES AD1/111	Structure: Heating apparatus, greenhouse Location: Maesyrcugiau Manor RSO, Carmarthenshire, Wales Client: C. Mansel	1906
TR MES AD1/112	Structure: Conservatory Location: Sherwood Hall, Mansfield, Nottinghamshire Client: H.W. Mills	1899
TR MES AD1/113	Structure: Conservatory Location: The Dormers, Langley Avenue, Surbiton, Surrey Client: Mr Mazetti per Hampton and Sons [Builders]	1905
TR MES AD1/114	Structure: Conservatory Location: Glenn, 69 Crystal Palace Park Road, London Client: M. Michaelson	1895
TR MES AD1/115	Structure: Vinery and conservatory Location: Mere House, Weaverham, Northwich, Cheshire Client: William Marshall	1896
TR MES AD1/116	Structure: Stove and vinery Location: Englemere, Ascot, Berkshire Client: Hon. Sir Robert H. Meade	1895
TR MES AD1/117 See also TR MES AD1/1396	Structure: Plant house Location: Arndene, Abbey Road, Barrow-in-Furness, Cumbria Client: J.P. Smith JP per Messrs. Mackereth Ltd	1905
TR MES AD1/118	Structure: Glasshouse Location: Thoresby Park, Ollerton, Nottinghamshire Client: Earl Manvers	1899
TR MES AD1/119	Structure: Glass House Location: 1 Green Street, Park Lane, London Client: Mathews and Rogers	1894-1900
TR MES AD1/121	Structure: Plant house and intermediate house; Peach House Location: Melton Park, Doncaster, South Yorkshire Client: Mrs Montague	1896; 1904
TR MES AD1/122	Structure: Peach House/Glass Houses Location: Dawson Street, Dublin, Ireland Client: Maguire and Catchell LTD	1898
TR MES AD1/123	Structure: Plant house Location: Ivy House, Churchstoke, Montgomeryshire, Wales Client: A.G. Montford	1888
TR MES AD1/124	Structure: Cucumber and Melon houses Location: Wickham Hall, West Wickham, Beckenham, Kent Client: G. Mellin	1897
TR MES AD1/125	Structure: Vinery Location: Grove House, South Woodford, Essex Client: J. Miller	1891
TR MES AD1/127	Structure: Heating apparatus Location: Hampworth Lodge, Downton, Salisbury, Wiltshire Client: Mrs Morrison	1896

TR MES AD1/128	Structure: Plant house Location: Queens Park, Kilburn, North Yorkshire Client: Alex McKenzie	1890
TR MES AD1/129	Structure: Greenhouse Location: Palace House, Beaulieu, Southampton, Hampshire Client: Lord Montague	1894
TR MES AD1/131	Structure: Extension to greenhouse Location: Ardnaveigh, Birch Hill, Antrim, Ireland Client: Henry B. Murray	1890
TR MES AD1/132	Structure: Conservatory Location: Heworth Hyrst, York, Yorkshire Client: Mrs Middlewood	1899
TR MES AD1/133	Structure: Orchid House and boiler shed Location: Richmond House, Hayling Island, Hampshire Client: Charles H. McEuen	1897
TR MES AD1/134	Structure: Glass house Location: The Willows, Wickhambreaux near Dover, Kent Client: John G. Meiggs	1891
TR MES AD1/136	Structure: Conservatory Location: Pinner, Middlesex Client: F.H. Mabbett per Baker and Turrill [Architects]	1895
TR MES AD1/139	Structure: Orangery Location: Markeaton Hall, near Derby, Derbyshire Client: Mrs Mundy	1904
TR MES AD1/140	Structure: Glass veranda Location: Savernake Hospital, near Marlborough, Wiltshire Client: Marlborough Cottage Hospital	1904
TR MES AD1/141	Structure: Plant house Location: Howard Villa, Cardington, Bedfordshire Client: Mrs Gertrude Mills	1904
TR MES AD1/142	Structure: Heating apparatus Location: Lea Court, The Lees, Westcliff-on-Sea, Essex Client: W.J. Maddison	1904
TR MES AD1/143	Structure: Greenhouses Location: 10 Rothsay Gardens, Bedford, Bedfordshire Client: R.H. Kinsey	1899
TR MES AD1/144	Structure: Greenhouse Location: Tissington Hall, Ashbourn, Derbyshire Client: Mrs Reid Martin	1892
TR MES AD1/145	Structure: Greenhouse Location: Culmington House, Bromfield, Shropshire Client: Capt. Money DSO	1906
TR MES AD1/146	Structure: Greenhouse Location: Westfield, Catherine Road, Surbiton, Surrey Client: Dr H.A. Martin	1900
TR MES AD1/147	Structure: Conservatory Location: The Manor House, Limpley Stoke, Bath, Somerset Client: H.M. Marshall	1904
TR MES AD1/148	Structure: Greenhouse Location: The Red House, Bodicote, Banbury, Oxfordshire Client: Lt. Col. Hon. C.C. Molyneux	1906

TR MES AD1/149	Structure: Peach house and vinery Location: Townleigh, Lewdown, Devon Client: Mr H.B. Blackburn per G.H. Mounsdon [Nurseryman]	1893
TR MES AD1/150	Structure: Heating apparatus Location: The Hall, Angle, Pembrokeshire, Wales Client: Col. R. Mirehouse	1906
TR MES AD1/151	Structure: Conservatory and porch Location: Northwood Lodge, Finsbury Park, London Client: J.W. Maltby	1902
TR MES AD1/153	Structure: Conservatory Location: Smedmore, Corfe Castle, Dorset Client: Col. Marsel	1894
TR MES AD1/154	Structure: Greenhouse and Vinery Location: Brecon, Powys, Mid Wales Client: Col. J. Morgan, Mayor of Brecon	1890
TR MES AD1/155	Structure: Vinery Location: Mostyn Hall, Mostyn, Flintshire, North Wales Client: Lord Mostyn	1903-1951
TR MES AD1/156	Structure: Plant house Location: 'Gladswood', Wimbledon Common, London Client: W.E. Martyn	1898
TR MES AD1/157	Structure: Conservatory Location: Barnadistron Hall, Haverhill, Suffolk Client: Lady Malcolm of Potallock	1903
TR MES AD1/158	Structure: Conservatory, Heating Apparatus Location: Bolehall Manor house, Tamworth, Staffordshire Client: W. McGregor	1890
TR MES AD1/159	Structure: Conservatory Location: House at Kenyon Junction, Cheshire Clients: W.E. and R.T. Marsh	1891
TR MES AD1/161 [2 packets]	Structure: Conservatory; Greenhouse and heating Location: The Brooms, Stone, Staffordshire Client: C. McIlroy	1899; 1924
TR MES AD1/189	Structure: Plant House Location: Park Nurseries, Barrack Lane, Lenton, Nottinghamshire Client: Mr Kingdon per Mr Butters	1903
TR MES AD1/190	Structure: Glass Houses Location: Alveston Hall, Nantwich, Cheshire Client: A. Knowles	1903
TR MES AD1/193	Structure: Greenhouse boiler Location: The White House, Barrowby, Grantham, Lincolnshire Client: T.G. Jackson	1919
TR MES AD1/193	Structure: Conservatory; Plant house Location: Welby, Grantham, Lincolnshire Client: T.G. Jackson	1905; 1909
TR MES AD1/194	Structure: Boiler Location: To be shipped to Calcutta Client: Indian Government, India Office, Whitehall	1903
TR MES AD1/195	Structure: Conservatory Location: Quince Lawn, Cheltenham, Gloucestershire Client: Percy Hubert Hepburn Kenworthy	1903

TR MES AD1/196 See also TR MES AD1/230	Structure: Carnation House Location: The Abbey, Cirencester, Gloucestershire Client: Thomas Kingscote	1904
TR MES AD1/197	Structure: Heating apparatus for greenhouse Location: 17 Spring Gardens, Spalding, Lincolnshire Client: W. Jepson	1904
TR MES AD1/198	Structure: Tomato house Location: Walney Island, Barrow in Furness, Cumbria Client: Isle of Walney Estates Co. Ltd [Branch of Vickers, Sons and Maxim Ltd]	1902
TR MES AD1/199	Structure: Vinery and peach house; Greenhouse Location: Fawley House, Hillmorton Road, Rugby, Warwickshire Client: J.H. Ivens	1903; 1913
TR MES AD1/201	Structure: Vinery Location: Snatchwood Park, Pontypool, Gwent, Wales Client: P.H. Jones	1905
TR MES AD1/202	Structure: Peach house; Conservatory; Fernery Location: Northgate Place, Winchester, Hampshire Client: H.E. Johnson	1897; 1899; 1906
TR MES AD1/204	Structure: Extension to Greenhouse Location: Rotherwood, Stafford, Staffordshire Client: Nicolas Joyce	1902
TR MES AD1/204	Structure: Plant house and stove Location: The Smallthornes, Stafford, Staffordshire Client: Nicolas Joyce	1895
TR MES AD1/205	Structure: Plant house and stove Location: Oulton Old Hall, Stone, Staffordshire Client: F.G. Kitchener	1898
TR MES AD1/206	Structure: Vinery Location: Walton Lodge, Chesterfield, Derbyshire Client: W.Wynne Jendwine	1902
TR MES AD1/209	Structure: Greenhouses Location: Treeton Grange, Treeton, near Rotherham, South Yorkshire Client: F.J. Jones	1893; 1901
TR MES AD1/210	Structure: Greenhouse Location: Vancouver House, Forest Hill, London Client: Walter King	1906
TR MES AD1/211	Structure: Greenhouse Location: Dundee House, Mill Plat, Isleworth, Middlesex Client: G.M. Gerality per R. Knight	1898
TR MES AD1/212	Structure: Painting Vinery and other buildings, and fitting ventilator Location: "Fern Bank", 32 Palatine Road, Withington, Manchester, Lancashire Client: George King	1902
TR MES AD1/213	Structure: Conservatory Location: Spring Lodge, Richmond Road, Twickenham, London Client: Capt. Leonard O. Kelly	1901
TR MES AD1/214	Structure: Plant house and stove Location: The Oaklands, Preston Brook, near Warrington, Cheshire Client: W.C. Jones	1891

TR MES AD1/216	Structure: Vineries Location: Pevensey, Hastings, East Sussex Client: W.J. Kelsey	1894
TR MES AD1/217	Structure: Greenhouse Location: "Invergloy", Grasmere Road, Bromley, Kent Client: G/C.H. Kenning	1894
TR MES AD1/218	Structure: Guttering and pipes Location: Keppoch Iron Works, Glasgow, Scotland Client: David King and Sons	1891
TR MES AD1/220	Structure: Boiler Location: Stourbridge, West Midlands Client: Jones and Attwood [Engineers]	1891
TR MES AD1/221	Structure: Conservatory Location: Lovelace Gardens, Surbiton, Surrey Client: J. Jenkins	1890
TR MES AD1/223	Structure: Heating apparatus Location: Albert Court Works and Wood Lane Works, London Client: Kensington and Knightsbridge Electric Lighting Company/Nottina Hill Electric Company	1900
TR MES AD1/224	Structure: Glasshouse Location: Quarndon Hill, near Derby, Derbyshire Client: Alfred Jacobson	1902
TR MES AD1/225	Structure: Greenhouse/Conservatory Location: Badsworth Grange, Pontefract, West Yorkshire Client: Mrs Heywood Jones	1889-1891
TR MES AD1/226	Structure: Heating apparatus for house and conservatory Location: Rotherhill, Midhurst, West Sussex Client: Rev. H.R. Keene	1889
TR MES AD1/227	Structure: Greenhouse; Vinery Location: Heron Lodge, Red Hill, Worcester, Worcestershire Client: W.Kilbourne Kay	1897-1898; 1903
TR MES AD1/228	Structure: Mains water lines Location: Sunnyhill Vineries, Littleover, Derby, Derbyshire Client: J.M. Kitley	1900
TR MES AD1/229	Structure: Verandah Location: Leighton Hall, Ironbridge, Shropshire Client: J.T. Kynnersley	1888-1890
TR MES AD1/230 [1 of 2 packets] See also TR MES AD1/196	Structure: Carnation house Location: Watermoor House, Cirencester, Gloucestershire Client: Thomas Kingscote, MVO	1919
TR MES AD1/230 [2 of 2 packets]	Structure: Carnation house; Extension to greenhouse Location: Faringdon House, Faringdon, Berkshire Client: Thomas Kingscote; Lord Berners	1899; 1933-1937
TR MES AD1/231	Structure: Heating apparatus Location: Westgate, Sleaford, Lincolnshire Client: Gerald Knight	1895
TR MES AD1/232	Structure: Vinery and plant house Location: Hawthorne Villa, Huddersfield Road, Barnsley, South Yorkshire Client: H. Johnson	1896
TR MES AD1/234	Structure: Vineries and repainting greenhouses Location: Shoreham Place, Shoreham, Sevenoaks, Kent Client: Sir Henry James	1894

TR MES AD1/235	Structure: Conservatory Location: Lisselan, Clonakilty, Ireland Client: Reginald Bence Jones	1896
TR MES AD1/236	Structure: Conservatory Location: Brynteg, Merthyr Tydfil, South Wales Client: C.H. James	1890
TR MES AD1/237	Structure: Vineries Location: Horsley Woodhouse, Derby, Derbyshire Client: H. Jordan	1899
TR MES AD1/240 [2 packets]	Structure: Plant houses, heating to mushroom house Location: Thorpe Hall, Tamworth, Staffordshire Client: W.F. Inge	1890-1900
TR MES AD1/241	Structure: Glasshouse Location: Holmesfield, Kimberworth, Rotherham, South Yorkshire Client: J.B. Jenkinson	1902
TR MES AD1/243	Structure: Heating apparatus Location: The Mount, Chepstow, Monmouthshire, Wales Client: M. Pegler per W. Jones and Son [Builders]	1901
TR MES AD1/244	Structure: Heating apparatus Location: Rauceby Asylum, M.S. House, Lincolnshire Client: Kirk, Knight and Co., Sleaford	1901
TR MES AD1/246	Structure: Conservatory and heating apparatus Location: Windcliffe, Niton, Isle of Wight Client: R. Temple G. Kirkpatrick	1901
TR MES AD1/247	Structure: Boiler Location: Fawsley Park, Daventry, Northamptonshire Client: Lady Knightley	1902
TR MES AD1/248	Structure: Plant house and stove Location: Gladwyn, Stoke-on-Trent, Staffordshire Client: H. Gwynne Kirkham	1902
TR MES AD1/249	Structure: Conservatory Location: Hailsham, Sussex Client: Alfred Kent	1898
TR MES AD1/250	Structure: Glasshouse Location: The Orphanage, Aberlour, Strathspey, Scotland Client: Rev. Charles Jupp	1894
TR MES AD1/251	Structure: Conservatory Location: 5 Chartfield Road, Putney, London Client: Mrs Jackson	1901
TR MES AD1/252	Structure: Conservatory Location: Kents Bank, via Carnforth, Cumbria Client: R. Illingworth	1896
TR MES AD1/253	Structure: Heating apparatus Location: Bayfield Hall, Holt, Norfolk Client: Sir Alfred Jodrell, Bart	1894
TR MES AD1/254	Structure: Glasshouses Location: Delvin Lodge, Balbriggan, Ireland Client: R.D. Jameson	1892
TR MES AD1/257	Structure: Boilers Location: Rotherham, South Yorkshire Client: Messrs. Robert Jenkins and Co, boiler makers	1894-1898
TR MES AD1/258	Structure: Greenhouse Location: Babington Lane, Elmbank, Burton Road, Derby, Derbyshire Client: John Jerram	1896

TR MES AD1/260	Structure: Boiler Location: Dorset House, Heaton Chapel, near Stockport, Cheshire Client: William Jennison	1893
TR MES AD1/260	Structure: Plant house Location: Derby House, Heaton Moor, Stockport, Cheshire Client: John Jennison	1892
TR MES AD1/261	Structure: Stove and porch; Plant house Location: Broomsleigh, Seal Chart, Sevenoaks, Kent Client: Thomas Johnson	1886; 1894
TR MES AD1/262	Structure: Vinery Location: Mount Alyn, Rossett RSO, Denbighshire, Wales Client: W.T. Jolliffe	1901
TR MES AD1/264	Structure: Conservatory Location: Mountains, Tonbridge, Kent Client: J.H. Johnson	1889
TR MES AD1/265	Structure: Conservatory Location: Snatchwood House, Pontypool, Gwent, Wales Client: Edward Jones	1900
TR MES AD1/266	Structure: Boiler; Greenhouse Location: Middleton Park, Bicester, Oxfordshire Client: Right Hon. Earl of Jersey	1903; 1920
TR MES AD1/266	Structure: Palm house; Boiler Location: Osterley Park, Isleworth, Middlesex Client: Right Hon. Earl of Jersey	1898; 1932
TR MES AD1/267	Structure: Greenhouse Location: The Old Hall, Rearsby, Leicestershire Client: Major Campbell Johnson	1905
TR MES AD1/269	Structure: Greenhouse Location: High View, Oatlands, Walton-on-Thames, Surrey Client: Ernest Hill	1904
TR MES AD1/270	Structure: Conservatory Location: Sherwood Rise, Nottingham, Nottinghamshire Client: C. Hibbert	1890
TR MES AD1/272	Structure: Greenhouse Location: Grendon Rectory, Grendon, Atherstone, Warwickshire Client: Rev. H. Hanmer	1906
TR MES AD1/273	Structure: Plant house Location: Dunnington Hall, York, Yorkshire Client: John Hildyard	1906
TR MES AD1/275	Structure: Conservatory Location: The Manor, Little Berkhamstead, Hertfordshire Client: C. Hanbury	1903
TR MES AD1/276	Structure: Peach house and Vinery; Boiler Location: Coed Helen, Caernarvon, North Wales Client: Lloyd W.J. Hughes; Major Trevor Hughes	1904; 1931
TR MES AD1/277	Structure: Glasshouse Location: Hylands, Arlington, near Hailsham, Sussex Client: G.S. Harris	1902
TR MES AD1/278	Structure: Repair work Location: Clare Court, Wokingham, Berkshire Client: Mrs Hatherill	1906

TR MES AD1/280	Structure: Vinery and pits Location: Rock House, Lansdowne Road, Bath, Somerset Client: Miss Hope	1904
TR MES AD1/282	Structure: Conservatory Location: Oakdene, New Barnet, Hertfordshire Client: C. Honeywill	1912
TR MES AD1/282	Structure: Conservatory Location: Cedardale, Richmond Road, New Barnet, Hertfordshire Client: C. Honeywill	1903
TR MES AD1/283	Structure: Glasshouse Location: Morington, Dunscore, Dumfries-shire, Scotland Client: T. Hope-Bell	1903
TR MES AD1/284	Structure: Vineries; Forcing house Location: Binfield Manor, Bracknell, Berkshire Client: Right Hon. Lord Arthur Hill; L.R. Erskine	1904; 1908
TR MES AD1/285 See also TR MES AD1/261	Structure: Heating apparatus Location: Broomsleigh, Seal Chart, Sevenoaks, Kent Client: H.A. Hooker	1902; 1909
TR MES AD1/286	Structure: Plant house Location: The Merrie Thought, Fordingbridge, Hampshire Client: Miss Hulse	1901
TR MES AD1/287	Structure: Bridge passageway Location: Southfield House, Cottingham, East Yorkshire Client: Joseph H. Horsley	1896
TR MES AD1/289	Structure: Plant house Location: Holloway Sanitorium, Virginia Water, Berkshire Client: Dr W.D. Moore	1900
TR MES AD1/290	Structure: Greenhouse Location: Glascoed, Llanrug RSO, Caernarvonshire, Wales Client: Trevor Hughes	1904
TR MES AD1/292	Structure: Greenhouses and Peach House; Heating apparatus Location: Chavenage, Tetbury, Gloucestershire Client: Col. W.W. Hoole; Major Lowsley Williams	1891-1893; 1913
TR MES AD1/293	Structure: Conservatory; Heating apparatus Location: Oaklands, Kenilworth Road, Leamington, Warwickshire Client: A. Holt	1901; 1909
TR MES AD1/294	Structure: Plant house; Additions to greenhouse Location: Manor House, Overseal, Ashby de la Zouch, Leicestershire Client: John Hall	1894; 1902
TR MES AD1/296	Structure: Greenhouse Location: Hilderstone, Hartford, Cheshire Client: Charles Humfrey	1908
TR MES AD1/296	Structure: Conservatory Location: The Poplars, Winnington Park, Northwich, Cheshire Client: Charles Humfrey	1893
TR MES AD1/297 See also TR MES AD1/1768	Structure: Conservatory and tea room Location: Alderwasley Hall, near Wirksworth, Derbyshire Client: Lieut. Col. A.F. Hurt	1902

TR MES AD1/300	Structure: Plant house, stove and pit Location: Clewer Lodge, Windsor, Berkshire Client: Mrs Hornby	1889
TR MES AD1/301	Structure: Conservatory Location: The Dene, Woburn Sands, Bedfordshire Client: H.B. Mallam per A. Hudson [Plumber]	1896
TR MES AD1/302	Structure: Greenhouses and conservatory Location: The Rookery, Southport [Estate Office at The Grove, Roe Lane, Southport], Merseyside Client: Charles H.B. Hesketh	1904; 1912
TR MES AD1/306	Structure: Heating apparatus Location: Mendip Lodge, De Parys Avenue, Bedford, Bedfordshire Client: L.A.W. Auley per W. Hagnes [Builder]	1891
TR MES AD1/307	Structure: Greenhouse Location: 17 Thornhill Road, Croydon, Cambridgeshire Client: W. Hunter	1894
TR MES AD1/308	Structure: Conservatory Location: Pinehurst, Headley, Hampshire Client: E.F. Hubbuck	1900
TR MES AD1/310	Structure: Plant house Location: Rock Hill, Sherwood Rise, Nottingham, Nottinghamshire Client: H. Hopkinson	1897
TR MES AD1/311	Structure: Greenhouses Location: St Mary's Abbey, Cardington Road, Bedford, Bedfordshire Client: Hurst Hodgson	1902
TR MES AD1/313	Structure: Peach House; Vinery Location: Branstone House, near Burton-on-Trent, Staffordshire Client: Charles Harrison	1894; 1900
TR MES AD1/314	Structure: Greenhouses Location: Brambridge House, near Bishopstoke, Hampshire Client: Major Powney per Hampton and Sons [Builders]	1901
TR MES AD1/315	Structure: Plant house; Orchid house Location: Oakfield Cottage, Dartford Heath, Kent Client: J.G. Hepburn	1899; 1903
TR MES AD1/318	Structure: Greenhouse Location: Ware, Hertfordshire Client: Thomas Hunt	1895
TR MES AD1/319	Structure: Greenhouse Location: Moel Llys, Penmaenmawr, Conwy, South Wales Client: T.E. Horton	1892
TR MES AD1/320	Structure: Peach house; Greenhouses Location: Manor House, Alton, Hampshire Client: Henry Hall; Goodwyn Hall	1899; 1908-1914
TR MES AD1/321	Structure: Conservatory Location: Mangersbury Manor, Stow on the Wold, Gloucestershire Client: J.H. Hewitt	1900
TR MES AD1/322	Structure: Greenhouse Location: Fraysbrook, West Drayton, Middlesex Client: E. Humbert	1892

TR MES AD1/324	Structure: Greenhouse Location: Shepherds Hill, Highgate, London Client: Frederick Hindley	1892
TR MES AD1/326	Structure: Vineries Location: Hailsham Vicarage, Hailsham, Sussex Client: Rev. F. Clyde Harvey	1892
TR MES AD1/328	Structure: Stove and plant house Location: Cyprus Road, Nottingham, Nottinghamshire Client: Charles Hill	1892
TR MES AD1/329	Structure: Conservatory Location: Laxton Park, Stamford, Lincolnshire Client: James Hornsby	1896
TR MES AD1/331	Structure: Greenhouse Location: Tumbly Lawn, Boston, Lincolnshire Client: Sir H.M. Hawley, Bart	1900
TR MES AD1/332	Structure: Greenhouse Location: Sandle Manor, Fording Bridge, Salisbury, Wiltshire Client: Sir Edward Hulse, Bart	1900
TR MES AD1/333	Structure: Plant house Location: Highfield, Shrewsbury, Shropshire Client: T.M. Howells	1898
TR MES AD1/335	Structure: Greenhouse and Vinery Location: The Grove, Henley on Thames, Oxfordshire Client: F.C. Hill	1895-1896
TR MES AD1/338	Structure: Conservatory heating apparatus Location: Ingleside, Edge Hill Road, Castle Bar, Ealing, London Client: M. Hulbert	1894-1895
TR MES AD1/339	Structure: Ventilation and lighting Location: 100a Queen Victoria Street, London Client: James Hill	1889-1890
TR MES AD1/340	Structure: Greenhouse Location: Walton House, nr. Chesterfield, Derbyshire Client: Mansfeldt H. Humble	1893-1894
TR MES AD1/341	Structure: Conservatory Location: "The Hollies", Norton Lees, Sheffield, South Yorkshire Client: J. Hall	1902
TR MES AD1/342	Structure: Conservatory Location: Thorpe House, Norton Lees, Sheffield, South Yorkshire Client: G. Hall	1893
TR MES AD1/343	Structure: Conservatory; Vinery Location: Rock Lea, Barrow-in-Furness, Cumbria Client: G.S. Heath	1899; 1901
TR MES AD1/344	Structure: Conservatory at Whatstandwell Location: Crich, nr. Matlock Bath, Derbyshire Client: John Haynes	1902
TR MES AD1/345	Structure: Conservatory at "New Close" Location: "Holm-Leigh", Cottingley Grange, Nab Wood, Shipley, Bradford, West Yorkshire Client: G. Holmes	1902
TR MES AD1/346	Structure: Potting shed, plus heating apparatus Location: Twycross, Atherstone, Warwickshire Client: Harrington Hulton	1891

TR MES AD1/347	Structure: Plant house Location: Sutton Place, Guildford, Surrey Client: Sydney Harrison	1889
TR MES AD1/348	Structure: Conservatory Location: Burleigh House, Belsize Lane, London Client: D.R. Harvest	1891
TR MES AD1/349	Structure: Greenhouse Location: Ketton Hall, Rutland, Rutlandshire Client: R.R. Hollins per T. Hare and Son	1902
TR MES AD1/350	Structure: Heating apparatus; Vineries Location: Stagenhoe Park, Welwyn, Hertfordshire Client: W. Bailey Hawkins	1895; 1906
TR MES AD1/351	Structure: Heating in greenhouse Location: Hapstead Gardens, Ardingley, Sussex Client: H.H. Hett	1901
TR MES AD1/352	Structure: Conservatory Location: The Wilderness, Blagdons Lane, Old Southgate, London Client: P.P. Hasluck	1896
TR MES AD1/353	Structure: Conservatory Location: Slindon House, Arundel, West Sussex Client: Major Leslie per Hampton and Sons	1905
TR MES AD1/355 [4 packets]	Structure: Greenhouse; Painting of greenhouse Location: South Heath, East Heath Road, Hampstead, London Client: H. Haines	1906; 1908-1933
TR MES AD1/356	Structure: Orchid house Location: Westonbirt House, Tetbury, Gloucestershire Client: Capt. Holford	1900
TR MES AD1/358	Structure: Vinery, new boiler Location: The Brewery, Ewaunfarren, Myrthyr Tydful, South Wales Client: Richard Harrop	1894
TR MES AD1/360	Structure: Heating apparatus Location: Hounslow Town Hall, London Client: H.G. Cresswell [Architect], T. Hiscock [Builder]	1889-1890
TR MES AD1/361	Structure: Conservatory Location: Molescroft, Beverley, East Yorkshire Client: Richard Hodgson	1900
TR MES AD1/370	Structure: Greenhouse Location: National School, Darfield, Barnsley, South Yorkshire Client: George Hoyle	1894
TR MES AD1/371	Structure: Forcing house Location: Froxmer Court, Worcester, Worcestershire Client: T.W. Hill	1893
TR MES AD1/373	Structure: Heating apparatus Location: The Gardens, Sawley near Derby, Derbyshire Client: Miss Burnett and Miss Page per Miss Grace Harriman	1895
TR MES AD1/374	Structure: Heating apparatus for fruit houses Location: Berry Hill, Mansfield, Nottinghamshire Client: Mrs Hollins	1897-1898
TR MES AD1/375	Structure: Pit and heating apparatus Location: Haffield, Ledbury, Herefordshire Client: Dr W.C. Henry	1891

TR MES AD1/377	Structure: Plant house Location: Hasley Manor, Warwick, Warwickshire Client: Alfred Hawlett	1896
TR MES AD1/378	Structure: Conservatory Location: Goddington, Chelsfield, Orpington, Hertfordshire Client: A. Miller Hallett	1892-1894
TR MES AD1/379	Structure: Greenhouses Location: Castle House, Buckingham, Buckinghamshire Client: H. Hearn per R.C. Hadland	1897; 1903
TR MES AD1/380	Structure: Conservatory Location: Sunnyside, Grimsby Road, Cleethorpes, Lincolnshire Client: Mrs Hill	1903
TR MES AD1/381	Structure: Vinery and potting house Location: The Rifleman Inn, Derby Street, Burton-on-Trent, Staffordshire Client: R.A. Haines	1903
TR MES AD1/382	Structure: Plant house Location: Margate Cemetery, Kent Client: R.A. Harris [Architect]	1903-1904
TR MES AD1/383	Structure: Glass house Location: 55 North Road, Carnarvon, South Wales Client: Mr W.G.S. Hynde	1903-1904
TR MES AD1/384	Structure: Heating apparatus Location: 52 Gower Street, Bedford Square, London Client: Miss Alice Hughes	1903-1904
TR MES AD1/384	Structure: Heating apparatus Location: Winfrith House, Winfrith, Dorchester, Dorset Client: Miss Alice Hughes	1903-1904
TR MES AD1/385	Structure: Fernery Location: Gospel Oak, Lapworth, Warwickshire Client: John Hildick	1905
TR MES AD1/386	Structure: Greenhouse Location: Fern Dene, Ryton on Tyne, Northumberland Client: H.C. Harvey	1892-1893
TR MES AD1/387	Structure: Greenhouse and stove; Boiler Location: The Gardens, Mower Hill, Pinner, Middlesex Client: Ambrose Heal; Mrs Heal	1898-1899; 1926
TR MES AD1/388	Structure: Vinery, plant house and store Location: "Avalon", Green Lanes, Finsbury Park, London Client: G. Hand	1892-1893
TR MES AD1/390	Structure: Greenhouse Location: Mayfield, West Park Road, Blackburn, Lancashire Client: Miss Hoyle	1889
TR MES AD1/391	Structure: Stove and intermediate house Location: Oldown, Almondsbury, Gloucestershire Client: W.H. Harford	1888
TR MES AD1/394	Structure: Renewing glasshouses Location: Finney Spring, Shepshed, Leicestershire Client: S. Tebbutt per Reginald J. Hill	1898
TR MES AD1/396	Structure: Conservatory Location: The Hoo, Welwyn, Hertfordshire Client: Viscount Hampden	1894

TR MES AD1/397	Structure: Conservatory Location: Holm Lea, Rainhill, Lancashire Client: Douglas Herman	1903
TR MES AD1/398	Structure: Greenhouse Location: Forest House, Binfield, Bracknell, Berkshire Client: Hon. Hugh Hare	1905
TR MES AD1/399	Structure: Orchid houses Location: Wonham, Bampton, Devon Client: Mrs John Holland	1896
TR MES AD1/400	Structure: Conservatory Location: Barton Mark, Winchester, Hampshire Client: James Harris	1898
TR MES AD1/401	Structure: Heating apparatus Location: Clifton House, Clifton, Derbyshire Client: Mrs C.M. Hodge	1897
TR MES AD1/403	Structure: Peach house, Cucumber house and potting shed Location: Abbeydale Park, Dore near Sheffield, South Yorkshire Client: E. Hall	1891
TR MES AD1/404	Structure: Peach House Location: Elmestree, Tetbury, Gloucestershire Client: F. Henry	1896
TR MES AD1/405	Structure: Heating apparatus Location: Stourton, Gillingham, Wiltshire Client: Sir Henry Ainslie Hoare	1895
TR MES AD1/407	Structure: Conservatory Location: 1 Claremont Buildings, Shrewsbury, Shropshire Client: Samuel Heighway	1898
TR MES AD1/408	Structure: Conservatory Location: Olton Court, Olton, Birmingham, West Midlands Client: D.C. Hasluck	1891
TR MES AD1/409	Structure: Plant house and propagating house Location: Birnam, Castle Hill Park, Ealing, London Client: J. Henderson	1887
TR MES AD1/410	Structure: Greenhouse Location: Cowley Manor, Cheltenham, Gloucestershire Client: James Horlick	1899
TR MES AD1/411	Structure: Conservatory Location: Oakdale, Ockley, Surrey Client: E.A. Hamlyn	1902
TR MES AD1/412	Structure: Orchid house Location: Elm House, Leatherhead, Surrey Client: Frank G. Howell	1891
TR MES AD1/414	Structure: Rose House Location: Oak Hall, Buckhurst Hill, Essex Client: W.G. Huxley	1898
TR MES AD1/415	Structure: Heating apparatus Location: 17 Palatine Square, Burnley, Lancashire Client: W.M. Holmes	1888
TR MES AD1/417	Structure: Plant house Location: Woodhouse Moor, Leeds, West Yorkshire Client: Thomas Hewson	1891

TR MES AD1/419 [3 Packets]	Structure: Plant house; Painting greenhouse; Repairs Location: Grove Lodge, Highgate Hill, London Client: Percival Hart	1899; 1923; 1928
TR MES AD1/421	Structure: Conservatory Location: The Elms, Thorpe Satchville, near Melton Mowbray, Leicestershire Client: G.W. Hillyard	1899
TR MES AD1/422	Structure: Plant house and stove Location: Oaklands, Plumstead Common, Woolwich, London Client: E. Hughes	1898
TR MES AD1/424	Structure: Intermediate plant house Location: South Hill Park, Bracknell, Berkshire Client: Sir Arthur Hayter	1897
TR MES AD1/425 [2 packets]	Structure: Plant house, Stove and Forcing houses; Painting Location: Hill House, Lexdon, Colchester, Essex Client: S.F. Hurnard	1892; 1919
TR MES AD1/426	Structure: Forcing house Location: Hutton John, Penrith, Cumbria Client: W.J. Hudleston	1892
TR MES AD1/427	Structure: Vinery and Stove Location: Upcott House, Barnstaple, Devon Client: Stafford Harding	1889
TR MES AD1/428	Structure: Greenhouses Location: The Gables, Burnham, Maidenhead, Berkshire Client: F.C.D. Haggard per A.F. Nutt [Architect]	1898
TR MES AD1/429	Structure: Heating apparatus Location: Bulwell Hall, Nottingham, Nottinghamshire Client: Thomas Hardy	1894
TR MES AD1/431	Structure: Porch Location: Bridgewater Villa, Margate, Kent Client: Robert A. Harris	1898
TR MES AD1/434	Structure: Vinery and Orchid house Location: The Acorns, Oakleigh Park, London Client: J.M. Holt	1898
TR MES AD1/436	Structure: Conservatory Location: Swanmore Cottage, Bishops Waltham, Hampshire Client: Charles R. Gunner	1898
TR MES AD1/437	Structure: Heating apparatus Location: St Johns College, Battersea, London Client: Messrs Gregory and Co. [Builders]	1898
TR MES AD1/438	Structure: Boiler Location: Victoria Works, Syston near Leicester, Leicestershire Client: H. Garner and Sons	1916
TR MES AD1/440	Structure: Conservatory Location: Briars Hey, Rainhill, Lancashire Client: William Gamble	1900
TR MES AD1/441	Structure: Conservatories Location: Four Elms/The Court, Ullesthorpe, Rugby, Warwickshire Client: H.G. Goodacre per Robert Cooke [Builder]	1902

TR MES AD1/441	Structure: Conservatories Location: Claybrook Grange near Rugby, Warwickshire Client: H.G. Goodacre per Robert Cooke [Builder]	1902
TR MES AD1/442	Structure: Plant House Location: Tapley, Bishops Teignton, Devon Client: Dr Galabin	1899
TR MES AD1/443	Structure: Plant House and Vinery Location: Graythwaite Manor, Grange-over-Sands, Cumbria Client: W.M. Gray	1903
TR MES AD1/446	Structure: Conservatory Location: The Towers, Hillingdon, Uxbridge, London Client: Dr H.Gervis	1902
TR MES AD1/447	Structure: Heating apparatus Location: Beaumont Manor, Cheshunt, Hertfordshire Client: G.F.H. Grant [Formerly T.J. Fisher]	1900
TR MES AD1/448	Structure: Conservatory Location: 1 Dorset Mansions, Bexhill on Sea, East Sussex Client: Mrs Gibson	1901
TR MES AD1/449	Structure: Conservatory Location: Summertown, Oxford, Oxfordshire Client: O. Grimby	1891
TR MES AD1/453	Structure: Orchid House; Peach house and cool Orchid House; Orchid House Location: Lesbury House, Lesbury RSO, Northumberland Client: T.G. Gibson	1893; 1894; 1897
TR MES AD1/454	Structure: Glass porch Location: Barholm, Bushmead Avenue, Bedford, Bedfordshire Client: Col. Grierson	1896
TR MES AD1/455	Structure: Conservatory; Glass roof Location: Parkside, Warham Road, South Croydon, Cambridgeshire Client: P.G. Guimareans	1898; 1900
TR MES AD1/460 [3 packets]	Structure: Greenhouse; Conservatory Location: Shamrock, Matham Road, East Molesey, Surrey Client: A.J. Gillott	1891-1895
TR MES AD1/461	Structure: Conservatory Location: Stoneywood, Victoria Park, Manchester, Lancashire Client: W. Gaddum	1889
TR MES AD1/462	Structure: Conservatory Location: Cathedral Precincts, Peterborough, Cambridgeshire Client: H.P. Gates	1890
TR MES AD1/464	Structure: Peach house Location: Gaunts House, Wimborne, Dorset Client: Sir Richard G. Glyn, Bt	1898
TR MES AD1/466	Structure: Forcing house Location: Garswood Hall, Newton le Willows, North Yorkshire Client: Lady Gerard	1889

TR MES AD1/467	Structure: Plant house and stove Location: Derwydd, Llandebie RSO, Carmarthenshire, Wales Client: Alan Stepney-Gulston	1894
TR MES AD1/468	Structure: Plant house Location: Butlers Court, Beaconsfield, Buckinghamshire Client: A. Grenfell	1894
TR MES AD1/469	Structure: Forcing house and stove house Location: Brydekirk, Parbold, near Southport, Lancashire Client: G. Graham	1902
TR MES AD1/470	Structure: Peach House Location: Stratton Audley Park, Bicester, Oxfordshire Client: Col. Gosling	1900
TR MES AD1/471	Structure: Range and Orchid House Location: East Haddon Hall, near Northampton, Northamptonshire Client: Mrs Guthrie	1892
TR MES AD1/473	Structure: "Live" steam heating apparatus for offices Location: Swadlincote near Burton-on-Trent, Staffordshire Client: Granville Colliery Company	1899
TR MES AD1/474	Structure: Conservatory and stove Location: The Hollies, Bramley, near Leeds, West Yorkshire Client: Edwin Gaunt	1895
TR MES AD1/475	Structure: Greenhouse Location: Ebrington, Campden, Gloucestershire Client: A.H. Gordon Duff	1899
TR MES AD1/475	Structure: Plant house Location: Churchmead, Hatherop, Fairford, Gloucestershire Client: A.H. Gordon Duff	1907
TR MES AD1/476	Structure: Vinery Location: 6 Wingfield Villas, Mannamead, Plymouth, Hampshire Client: Mr Goulding	1896
TR MES AD1/477	Structure: Plant house and stove Location: Hazelhurst, Worcester Park, Surrey Client: Charles Garton	1891
TR MES AD1/478	Structure: Conservatory Location: The Gables, Whittington, near Worcester, Worcestershire Client: S. Bromley Garrard	1892
TR MES AD1/479	Structure: Greenhouses Location: 5 The Grove, Highgate, London Client: R. Gaskell	1901; 1910
TR MES AD1/480	Structure: Vineries and peach houses Location: Hadzor, Droitwich, Worcestershire Client: H. Gough [Market Gardener]	1891
TR MES AD1/482 [2 packets]	Structure: Conservatory Location: Grosvenor House, 32 Harvard Road, Gunnersbury, London Client: Robert C. Gaverick	1902
TR MES AD1/483	Structure: Conservatory Location: Ivy Tower, near Tenby, Pembrokeshire, South Wales Client: Col. H.H. Goodeve	1892

TR MES AD1/484	Structure: Heating apparatus Location: The Hundred, Romsey, Hampshire Client: Mr Short per Messr. Golding and Son [Builders]	1892
TR MES AD1/485	Structure: Greenhouse Location: 55 The Grove, Bedford, Bedfordshire Client: W. Gilpin	1889-1890
TR MES AD1/486	Structure: Conservatory Location: Reedley Grove, near Burnley, Lancashire Client: J.R. Grimshaw	1889
TR MES AD1/488	Structure: Rose house Location: Tothill Nurseries, Plymouth, Hampshire Client: Amos Groombridge	1904
TR MES AD1/490	Structure: Conservatory Location: Redington Road, West Heath, Hampstead, London Client: Dr William Garnett	1902
TR MES AD1/492	Structure: Plant house and conservatory Location: The Larches, Luton, Bedfordshire Client: J.W. Green	1902-1903
TR MES AD1/494	Structure: Vinery and Plant House Location: West Street, Godmanchester, Cambridgeshire Client: W. Gadsby	1899
TR MES AD1/497	Structure: Conservatory Location: The Grove, Craven Arms, Shropshire Client: H.D. Greene, MP	1901
TR MES AD1/498	Structure: Conservatory Location: Mytton Hall, Shrewsbury, Shropshire Client: J.R. Greatorix	1901
TR MES AD1/499	Structure: Conservatory Location: 50 Plymouth Road, Penarth, Glamorganshire, Wales Client Henry Green	1898
TR MES AD1/500	Structure: Greenhouse Location: Aubrey House, Riverside, Twickenham, London Client: Col. Gardener	1894
TR MES AD1/501	Structure: Heating apparatus Location: Forest House, Shepshed, Loughborough, Leicestershire Client: H.H. Gibbs	1904
TR MES AD1/502	Structure: Conservatory Location: Keverstone Court, Manor Road, Bournemouth, Hampshire Client: W.E. Gibb per Samuel S. Dottridge [Architect]	1902
TR MES AD1/503	Structure: Plant house and heating apparatus Location: Abbotsfield, Tavistock, South Devon Client: F.F. Freeman	1894-1895
TR MES AD1/504 [2 packets]	Structure: Boiler replacement and repairs Location: Springkell, Ecclefechan, Eaglesfield, Dumfriesshire, Scotland Client: Sir J.E. Johnson-Ferguson, Bart	1917-1923
TR MES AD1/505	Structure: Conservatory Location: The Friary, Southgate Road, Winchester, Hampshire Client: Rev. Canon Furneaux	1900

TR MES AD1/506	Structure: Heating apparatus Location: 2 St Peters Terrace, Bournemouth, Hampshire Client: J.F. Fogerty	1900
TR MES AD1/509	Structure: Greenhouse Location: The College, All Saints, Derby, Derbyshire Client: T.A. Fuller	1901
TR MES AD1/510	Structure: Heating apparatus, enlarging stove Location: Haddon House, Bakewell, Derbyshire Client: Mrs Ward Fox	1890
TR MES AD1/512	Structure: Palm House and Orchid House Location: Dedworth Manor, Windsor, Berkshire Client: Edmund B. Foster	1897-1898
TR MES AD1/513 [3 packets]	Structure: Conservatory; Heating apparatus; Peach house Location: Woodlands, Clapham, Bedford, Bedfordshire Client: William L. Fitzpatrick	1901; 1902; 1903
TR MES AD1/514	Structure: Greenhouse Location: Long Royds, Skelmanthorpe near Huddersfield, South Yorkshire Client: John F. Field	1906
TR MES AD1/515	Structure: Vinery Location: Riverside, Kempsford, near Fairford, Gloucestershire Client: Tom Faulkner	1903
TR MES AD1/516	Structure: Glasshouses Location: Charlton House, Charlton, Pershore, Worcestershire Client: J. Faulkner	1899
TR MES AD1/517	Structure: Greenhouse Location: Catthorpe Hall, Catthorpe near Rugby, Leicestershire Client: W. Foster per Foster and Dicksie [Contractors]	1901
TR MES AD1/518	Structure: Glasshouses Location: Eastbury Park, Blandford, Dorset Client: Henry R. Farquharson	1891
TR MES AD1/519	Structure: Conservatory; Plant and forcing house Location: The Querns, Cirencester, Gloucestershire Client: J.P. Forsyth Forest; Capt. Hamilton Gordon	1898; 1911
TR MES AD1/520	Structure: Heating apparatus Location: Bohemia, Lichfield Road, Stafford, Staffordshire Client: Mrs Follows	1899
TR MES AD1/523	Structure: Conservatory Location: Cathedine, Burley-in-Wharfedale near Leeds, West Yorkshire Client: E.P. Arnold Foster	1901
TR MES AD1/524	Structure: Forcing house Location: Valencia Island, Ireland Client: Sir Maurice Fitzgerald, Bt, Knight of Kerry	1897
TR MES AD1/525	Structure: Heating of premises Location: 78 Upper Thames Street, London Client: Robert Fletcher and sons	1896
TR MES AD1/526	Structure: Heating apparatus Location: Rifle Street, Poplar, London Client: Far Famed Cake Company	1895
TR MES AD1/527	Structure: Forcing House Location: Broome Park, Betchworth, Surrey Client: Lady Louisa Fielding	1905

TR MES AD1/530	Structure: Heating apparatus Location: Warfleet, Dartmouth, Devon Client: Sir Thomas Freake	1898
TR MES AD1/531	Structure: Heating apparatus Location: Higham Bury, Ampthill, Bedfordshire Client: E. Jekyll per Samuel Foster [Contractor]	1899
TR MES AD1/532	Structure: Conservatory Location: Youghal, Co. Cork, Ireland Client: S.J. Merrick	1900
TR MES AD1/533	Structure: Greenhouse Location: Moreton Pinkney Manor, Byfield RSO, Northamptonshire Client: Miss Grey	1905
TR MES AD1/534	Structure: Plant House Location: Fox Hill, West Haddon, Rugby, Warwickshire Client: Hon. E.A. Fitzroy	1899
TR MES AD1/535	Structure: Greenhouse Location: The Parade, White Hart Lane, Tottenham, London Client: J.B. Ferreira	1891
TR MES AD1/536	Structure: Plant house Location: Milton Park, Peterborough, Cambridgeshire Client: G.W.C. Fitzwilliam	1893
TR MES AD1/537 [2 packets]	Structure: Heating apparatus and greenhouse; Boiler Location: The Croft, Hillmorton, Rugby, Warwickshire Client: George A. Fenwick; Alice K. Fenwick	1893; 1927
TR MES AD1/538	Structure: Plant House Location: Nettleworth Manor, Mansfield, Nottinghamshire Client: Lady Fitzherbert	1896
TR MES AD1/539	Structure: Fernery Location: The Uplands, Whitefield, near Manchester, Lancashire Client: J.R. Fletcher	1897
TR MES AD1/540	Structure: Conservatory Location: Ightfield Rectory, Whitchurch, Shropshire Client: Rev. R.B. Faulkner	1892
TR MES AD1/541	Structure: Conservatory Location: Belvoir House, Sandiacre, Derbyshire Client: E.W. Field	1897
TR MES AD1/542	Structure: Palm house Location: Sutton Court Nursery, Chiswick, London Client: W. Fromow and Son	1894
TR MES AD1/543	Structure: Conservatory; Glazing conservatory Location: Beechwood, 239 Osmaston Road, Derby, Derbyshire Client: Henry Fowke; Ernest E. Jordan	1899; 1916
TR MES AD1/544	Structure: Re-heating Vineries Location: The Coplow, Billesdon, Leicestershire Client: Rev. C.R. Fowke	1898
TR MES AD1/545	Structure: Vinery Location: Statton Hall, Ipswich, Suffolk Client: J.O. Fison	1895
TR MES AD1/546	Structure: Peach House Location: Hanbury, Burton-on-Trent, Staffordshire Client: Rev. J.R. Foot	1891

TR MES AD1/547	Structure: Heating apparatus Location: St Marys Parish Hall, Kilburn, London Client: E.H. Francis and Son	1890
TR MES AD1/548	Structure: Vinery, stove and pits Location: The Grange, Sutton, Surrey Client: R.C. Forster	1903
TR MES AD1/549	Structure: Plant house Location: Broomfield, Yalding, Maidstone, Kent Client: Charles E. Fletcher	1905
TR MES AD1/552	Structure: Greenhouse Location: Egerton, Mount Park, Harrow, London Client: Miss Forbes	1890
TR MES AD1/553	Structure: Glasshouses Location: Enstone, Oxfordshire Client: J. Faulkner	1889
TR MES AD1/554	Structure: Greenhouse Location: Merlebank, Donnington Holt, Newbury, Berkshire Client: Mrs Fellows	1905
TR MES AD1/556	Structure: Iron stage for greenhouse Location: Campsall Hall, Doncaster, South Yorkshire Client: F.B. Frank	1905
TR MES AD1/557	Structure: Skylights and opening apparatus Location: Parkneuk Works, Motherwell, North Lanarkshire, Scotland Client: Alex Findlay and Co	1903
TR MES AD1/558	Structure: Plant House Location: Mon Plaisir, Sherringham, Norfolk Client: C. Foster	1901
TR MES AD1/559	Structure: Heating apparatus Location: Bottling Stores, 121 Mostyn Street, Llandudno, Wales Client: T.H. Fitzsimmons	1905
TR MES AD1/560	Structure: Plant house Location: Christs College, Cambridge, Cambridgeshire Client: Rev. Thomas C. Fitzpatrick	1905
TR MES AD1/561	Structure: Conservatory Location: Kirkconnel, Ealing Common, London Client: Mrs Forbes per Robert Griggs [Architect]	1906
TR MES AD1/561	Structure: Fernery Location: Hazeldean, Putney Hill, London Client: Mrs J. Forbes per Robert Griggs [Architect]	1901
TR MES AD1/563 [2 packets]	Structure: Heating apparatus; Vinery and plant houses Location: Holme House, Lightcliffe near Halifax, West Yorkshire Client: Sir Algernon Firth	1902; 1913
TR MES AD1/564	Structure: Greenhouse Location: Fountain Hospital, Grove Road, Lower Tooting, London Client: Messrs Wilson, Son & Aldwinckle [Architects]	1894
TR MES AD1/565	Structure: Greenhouse Location: Lodge Hill, Farnham, Surrey Client: Miss J. Fildes	1901
TR MES AD1/566	Structure: Plant house Location: Halford Manor, Ettington, Warwickshire Client: F.M. Freake	1903

TR MES AD1/613	Structure: Glasshouses Location: Swaylands, Tonbridge, Kent Client: G.J. Drummond per Hope Constable [Builder]	1898
TR MES AD1/614	Structure: Greenhouse Location: Railway Signal Works, Worcester, Worcestershire Client: Messrs. Dutton and Co.	1896
TR MES AD1/615	Structure: Greenhouse Location: Tanfield, West Clandon, Guildford, Surrey Client: Mrs Du Buisson	1898
TR MES AD1/616	Structure: Plant house Location: The Priory, Royston, Hertfordshire Client: Lady Dacre	1891
TR MES AD1/619	Structure: Glass range Location: Wappenbury, Leamington Spa, Warwickshire Client: George Darlinson	1897
TR MES AD1/620	Structure: Forcing house and vineries Location: Cramore Place, Chislehurst, Kent Client: J. Dewrance	1901
TR MES AD1/621	Structure: Vinery and heating apparatus Location: The Lodge, Darley Dale, Matlock, Derbyshire Client: T. Cooper Drabble	1900
TR MES AD1/622	Structure: Glasshouse Location: 2 St Margarets Road, Oxford, Oxfordshire Client: H.A. Dickson	1896
TR MES AD1/623	Structure: Greenhouse Location: Avenue House, Sunbury-on-Thames, Surrey Client: Horace Dove	1899
TR MES AD1/624	Structure: Greenhouse Location: Blackbridge House, Winchester, Hampshire Client: Col. F.A. Dickens	1899
TR MES AD1/625	Structure: Plant house Location: Bexhill-on-Sea, East Sussex Client: Earl de la Warr	1899
TR MES AD1/626	Structure: Conservatory Location: Wilford Lane, West Bridgford, Nottinghamshire Client: H. Daubrey	1902
TR MES AD1/627	Structure: Heating apparatus Location: 66 Victoria Street, Westminster, London Client: Drake & Gorham	1894
TR MES AD1/627	Structure: Greenhouse Location: Copyhold, Cuckfield, Sussex Client: Bernard L. Drake	1913
TR MES AD1/628	Structure: Heating apparatus Location: Broome Place, Bungay, Norfolk Client: Edmund de Poix	1888
TR MES AD1/630	Structure: Range of glasshouses Location: Childwell Lodge, Wavertree, Liverpool, Merseyside Client: A. Earle	1892
TR MES AD1/631	Structure: Heating apparatus Location: Syleham Nurseries, Scole, Norfolk Client: Evans and Co.	1906
TR MES AD1/632	Structure: Conservatory Location: Warren Road, Guildford, Surrey Client: Stanley Ellis [Builder]	1903

TR MES AD1/632	Structure: Greenhouse Location: 29 Chertsey Street, Guildford, Surrey Client: Stanley Ellis [Builder]	1933
TR MES AD1/634	Structure: Greenhouse Location: The Cottage, Lyne, Chartsey, Surrey Client: Wallace Elliot	1904
TR MES AD1/635	Structure: Peach house, Vinery and plant house Location: Sparken House, Worksop, Nottinghamshire Client: J.D. Ellis	1894
TR MES AD1/637	Structure: Stove and repair work Location: Woodlands, Cobham, Surrey Client: C.W. Earle	1889
TR MES AD1/638	Structure: Conservatory Location: Heather Bank, Carlton Road, Tunbridge Wells, Kent Client: George Evans	1889
TR MES AD1/639	Structure: Conservatory Location: The Elms, Wokingham, Berkshire Client: T.E. Ellison	1893
TR MES AD1/640	Structure: Stove, intermediate house and plant house Location: Creag Mhor, Onich, Highland, Scotland Client: Lady Alice Ewing	1890
TR MES AD1/641	Structure: Greenhouse Location: Kingston Estate, Beaufort Road, near Surbiton, Surrey Client: Messrs Edmeston and Gabriel [Architects]	1896
TR MES AD1/643 [2 packets]	Structure: Greenhouse; Stove house, heating and ventilating apparatus; Peach houses Location: Youlbury, Boars Hill, near Oxford, Oxfordshire Client: Sir Arthur J. Evans	1893; 1911; 1914
TR MES AD1/644	Structure: Boiler Location: Littlebury, Saffron Walden, Essex Client: E. Emson	1906
TR MES AD1/645	Structure: Greenhouse Location: Woodlands, Sevenoaks, Kent Client: Mrs Ellerton	1889
TR MES AD1/646	Structure: Conservatory Location: Blantyre, 5 Cavendish Crescent, The Park, Nottingham, Nottinghamshire Client: Francis M. Ellis	1901
TR MES AD1/647	Structure: Stove and plant house Location: Deeping St James Manor, Market Deeping, Lincolnshire Client: Lady Exeter	1901
TR MES AD1/648	Structure: Vineries Location: Holmehurst, Loughton, Essex Client: F.L. Edwards	1887
TR MES AD1/649	Structure: Greenhouse Location: Ewe and Lamb Inn, The Butts, Worcester, Worcestershire Client: Yeates and Jones [Architects] per Lewis Clarke and Co.	1901
TR MES AD1/650	Structure: Conservatory Location: Fenton Hall, Fenton, Staffordshire Client: J. Linday per H.P. Embrey and Co. [Builders]	1901

TR MES AD1/651	Structure: Forcing house Location: Eversley, Westwood Park, Forest Hill, Oxfordshire Client: E.H.P Eason	1893
TR MES AD1/653	Structure: Greenhouse Location: Diamond House, Burgess Hill, Sussex Client: Ellis, Drew and Co.	1892
TR MES AD1/655	Structure: Peach house Location: Lindley Hall, Nuneaton, Warwickshire Client: Capt. Vincent T. Eyre	1889-1891
TR MES AD1/657	Structure: Pit framed lights and heating apparatus Location: Standish Hall, Wigan, Lancashire Client: N. Eckersley	1890-1891
TR MES AD1/658	Structure: Greenhouses Location: Hollydene, Longton, Staffordshire Client: C.J. Edwards	1897-1898
TR MES AD1/660	Structure: Boiler Location: Farington House, Preston, Lancashire Client: John Eccles	1900
TR MES AD1/661	Structure: Photographic Studio Location: Alexandria, Egypt Client: Egyptian Government per C.W. Burton [engineer]	1897
TR MES AD1/662	Structure: Glasshouse Location: Frogmore, Rickmansworth, Hertfordshire Client: Allan Edwards	1897-1898
TR MES AD1/663	Structure: Conservatory Location: Knivedon, Leek, Staffordshire Client: C.C. Ellis	1902
TR MES AD1/664	Structure: Forcing House and heating apparatus Location: Weston House, Swadlincote, near Burton-on-Trent, Staffordshire Client: A.H. and W.E. Eley [Nurserymen]	1903
TR MES AD1/664	Structure: Forcing House and heating apparatus Location: Seal Wood Nurseries, Linton, near Burton-on-Trent, Staffordshire Client: A.H. and W.E. Eley [Nurserymen]	1903
TR MES AD1/665	Structure: Plant house Location: Penrhiantyn House, Neath, Port Talbot, Wales Client: H. Eccles	1902
TR MES AD1/666	Structure: Conservatory Location: Wootton House, Dorking, Surrey Client: W.E. Evelyn per Pulman and Son	1901
TR MES AD1/667	Structure: Glasshouse Location: Dodwell Lodge, Bursledon, Southampton, Hampshire Client: Lieut. C.D. Eden, R.N.	1892
TR MES AD1/668	Structure: Conservatory Location: Bramcote, Nottingham, Nottinghamshire [house occupied by R. Enfield, but owned by Mrs Sherwin Gregory, sister to Capt. Holden] Client: Richard Enfield	1891
TR MES AD1/672	Structure: Painting glasshouses Location: Belfield, Long Eaton, Derbyshire Client: F.R. Claye	1903

TR MES AD1/673	Structure: Heating apparatus; Peach house Location: The Poplars, Duffield Road, Derby, Derbyshire Client: Edgar H. Claye	1894; 1897
TR MES AD1/673	Structure: Heating apparatus Location: Darleyfields, Duffield Road, Derby, Derbyshire Client: Edgar H. Claye	1898
TR MES AD1/674	Structure: Conservatory; Replacing roof of conservatory; Painting of greenhouses Location: Conifer Crest, Montpelier Road, Ealing, London Client: Ralph Callard	1899; 1903; 1911
TR MES AD1/674	Structure: Greenhouse Location: Lyncombe, 2 Aston Road, Ealing, London Client: Ralph Callard	1893
TR MES AD1/675	Structure: Conservatory Location: The Gables, Beverley, East Yorkshire Client: Mrs Crust	1894
TR MES AD1/677	Structure: Glasshouses Location: Bella Vista, Hartopp Road, Sutton Coldfield, West Midlands Client: Job Coley	1897-1898
TR MES AD1/679	Structure: Heating apparatus; Glasshouse Location: Tyrells, Leatherhead, Surrey Client: L.D. Cunliffe	1891; 1896
TR MES AD1/680	Structure: Plant house Location: The Lodge, Thames Ditton, Kingston-on-Thames, Surrey Client: Sir Guy Campbell	1900
TR MES AD1/681	Structure: Conservatory; Painting glasshouse Location: Streatham Ladge, Lower Streatham, Surrey Client: E. Coulthurst	1888; 1895
TR MES AD1/682	Structure: Glasshouse Location: Summerholme, Fishery Estate, Bray, Berkshire Client: N.M. Cohen	1902
TR MES AD1/684	Structure: Fernery Location: Sunville House, Limerick, Ireland Client: Thomas H. Cleere, J.P.	1900
TR MES AD1/686	Structure: Conservatory Location: St Georges Lodge, Oldfield Road, Bath, Somerset Client: John J.S. Collins	1904
TR MES AD1/689	Structure: Vinery and plant protector; Replacement boiler Location: Letheringsett Hall, Holt, Norfolk Client: Right Hon. Lord Edward H. Cozens-Hardy [Justice]	1899; 1917
TR MES AD1/690	Structure: Plant house Location: Aveley South Hill, Bromley, Kent Client: Kenneth E. Chalmers	1899-1900
TR MES AD1/691	Structure: Heating apparatus for cells Location: Chislehurst Police Station, Kent Client: Wiltshire and Son [Builders]	1893
TR MES AD1/692	Structure: Peach house Location: Polapit Tamar, Launceston, Cornwall Client: R.C. Coode	1898
TR MES AD1/694	Structure: Plant house Location: Clayhook Grange, Rugby, Warwickshire Client: George Beale	1924

TR MES AD1/696	Structure: Glass house; Vinery Location: Newbridge House, Donabate, Co. Dublin, Ireland Client: Mrs Cobbe	1892; 1894
TR MES AD1/698 [See also TR MES AD1/613]	Structure: Vinery Location: Penshurst, Tonbridge, Kent Client: Mr Hope Constable [Builder]	1902-1903
TR MES AD1/699	Structure: Plant House Location: Cotefield, Leighton Buzzard, Bedfordshire Client: Major A. Cookson	1895
TR MES AD1/700	Structure: Plant house Location: Gatton Cottage, Reigate, Surrey Client: Mrs Crawford	1895
TR MES AD1/701	Structure: Heating Location: King James' Grammar School, Knaresborough, North Yorkshire Client: Messrs. Barrowcliff and Allcock [Architects]	1900
TR MES AD1/702	Structure: Glass house Location: Eastfield, Rugby, Warwickshire Client: J. Cumming	1894
TR MES AD1/703 [2 packets]	Structure: Plant House Location: Highfield, Shoreham, Sevenoaks, Kent Client: Benjamin L. Cohen, MP and Louisa E. Cohen	1898
TR MES AD1/704	Structure: Painting and heating of greenhouses and vinery Location: Chipperfield House, Kings Langley, Hertfordshire Client: Sands Clayton	1890
TR MES AD1/705	Structure: Conservatory Location: Kent Lodge, Sidcup, Kent Client: W. T. Crossweller	1898
TR MES AD1/706	Structure: Heating apparatus Location: Torthorwald, Holmwood, Dorking, Surrey Client: Rev. W Carlile	1895
TR MES AD1/707 [2 packets]	Structure: Plant house; Greenhouse Location: Queens Park, Crewe, Cheshire Client: Crewe Corporation per Borough Surveyor	1894; 1903
TR MES AD1/707	Structure: Plant protector; Greenhouse Location: Crewe Cemetary, Cheshire Client: Crewe Corporation per Borough Surveyor	1896; 1936
TR MES AD1/708	Structure: Vinery Location: Holker Hall, Cark-in-Cartmel, Cumbria Client: Lord Victor C.W. Cavendish, MP	1904
TR MES AD1/709	Structure: Glass houses Location: Hessle near Hull, Yorkshire Client: F. Costello	1904
TR MES AD1/710	Structure: Heating apparatus Location: Brookside Hill, Sandhurst, Camberley, Surrey Client: W. Napier Church	1904
TR MES AD1/711	Structure: Greenhouse Location: Burnaston House, Etwall, Derbyshire Client: G. D'Arcy Clark	1889
TR MES AD1/712 [3 packets]	Structure: Vinery, Conservatory, Peach house; Fernery and Orchid House Location: Radipole Manor, Radipole, Weymouth, Dorset Client: Henry Cox per Messrs Crickmay [Architects]	1899; 1903

TR MES AD1/713	Structure: Glasshouses Location: Combermere Abbey, Whitchurch, Shropshire Client: Lord Combermere	1899-1902
TR MES AD1/714	Structure: Heating apparatus Location: Friezewood, Rudgey, Gloucestershire Client: G.D. Crossman	1889
TR MES AD1/715	Structure: Conservatory Location: 8 Clarendon Gardens, Trowbridge, Wiltshire Client: J. P Cogswell	1892
TR MES AD1/716 [2 packets]	Structure: Glass houses; Vinery and cool peach house Location: Hedley Court, Epsom, Surrey Client: Walter Cunliffe	1894; 1901
TR MES AD1/717	Structure: Heating apparatus Location: Town Hall and Vestry Hall, Rosebery Avenue, Clerkenwell, London Client: C. Evans-Vaughan [Architect]	1895
TR MES AD1/718	Structure: Conservatory and lobby Location: Greenhayes, Doods Park Road, Reigate, Surrey Client: Miss Rosa E. Cooper	1902
TR MES AD1/719	Structure: Greenhouse Location: British Embassy, Constantinople Client: Sir Henry Tanner [Government architect]	1904
TR MES AD1/720	Structure: Heating apparatus Location: Gargrave House, Gargrave, Leeds, West Yorkshire Client: J.W. Coulthurst	1904
TR MES AD1/721 [3 packets]	Structure: Glasshouses and hot water; Conservatory; Painting Location: The Outwoods, Duffield, near Derby, Derbyshire Client: C.W. Catt	1900; 1901; 1905
TR MES AD1/722	Structure: Iron stages for vineries and forcing house Location: West Woodhay House, Newbury, Berkshire Client: Mrs Cole	1892
TR MES AD1/723	Structure: Orchid Houses Location: Rawdon Hill, Arthington, Leeds, West Yorkshire Client: W. Johnson Cheetham	1889
TR MES AD1/724 [2 packets]	Structure: Range and pit; Plant house; Boiler Location: Worplesdon St Mary, near Guildford, Surrey Client: Miss Cunliffe	1893; 1900; 1908
TR MES AD1/725	Structure: Conservatory and forcing house Location: 3 Westbourne Road, Edgbaston, Birmingham, West Midlands Client: E.M. Carter	1905
TR MES AD1/726	Structure: Plant house; Glasshouse Location: Wingfield House, Trowbridge, Wiltshire Client: Sir Vincent Caillard, Bart	1898; 1905
TR MES AD1/727	Structure: Heating apparatus; Boiler; Heating apparatus Location: Bryn-y-pys, Overton, Ellesmere, Shropshire Client: A.J.P. Child; Edmund Peel	1905; 1908; 1912
TR MES AD1/728	Structure: Heating apparatus Location: 76 Southwark Street, London Client: Celvicol Co.	1902

TR MES AD1/729	Structure: Conservatory Location: Wellesley Road, Croydon, Cambridgeshire Client: Dr Rosser [per Messrs Crickmay [architects]]	1895
TR MES AD1/730 [2 packets]	Structure: Boiler replacement; Greenhouse Location: Missenden Abbey, Great Missenden, Buckinghamshire Client: George Carrington; Miss Carrington	1903; 1921
TR MES AD1/732	Structure: Heating apparatus Location: Chessington Lodge, Chessington, Surrey Client: D.R. Cameron	1908
TR MES AD1/733	Structure: Heating apparatus for stables/Coach House Location: Ponsbourne Park, Hertfordshire Client: J.W. Carlisle	1897
TR MES AD1/734	Structure: Greenhouse Location: Pimley Manor, Shrewsbury, Shropshire Client: Mrs Corbett [Formerly Mrs Piggott]	1903
TR MES AD1/734	Structure: Greenhouse Location: Upton Magna Rectory, Shrewsbury, Shropshire Client: Mrs Piggott	1890
TR MES AD1/735	Structure: Heating for Greenhouse Location: The Farm Buildings, Chadwell Heath Asylum, Goodmayes, Essex Client: Chadwell Heath Asylum	1903
TR MES AD1/736	Structure: Heating apparatus for ground floor stores Location: West Bars, Chesterfield, Derbyshire Client: Chesterfield, Derbyshire and District Cooperative Society	1903
TR MES AD1/737	Structure: Heating Location: United Methodist Free Church, Lincoln Road, Peterborough, Cambridgeshire Client: Mr T. Casbon	1904
TR MES AD1/738	Structure: Boiler installation and replacement in greenhouse Location: "Chaleshurst", Chiddingfold, Surrey Client: Rev. S. Cooper	1904-1912
TR MES AD1/739	Structure: Greenhouse Location: Nately Hill, Hook, Hampshire Client: Mrs Frederica Cahen	1904
TR MES AD1/740	Structure: Glass houses - Vinery and plant house Location: Shrubbs Hill House, Sunningdale, Berkshire Client: Mrs Chambers	1891-1892
TR MES AD1/741	Structure: Greenhouse Location: Furze Bank, Queens Ride, Barnes Common, London Client: W.J. Cundall	1902-1903
TR MES AD1/742 [8 packets]	Structure: Conservatory, greenhouse, pits, Vineries Location: " Birtley", Bramley, Guildford, Surrey Client: Hon. Henry Cubitt	1891-1896
TR MES AD1/742	Structure: Conservatory/Vinery/fruit houses heating apparatus repairs Location: "The Denbies", Dorking, Surrey Client: Hon. Henry Cubitt	1904-1917
TR MES AD1/742	Structure: Heating to St Barnabas Church Location: Ranmore, Dorking, Surrey Client: Hon. Henry Cubitt	1907-1908

TR MES AD1/742	Structure: Vineries and Church boiler repairs Location: "The Denbies", Dorking, Surrey and St Barnabas Church, Ranmore Client: Rt. Hon. Lord Ashcombe [Hon. Henry Cubitt]	1924-1944
TR MES AD1/743	Structure: Glasshouse Location: Westcotes Lodge, Ashleigh Road, Leicester, Leicestershire Client: J.G. Chattaway	1896-1897
TR MES AD1/745	Structure: Conservatory Location: Queens Avenue, Victoria Park Estate, Dorchester, Dorset Client: Capt. D. Granville [per Messrs Crickmay Architects]]	1898
TR MES AD1/746	Structure: Conservatory, Vinery and heating for house Location: Staple Hall, Fenny Stratford, Bletchley, Buckinghamshire Client: Thomas E. Cornwardine	1894
TR MES AD1/747	Structure: Conservatory Location: O'Harabrook, Ballymorey, Co. Antrim, Ireland Client: Capt. J.S. Cramsie	1901
TR MES AD1/749	Structure: Plant House Location: Norfolk House, Kew Road, Richmond, Surrey Client: A. Chancellor	1899
TR MES AD1/750	Structure: Greenhouse Location: Brailsford Refectory, Derby, Derbyshire Client: Rev. J.G. Croker	1890
TR MES AD1/752	Structure: Conservatory Location: Paines Hill, Limpsfield, Surrey Client: E. Cooper per G.E. Streatfield [Architect]	1902
TR MES AD1/753	Structure: Hot water supply Location: Coventry, Warwickshire Client: Coventry and Warwickshire Hospital per Ellis G. Crien	1901-1902
TR MES AD1/754	Structure: Heating for house Location: Stanley Hall, Stroud, Gloucestershire Client: Col. James C. Collier	1890
TR MES AD1/756	Structure: Conservatory Location: Llangroyd, Colne, Lancashire Client: Miss Carr	1899
TR MES AD1/757 [3 packets]	Structure: Conservatory and painting Location: Thorncote, Staines, Surrey Client: Sir E. Clarke, KC	1901
TR MES AD1/758	Structure: Glass corridor Location: Convent of our Lady of Mercy, Clifford, Boston Spa RSO, Yorkshire Client: Sisters of Mercy	1900
TR MES AD1/760	Structure: Conservatory Location: The Old Hall, Hornsea, Hull, Yorkshire Client: Mrs Strickland Constable	1899
TR MES AD1/761	Structure: Camelia House, improvements to vinery and pits Location: Ospringe House, Faversham, Kent Client: Mrs Carter	1893

TR MES AD1/762	Structure: Heating apparatus Location: Coventry Public Bath, Warwickshire Client: Coventry Corporation	1897
TR MES AD1/763	Structure: Peach houses; Vinery and melon house; Carnation and plant house Location: Embley Park, Romsey, Hampshire Client: Major Spencer Chichester	1897; 1900; 1914
TR MES AD1/764	Structure: Greenhouse Location: 6 Keswick Road, Putney, London Client: G.R. Crickmay	1891
TR MES AD1/767	Structure: Heating apparatus for warehouse Location: Beccles, Suffolk Client: Messrs Clowes and Son [Printers]	1893
TR MES AD1/768	Structure: Conservatory Location: Surrey Lodge, Hersham, Walton on Thames, Surrey Client: Mr Capon per Messrs Crickmay [Architects]	1900
TR MES AD1/769 [3 packets]	Structure: Heating apparatus for house; Forcing house; Boiler; Rebuilding Palm house and fernery Location: Duffryn House, Duffryn near Cardiff, Wales Client: John Cory; Reginald and Florence Cory	1900; 1913; 1922; 1931
TR MES AD1/769	Structure: Vineries; Fernery, Plant house, Vinery Location: Porthkerry, Barry, near Cardiff, Wales Client: John Cory	1892; 1895
TR MES AD1/771	Structure: Plant house and stove Location: Headington Hill, Oxford, Oxfordshire Client: G.M. Child	1894
TR MES AD1/773	Structure: Vinery, stove and orchid house Location: Bodrhyddan, Rhyddlan RSO, Cardiff, Wales Client: Capt. Colway	1892
TR MES AD1/774	Structure: Plant house, Conservatory Location: Todwick Grange, Kiveton Park, Sheffield, South Yorkshire Client: J. Stavelev Coulton-Fox	1896
TR MES AD1/775	Structure: Porch Location: Glaslyn, Plum Lane, Plumstead, London Client: W. Coles	1894
TR MES AD1/778	Structure: Plant house and stove Location: 44 London Road, Clapton, Somerset Client: J.R. Cordall	1892
TR MES AD1/779	Structure: Glasshouses Location: Boyle House, West Ardsley, Wakefield, South Yorkshire Client: S. Colbeck	1893
TR MES AD1/780	Structure: Greenhouse Location: Woodruff, 14 Corfton Road, Ealing, London Client: Charles L. Cribb	1912
TR MES AD1/780	Structure: Greenhouse Location: Savernake, Ashton Road, Ealing, London Client: Charles L. Cribb	1905

TR MES AD1/781	Structure: Conservatory Location: 21 Bedford Square, London Client: Mrs Campbell per George Clegg and Son	1899
TR MES AD1/782	Structure: Boiler Location: 36 Corporation Street, Manchester, Lancashire Client: C.T. Chivers	1886
TR MES AD1/783	Structure: Heating apparatus Location: 41 Stepney Green, London Client: Mr Charrington per W. Catmur [Plumber]	1895
TR MES AD1/784	Structure: Plant house Location: Coghurst Hall, Ore, Hastings, East Sussex Client: H. Coghill	1897
TR MES AD1/786 See also TR MES AD1/1474	Structure: Vinery Location: Grendon Hall, Atherstone, Warwickshire Client: Sir Guy Chetwynd, Bart	1906
TR MES AD1/787	Structure: Plant house Location: Corran, Mount Park Road, Harrow, London Client: Mrs Cater	1905
TR MES AD1/791	Structure: Plant house Location: Bushey House, Bushey, Hertfordshire Client: E.H. Cuthbertson	1900
TR MES AD1/792	Structure: Glasshouses Location: Claybury Asylum, Woodford, Essex Client: George T. Hine [Architect]	1894
TR MES AD1/794	Structure: Forcing house and pits Location: Donhead House, Donhead St Andrew, Salisbury, Wiltshire Client: Horace G. Chapman	1899
TR MES AD1/795	Structure: Plant house Location: Kilmarnock Lodge, Caterham Valley, Surrey Client: Edmund Chalk	1896
TR MES AD1/796	Structure: Glasshouse Location: Ingarsby, Edge Hill, Wimbledon, London Client: Edward Carver	1891
TR MES AD1/798	Structure: Alterations to verandah Location: Hackwood, Widmore Road, Bromley, Kent Client: E. Clark	1898
TR MES AD1/799	Structure: Alterations to glasshouses Location: Selwood, Rotherham, South Yorkshire Client: C.E. Chrimes	1896
TR MES AD1/800	Structure: Greenhouse Location: Terham House, Clumber Crescent, Nottingham, Nottinghamshire Client: Mrs Cafferata	1893
TR MES AD1/801	Structure: Conservatory Location: Lady Foresters Charity Convalescent Home, Llandudno, Wales Client: E.B. L'Anson [Architect]	1904

TR MES AD1/802	Structure: Conservatory Location: Egerton Road, Ashton on Ribble, Lancashire Client: Henry Curwen per Robert Curwen [Architect]	1892
TR MES AD1/803	Structure: Conservatory Location: The Old House, Queniborough, Syston, Leicestershire Client: Thomas Cawdell	1901
TR MES AD1/804	Structure: Range Location: Garnons, Hereford, Herefordshire Client: Capt. Sir John Cotterell	1898
TR MES AD1/805	Structure: Plant house and melon house; Boiler Location: Skerton, Lancaster, Lancashire Client: Miss Coulston per Messrs. Coulston and Co.	1898
TR MES AD1/806	Structure: Portable Greenhouse Location: 40 Victoria Road, Kensington, London Client: Cooper and Taylor	1906
TR MES AD1/807	Structure: Heating apparatus Location: Baptists Sunday School, Lewes, East Suffolk Client: H. Curtis Card [Architect]	1899
TR MES AD1/809	Structure: Heating apparatus Location: Tixover Grange, Stamford, Lincolnshire Client: Lord John Pakenham Cecil	1899
TR MES AD1/810	Structure: Greenhouse Location: Tanaralla, Listowel, Co. Kerry, Ireland Client: Mrs M.G. Cooke	1890
TR MES AD1/811	Structure: Heating apparatus Location: Forest Hill, Worksop, Nottinghamshire Client: Peter Cadman	1896
TR MES AD1/812	Structure: Heating apparatus Location: Watford, Hertfordshire Client: Clifford and Gough [Contractors]	1894
TR MES AD1/814	Structure: Stove and cucumber house Location: Shottery Hall, Stratford-upon-Avon, Warwickshire Client: H.F. Carter	1906
TR MES AD1/815	Structure: Glasshouses and pits Location: Moray Lodge, Campden Hill, London Client: [D.J. Pullinger] per Creaton and Co.	1903
TR MES AD1/816	Structure: Vinery Location: Tehidy Park, Camborne, Cornwall Client: [G.L. Bassett] per Country Gentlemens Club	1906
TR MES AD1/817	Structure: Glasshouses Location: Walcot, Frodingham, Doncaster, South Yorkshire Client: J. Goulton Constable	1900
TR MES AD1/818	Structure: Heating apparatus Location: Chalfont Grange, Chalfont St Peter, Buckinghamshire Client: Mrs Fass	1906
TR MES AD1/819	Structure: Greenhouse Location: Homestead, Welland, Malvern Wells, Worcestershire Client: Mrs Farthing	1900

TR MES AD1/820	Structure: Glasshouse Location: Homestead, Banbury, Oxfordshire Client: Mrs Aubrey Cartwright	1905
TR MES AD1/821	Structure: Boiler; Heating apparatus; Boiler repairs; Rebuilding greenhouse Location: Bunney Park, Nottingham, Nottinghamshire Client: Mrs E. Cordeux (formerly Mrs Wilkinson Smith)	1904; 1918; 1927; 1928
TR MES AD1/821	Structure: Heating apparatus for Miss Hawksley, Bunney Park; Heating apparatus for Bunney Vicarage Location: Bunney Vicarage, Nottingham, Nottinghamshire Client: Rev. H. Cooper	1895; 1895-1896
TR MES AD1/823	Structure: Glasshouse Location: Old Mill House, Cowley, Uxbridge, London Client: Percy Caldecott	1906
TR MES AD1/824	Structure: Conservatory Location: Westoning Manor, Ampthill, Bedfordshire Client: J.G.C. Campion	1898
TR MES AD1/825 [1 of 7 packets]	Structure: Boiler house and twin houses Location: Newton Road Nurseries, near Westbourne Grove, London Client: William Whiteley per A.M. Ridge [Architect]	1897
TR MES AD1/825 [2 of 7 packets]	Structure: Ventilating equipment for stables Location: Kingston Road, Raynes Park, Surrey Client: William Whiteley per A.M. Ridge [Architect]	1898
TR MES AD1/825 [3 to 7 of 7 packets]	Structure: Vineries, peach houses, pineries, orchid houses, plant houses, cucumber and melon houses, strawberry houses, camellia houses, carnation house and rose house; Forcing house and pits; Peach houses and vinery Location: The Nurseries, Hillingdon Heath near Uxbridge, London Client: William Whiteley per J.F. Collinson [Builder]	1890; 1890; 1895
TR MES AD1/827	Structure: Plant house Location: Bourton House, Shrivenham, Berkshire Client: C.K. Butler	1900
TR MES AD1/828	Structure: Conservatory; heating apparatus; Greenhouse Location: Downton, Salisbury, Wiltshire Client: John Bailey [Builder]	1898; 1900; 1902
TR MES AD1/829	Structure: Vinery Location: Sandiacre, near Nottingham, Nottinghamshire Client: George Bastable	1898
TR MES AD1/830	Structure: Heating apparatus Location: Stairfoot, Barnsley, South Yorkshire Client: Wilton Brook	1894
TR MES AD1/831	Structure: Plant house; Blinds and painting Location: 55 Musters Road, West Bridgford, Nottinghamshire Client: A. Brotherton	1900; 1903
TR MES AD1/833	Structure: Greenhouse Location: Ouse Bank, Newport Pagnell, Buckinghamshire Client: W. Rogers Bull	1892

TR MES AD1/834 [4 packets]	Structure: Vinery; Glasshouses; Orchard and peach houses; Range; Roof Location: Tewkesbury Lodge, Forest Hill, London Client: Charles Bayer	1891; 1892; 1897; 1899 1900
TR MES AD1/834 See also TR MES AD1/836	Structure: Roof; Painting roof Location: Victoria Buildings, Golden Lane, London Client: Charles Bayer per Lewis Solomon [Architect]	1898; 1899
TR MES AD1/835 [5 packets] See also TR MES AD1/834	Structure: Conservatory; Boiler; Repairs to conservatory Location: Tewkesbury Lodge/Hamilton Lodge, Honor Oak Road, Forest Hill, London Client: Herbert C. Bayer; E. Scala	1899; 1915; 1953
TR MES AD1/836 See also TR MES AD1/834	Structure: Replacing and fixing glass roof Location: Golden Lane, London Client: C. Bayer and Co	1905
TR MES AD1/838	Structure: Plant house Location: The Pastures, Derby, Derbyshire Client: Walter Boden	1903
TR MES AD1/839	Structure: Conservatory and Fernery Location: Marlyn's House, Guildford, Surrey Client: W.H. Burbidge	1888
TR MES AD1/840 [5 packets]	Structure: Greenhouses and conservatories Location: Bradford Moor, Bowling, Harold, Wibsey, Lister and Horton Public Parks, Bradford, Yorkshire Client: Bradford Corporation	1889-1950
TR MES AD1/841	Structure: Greenhouse Location: Flaxley Abbey, Newnham, Gloucestershire Client: Lady Crawley Boevey	1890
TR MES AD1/842 See also TR MES AD1/958 and 959	Structure: Heating apparatus Location: Wallingford, Oxfordshire Client: A.L. Morphew per Brasher and Co.	1900
TR MES AD1/843	Structure: Greenhouse Location: Lindfield Lodge, Folkestone, Kent Client: Col. R.A. Blane	1889
TR MES AD1/844	Structure: Greenhouse Location: Borstal Road, Rochester, Kent Client: C. Willis per F. Braby and Co	1888
TR MES AD1/845	Structure: Heating apparatus Location: Manchester, Lancashire Client: Bells Asbestos Company	1889
TR MES AD1/846	Structure: Plant house Location: The Derwyn, Gobowen, Oswestry, Shropshire Client: F. Boughey	1895
TR MES AD1/847	Structure: Glass range Location: Pollard Hall, Gomersal, Cleckheaton, Kirkstall, West Yorkshire Client: T W Burnley	1897
TR MES AD1/848	Structure: Plant house Location: Tingley Mills, Morley, West Yorkshire Client: H.A. Bradley per W.L. Skinner	1896

TR MES AD1/849	Structure: Greenhouse Location: 16 Beswicks Road, Northwich, Cheshire Client: per Brunner, Mond and Co.	1911
TR MES AD1/849	Structure: Greenhouse Location: Winnington Hall, Northwich, Cheshire Client: Dr Ludwig Mond per Brunner, Mond and Co.	1904
TR MES AD1/849	Structure: Conservatory Location: Hillside, Sandbach, Cheshire Client: R.L. Allen per Brunner, Mond and Co.	1906
TR MES AD1/850	Structure: Heating apparatus; Greenhouse Location: Kingston Hall, Derby, Derbyshire Client: Right Hon. Lord Belper	1896; 1913
TR MES AD1/851	Structure: Plant house Location: Langdale, Stafford, Staffordshire Client: Thomas Bostock	1901
TR MES AD1/852	Structure: Greenhouse Location: The Pines, Englefield Green, Surrey Client: Henry Bishop	1903
TR MES AD1/853	Structure: Greenhouse Location: Dickhurst, near Haslemere, Surrey Client: J.H. Baker	1902
TR MES AD1/854	Structure: Conservatory Location: Hillside, Church Stretton, Shropshire Client: W.L. Browne	1899
TR MES AD1/855 [11 packets]	Structure: Heating apparatus and hot water supply Location: Ale Stores, Tablet Room and Joiners Shop, Kings Road, St Pancras : Dixie Ale Stores, Burton-on-Trent, Staffordshire : Shobnall Ale Stores, Staffordshire : Nags Head, Swadlincote, Staffordshire : Commercial Inn, Sleaford, Lincolnshire : Stores at Wellington Street, Hull, Yorkshire : St Chads Church, Hunter Street, Burton-on-Trent, Staffordshire : Hawkins Lane Stores, Burton-on-Trent, Staffordshire : Old Brewery, High Street, Burton-on-Trent, Staffordshire : General Offices, Kings Road, Pancras Road, London : New Loco Shed Client: Bass, Ratcliff and Gretton Ltd, Burton-on-Trent, Staffordshire	1893-1909
TR MES AD1/856	Structure: Conservatory Location: Elmhurst, Trowbridge, Wiltshire Client: Henry Blake	1893-1894
TR MES AD1/857 [3 and 4 of 6 packets]	Structure: Heating; Plant house and Vinery Location: Belcombe Court, Bradford-on-Avon, Wiltshire Client: Alfred W.N. Burder	1906; 1914
TR MES AD1/857 [2 and 5 of 6 packets]	Structure: Motor Garage; Heating to house Location: Powyke Court, Worcester, Worcestershire Client: A.W.N. Burder	1923-1924; 1927-1933

TR MES AD1/857 [1, 3 and 6 of 6 packets]	Structure: Refitting of house including heating Location: Wilcroft, Hertford, Hertfordshire Client: A.W.N. Burder	1901-1903
TR MES AD1/858	Structure: Greenhouses Location: Elm Croft, Hornsey Lane, Highgate, London Client: H.H. Barratt	1894
TR MES AD1/859	Structure: Orchid House; Boiler Location: The West Hill, Hessle RSO, near Hull, Yorkshire Client: W.P. Burkinshaw	1897; 1916
TR MES AD1/860	Structure: Heating for workshop Location: Hythe Road, Willesden Junction, London Client: The British Incandescent Electric Lamp Company	1898-1901
TR MES AD1/861	Structure: Vinery Location: The Lawn, Southchurch, Essex Client: E.W. Barnett	1891-1892
TR MES AD1/862	Structure: Conservatory Location: Beech Hill, Mayford, Woking, Surrey Client: Samuel Bircham	
TR MES AD1/863	Structure: Boiler and heating apparatus Location: London Road, Newark, Nottinghamshire Client: Messrs G. Brown and son	1904
TR MES AD1/864	Structure: Glasshouse Location: Botley, Hampshire Client: William J.C. Bailey [Builder]	1895
TR MES AD1/865 [1 of 2 packets]	Structure: Heating apparatus Location: Barkby Hall, near Syston, Leicestershire Client: Thomas Brooks	1888
TR MES AD1/865 [2 of 2 packets]	Structure: Plant house Location: Barkby Hall, near Syston, Leicestershire Client: Thomas Brooks	1899
TR MES AD1/866	Structure: Conservatory and greenhouse Location: Mannamead, Plymouth, Hampshire Client: J.A. Bellamy	1899
TR MES AD1/867 [2 packets]	Structure: Peach house; Conservatory and stove; Painting; Frames Location: Orient Lodge, Green Fairfield, Buxton, Derbyshire Client: J.S. Brittain	1892; 1896; 1897; 1899
TR MES AD1/868	Structure: Repairs to greenhouses; Painting; Location: Beech Hollow, Oatlands Park, Weybridge, Surrey Client: Alfred F. Bloxam	1893; 1898-1899
TR MES AD1/869	Structure: Vinery Location: 5 Fairfield Terrace, Denville Estate, Havant, Southampton, Hampshire Client: Mrs Barnes	1892
TR MES AD1/870 [1 of 3 packets]	Structure: Boiler and heating apparatus Location: The Bungalow, Hedsor Gardens, Bourne End, Buckinghamshire Client: Philip Shephard	1940
TR MES AD1/870 [2 of 3 packets]	Structure: Alterations to heating; Glasshouses; Flowering house; Peach house Location: South Lodge and Hedsor Court, Hedsor, Bourne End, Buckinghamshire Client: J. Amery Parkes	1926; 1927; 1928; 1933

TR MES AD1/870 [3 of 3 packets]	Structure: Plant house; Heating apparatus Location: Hedsor House, Bourne End, Buckinghamshire Client: Right Hon. Lord Boston; D'Arcy Baker	1897; 1928
TR MES AD1/871	Structure: Peach house Location: Quarry House, Bletchingley, Surrey Client: Harrington E. Broad	1904
TR MES AD1/872	Structure: Conservatory and boiler house Location: Amberwood, Christchurch, Hampshire Client: Mrs Braddyll	1889
TR MES AD1/873	Structure: Stove and vinery; Fruit house; Plant house Location: Fairthorne, Botley, Hampshire Client: Miss Burrell	1894; 1895; 1896
TR MES AD1/875 [5 packets]	Structure: Vinery; Conservatory and corridor; Painting; Boiler; Boiler; Location: Tiddington House, Wheatley SO, Oxfordshire Client: G.W. Bennett; Mrs Adrian Corbett	1891; 1900; 1893- 1916; 1923; 1938
TR MES AD1/876	Structure: Heating apparatus Location: Fir Grove, East Hoathly, Sussex Client: Capt. George Bryan	1889
TR MES AD1/877	Structure: Glasshouses Location: Boyton Manor, Codford, Bath, Somerset Client: G.R. Bryant	1889
TR MES AD1/878	Structure: Glasshouse Location: Draycott House, Bodicote, Banbury, Oxfordshire Client: F.B. Judge Baldwin	1903
TR MES AD1/880	Structure: Heating apparatus Location: Starling Lodge, Epping New Road, Buckhurst Hill, Essex Client: F.E. Bye	1904
TR MES AD1/881 [2 packets]	Structure: Conservatory; Glasshouses Location: 8 Hanover Crescent, Brighton, East Sussex Client: G.H. Attree; E.M. Marx	1893; 1907
TR MES AD1/882 [2 packets]	Structure: Stove and fernery; Heating apparatus; Repairs to vinery; Boiler Location: Foremark Hall, Repton, near Burton-on-Trent, Staffordshire Client: Sir Francis Burdett, Bart.	1892; 1911; 1924; 1928
TR MES AD1/883 [1 of 3 packets]	Structure: Glasshouses Location: Greystone, Hill Top Road, Hale, Cheshire Client: Mrs H.J. Marsland	1916
TR MES AD1/883 [2 and 3 of 3 packets]	Structure: Glasshouses; Conservatory Location: Eaves Hall, Clitheroe, Lancashire Client: Edward Burton; Mrs H.J. Marsland	1890; 1906
TR MES AD1/884	Structure: Greenhouse Location: Cannon Hill, Old Southgate, London Client: H.M. Bourne	1900
TR MES AD1/885	Structure: Plant house Location: Minera Hall, Wrexham, Flintshire, North Wales Client: John R. Burton	1896
TR MES AD1/886	Structure: Greenhouse Location: Colley Manor, Reigate Heath, Surrey Client: F.N. Horne per Buckland and Waters [Builders]	1904
TR MES AD1/887	Structure: Heating apparatus Location: Tipahi Street, Nelson, New Zealand Client: Henry B. Bolton	1903

TR MES AD1/888	Structure: Vineries Location: Hessle Mount, near Hull, East Yorkshire Client: Col. J.H. Burstall	1897
TR MES AD1/889	Structure: Boiler Location: Downes, Crediton, Devon Client: General Sir Redvers Buller, VC	1932
TR MES AD1/890	Structure: Greenhouse Location: Walton on the Hill, Staffordshire Client: Joseph S. Burton [Builder]	1905
TR MES AD1/891	Structure: Conservatory, Plant house and stove Location: The Woodlands, Reigate, Surrey Client: J.J. Brown	1893
TR MES AD1/893	Structure: Heating apparatus Location: Arundel Police Station, Arundel, West Sussex Client: Arthur Burrell [Builder]	1901
TR MES AD1/894	Structure: Heating apparatus Location: Buxton, Derbyshire Client: Buxton Lime Firms Company Ltd.	1897
TR MES AD1/895	Structure: Conservatory Location: Park Gate Mansion, Normanhurst, Battle, Suffolk Client: Right Hon. Lord Brassey, KCB	1889
TR MES AD1/897	Structure: Heating apparatus Location: Ballintaggart House, Colbinstown, Co. Kildare, Ireland Client: Col. Bonham	1894
TR MES AD1/898	Structure: Boiler Location: 1 Broad Street, Oxford, Oxfordshire Client: W. Baker and Co.	1903
TR MES AD1/900	Structure: Conservatory and vinery Location: Broadfield House, Branston Road, Burton-on-Trent, Staffordshire Client: Mrs Brooks	1904
TR MES AD1/901	Structure: Greenhouse; Greenhouse; Plant house Location: The College, Winchester, Hampshire Client: Rev. Dr Hubert Burge and Mrs Burge	1901; 1906; 1910
TR MES AD1/902	Structure: Painting Location: Pollard Hall, Gomersal, near Leeds, West Yorkshire Client: Thomas W. Burnley	1903
TR MES AD1/903	Structure: Heating apparatus Location: Brent Pelham Hall, Buntingford, Hertfordshire Client: Edward E. Barclay	1904
TR MES AD1/906	Structure: Boiler Location: Tudor House, West Hill Road, Wandsworth, London Client: R.L. Burrows	1891
TR MES AD1/907	Structure: Greenhouse Location: 168 Claremont Road, Forest Gate, London Client: E. Bluemel	1900
TR MES AD1/908	Structure: Vineries and peach house; Conservatory Location: Bryn Parsonage, Pen-y-lan, Rhuabon, Denbighshire, North Wales Client: Rev. T Bunscombe per Capt. Peter Ormrod	1890; 1891

TR MES AD1/909	Structure: Smoke room Location: Buxton palace Hotel, Buxton, Derbyshire Client: W. Holland [Architect]	1900
TR MES AD1/910	Structure: Heating apparatus Location: Norton Stone and Concrete Company, Norton near Stockton on Tees, Cleveland, Yorkshire Client: John Burn [Builder]	1900
TR MES AD1/912	Structure: Heating apparatus Location: Blue Bell, Church Street, Melbourne, Derbyshire Client: Joseph Burton [Plumber]	1904
TR MES AD1/913 [2 packets]	Structure: Greenhouse [Pot experimental station] Location: Woburn, Bedfordshire Client: Royal Agricultural Society of England	1897
TR MES AD1/914	Structure: Five glasshouses Location: Sutton on Trent near Newark, Nottinghamshire Client: James Blackburn	1894
TR MES AD1/915	Structure: Heating apparatus Location: New Farmstead, Scartho, near Grimsby, Lincolnshire Client: Thomas Baskcomb	1903
TR MES AD1/916 [1 of 2 packets]	Structure: Heating apparatus Location: Factory in Ilkeston, Derbyshire Client: William Barton [Architect]	1904
TR MES AD1/916 [2 of 2 packets]	Structure: Conservatory Location: St Mary's Gate, Lancaster, Lancashire Client: Miss Burton	1894
TR MES AD1/917	Structure: Heating apparatus Location: Lampern House, near Dussley, Gloucestershire Client: G. Lloyd Baker	1896
TR MES AD1/917	Structure: Heating apparatus Location: Hardwicke Court, Gloucester, Gloucestershire Client: G. Lloyd Baker	1892-1893
TR MES AD1/918	Structure: Cucmber house, plant house and stokery Location: Southend, Essex Client: Messrs Baker and Wiseman [Builders]	1889
TR MES AD1/919	Structure: Conservatory; Greenhouse Location: Fyfyde, Winchester, Hampshire Client: Frederick Bowker	1900; 1925
TR MES AD1/920	Structure: Heating apparatus Location: Gosbury Hall, Hook, Surbiton, Surrey Client: A. Barnett	1896
TR MES AD1/921 [3 packets]	Structure: Plant house; Show house; Heating apparatus; Greenhouse; Greenhouses Location: Elvaston Nurseries, Borrowash, Derbyshire Client: William Barron and Son Ltd.	1903; 1906; 1921; 1936; 1939
TR MES AD1/922	Structure: Conservatory and stove Location: Park Road, Peterborough, Cambridgeshire Client: Perkins per Perkins and Barford, Queen Street Iron Works	1904
TR MES AD1/923	Structure: Vinery, Forcing, Tomato, Peach and Plant houses Location: Oaklands, Haywards Heath, Sussex Client: James Bradford	1906

TR MES AD1/924	Structure: Glasshouse Location: Duncross, Shepherds Hill, Highgate, London Client: W. Balden	1906
TR MES AD1/925	Structure: Heating apparatus Location: Kencott House, Lechlade, Gloucestershire Client: Dr Pilkington per Joseph Bowley and Son [Builders]	1903
TR MES AD1/926	Structure: Heating apparatus and repair work Location: Wakehurst Place, Haywards Heath, Sussex Client: T.W. Boord	1894
TR MES AD1/927	Structure: Conservatory Location: The Grange, Harmondsworth, Slough, Berkshire Client: John Bolders	1895
TR MES AD1/928	Structure: Heating apparatus; Plant house; Carnation house Location: Middleton Hall, Middleton on the Wolds, Driffield, Yorkshire Client: Capt. A.H. Brooksbank	1904; 1905; 1908
TR MES AD1/929	Structure: Greenhouse Location: Greenham, Newbury, Berkshire Client: J.H. Bowman	1902
TR MES AD1/930	Structure: Glasshouses Location: Laddington Hall, Kettering, Northamptonshire Client: Capt. A.W. de Capel Brooke	1892
TR MES AD1/931	Structure: Greenhouses Location: Roundhill House, Sydenham, London Client: A.H.J. Boass	1894
TR MES AD1/932	Structure: Stove and pit Location: Loxley Hall, Uttoxeter, Staffordshire Client: Stephen Blount	1903
TR MES AD1/933	Structure: Greenhouses Location: Brook Fever Hospital, Shooters Hill, Kent Client: Metropolitan Asylums Board	1896
TR MES AD1/934	Structure: Conservatory Location: Rolston House, Hornsea, North Yorkshire Client: Capt. H. Booth	1900
TR MES AD1/941	Structure: Heating apparatus Location: Heythrop Park, Chipping Norton, Oxfordshire Client: Albert Brassey	1899
TR MES AD1/942	Structure: Rose and carnation house Location: Weston Park, Weston-under-Lizard, near Shifnal, Shropshire Client: Earl of Bradford	1901
TR MES AD1/944	Structure: Heating apparatus Location: St Martins Church, Ruislip near Pinner, Middlesex Client: L. Ingham Baker	1893
TR MES AD1/945	Structure: Vinery and peach house; Plant house Location: Ashtead Grange, Leatherhead, Surrey Client: W.T. Birts	1895; 1902
TR MES AD1/946	Structure: Plant house and vinery Location: Sarnia House, Kettering, Northamptonshire Client: Thomas Bird	1900

TR MES AD1/947 See also TR MES AD1/1529	Structure: Greenhouses Location: Bishopswood, Ross, Herefordshire Client: James Murray Bannerman	1896
TR MES AD1/947	Structure: Heating alterations Location: Wyaston Leys, near Monmouth, Wales Client: James Murray Bannerman	1891
TR MES AD1/948	Structure: Plant house Location: Broadlands, Bridgend, South Wales Client: Miss Blandy	1891
TR MES AD1/949	Structure: Greenhouse Location: Newlyn, Driffold Road, Sutton Coldfield, West Midlands Client: Charles H. Brampton	1891
TR MES AD1/951	Structure: Plant house and Stove Location: Castle House, Lancaster, Lancashire Client: Thomas Barton	1891
TR MES AD1/952 [2 packets]	Structure: Heating apparatus Location: Barking Public Offices, Barking, Essex Client: Barking Town Urban District Council	1894; 1920; 1922; 1924
TR MES AD1/953	Structure: Glasshouses; Boiler Location: Ashgate Lodge, Chesterfield, Derbyshire Client: A. Barnes, MP	1891; 1935
TR MES AD1/954	Structure: Conservatory Location: The Lodge, The Heath, Leighton Buzzard, Bedfordshire Client: F. Bassett	1892
TR MES AD1/955 [2 of 3 packets]	Structure: Glasshouses Location: Cemetary, Blackburn, Lancashire Client: Blackburn Corporation	1913
TR MES AD1/955 [2 of 3 packets]	Structure: Greenhouses Location: Queens Park, Blackburn, Lancashire Client: Blackburn Corporation	1889
TR MES AD1/955 [1 and 3 of 3 packets]	Structure: Greenhouse; Stove house; Greenhouse Location: Corporation Park, Blackburn, Lancashire Client: Blackburn Corporation	1907; 1920; 1925
TR MES AD1/955 [3 of 3 packets]	Structure: Plant drawing class room Location: Municipal Technical School, Blackburn, Lancashire Client: Blackburn Corporation	1903
TR MES AD1/956	Structure: Heating apparatus Location: Barrow on Soar Liberal [and Labour and Institute] Club, Melton Road, Barrow on Soar, Leicestershire Client: Mr Bennett and H. Jacques[Club Secretaries]	1904; 1929
TR MES AD1/957	Structure: Vinery and peach cover Location: Abington Hall, Cambridgeshire Client: E. Barker	1890
TR MES AD1/958	Structure: Vinery Location: Wallingford, Oxfordshire Client: Brasher and Sons	1903

TR MES AD1/959	Structure: Plant house and stove; Glasshouses; Pits Location: East Lodge, Strathbraan, Shillingford, Wallingford, Oxfordshire Client: F.W. Mortimer per Messrs Brasher and Sons [Builders]	1898; 1899; 1900
TR MES AD1/960	Structure: Heating apparatus Location: Police Station, Colchester, Essex Client: Brightwen Binyon [Architect]	1895
TR MES AD1/961 See also TR MES AD1/962	Structure: Glasshouse; Boiler Location: The Rowans, Ashby Road, Burton-on-Trent, Staffordshire Client: S. Briggs	1906; 1924
TR MES AD1/962 See also TR MES AD1/961	Structure: Propagating house Location: Rowans, Ashby Road, Burton-on-Trent, Staffordshire Client: S. Briggs	1905
TR MES AD1/962	Structure: Plant and forcing house Location: The Burton Copper Mills, Burton-on-Trent, Staffordshire Client: Briggs and Co.	1892
TR MES AD1/963	Structure: Repairs to vinery Location: Elmhurst, Derby, Derbyshire Client: W. Bemrose	1903
TR MES AD1/964	Structure: Greenhouse Location: Sherwood Street, Nottingham, Nottinghamshire Client: Bell and Sons [Builders]	1891
TR MES AD1/965	Structure: Vinery; Vinery Location: Upper Gatton Park, Merstham, Surrey Client: Alex D. Druce; A. Benson	1893; 1900
TR MES AD1/966	Structure: Glasshouse Location: Stambourne, 147 Auckland Road, Upper Norwood, London Client: J. Beddow	1893
TR MES AD1/967	Structure: Conservatory Location: Grove House, Worksop, Nottinghamshire Client: E.R. Berry	1895
TR MES AD1/968	Structure: Conservatory; Fernery Location: 62 Dale Street, Liverpool, Merseyside Client: E. Berry	1892; 1893
TR MES AD1/969	Structure: Conservatory Location: Holly Grove House, Staines Road, Hounslow, Middlesex Client: J.R. Berry	1893
TR MES AD1/970	Structure: Conservatory Location: Snakemoor, Botley, Hampshire Client: Edward B. Bernard	1891
TR MES AD1/971	Structure: Greenhouse Location: Islip, Thrapston, Northamptonshire Client: Miss Beauford	1896
TR MES AD1/972	Structure: Greenhouse Location: Standish House, Spilsby Road, Boston, Lincolnshire Client: John Beulah	1893

TR MES AD1/974 [5 packets]	Structure: Museum roof; Conservatory; Forcing house; Glass house; Potato Pits; Peach House; Glazed wall cover; Peach house; Apricot house; Glass wall cover Location: Woburn Abbey, Bedfordshire Client: Duke of Bedford, KG	1903; 1906; 1908; 1909; 1910; 1912; 1921; 1925; 1927; 1929
TR MES AD1/975	Structure: Heating apparatus Location: 20 Red Lion Street, Clerkenwell, London Client: S. Betts	1896
TR MES AD1/976	Structure: Plant house Location: Gosford House, Ottery St Mary, Devon Client: S. Bennett	1892
TR MES AD1/977	Structure: Heating apparatus Location: Red Rice, Andover, Hampshire Client: Thomas Best	1903
TR MES AD1/978	Structure: Greenhouse Location: San Remo, The Walk, Merthyr Tydvil, South Wales Client: J.C. Bernascone	1904
TR MES AD1/979	Structure: Greenhouse Location: Woodside House, Chenies, Buckinghamshire Client: Joseph Bates [Builder]	1893
TR MES AD1/980	Structure: Heating apparatus Location: Fairford Vicarage, Fairford, Gloucestershire Client: Rev. F.R. Carbonell per George Barrett and Co. [Ironmongers]	1892
TR MES AD1/981	Structure: Heating apparatus Location: Lynderswood, Braintree, Essex Client: Edgar Barker	1897
TR MES AD1/989	Structure: Plant house; Conservatory Location: Ravensmere, Kendal Avenue, Epping, Essex Client: George Brooke	1899; 1902
TR MES AD1/990	Structure: Ventilating equipment for linotype room; Location: Fleet Street, London Client: Daily Telegraph	1931; 1938
TR MES AD1/990	Structure: Plant house Location: Hall Barn, Beaconsfield, Buckinghamshire Client: Lord Burnham	1903
TR MES AD1/991	Structure: Conservatory Location: Bents Green, Sheffield, South Yorkshire Client: Mr Blakelock	1899
TR MES AD1/992	Structure: Conservatory Location: Essex Lodge, Osborne Road, Windsor, Berkshire Client: E.R. Blewitt	1898
TR MES AD1/993	Structure: Conservatory Location: Garth, Broadstairs, Kent Client: B. Beech	1896
TR MES AD1/994	Structure: Forcing house Location: 51 Conway Street, Long Eaton, Derbyshire Client: Henry Broomfield	1903
TR MES AD1/995	Structure: Camelia house and vinery; Repairs Location: Tupton Hall, Chesterfield, Derbyshire Client: A.G. Barnes; Packman Estate	1893; 1917
TR MES AD1/996	Structure: Greenhouse Location: Adswood House, Stockport, Cheshire Client: Thomas Bell	1889

TR MES AD1/998 [2 packets]	Structure: Conservatory; Vinery; Peach house; Repairs; Painting Location: Cadoxten House, Neath, Glamorganshire, South Wales Client: Evan Evans Bevan	1903; 1905; 1907; 1908; 1909
TR MES AD1/999	Structure: Plant house Location: Cleveland, Kidlington, Oxfordshire Client: J.A. Baines	1902
TR MES AD1/1000	Structure: Conservatory Location: Tyringham, Duchy Road, Harrogate, Yorkshire Client: A.H. Briggs	1906
TR MES AD1/1001 [4 packets]	Structure: Stove and muscat vinery; Heating apparatus; Boiler; Painting and carnation house; Stove, vinery, plant house and melon house Location: Lytchett House, Poole, Dorset Client: Lord Eustace Cecil; Lord Evelyn Cecil, GBE, MP	1893; 1895; 1917; 1925; 1928
TR MES AD1/1003	Structure: Orchid, carnation and plant houses Location: Hatherop Castle, Fairford, Gloucestershire Client: Gardner S. Bazley	1903
TR MES AD1/1004 [2 packets]	Structure: Glasshouses Location: The Rookery, Brixworth, Northamptonshire Client: Percy E. Bucknall	1905; 1925
TR MES AD1/1006	Structure: Heating apparatus Location: Men's Wing, Belper, Derbyshire Client: Belper Union Workhouse	1903
TR MES AD1/1007	Structure: Greenhouse Location: Ridgebourne, Kington, Herefordshire Client: Mrs Banks	1902
TR MES AD1/1008 [3 packets]	Structure: Conservatory; Repairs Location: Hergest Croft, Kington, Herefordshire Client: W.H. Banks	1899; 1911
TR MES AD1/1009	Structure: Conservatory Location: Robson House, Surrenden Road, Preston Park, Brighton, Sussex Client: H.R. Blackburn	1898
TR MES AD1/1010	Structure: Conservatory Location: Powerscourt, Beckenham, Kent Client: L.E.G. Bryan	1904
TR MES AD1/1011 [2 packets]	Structure: Camellia, intermediate and stokery houses; Forcing houses Location: Spring Grove, Bewdley, Worcestershire Client: T.W. Binyon; Major W. Harcourt Webb	1905
TR MES AD1/1016	Structure: Conservatory Location: 29 Abercorn Place, Maida Vale, London Client: Major Blumenthal	1900
TR MES AD1/1017	Structure: Plant house Location: St Leonards Lodge, Maze Hill, St Leonards-on- sea, East Sussex Client: A.H. Burton	1900
TR MES AD1/1019	Structure: Heating apparatus Location: The Manor House, Linton, Burton-on-Trent, Staffordshire Client: Mrs J. Beard	1904

TR MES AD1/1021	Structure: Conservatory Location: Reinwood, Lindley, Huddersfield, West Yorkshire Client: F.W. Bentley	1900
TR MES AD1/1022	Structure: Glasshouse Location: St Leonards, Windsor, Berkshire Client: Lady Brinkman	1906
TR MES AD1/1024	Structure: Painting and repairs to glasshouses Location: 17 Sydenham Hill, London Client: Mrs Barry	1907
TR MES AD1/1025 [2 packets]	Structure: Conservatory and verandah; Plant house Location: The Oaklands, Rowley Avenue, Stafford, Staffordshire Client: H. Bostock	1903; 1906
TR MES AD1/1027	Structure: Peach cover Location: Measham Hall, Atherstone, Warwickshire Client: Sir William Abney	1901
TR MES AD1/1028	Structure: Greenhouse and plant house Location: Newtown House, Newbury, Berkshire Client: Sir Alexander Arbuthnot, Bart.	1891
TR MES AD1/1029	Structure: Heating alterations Location: The Parsonage, Sandbach Heath, Sandbach, Cheshire Client: Rev. S.H. Armistead	1891
TR MES AD1/1031	Structure: Greenhouses Location: 43 Hillmorton Road, Rugby, Warwickshire Client: Mrs Arundel	1895; 1897
TR MES AD1/1032	Structure: Glasshouses and heating apparatus; Glass porch Location: Lostock Dene, Lostock, Bolton, Lancashire Client: Frank Ainsworth	1893; 1894
TR MES AD1/1033	Structure: Heating apparatus Location: Lightwood Rocks, Longton, Staffordshire Client: W.A. Adderley	1894
TR MES AD1/1034	Structure: Rose and azalea house Location: Holcombe Hall, Ramsbottom, near Manchester, Lancashire Client: Thomas Aitken	1896
TR MES AD1/1035	Structure: Vineries Location: Manhattan, Gateacre, Liverpool, Merseyside Client: J.B. Atherton	1899
TR MES AD1/1036 [2 packets]	Structure: Orchid houses; Vinery; Conservatory; Glasshouse; Boiler Location: Pippbrook, Dorking, Surrey Client: H. Gurney Aggs	1891; 1892; 1913; 1914; 1915
TR MES AD1/1038	Structure: Glasshouses Location: Milford House, Milford, Co. Carlow, Ireland Client: Major Alexander	1903
TR MES AD1/1039	Structure: Plant house, stove, fernery and passageway Location: Heathersett, Reigate, Surrey Client: Julius Auerback	1904
TR MES AD1/1042	Structure: Glasshouse Location: West Field, Nether Street, Finchley, London Client: C.H. Attrears	1902

TR MES AD1/1043	Structure: Conservatory Location: Linden, Morpeth, Northumberland Client: Louis Ames	1890
TR MES AD1/1046	Structure: Greenhouse Location: Mount Nelson Hotel, Cape Town, South Africa Client: African Lands and Hotels Ltd	1899
TR MES AD1/1047 [1 of 2 packets]	Structure: Extension to ballroom, stable roof and windows; Conservatory Location: Normanhurst, Boldmere, Wylde Green, West Midlands Client: Joseph Appleby	1897; 1899
TR MES AD1/1047 [2 of 2 packets]	Structure: Heating apparatus; Heating apparatus; Boiler; Boiler Location: New works, Tower Road, Aston, Birmingham, West Midlands Client: Joseph Appleby Ltd	1915; 1920; 1931; 1945
TR MES AD1/1049	Structure: Vineries Location: Beechcroft, Kingsdown, Swindon, Wiltshire Client: Thomas Arkell	1898; 1900
TR MES AD1/1050	Structure: Glasshouses Location: Malling Place, West Malling, Kent Client: James Adams	1902
TR MES AD1/1051 [2 of 4 packets]	Structure: Huts Location: H.M. Dockyard, Chatham, Kent Client: H.M. Admiralty	1914
TR MES AD1/1051 [2 of 4 packets]	Structure: Boiler Location: H.M. Dockyard, Portsmouth, Hampshire Client: H.M. Admiralty	1915
TR MES AD1/1051 [1 and 3 of 4 packets]	Structure: Garage; Hut Location: R.N. Aviation Depot, Kingsnorth, Kent Client: H.M. Admiralty	1915
TR MES AD1/1051 [4 of 4 packets]	Structure: Vinery, plant house and pits Location: Commander-in-chief's residence, H.M. Docks, Chatham, Kent Client: H.M. Admiralty	1906
TR MES AD1/1051 [4 of 4 packets]	Structure: Conservatory Location: Whale Island, Portsmouth, Hampshire Client: H.M. Admiralty	1897
TR MES AD1/1052	Structure: Greenhouse Location: 163 Victoria Cottages, Station Road, Long Eaton, Derbyshire Client: J.V. Allen	1903
TR MES AD1/1054	Structure: Heating apparatus Location: Melrose, Knockholt, Kent Client: J. Airey	1899
TR MES AD1/1055	Structure: Heating apparatus Location: Faringdon, Berkshire Client: J. Thorley per T.W. Anns [Ironmonger]	1892
TR MES AD1/1055	Structure: Heating apparatus Location: Faringdon, Berkshire Client: John Heath per T.W. Anns [Ironmonger]	1892
TR MES AD1/1055	Structure: Plant house Location: Faringdon, Berkshire Client: Dr Lockwood per T.W. Anns [Ironmonger]	1898

TR MES AD1/1058	Structure: Conservatory; Forcing house; Peach house Location: The Limes, Mickleover, Derbyshire Client: H.E. Ayres and Mrs Ayres	1893; 1895; 1899
TR MES AD1/1059	Structure: Greenhouse Location: Ellershie, Marple, near Stockport, Cheshire Client: F.C. Aldous	1905
TR MES AD1/1060	Structure: Plant house Location: Willow Grange, Church Road, Watford, Hertfordshire Client: F. Armstrong	1901
TR MES AD1/1061	Structure: Conservatory Location: Rowley Park, Stafford, Staffordshire Client: F. Amies	1902
TR MES AD1/1062	Structure: Forcing house Location: Shernfold Park, Frant, Tunbridge Wells, East Sussex Client: Hon. J. Ashburnham	1895
TR MES AD1/1063	Structure: Heating apparatus Location: New House, Pollard Wood, Chalfont St Giles, Buckinghamshire Client: T.A. Allen	1905
TR MES AD1/1064	Structure: Plant house Location: 9 Barn Hill, Stamford, Lincolnshire Client: J.E. Ather	1887
TR MES AD1/1065	Structure: Stove Location: Cliffe Hill, Lightcliffe, Halifax, West Yorkshire Client: W.H. Aykroyd	1900
TR MES AD1/1066	Structure: Conservatory Location: Eastfield Lodge, Guildford, Surrey Client: Rev. F. Ashpital	1894
TR MES AD1/1067	Structure: Vinery Location: Wixenford, Wokingham, Berkshire Client: E.P. Arnold per Agricultural and Horticultural Association	1902
TR MES AD1/1069	Structure: Tomato house Location: 101 High Street, Ilfracombe, Devon Client: F.M. Watkin	1903
TR MES AD1/1071	Structure: Conservatory Location: Nantymoel, Glamorganshire, Wales Client: David Walters [Builder]	1903
TR MES AD1/1072	Structure: Heating apparatus Location: Roc Steel Foundry, West Drayton, Middlesex Client: Edmund Trevor Lloyd Williams	1903
TR MES AD1/1073	Structure: Vinery Location: Bainton, Stamford, Lincolnshire Client: W.C. Welby	1889
TR MES AD1/1074 [1 of 2 packets]	Structure: Conservatory Location: South Collingham, Newark, Nottinghamshire Client: John Wigram	1893
TR MES AD1/1074 [2 of 2 packets]	Structure: Glass porch Location: The Manor, Collingham, Newark, Nottinghamshire Client: John Wigram	1903
TR MES AD1/1075	Structure: Plant house Location: The Croft, Knutsford, Cheshire Client: R.H. Watt	1903

TR MES AD1/1076 [2 packets]	Structure: Heating apparatus; Boiler; Heating apparatus Location: Bartholomew Press, South Street, Dorking, Surrey Client: Adland and Son [Printers]	1906; 1927; 1949
TR MES AD1/1077	Structure: Plant house and pit Location: Blackheath, Saxmundham, Suffolk Client: Commander Vernon Wentworth	1902
TR MES AD1/1078 [1 of 2 packets]	Structure: Greenhouse; Cold frames Location: One Ash, Woodthorpe, near Loughborough, Leicestershire Client: A.C. Faire	1931; 1934
TR MES AD1/1078 [2 of 2 packets]	Structure: Stove and plant house; Boiler Location: One Ash, Woodthorpe, near Loughborough, Leicestershire Client: William Wright	1899; 1918
TR MES AD1/1079	Structure: Conservatory Location: Little Beville, Bures, Suffolk Client: F. Welsted	1899
TR MES AD1/1081	Structure: Conservatory; Conservatory Location: Essex House, Ballards Lane, Finchley, London Client: Ludwig Wagner	1896; 1902
TR MES AD1/1082	Structure: Greenhouse Location: Greenhill, Evesham, Essex Client: Lewis G. Wait	1901
TR MES AD1/1082	Structure: Boiler; Twin houses Location: Chadbury Fruit Farm, Evesham, Essex Client: Lewis G. Wait	1900; 1901
TR MES AD1/1083	Structure: Glasshouses including vinery; Fernery roof; Conservatory Location: Eureka Lodge, Swadlincote, Burton-on-Trent, Staffordshire Client: John D. Wragg	1892; 1896; 1901
TR MES AD1/1084	Structure: Orangery; Greenhouse Location: Langton, Hornchurch, Essex Client: Mr W. and Miss E. Varco Williams	1906; 1907
TR MES AD1/1085	Structure: Peach house; Peach house; Palm house roof Location: Curraghmore, Portlaw, Ireland Client: Right Hon. Lord Waterford, Marquis of Waterford	1890; 1895; 1901
TR MES AD1/1086	Structure: Boiler Location: Halfway Lodge, Esher, Surrey Client: Frederick Wicks	1897
TR MES AD1/1086	Structure: Steam heating apparatus Location: Hythe Road, Cumberland Road, Willesden Junction, London Client: Wicks Rotary Type Company Ltd	1897
TR MES AD1/1087	Structure: Greenhouse; Plant houses Location: Forest Park, Windsor, Berkshire Client: Arthur L. Wigan	1899; 1900
TR MES AD1/1088 [1 of 2 packets]	Structure: Peach house; Plant house; Heating apparatus Location: The Elms, Whitefield, Lancashire Client: Walter Wild	1903; 1905; 1908
TR MES AD1/1088 [2 of 2 packets]	Structure: Stove and cool house Location: The Elms, Whitefield, Lancashire Client: Walter Wild	1912

TR MES AD1/1089	Structure: Vinery; Vinery; Ventilation; Greenhouse Location: 67 Branstone Road, Burton-on-Trent, Staffordshire Client: John A. Walker	1894; 1897; 1904; 1906
TR MES AD1/1090 [1 of 2 packets]	Structure: Painting; Glasshouse; Boiler Location: Bedfont House, East Bedfont, Middlesex Client: D.H. Rhiner Waring; Miss Rowe-Waring	1900; 1904; 1938
TR MES AD1/1090 [2 of 2 packets]	Structure: Winter Garden Location: Bedfont House, East Bedfont, Middlesex Client: D.H. Rhiner Waring	1899
TR MES AD1/1091 [1, 2 and 3 of 8 packets]	Structure: Repairs to greenhouses Location: Bishop Burton Hall, Beverley, East Yorkshire Client: Owen S. Hellyer	1937-1938
TR MES AD1/1091 [4, 5, 6 and 8 of 8 packets]	Structure: Greenhouses, vineries, conservatory and verandah; Plant houses Location: Bishop Burton Hall, Beverley, East Yorkshire Client: Ernest Hall Watt	1890-1891; 1895
TR MES AD1/1091 [7 of 8 packets]	Structure: Boilers Location: Bishop Burton Hall, Beverley, East Yorkshire Client: Ernest Hall Watt	1904
TR MES AD1/1092 [2 packets]	Structure: Conservatory and glasshouse Location: Burbage House, Buxton, Derbyshire Client: T.H. Lowthran per W.R. Bryden [Architect]	1903
TR MES AD1/1094	Structure: Heating residence Location: The Manor House, Cossington, Leicestershire Client: G.H. Woolley	1903
TR MES AD1/1095 [2 packets]	Structure: Repairs and painting Location: Sanderstead Court, Sanderstead, near Croyden, Surrey Client: L.A. Wallace; E.D. Morton	1905; 1915
TR MES AD1/1096	Structure: Greenhouse; Wall cover Location: Hurstbourne Priors, near Whitchurch, Hampshire Client: Peter Williams	1903; 1905
TR MES AD1/1097 [2 of 2 packets]	Structure: Vinery and plant house Location: Hafod, Ystrad Meurig, Aberystwyth, Wales Client: Mrs Waddingham	1892
TR MES AD1/1097 [1 and 2 of 2 packets]	Structure: Heating apparatus and vinery; Boiler Location: Hafod, Devils Bridge RSO, Cardiganshire, South Wales Client: T.J. Waddingham	1902; 1919
TR MES AD1/1098	Structure: Greenhouse; Greenhouses Location: The Grange, Butterley, Derbyshire Client: Fitzherbert Wright per Alfred M. Wright; G.F. Wright	1907; 1911
TR MES AD1/1099	Structure: Plant house; Rose house; Extension to glasshouse Location: Whitmore Lodge, Bobbers Mill, Nottingham, Nottinghamshire Client: J. White	1905; 1906; 1907
TR MES AD1/1100	Structure: Conservatory Location: Shotley Grove, South Boldon, County Durham Client: Mrs J. Whitlock	1901

TR MES AD1/1101	Structure: Glasshouses Location: Wistaston Hall, Crewe, Cheshire Client: J. Baskerville Clegg per Capt. Walthall [Landlord] per Lionel C. Molesworth [Agent]	1904
TR MES AD1/1103	Structure: Carnation house Location: Warter Priory, Pocklington, Yorkshire Client: Mrs C.H. Wilson	1894
TR MES AD1/1104	Structure: Greenhouse Location: Firwood House, near Chalford, Gloucestershire Client: Rev. C. Smyth per Wall and Hook [Builders]	1892
TR MES AD1/1105	Structure: Plant house Location: Thurlby Hall, Newark, Lincolnshire Client: Cecil H. Wray	1891
TR MES AD1/1106	Structure: Conservatory; Heating apparatus Location: Wing, Oakham, Rutlandshire Client: E. Worrall	1892; 1895
TR MES AD1/1108	Structure: Glasshouse Location: Priestlands, near Lymington, Hampshire Client: Major Blunt per Wilfred T. Wire [Architect]	1906
TR MES AD1/1109	Structure: Greenhouse Location: Century Nurseries, Kedleston Road, Derby, Derbyshire Client: George A. Wheeldon	1901
TR MES AD1/1109	Structure: Greenhouses and pits Location: Parkfields House, Derby, Derbyshire Client: George A. Wheeldon	1900
TR MES AD1/1111	Structure: Painting; Boiler Location: Wood House, North Finchley, London Client: C.W. Wright Ingle	1899; 1903
TR MES AD1/1112	Structure: Conservatory; Glazed stoker Location: Highlands, Stoneygate Avenue, Knighton, Leicestershire Client: E.G. Ward	1901; 1907
TR MES AD1/1113	Structure: Plant house and forcing house Location: Courteenhall, Northamptonshire Client: Sir Hereward Wake, Bart	1901
TR MES AD1/1114	Structure: Heating apparatus Location: Coverham Abbey, Middleham, Yorkshire Client: Mrs A. Wright per J.G. Wright [Solicitor]	1903
TR MES AD1/1116	Structure: Heating apparatus and plant house Location: Burton Latimer, Kettering, Northamptonshire Client: T. and J. Wallis	1889
TR MES AD1/1117	Structure: Glass passage Location: Farnley Tyas Parsonage, near Huddersfield, Yorkshire Client: Rev. C.W. Wardroper	1889
TR MES AD1/1118	Structure: Stove and conservatory Location: Warleigh Lodge, Bathford, Bath, Somerset Client: J. Onslow Watts	1893
TR MES AD1/1119	Structure: Greenhouse; Rebuilding vinery; Peach house; Vinery Location: Shakenhurst, Cleobury Mortimer, Shropshire Client: C.W. Wickstead; Hugh Gurney	1892; 1900; 1908; 1909
TR MES AD1/1120	Structure: Vinery, Forcing house and greenhouse Location: Mount Sandford, Barnstaple, North Devon Client: Eustace R. Wigram	1902

TR MES AD1/1122	Structure: Covered way from billiard room to conservatory Location: Etherton Hall, Speldhurst, Tunbridge Wells, Kent Client: E.W. Winter	1896
TR MES AD1/1123	Structure: Plant house Location: Crescent Brewery, Burton-on-Trent, Staffordshire Client: E. Wright	1889
TR MES AD1/1124	Structure: Greenhouse Location: The Pymys, Wem, Shropshire Client: Samuel Hudson per George T. Whitfield [Timber merchant]	1895
TR MES AD1/1125	Structure: Heating apparatus Location: Bearwood Estate, Wokingham, Berkshire Client: A.F. Walter	1901-1908`
TR MES AD1/1126	Structure: Peach house; Early Vineries and camellia house Location: Shrubbs Hill, Sunningdale, Ascot, Berkshire Client: E.S. Walmsley	1892; 1893
TR MES AD1/1127	Structure: Conservatory; Plant house Location: Herrington, Dorchester, Dorset Client: Capt. Williams	1903; 1905
TR MES AD1/1129	Structure: Conservatory and orchard house Location: Bryn, Beaumaris, Anglesey, North Wales Client: Arthur F. Wrigley	1903
TR MES AD1/1129	Structure: Heating apparatus; Orchard house; Greenhouse Location: Beech House, Helsby, Warrington, Cheshire Client: Arthur F. Wrigley	1911; 1912; 1913
TR MES AD1/1130	Structure: Vinery and peach house Location: Meredith, Gloucester, Gloucestershire Client: Sir W. Wedderburn, Bart.	1903
TR MES AD1/1131	Structure: Plant house Location: The Nuns, Stamford, Lincolnshire Client: Lieut. Col. F.A. White	1902
TR MES AD1/1132	Structure: Glasshouses including vinery Location: Sunnyside, Upper Lewes Road, Brighton, Sussex Client: A. Wallis	1900
TR MES AD1/1133	Structure: Painting, plant house Location: Laurel Lodge, Dancers Hill, Barnet, Hertfordshire Client: H.A. Whateley	1898
TR MES AD1/1135	Structure: Glasshouses including vinery Location: Fernbank, Heaton, Bradford, West Yorkshire Client: J. Whittingham	1898
TR MES AD1/1136	Structure: Stove Location: Burton Closes, Bakewell, Derbyshire Client: S. Taylor Whitehead	1890
TR MES AD1/1138 [1 of 2 packets]	Structure: Stove; Rebuilding woodwork Location: Easton Lodge, Dunmow, Essex Client: Countess of Warwick	1894; 1896
TR MES AD1/1138 [2 of 2 packets]	Structure: Boiler; Boiler Location: Easton Lodge, Dunmow, Essex Client: Countess of Warwick	1927; 1930

TR MES AD1/1139	Structure: Peach cover Location: Hurstled, Sevenoaks, Kent Client: Mr Humphreys per Wiltshire and Sons [Builders]	1900
TR MES AD1/1141	Structure: Forcing house Location: 285 Upper Richmond Road, Putney, London Client: T. Blanco White	1903
TR MES AD1/1143	Structure: Heating apparatus; Conservatory; Hot water apparatus Location: Ampthill House, Ampthill, Bedfordshire Client: A.H. and Mrs Wingfield	1893-1895 1898; 1908
TR MES AD1/1144	Structure: Heating apparatus Location: Garage on Derby Road, Loughborough, Leicestershire Client: Midland Brewery Company	1924
TR MES AD1/1144	Structure: Glass roof to passage Location: Greyhound Hotel [Midland Brewery], Nottingham Road, Loughborough, Leicestershire Client: E.H. Warner	1897
TR MES AD1/1145	Structure: Palm house Location: Palermo, Sicily Client: Joshua Whitaker per J. Henry Christian	1897
TR MES AD1/1146	Structure: Conservatory; Painting; Painting Location: The Elms, Southam, Warwickshire Client: William Wood	1895; 1910; 1918
TR MES AD1/1147	Structure: Greenhouse Location: Beech hurst, Hawick NB, Roxburghshire, Scotland Client: Edward Wilson	1901
TR MES AD1/1148	Structure: Conservatory Location: Frolbury Manor, Dorking, Surrey Client: G.F.S. Warne	1898
TR MES AD1/1149 [1 of 3 packets]	Structure: Conservatory Location: Hillside Cottage, Woodspeen near Newbury, Berkshire Client: A.C. Wylie	1901
TR MES AD1/1149 [2 of 3 packets]	Structure: Forcing house and potting shed Location: Hillside Cottage, Woodspeen near Newbury, Berkshire Client: A.C. Wylie	1902
TR MES AD1/1149 [3 of 3 packets]	Structure: Plant house and alterations to conservatory Location: Hillside Cottage, Woodspeen near Newbury, Berkshire Client: A.C. Wylie	1900
TR MES AD1/1150	Structure: Reglazing roof Location: Winchester, Hampshire Corn Exchange, Winchester, Hampshire Client: Walter Bailey [Solicitor]	1902
TR MES AD1/1151	Structure: Greenhouse Location: Merstham House, Merstham, Surrey Client: Andrew Walker	1903
TR MES AD1/1153	Structure: Heating apparatus Location: Arley Cottage, Bewdley, Worcestershire Client: Charles J. Woodward	1897
TR MES AD1/1154	Structure: Glasshouse Location: Barrington Park, Burford, Oxfordshire Client: E.G.R. Wingfield	1905

TR MES AD1/1155	Structure: Plant house Location: The Banks, Honley near Huddersfield, Yorkshire Client: Charles Holdroyd per Harris Wood [Contractor]	1900
TR MES AD1/1156	Structure: Vinery; Forcing house Location: Rûg, Corwen, North Wales Client: P.W Wynn and the Hon. C.H. Wynn	1890
TR MES AD1/1157	Structure: Glasshouse; Plant house Location: Cantreyn, Bridgnorth, Shropshire Client: Alfred P. Welch	1894; 1898
TR MES AD1/1158	Structure: Greenhouse Location: Hopton Court, Cleobury Mortimer, Shropshire Client: Rear Admiral K. Woodward	1897
TR MES AD1/1159	Structure: Conservatory Location: Ferndale Bank, Tunbridge Wells, East Sussex Client: J.S. Weare	1887
TR MES AD1/1160	Structure: Stove and greenhouse Location: Brooklands, Broughton near Preston, Lancashire Client: A. Westworth	1902
TR MES AD1/1161 [1 of 2 packets]	Structure: Rebuilding stove house; Ventilation and conservatory roof repairs Location: Chesham, Bury, Lancashire Client: The Misses Walker	1927; 1940
TR MES AD1/1161 [2 of 2 packets]	Structure: Plant house; Conservatory; Vinery; Glasshouse Location: Chesham, Bury, Lancashire Client: Col. O. Ormrod Walker	1899; 1901; 1904; 1910
TR MES AD1/1162	Structure: Fernery Location: Mansion House Farm, Crowhurst, Lingfield, Surrey Client: John T. Williams	1902
TR MES AD1/1166 [1 of 2 packets]	Structure: Vinery; Cool house Location: Uplands, Selly Hill, Birmingham, West Midlands Client: Charles Winn	1906; 1910
TR MES AD1/1166 [2 of 2 packets]	Structure: Vinery; Rebuilding vineries Location: Uplands, Selly Hill, Birmingham, West Midlands Client: Charles Winn	1905; 1914
TR MES AD1/1167	Structure: Early vinery; Plant house and vinery Location: Hartfield Grove, Colemans Hatch, Sussex Client: Sir Spencer Walpole KCB	1905; 1906
TR MES AD1/1168	Structure: Conservatory Location: The Old House, Shalford, Guildford, Surrey Client: Miss Warburton	1891
TR MES AD1/1170	Structure: Plant house Location: West Park, Wolverhampton, West Midlands Client: Wolverhampton Corporation per borough surveyor	1897
TR MES AD1/1171	Structure: Conservatory Location: Broughton, Fountain Road, Upper Norwood, London Client: Mrs Wolff	1899
TR MES AD1/1173	Structure: Greenhouse Location: Banstead, Surrey Client: W.J. Wells [Builder]	1891

TR MES AD1/1174	Structure: Greenhouse Location: Moss Field, Pleasington, Blackburn, Lancashire Client: John F. Wilding	1886
TR MES AD1/1176	Structure: Greenhouse Location: Bedford House, Roundhay, Leeds, West Yorkshire Client: J.W.H. White	1895
TR MES AD1/1177	Structure: Greenhouse and potting shed Location: Fulbeck Rectory, Grantham, Lincolnshire Client: Rev. T. Vere Willson	1894
TR MES AD1/1178	Structure: Glasshouse Location: Idle Rocks, Stone, Staffordshire Client: Mrs Godfrey Wedgwood	1905
TR MES AD1/1179	Structure: Glasshouse Location: The Cedars, Epsom, Surrey Client: A.J. Warren	1905
TR MES AD1/1181	Structure: Plant house Location: Westmead, Bridport, Dorset Client: William Colfox, JP	1891
TR MES AD1/1183	Structure: Plant house Location: Russettings, Streatham Hill, London Client: A.S. Cochrane	1893
TR MES AD1/1185	Structure: Glasshouse Location: Dormans, Surrey Client: Dr James Watson MD	1901
TR MES AD1/1186	Structure: Heating apparatus Location: Earlsdon, Coventry, Warwickshire Client: R.J. Pike per J. Worwood [Builder]	1889
TR MES AD1/1187	Structure: Heating apparatus Location: Trustees Primitive Methodist Chapel, West Stockwith, Gainsborough, Lincolnshire Client: James Wood	1890
TR MES AD1/1188	Structure: Palm house, plant house, potting shed and vinery; Heating apparatus Location: The Cedars, Chislehurst Common, Kent Client: W. Willett	1897
TR MES AD1/1189	Structure: Glasshouse Location: Waltham House, Wirksworth, Derbyshire Client: George H. Wheatcroft	1898
TR MES AD1/1190	Structure: Forcing house Location: Holcombe, Chatham, Kent Client: George Wrinch	1896
TR MES AD1/1191	Structure: Greenhouse Location: Victoria Road, Morecambe, Lancashire Client: G. Willson	1887
TR MES AD1/1192	Structure: Conservatory and fernery roof; Moving and re-erecting conservatory Location: Culmington Manor, Craven Arms, Shropshire Client: Edward Wood; Capt. Wood	1894; 1908
TR MES AD1/1193	Structure: Conservatory Location: Hamilton House, Newmarket, Suffolk Client: John Watts	1892

TR MES AD1/1194	Structure: Conservatory Location: 401 Mansfield Road, Carrington, Nottinghamshire Client: John Woollatt	1895
TR MES AD1/1196	Structure: Conservatory Location: Ruddington, near Nottingham, Nottinghamshire Client: George Wadsley	1902
TR MES AD1/1198	Structure: Roof for Eastern Aviary Location: Zoological Gardens, Regents Park, London Client: Zoological Society of London	1903
TR MES AD1/1200	Structure: Plant house and stove Location: Wellbank, Sandbach, Cheshire Client: Mrs Yates	1889
TR MES AD1/1201	Structure: Plant house; Pit frames; Glasshouse; Violet frames Location: Forthampton Court, Tewkesbury, Gloucestershire Client: Joseph R. Yorke	1890; 1895; 1897; 1900
TR MES AD1/1203	Structure: Glasshouses Location: Stoke Bruerne park, Towcester, Northamptonshire Client: B.W. Vernon	1895
TR MES AD1/1204	Structure: Roof house; Greenhouse Location: Grayshott Court, Liphook, Hampshire Client: Charles Erskine Vertue; Miss Vertue	1894; 1907
TR MES AD1/1230	Structure: Greenhouse Location: Russell House, 15 Cann Hall Road, Leytonstone, London Client: P.W. Withers	1897
TR MES AD1/1231	Structure: Vinery; Forcing houses Location: Onslow, Shrewsbury, Shropshire Client: Mrs M. Wingfield	1896; 1901
TR MES AD1/1232	Structure: Vinery, peach house and glasshouses; Plant house and vinery Location: Oakwood Grange, Roundhay, Leeds, West Yorkshire Client: Thomas Walker; H.S. Walker	1893; 1907
TR MES AD1/1233	Structure: Heating apparatus Location: Ravensthorpe Manor, Thirsk, North Yorkshire Client: F.E. Walker	1900
TR MES AD1/1235	Structure: Glass vestibule Location: Lion Works, West Thurrock, Essex Client: Wouldham Cement Company	1902
TR MES AD1/1236	Structure: Conservatory Location: Oakcroft, Fareham, Hampshire Client: W.J. Wilson, MD	1894
TR MES AD1/1238	Structure: Heating alterations Location: Scarletts, Twyford, Berkshire Client: Rev. H.M. Wells	1893
TR MES AD1/1239	Structure: Heating apparatus and glasshouses Location: Meece House, near Stone, Staffordshire Client: E.J.W. Wood	1901
TR MES AD1/1240 [2 packets]	Structure: Glasshouses, painting and heating apparatus Location: Lea Wood, Matlock, Derbyshire Client: Mrs Walker	1900

TR MES AD1/1262	Structure: Plant house Location: The Elms, Sleaford Road, Boston, Lincolnshire Client: J.B. Wood	1902
TR MES AD1/1265	Structure: Range Location: Whitcliffe, Cleckheaton, West Yorkshire Client: Thomas Walker	1896
TR MES AD1/1266 [1 of 6 packets]	Structure: Heating apparatus Location: Ramsdale Park, near Arnold, Nottinghamshire Client: Sir Charles Secley, Bart.	1912
TR MES AD1/1266 [2 of 6 packets]	Structure: Peach houses, muscat vinery, Carnation house, tomato houses, plant houses Location: Sherwood Lodge, Nottinghamshire Client: Sir Charles Secley, Bart.	1916
TR MES AD1/1266 [3 of 6 packets]	Structure: Boiler and heating apparatus Location: Ramsdale Park, near Arnold, Nottinghamshire Client: Sir Charles Secley, Bart.	1911
TR MES AD1/1266 [4 of 6 packets]	Structure: Heating apparatus and boiler repairs Location: Sherwood Lodge, Nottinghamshire Client: Sir Charles Secley, Bart.	1924
TR MES AD1/1266 [5 of 6 packets]	Structure: Heating apparatus for residence Location: Ramsdale Park, near Arnold, Nottinghamshire Client: Sir Charles Secley, Bart.	1910
TR MES AD1/1266 [6 of 6 packets]	Structure: Boiler; Heating apparatus Location: Ramsdale Park, near Arnold, Nottinghamshire [Includes two letters regarding East Leake Church, near Loughborough] Client: Col. F.E. Secley	1916; 1922
TR MES AD1/1267 [1 of 2 packets]	Structure: Plant house, ferneries, vinery, repairs and heating apparatus Location: Shottesbrooke Park, Maidenhead, Berkshire Client: Guy Oswald Smith	1897
TR MES AD1/1267 [2 of 2 packets]	Structure: Palm house roof Location: Shottesbrooke Park, Maidenhead, Berkshire Client: Guy Oswald Smith	1904
TR MES AD1/1268	Structure: Heating apparatus Location: Douglas House, Osmaston Road, Derby, Derbyshire Client: A. Swingler	1894
TR MES AD1/1269	Structure: Heating apparatus; Boiler repairs Location: Leggatts, Potters Bar, Middlesex Client: Mrs J. Gurney Sheppard; W.F. Jackson	1897; 1915
TR MES AD1/1270	Structure: Hot house;Boiler; Heating apparatus Location: Burton Hall, Loughborough, Leicestershire Client: Lord Seymour; Duke of Somerset; Right Hon. Earl of Huntingdon	1892; 1921; 1928
TR MES AD1/1270	Structure: Renewing forcing house Location: Burton Hall, Banbury, Oxfordshire Client: Lord Ernest St Maur	1910
TR MES AD1/1271	Structure: Heating apparatus Location: Isel Church, Cockermouth, Cumbria Client: Rev. B. Hawker	1901
TR MES AD1/1272	Structure: Glasshouse Location: Whin-hurst, Hayling Island, Havant, Hampshire Client: John Glas Sanderman	1902

TR MES AD1/1276	Structure: Glasshouse; Glasshouse Location: Thames Bank, Goring, Oxfordshire Client: F. Shoolbred	1891; 1894
TR MES AD1/1277	Structure: Boiler Location: The Cottage, 44 Streatham Hill, London Client: F. Stokes	1902
TR MES AD1/1278	Structure: Conservatory; Vinery and peach house Location: Cross Lanes, London Road, Guildford, Surrey Client: Ferdinand F. Smallpiece	1892; 1902
TR MES AD1/1279	Structure: Heating apparatus, painting and repairs Location: Westbury Manor, near Bracknell, Buckinghamshire Client: Sir Samuel Scott, Bart.	1903
TR MES AD1/1280	Structure: Plant house Location: Kimbolton Road, Bedford, Bedfordshire Client: Dr Sharpin	1896
TR MES AD1/1281	Structure: Plant house and vinery Location: D'Urban Lodge, Woodchurch Road, West Hampstead, London Client: Martin Short	1898
TR MES AD1/1283	Structure: Conservatory Location: Manor House, Reepham, Lincolnshire Client: Mrs Wilson per Messrs Thomas Simpson and Sons	1893
TR MES AD1/1284	Structure: Heating apparatus Location: Broadfields, Winchmore Hill, London Client: W.T. Pauler, JP per Messers F. Smith and Co	1905
TR MES AD1/1285	Structure: Heating apparatus Location: Woodlands, Remenham Hill, Henley, Oxfordshire Client: Rawlins per W.F. Sargeant [Builder]	1896
TR MES AD1/1287	Structure: Conservatory Location: Castle Avenue, Conisborough, Doncaster, South Yorkshire Client: Mr Sharp	1901
TR MES AD1/1290	Structure: Hot water heating Location: Sussex County Lunatic Asylum, Haywards Heath, Sussex Client: Henry Card [Architect]	1899
TR MES AD1/1291	Structure: Vinery; Painting Location: Derwydd, Llandebie RSO, Carmathenshire, Wales Client: Alan Stepney-Gulston	1897; 1911
TR MES AD1/1292	Structure: Greenhouse and heating apparatus Location: Radley College, Abingdon, Berkshire Client: E.F. Simpkinson	1903
TR MES AD1/1293	Structure: Plant house and vinery Location: Kentchurch Court, Pontrilas, Herefordshire Client: G. Lee Morris	1890
TR MES AD1/1294 [1 of 2 packets]	Structure: Vinery and plant house; Peach house; Wall cover Location: Danby, Ballyshannon, Donegal, Ireland Client: Alfred Stubbs	1890; 1893; 1906
TR MES AD1/1294 [2 of 2 packets]	Structure: Peach house and vinery; Verandah Location: St Erman's, Donegal, Ireland Client: H. Stubbs	1905; 1906

TR MES AD1/1295 [1 of 2 packets]	Structure: Painting; Boiler Location: Fairfield, 65 Upper Richmond Road, Putney, London Client: J. Bridson Seattle	1901; 1926
TR MES AD1/1295 [2 of 2 packets]	Structure: Glasshouse Location: Fairfield, 65 Upper Richmond Road, Putney, London Client: J. Bridson Seattle	1906
TR MES AD1/1296	Structure: Vinery and peach house; Conservatory Location: Stanground Manor House, Peterborough, Cambridgeshire Client: John D. Selby	1887; 1889
TR MES AD1/1297	Structure: Ante room; Plant house and stove Location: Matlock, Derbyshire Client: Smedley's Hydropathic Company	1893; 1900
TR MES AD1/1298	Structure: Glasshouse; Painting Location: Weston Colville Hall, Cambridgeshire Client: Martin Slater	1901; 1904
TR MES AD1/1299	Structure: Heating apparatus Location: Drayton House, Thrapston, Northamptonshire Client: Mrs Stopford Sackville	1894
TR MES AD1/1300	Structure: Steam heating Location: Netherfield, Nottinghamshire Client: Stafford and Co [Printers]	1901
TR MES AD1/1301	Structure: Plant house Location: Ivy Dene, Wanlip Road, Syston, Leicestershire Client: J.W. Smith	1904
TR MES AD1/1304	Structure: Pit Location: Broomhall, Mount Park, Harrow, London Client: J.W. Stuart	1900
TR MES AD1/1305	Structure: Heating apparatus Location: Rock Pottery, Mexborough, South Yorkshire Client: George H. Smith [Builder]	1900
TR MES AD1/1306	Structure: Heating apparatus Location: Dromana, Cappoquin, Co. Waterford, Ireland Client: G.F. Villiers Stuart	1900
TR MES AD1/1307	Structure: Conservatory Location: Horton Street West, Rugby, Warwickshire Client: G. Stallard	1893
TR MES AD1/1308	Structure: Heating apparatus; Vinery Location: Chipley Park, Wellington, Somerset Client: Capt. H.W. Carleton Smith	1895; 1896
TR MES AD1/1310	Structure: Heating apparatus Location: Shepshed, near Loughborough, Leicestershire Client: Shepshed Conservative Club	1904
TR MES AD1/1311	Structure: Conservatory Location: Hoton, Loughborough, Leicestershire Client: Frederick Clarke per Mr Spencer	1893
TR MES AD1/1314	Structure: Conservatory Location: Hawthorn Villa, Merthyr Tydfil, South Wales Client: John Sibbering	1889
TR MES AD1/1316 [2 packets]	Structure: Plant house; Carnation houses and repairs; Summer house Location: Woodside, South Hill Park, Bromley, Kent Client: H.W. Symondson	1906; 1916-1923; 1924

TR MES AD1/1317	Structure: Heating apparatus; Heating alterations Location: Fingest Grove, High Wycombe, Buckinghamshire Client: F. Crawford Smith	1904; 1906
TR MES AD1/1319	Structure: Plant house Location: Kenwolde Court, Virginia Water, Surrey Client: G. Stevens	1898
TR MES AD1/1320	Structure: Vinery; Greenhouse; Repairs Location: Thorncliffe, Niton-under-Cliff, Isle Of Wight Client: S.H. Schmitz; Theodore John Hubert Schmitz	1896; 1923; 1924
TR MES AD1/1321 [2 packets]	Structure: Repairs and renewals Location: Eden Hall, Langwathby RSO, Cumbria Client: Charles H. Shaw	1906
TR MES AD1/1322	Structure: Plant house Location: Thorpe Hall, Peterborough, Cambridgeshire Client: Lt. Col. C.J. Strong	1903
TR MES AD1/1323	Structure: Conservatory Location: Gilmuire, Ascot, Berkshire Client: E. Maxwell Stuart	1897
TR MES AD1/1324	Structure: Glazing, painting and ventilating Location: Esholt Hall, Shipley, Yorkshire Client: Miss Crompton Stanfield	1892
TR MES AD1/1326	Structure: Plant house Location: Seabrook Hotel, Hythe, Kent Client: South Eastern Railway Company	1899
TR MES AD1/1327	Structure: Forcing house Location: Priors Lea, Broughton near Preston, Lancashire Client: B. Sykes	1899
TR MES AD1/1328	Structure: Heating apparatus Location: 59 Pierrepont Road, Trent Boulevard, West Bridgford, Nottinghamshire Client: R. Simpson	1895
TR MES AD1/1328	Structure: Greenhouse Location: 39 Greyfriars Gate, Nottingham, Nottinghamshire Client: R. Simpson	1895
TR MES AD1/1329	Structure: Conservatory Location: Highfield, Radcliffe-on-Trent, Nottinghamshire Client: J. Selby	1903
TR MES AD1/1330	Structure: Conservatory Location: Lyndhurst, Wadsley, Sheffield, Yorkshire Client: John Henry Swift	1899
TR MES AD1/1331	Structure: Conservatory Location: Egerton House, 450 Glossop Road, Sheffield, Yorkshire Client: Samuel Smith	1897
TR MES AD1/1333	Structure: Greenhouse Location: Bestwood, Arnold, Nottinghamshire Client: Duke of St Albans	1889
TR MES AD1/1334 [1 of 3 packets]	Structure: Plant house Location: 20 Denmark Avenue, Wimbledon, London Client: Ferdinand Rosing	1899
TR MES AD1/1334 [2 of 3 packets]	Structure: Alterations and additions to greenhouses Location: 20 Denmark Avenue, Wimbledon, London Client: Ferdinand Rosing	1900

TR MES AD1/1334 [3 of 3 packets]	Structure: Glasshouse Location: Iddesleigh, Kingston Vale, Putney, London Client: Ferdinand Rosing	1896
TR MES AD1/1335	Structure: Stove house Location: The Wakes, Selbourne, Hampshire Client: F.M. Read	1892
TR MES AD1/1337 See also TR MES AD1/1868	Structure: Conservatory, plant house and pit Location: Guilsborough House, Northampton, Northamptonshire Client: Capt. W.G. Renton	1897
TR MES AD1/1338	Structure: Peach houses Location: Bradstone Brook, Shalford, Guildford, Surrey Client: J.F. Renton	1890
TR MES AD1/1339	Structure: Greenhouse Location: Widgeon House, Beaconsfield, Buckinghamshire Client: John Rolfe	1893
TR MES AD1/1340	Structure: Stove house, muscat vinery, peach house and vinery Location: The Friars, Matfield Green, Paddock Wood, Kent Client: D'Arcy Reeve	1895
TR MES AD1/1341	Structure: Conservatory Location: The Limes, Kedleston Road, Derby, Derbyshire Client: A.H. Rowbotham	1896
TR MES AD1/1342	Structure: Greenhouse Location: Paddock, near Huddersfield, Yorkshire Client: Messrs Ramsden and Marsden [Builders]	1893
TR MES AD1/1343 [2 packets]	Structure: Hot water supply and heating apparatus Location: St Georges, Ampthill, Bedfordshire Client: G.H. Rushbrooke	1895; 1904
TR MES AD1/1345	Structure: Conservatory, stove, porch and orchid house Location: Beardwood, Blackburn, Lancashire Client: John Rutherford, MP	1896
TR MES AD1/1346	Structure: Greenhouse Location: Lavant, Chichester, West Sussex Client: Rev. G. Riadore	1888
TR MES AD1/1347	Structure: Plant house Location: Barrow on Soar, Leicestershire Client: Montagu Stone	1901
TR MES AD1/1350	Structure: Greenhouse Location: Ravensdene, Magdala Road, Nottingham, Nottinghamshire Client: A. Stafford	1897
TR MES AD1/1351	Structure: Greenhouses; Vinery Location: Hedgerley Park, Stoke Poges, Buckinghamshire Client: Mrs Stevenson	1893; 1895
TR MES AD1/1352	Structure: Conservatory Location: Steepleton Manor, Dorchester, Dorset Client: H. Stilwell	1896
TR MES AD1/1353	Structure: Boilers Location: Buenos Aires, Argentina Client: J.R. Sutton	1897

TR MES AD1/1354	Structure: Plant house Location: Weyhill, Andover, Hampshire Client: Capt. W. Smith	1901
TR MES AD1/1355	Structure: Plant house Location: Wickersley, Brough RSO, East Yorkshire Client: George L. Shackles	1907
TR MES AD1/1355	Structure: Stove and intermediate house Location: Southfield, Hessle, near Hull, Yorkshire Client: George L. Shackles	1903
TR MES AD1/1357	Structure: Heating apparatus Location: Ecclesbourne, The Avenue, Grove Park, Wanstead, Essex Client: William Stewart	1904
TR MES AD1/1358	Structure: Greenhouses; Painting Location: Shalimar, Ewell, Surrey Client: C. Chaloner Smith	1898; 1902
TR MES AD1/1359	Structure: Conservatory Location: Whitefriars, Chislett Road, Hampstead, London Client: N.M. Shimberg	1905
TR MES AD1/1360	Structure: Glasshouses; Plant house Location: 9 South Bailey, Durham, Co. Durham Client: C. Duncombe Shafts	1906; 1910
TR MES AD1/1361	Structure: Tomato houses Location: Croft House, Weeby, Lincolnshire Client: F.W. Stephenson	1892
TR MES AD1/1362	Structure: Heating apparatus to house Location: Hatfield Peverel House, Witham, Essex Client: Alfred Rosling	1894
TR MES AD1/1362	Structure: Heating apparatus to house Location: Cardfields, Hatfield Peverel, Witham, Essex Client: Alfred Rosling	1895
TR MES AD1/1363 [1 and 2 of 3 packets]	Structure: Greenhouses and palm house Location: Vernon Park, Stockport, Cheshire Client: Stockport, Cheshire Corporation	1904
TR MES AD1/1363 [3 of 3 packets]	Structure: Plant house and pit Location: Vernon Park, Stockport, Cheshire Client: Stockport, Cheshire Corporation	1912
TR MES AD1/1364	Structure: Greenhouse; Rebuilding tomato and melon house, frames and painting Location: Glandare, Aberdare, Glamorgan, South Wales Client: Robert T. Rees; Miss A.G. Rees	1895; 1935
TR MES AD1/1365	Structure: Plant house and conservatory Location: North Clifton Hall, Newark, Nottinghamshire Client: Capt S. Hutton Riddell per Smith, Woolley and Wigram	1896
TR MES AD1/1366	Structure: Heating apparatus Location: John O'Gaunts Gate, Lancaster, Lancashire Client: Shrigley and Hunt	1896
TR MES AD1/1367	Structure: Conservatory Location: Sherborne, Thurlow Park Road, West Dulwich, London Client: Henry Smith	1894
TR MES AD1/1368	Structure: Vinery Location: 2, The Gables, Uttoxeter Road, Derby, Derbyshire Client: W.R. Smith	1887

TR MES AD1/1369	Structure: Glasshouses Location: Newbold Revel, Rugby, Warwickshire Client: Rev. Richard Wood	1887
TR MES AD1/1370	Structure: Vinery and greenhouses Location: The Waylands, Hessle, Hull, Yorkshire Client: A. Spring	1902
TR MES AD1/1371	Structure: Heating apparatus Location: Loughananna, Mitchelstown, Co. Cork, Ireland Client: W. Summers	1900
TR MES AD1/1372	Structure: Boiler Location: Newbold Revel, Rugby, Warwickshire Client: A.H.E. Wood	1896
TR MES AD1/1373	Structure: Conservatory Location: Bodicote House, Banbury, Oxfordshire Client: J.F. Starkey	1898
TR MES AD1/1374	Structure: Conservatory Location: Wadhurst Place, Sussex Client: W.D. Watson Smyth	1886
TR MES AD1/1375	Structure: Greenhouse Location: Paper Staining Works, Chiswick, London Client: Arthur Sanderson and Son	1894
TR MES AD1/1376	Structure: Stoves and earl Vinery Location: Dudley Street, Grimsby, Lincolnshire Client: Jack Sutcliffe	1890
TR MES AD1/1379	Structure: Glasshouse Location: Walton Lodge, Broxbourne, Hertfordshire Client: C. Simpson	1905
TR MES AD1/1380	Structure: Glasshouse; Winter garden Location: Glenthorne, Bishops Avenue, East Finchley, London Client: G. Sainsbury	1903; 1910
TR MES AD1/1381	Structure: Vineries and plant house Location: Belmont Park, Havant, Hampshire Client: Mrs R.J. Snell	1905
TR MES AD1/1382	Structure: Tomato house Location: Sparrows Herve Hall, Bushey Heath, Hertfordshire Client: J. Walter Smith	1906
TR MES AD1/1382	Structure: Refixing peach house, plant house, stove and forcing houses Location: Eastcote, Pinner, Middlesex Client: J. Walter Smith	1906
TR MES AD1/1382	Structure: Peach house, plant house and stove; Heating to house; Location: Ivy House, North End, Hampstead, London Client: J. Walter Smith	1898; 1900
TR MES AD1/1383 [2 packets]	Structure: Heating apparatus, steam cooking apparatus and hot water supply Location: Gate Hotel, Nuneaton, Warwickshire Client: R. Stanley	1896
TR MES AD1/1384	Structure: Conservatory and plant house Location: Springfield Road, Leicester, Leicestershire Client: W.H. Stevens	1890

TR MES AD1/1384	Structure: Greenhouses; Peach house Location: Nether Close, Stoughton Drive, Oadby Road, Leicester, Leicestershire Client: W.H. Stevens	1902; 1907
TR MES AD1/1386	Structure: Greenhouse Location: Entwistle, Bolton, Lancashire Client: William Simpson per Simpson and Godlee	1892
TR MES AD1/1387	Structure: Heating apparatus; Heating to house Location: Dunstead House, Langley Mills, Nottinghamshire Client: William Smith; Lady Smith	1892; 1927
TR MES AD1/1388	Structure: Peach houses; Painting Location: The Priory, Reigate, Surrey Client: Lady Henry Somerset	1896; 1900
TR MES AD1/1389	Structure: Heating apparatus Location: Hinchinbrook, Huntingdon, Cambridgeshire Client: Earl of Sandwich	1897
TR MES AD1/1390	Structure: Heating apparatus Location: Corn Exchange, Sleaford, Lincolnshire Client: F.F. Bellamy [Secretary]	1902
TR MES AD1/1391	Structure: Heating apparatus Location: Hazlebrow, Duffield, Derbyshire Client: George Simpson	1894
TR MES AD1/1392 [1 of 2 packets]	Structure: Greenhouses; Glasshouse Location: Caversfield House, Bicester, Oxfordshire Client: Mrs Phillips per Messrs Thomas Smith and Sons	1893; 1907
TR MES AD1/1392 [2 of 2 packets]	Structure: Peach hosue and vinery Location: Caversfield House, Bicester, Oxfordshire Client: Major the Hon. E.H. Wyndham, MC	1924
TR MES AD1/1393 [4 packets]	Structure: Greenhouses, conservatory, forcing house, intermediate house, pit, installing running water and heating apparatus, painting; Firebars Location: Stonehurst, Ardingley, Sussex Client: J. Stuart	1894-1899; 1909
TR MES AD1/1395	Structure: Conservatory Location: Kynaston House, Ross, Herefordshire Client: H.L. Lutwyche per W.H. Smith [Builder]	1890
TR MES AD1/1396 See also TR MES AD1/117	Structure: Greenhouse Location: Arndene, Abbey Road, Barrow-in-Furness, Cumbria Client: J.P. Smith per Messrs Mackereths and Ulverstone	1905
TR MES AD1/1397	Structure: Glasshouse Location: Grendon Hall, Aylesbury, Buckinghamshire Client: A.E. Skinner	1905
TR MES AD1/1398	Structure: Conservatory and forcing house Location: Hillcrest, Brentwood, Essex Client: Alfred Smart	1905
TR MES AD1/1399 [1 of 2 packets]	Structure: Greenhouse Location: Lydhurst, Haywards Heath, Sussex Client: E. Steinkopff	1901
TR MES AD1/1399 [2 of 2 packets]	Structure: Plant and forcing houses Location: Lydhurst, Haywards Heath, Sussex Client: Mrs Stewart Mackenzie	1907

TR MES AD1/1401 [2 packets]	Structure: Plant house and vineries Location: Albert Cottage, Leigham Court Road, Streatham, London Client: R. Summers	1888
TR MES AD1/1402 [3 packets]	Structure: Palm house, Orchid house, Cattleya house, Laelia house, heating apparatus and weather vane Location: Lea Green, near Matlock, Derbyshire Client: J.B. Marsden Smedley	1896
TR MES AD1/1403	Structure: Conservatory roof and painting Location: Milton Park, Peterborough, Cambridgeshire Client: G.W.C. Fitzwilliam	1897
TR MES AD1/1404	Structure: Conservatory Location: Hillstead, St Mary Church Road, Torquay, Devon Client: Dr Stark	1889
TR MES AD1/1405	Structure: Conservatory Location: Heathside, Newmarket, Suffolk Client: W.B. Sheppard	1890
TR MES AD1/1406 [1 of 4 packets]	Structure: Plant houses Location: Harestone, Caterham Valley, Surrey Client: W. Garland Soper	1901
TR MES AD1/1406 [2 of 4 packets]	Structure: Peach house, vinery, fernery and heating apparatus Location: Harestone, Caterham Valley, Surrey Client: W. Garland Soper	1893
TR MES AD1/1406 [3 of 4 packets]	Structure: Vineries and peach house Location: Harestone, Caterham Valley, Surrey Client: W. Garland Soper	1898
TR MES AD1/1406 [4 of 4 packets]	Structure: Painting Location: Harestone, Caterham Valley, Surrey Client: W. Garland Soper	1904
TR MES AD1/1407	Structure: Greenhouses Location: 6 The Grove, Highgate, London Client: A. Pye Smith	1898
TR MES AD1/1408	Structure: Vinery and Forcing houses Location: Toddington Grange, Winchcomb RSO, Gloucestershire Client: Capt. Stacey	1897
TR MES AD1/1409	Structure: Vinery, plant house and pit Location: Priors Lee, Barrow-in-Furness, Cumbria Client: A.H. Strongitharm	1887
TR MES AD1/1410	Structure: Vinery; Boiler Location: Thurgarton Vicarage, Nottinghamshire Client: Rev. A.M.Y. Bailey per Messrs Smith, Woolley and Wigram	1892; 1914
TR MES AD1/1411	Structure: Vinery, forcing house, conservatory Location: Turfcote, Helmshore, Haslingden, Lancashire Client: W.H. Smith	1894
TR MES AD1/1413	Structure: Conservatory Location: The Hollies, Thrapston, Northamptonshire Client: G. Smith	1901
TR MES AD1/1414	Structure: Plant and forcing house Location: Tettenhall, Wolverhampton, West Midlands Client: C.E. Shaw, MP	1902

TR MES AD1/1415 [2 packets]	Structure: Conservatory, plant house, pits, heating apparatus and painting Location: The Red House, Streatham, London Client: H. Stevenson	1902
TR MES AD1/1417	Structure: Repairs and painting Location: Edge Hill, Duffield, Derbyshire Client: H. Swingler	1901
TR MES AD1/1418	Structure: Greenhouse Location: Glenholme, Gregory Boulevard, Nottingham, Nottinghamshire Client: James B. Snook	1894
TR MES AD1/1419	Structure: Greenhouse Location: The Cliffe, Wakefield, Yorkshire Client: A.W. Stanfield	1900
TR MES AD1/1421 [1 of 2 packets]	Structure: Conservatory and heating apparatus Location: Bawnmore, Bilton, Rugby, Warwickshire Client: Capt. H. Riall Sankey	1902
TR MES AD1/1421 [2 of 2 packets]	Structure: Heating apparatus; Stove, plant house and pit Location: Bawnmore, Bilton, Rugby, Warwickshire Client: Capt. H. Riall Sankey	1897; 1898
TR MES AD1/1422	Structure: Plant and peach houses Location: Idlicote, Shipston on Stour, Warwickshire Client: Right Hon. Lord Southampton	1899
TR MES AD1/1423	Structure: Conservatory Location: Tivoli House, Withdean, Brighton, East Sussex Client: James Savage	1902
TR MES AD1/1424	Structure: Conservatory Location: Craigisla, Penylan, Cardiff, Wales Client: T. Strachan	1898
TR MES AD1/1425	Structure: Heating apparatus Location: Remenham Hill, Henley on Thames, Oxfordshire Client: F. Sargeant [Builder]	1893
TR MES AD1/1426	Structure: Vinery Location: The Rectory, Oundle, Northamptonshire Client: J.W. Smith	1887
TR MES AD1/1427	Structure: Greenhouse Location: Slaugham, near Crawley, Sussex Client: Capt. Sergison	1900
TR MES AD1/1429	Structure: Greenhouse Location: Glen Cottage, Buckland Brewer, Bideford, Devon Client: Capt. Saunders	1887
TR MES AD1/1430	Structure: Camellia house and vinery Location: Gleadthorpe, Cavendish Crescent, The Park, Nottingham, Nottinghamshire Client: R. Steele	1889
TR MES AD1/1431	Structure: Wall cover Location: Waltham Hall, Grimsby, Lincolnshire Client: Arthur Soames	1887
TR MES AD1/1432	Structure: Heating apparatus Location: Clandown Church, Radstock, Bath, Somerset Client: Rev. W. Symonds	1886
TR MES AD1/1433	Structure: Heating apparatus Location: St Peters Church, Frocester, Gloucestershire Client: Rev. W Symonds	1889

TR MES AD1/1434	Structure: Heating apparatus Location: Melchbourne Park, Sharnbrook, Bedfordshire Client: Lord St John	1894
TR MES AD1/1436	Structure: Heating apparatus Location: Somerset Wheel and Wagon Works, Martock, Somerset Client: William Sparrow	1899
TR MES AD1/1437	Structure: Conservatory Location: Little Missenden House, Little Missenden, Buckinghamshire Client: P.S. Stephens, KC	1901
TR MES AD1/1440	Structure: Plant house Location: Side Hill Stud, Newmarket, Suffolk Client: Mrs Sherwood	1900
TR MES AD1/1441	Structure: Glasshouses Location: Hollins Lane, Keighley, Bradford, West Yorkshire Client: Prince Smith Jnr	1899
TR MES AD1/1442	Structure: Greenhouse Location: Hazledene, Sherwood, Nottinghamshire Client: Percy James Smith	1903
TR MES AD1/1443	Structure: Greenhouse Location: Church Works, Church, Lancashire Client: F. Steiner and Co	1902
TR MES AD1/1445	Structure: Plant house Location: The Knoll, Sutton Coldfield, West Midlands Client: John Charles Skelton	1889
TR MES AD1/1446	Structure: Conservatory Location: Goldwell Bank, Ashgate Road, Chesterfield, Derbyshire Client: William Spooner	1901
TR MES AD1/1447	Structure: Greenhouses Location: Meersbrook Park, Sheffield, Yorkshire Client: Sheffield Corporation	1902
TR MES AD1/1448	Structure: Conservatory Location: Solent Cottage, near Southampton, Hampshire Client: Lord Scarborough	1895
TR MES AD1/1449	Structure: Plant house Location: 6 Bond Street, Wakefield, Yorkshire Client: Miss Scott	1895
TR MES AD1/1450	Structure: Heating apparatus Location: Bennet Street, Long Eaton, Nottinghamshire Client: H.B. Sketchley	1904
TR MES AD1/1451	Structure: Ventilating and heating apparatus Location: Glossop House, Ilkeston, Derbyshire Client: E. Smith	1901
TR MES AD1/1454	Structure: Exhaust steam heating Location: Southend Works, Bridgewater Street, Liverpool, Merseyside Client: Read Bros.	1898; 1900
TR MES AD1/1455	Structure: Vinery, Cucumber house, and greenhouses Location: The Lodge, Cosham, Hampshire Client: Col. C.L. Reynolds	1889
TR MES AD1/1456	Structure: Heating apparatus Location: Rugby Conservative Club, Rugby, Warwickshire Client: T.W. Willard [Architect]	1899

TR MES AD1/1457 [2 of 6 packets]	Structure: Vinery and orchid house Location: Camden Holt, Chislehurst, Kent Client: F.A. Robinson	1897
TR MES AD1/1457 [1, 3 and 4 of 6 packets]	Structure: Conservatory and verandah Location: Camden Holt, Chislehurst, Kent Client: F.A. Robinson	1896
TR MES AD1/1457 [5 and 6 of 6 packets]	Structure: Rebuilding glasshouses Location: Camden Holt, Chislehurst, Kent Client: Evan Spicer	1930
TR MES AD1/1458	Structure: Conservatory Location: St Peters Vicarage, Tunbridge Wells, Kent Client: Rev. Joseph Rogers	1887
TR MES AD1/1459	Structure: Conservatory and forcing house Location: The Cottage, Coundon, Coventry, Warwickshire Client: William Ratcliff	1897
TR MES AD1/1460	Structure: Heating apparatus Location: Sudbury Priory, near Harrow, London Client: M.C. Robinson [Architect]	1895
TR MES AD1/1461	Structure: Forcing house and plant house Location: Stone Lodge, Cheam, Surrey Client: J.M. Ryrie	1898
TR MES AD1/1463	Structure: Conservatory and heating apparatus Location: Fernwood, Cape Town, South Africa Client: C.D. Rudd	1891
TR MES AD1/1464	Structure: Porch Location: Newholm, Whitby, North Yorkshire Client: Mr Pyman per David Richardson	1889
TR MES AD1/1466	Structure: Conservatory; Forcing house Location: The Pines, Penn Road, Wolverhampton, West Midlands Client: J. Rollings	1895; 1897
TR MES AD1/1467	Structure: Forcing house; Greenhouse Location: Cliff Lodge, Hyde Park, Leeds, Yorkshire Client: Richard Reynolds	1891; 1899
TR MES AD1/1468	Structure: Conservatory Location: The Hollies, Sutton Bassett, Northamptonshire Client: Mrs W. Rowlatt	1900
TR MES AD1/1469	Structure: Conservatory Location: Queniborough Hall, Syston, Leicestershire Client: Herbert W. Reynolds	1902
TR MES AD1/1470	Structure: Plant house; Greenhouse Location: Holmesland, Botley, Hampshire Client: Admiral Rowley	1898; 1899
TR MES AD1/1471	Structure: Conservatory; Greenhouse Location: The Elms, Coventry, Warwickshire Client: W.L. Robinson	1890; 1899
TR MES AD1/1472	Structure: Heating apparatus Location: The Orchard, Crofton, Lee-on-Solent, Hampshire Client: Matthew William Rowles [Builder]	1896
TR MES AD1/1473	Structure: Conservatory Location: The Gables, Collingham, Newark, Nottinghamshire Client: R.L. Rice	1894

TR MES AD1/1475	Structure: Greenhouses Location: Regent Villa, Colwyn Bay, North Wales Client: William Rothwell	1890
TR MES AD1/1476 [2 packets]	Structure: Conservatory, corridor, stove, intermediate house, plant house, potting shed and fernery Location: Broadhill, Keymer, Hassocks RSO, Sussex Client: G.W. Ryder	1901
TR MES AD1/1478	Structure: Conservatory Location: Medfa, Gloucester Road, Kingston Hill, Surrey Client: W.J. Russell	1896
TR MES AD1/1479	Structure: Plant house; Painting Location: Barra Hall, Hayes, Middlesex Client: Robert Reid	1892; 1902
TR MES AD1/1480	Structure: Glasshouses Location: Quarry Glen, Blackburn, Lancashire Client: T.P. Ritzema, JP	1899
TR MES AD1/1481	Structure: Greenhouse Location: Highfield, Englefield Green, Surrey Client: Miss Ridge	1894
TR MES AD1/1482	Structure: Greenhouse; Boiler Location: Coopers Hill, Englefield Green, Surrey Client: Royal Indian Engineering College	1901; 1902
TR MES AD1/1485	Structure: Heating apparatus and conservatory Location: Overslade, Rugby, Warwickshire Client: Mark Robinson	1897
TR MES AD1/1486	Structure: Riding school Location: Mentmore, Leighton Buzzard, Bedfordshire Client: Right Hon. Earl of Roseberg	1887
TR MES AD1/1487	Structure: Conservatory Location: Holgate, York, Yorkshire Client: A.A. Russell	1891
TR MES AD1/1488	Structure: Glasshouses Location: Greenford Hall, Southall, Middlesex Client: J.R. Roy	1891
TR MES AD1/1489	Structure: Glasshouses Location: Normanswood, Farnham, Surrey Client: Thomas Russell, CMG	1900
TR MES AD1/1490	Structure: Greenhouse Location: Ashbourne Road, Derby, Derbyshire Client: Railway Servants Orphanage	1896
TR MES AD1/1491	Structure: Winter garden Location: Longford Hall, Manchester, Lancashire Client: Mrs Rylands	1892
TR MES AD1/1492	Structure: Melon, Cucumber and plant houses Location: 24 Darnley Road, Gravesend, Kent Client: W. Russell	1898
TR MES AD1/1493	Structure: Heating alterations; Glasshouses Location: Hall Place, Cranleigh, Surrey Client: E.L. Rowcliffe	1899; 1902
TR MES AD1/1494	Structure: Glasshouses; Forcing house Location: Beechfield, Penkhull, Stoke-on-Trent, Staffordshire Client: H.M. Robinson	1893; 1896

TR MES AD1/1495	Structure: Conservatory and plant house Location: Lynwood, Totteridge Lane, Totteridge, Hertfordshire Client: F.R. Reeves	1901
TR MES AD1/1496	Structure: Glasshouses Location: Lucknow Drive, Nottingham, Nottinghamshire Client: John Robinson	1887
TR MES AD1/1497	Structure: Greenhouses Location: 4 Devonshire Road, Forest Hill, London Client: T.R. Roberts and Co. [Builders]	1902
TR MES AD1/1498	Structure: Peach house Location: Keresley Grange, Coventry, Warwickshire Client: John Rotherham	1902
TR MES AD1/1501 [3 of 3 packets]	Structure: Vinery and peach house Location: The Manor House, Hinton St. Mary, Sturminster Newton, Dorset Client: Capt. G.F. Pitt-Rivers	1929
TR MES AD1/1501 [2 of 3 packets]	Structure: Glasshouse Location: The Manor House, Hinton St. Mary, Sturminster Newton, Dorset Client: A. Pitt-Rivers	1903
TR MES AD1/1501 [2 of 3 packets]	Structure: Loggia Location: Rushmore, Wiltshire Client: A.E.L.F. Pitt-Rivers	1910
TR MES AD1/1501 [1 of 3 packets]	Structure: Orangery roof and boiler Location: The Manor House, Hinton St. Mary, Sturminster Newton, Dorset Client: Pitt-Rivers Estate	1902
TR MES AD1/1502	Structure: Plant house and stove Location: Rogerthorpe Manor, Pontefract, West Yorkshire Client: Mrs Ramsden	1890
TR MES AD1/1504	Structure: Conservatory Location: Boothly Hall, Grantham, Lincolnshire Client: Rev. R.A. Walts per J.W. Rimington [Plumber]	1905
TR MES AD1/1505	Structure: Greenhouse Location: Haven House, Conway, North Wales Client: A. Rice	1906
TR MES AD1/1506	Structure: Glasshouse Location: Glandore House, Glandore, Co. Cork, Ireland Client: Very Rev. J.M. Reeves, Dean of Ross	1893
TR MES AD1/1507	Structure: Heating apparatus Location: Great Northern Wharf, Wetmore Road, Burton-on-Trent, Staffordshire Client: Redfern and Mason	1905
TR MES AD1/1509	Structure: Conservatory Location: Rosslyn, 70 Castlenau, Barnes, London Client: H.C. Roberts	1904
TR MES AD1/1511	Structure: Glasshouse; Boiler Location: Soloms Court, Banstead, Surrey Client: H.K. Rutherford	1906; 1940
TR MES AD1/1512	Structure: Glasshouse Location: East Sheen, London Client: R.H. Leycester Penryhn	1894

TR MES AD1/1513	Structure: Fernery Location: Picton Castle, Haverford West, Pembrokeshire, Wales Client: Sir Charles E.G. Phillips, Bart.	1890
TR MES AD1/1514	Structure: Conservatory, vinery and potting house Location: Rivington, Eccles, Manchester, Lancashire Client: Alfred Pilkington	1890
TR MES AD1/1515	Structure: Mushroom house, plant house, vinery, stove, potting house, conservatory, and orchid house Location: Stoke Hill, Guildford, Surrey Client: Rev. F. Paynter	1893
TR MES AD1/1516	Structure: Conservatory; Heating Location: Higham Grange, Nuneaton, Warwickshire Client: Hon. E.H. Pierrepont	1887; 1901
TR MES AD1/1517	Structure: Orchid house Location: Trentham Vicarage, Stoke-on-Trent, Staffordshire Client: Rev. Edmund V. Piggott	1888
TR MES AD1/1518	Structure: Conservatory Location: Modern School House, Bedford, Bedfordshire Client: Dr R.B. Poole	1887
TR MES AD1/1519	Structure: Conservatory Location: Highfield, Stevenage, Hertfordshire Client: C. Poston	1899
TR MES AD1/1520	Structure: Repairing vinery Location: Bushey Park, Teddington, Richmond-upon-Thames, London Client: Lady Cecilia Paget	1887
TR MES AD1/1521	Structure: Greenhouse Location: St Andrews, Stamford, Lincolnshire Client: J.H. Phillips	1889
TR MES AD1/1523	Structure: Plant house Location: The Gables, Wolverton, Buckinghamshire Client: C.A. Park	1898
TR MES AD1/1525	Structure: Glasshouse Location: Pelham Road, Sherwood Rise, Nottingham, Nottinghamshire Client: A.F. Payne	1899
TR MES AD1/1527	Structure: Melon pit; Plant house Location: Cefn Park, Wrexham, Wales Client: Sir Roger Parker, Bart. per W. Shore	1901; 1904
TR MES AD1/1529	Structure: Conservatory Location: The Coppice, Ross, Herefordshire Client: Capt. W. Partridge	1897
TR MES AD1/1529 See also TR MES AD1/947	Structure: Vineries, stove, peach house and pits Location: Bishops Wood, Ross-on-Wye, Herefordshire Client: Capt. W. Partridge	1895
TR MES AD1/1530	Structure: New house Location: Skellow, Doncaster, South Yorkshire Client: D'Arcy S. Preston	1890
TR MES AD1/1531	Structure: Peach house, plant house and stove; Heating apparatus Location: Lillingstone Dagnell, Buckinghamshire Client: Hon. Mrs Douglas Pennant; Capt. Roberts	1904; 1919

TR MES AD1/1532	Structure: Boilers Location: Central London Railway, London Client: T. Potter and Sons [Engineers]	1906
TR MES AD1/1533	Structure: Boilers Location: Gorddinog, Llanfairfechan, North Wales Client: Col. Platt	1905
TR MES AD1/1534	Structure: Glasshouse Location: Pen Moel, Chepstow, Monmouthshire, Wales Client: Mrs W.E. Price	1905
TR MES AD1/1534	Structure: Forcing house Location: Tibberton Court, Tibberton SO, Gloucestershire Client: Mrs W.E. Price	1904
TR MES AD1/1535	Structure: Greenhouses Location: Pier Gardens, Cleethorpes, Lincolnshire Client: Great Central Railway Co. per G.A. Pillatt	1905
TR MES AD1/1536	Structure: Glasshouse Location: Hadley Dene, Hadley Wood, Middlesex Client: Alan Potter	1906
TR MES AD1/1537	Structure: Greenhouse; Stove; Vineries; Boiler Location: Rampsbeck House, Ullswater, Penrith, Cumbria Client: Mrs Pritt	1902; 1903; 1905; 1908
TR MES AD1/1538	Structure: Conservatory Location: The Cranhams, Trowbridge, Wiltshire Client: J.R. Philpott	1892
TR MES AD1/1539	Structure: Greenhouse Location: Oadby Road, Leicester, Leicestershire Client: M.H. Pearson	1903
TR MES AD1/1540	Structure: Plant and forcing house Location: Lynton, Vine Road, Sevenoaks, Kent Client: George S. Pinchin	1903
TR MES AD1/1541	Structure: Glasshouse Location: Thurlaston Grange, Derby, Derbyshire Client: Rev. Charles H. Prodggers	1904
TR MES AD1/1542	Structure: Propogating house Location: Keswick Lodge, East Putney, London Client: A.J. Picketts	1902
TR MES AD1/1543 [2 packets]	Structure: Plant house; Rebuilding greenhouse; Greenhouse; Painting Location: Poplar Recreation Ground, East India Dock Road, Poplar, London Client: Poplar Borough Council	1903; 1932 and 1951; 1937 1949
TR MES AD1/1544	Structure: Boiler Location: Feltham, Middlesex Client: Pritchettts and Gold	1902
TR MES AD1/1545	Structure: Glasshouse Location: Clark's Farm, Capel, Dorking, Surrey Client: George E.B. Pritchett	1909
TR MES AD1/1546 [1 of 2 packets]	Structure: Glasshouse Location: Uplands, Feltham, Middlesex Client: Theodore W. Pritchett	1905
TR MES AD1/1546 [2 of 2 packets]	Structure: Glasshouse Location: Bilbury, Mill Gap Road, Eastbourne, Sussex Client: Theodore W. Pritchett	1925

TR MES AD1/1547	Structure: Heating apparatus Location: Barton Court, Kintbury near Hungerford, Berkshire Client: W. Parrott	1902
TR MES AD1/1548	Structure: Conservatory Location: Varana, Hobart, Tasmania, Australia Client: R.C. Patterson	1902
TR MES AD1/1549 [2 packets]	Structure: Glasshouses; Heating apparatus Location: The Logs, East Heath Road, Hampstead Heath, London Client: F. Pusinelli	1898
TR MES AD1/1550	Structure: Stove house Location: Oakwood, Chislehurst, Kent Client: R. de Q. Quincey	1901
TR MES AD1/1551 [1 of 2 packets]	Structure: Greenhouse Location: Inglewood, Chislehurst, Kent Client: Richard De Q. Quincey	1899
TR MES AD1/1551 [2 of 2 packets]	Structure: Pit with ridge box Location: Fairholme, Langley Avenue, Surbiton, Surrey Client: H.D. De Quincey	1897
TR MES AD1/1552	Structure: Heating apparatus Location: Glencairn Abbey, Lismore, Co. Waterford, Ireland Client: A.W.B. Power	1900
TR MES AD1/1553	Structure: Conservatory Location: Powiscourt, Potters Bar, Middlesex Client: Alfred Parker	1900
TR MES AD1/1554	Structure: Glasshouses Location: Winston Hall, East Park Road, Blackburn, Lancashire Client: Rev. James Pickop	1903
TR MES AD1/1555	Structure: Glasshouse Location: Fairstowe, Ilkley, Yorkshire Client: F.W. Pearce	1899
TR MES AD1/1557	Structure: Vinery Location: Rocklands, Goodrich, Ross-on-Wye, Herefordshire Client: Admiral Pearson	1901
TR MES AD1/1558	Structure: Greenhouse Location: Woodlands, Beaconsfield, Buckinghamshire Client: Mrs Penfold	1901
TR MES AD1/1559	Structure: Heating apparatus and hot water supply Location: Westholme, Sleaford, Lincolnshire Client: H.A. Peake	1902
TR MES AD1/1560	Structure: Conservatory and verandah Location: 7 Elderslie Road, Eltham, Kent Client: A. Parker	1902
TR MES AD1/1561	Structure: Heating apparatus Location: Tramway Depot, Stoke-on-Trent, Staffordshire Client: Potteries Electric Traction Company	1901; 1907
TR MES AD1/1562	Structure: Greenhouse Location: Ashfield, Peterborough, Cambridgeshire Client: John A. Percival	1895
TR MES AD1/1563	Structure: Vinery Location: Wainsford, Lymington, Hampshire Client: E. Powell King per W. Parton	1900

TR MES AD1/1564	Structure: Vineries; Vinery; Painting Location: Stonelands, East Grinstead, West Sussex Client: F. Godwin King per W. Parton	1899; 1900; 1901
TR MES AD1/1565	Structure: Greenhouse Location: Calvesley Hall, Tarporley, Cheshire Client: Mrs H.R. Peel	1889
TR MES AD1/1566	Structure: Exhaust steam heating apparatus Location: Adamantine Brick Works, Reading, Berkshire Client: Poulton and Son	1895
TR MES AD1/1567	Structure: Conservatory Location: The Priory, Datchet, Berkshire Client: H.L. Prior	1890
TR MES AD1/1568	Structure: Stove Location: West Hill, Ledbury, Herefordshire Client: L.H. Palairt	1891
TR MES AD1/1569	Structure: Greenhouse Location: 2 St Helens Crescent, Swansea, Wales Client: Dr J.L. Pritchard	1890
TR MES AD1/1572	Structure: Conservatory Location: Brampton Manor, Chesterfield, Derbyshire Client: James Pearson	1897
TR MES AD1/1574	Structure: Plant house Location: Humberstone Hall, Leicester, Leicestershire Client: Mrs Thompson [Tenant] per Mrs Guy Paget	1898
TR MES AD1/1575	Structure: Peach house Location: Brooklyn, Coventry, Warwickshire Client: G.A. Pridmore	1892
TR MES AD1/1576	Structure: Peach house Location: Rousdon, Lyme Regis, Dorset Client: Sir Cuthbert Peek, Bart.	1900
TR MES AD1/1578	Structure: Greenhouse Location: Overleigh, Hough Green, Chester, Cheshire Client: Mr Roberts per Messrs Parker Bros [Builders]	1896
TR MES AD1/1579	Structure: Plant house Location: The Palace, Peterborough, Cambridgeshire Client: Bishop of Peterborough	1897
TR MES AD1/1580	Structure: Forcing house Location: Anthony House, Devonport, Hampshire Client: Col. Reginald Pole Carew, CB	1897
TR MES AD1/1581 [1 of 3 packets]	Structure: Plant house Location: Southfield House, Horton Street, Rugby, Warwickshire Client: Miss Pennington	1899
TR MES AD1/1581 [2 of 3 packets]	Structure: Painting and heating apparatus Location: Southfield House, Horton Street, Rugby, Warwickshire Client: Miss Pennington	1900
TR MES AD1/1581 [3 of 3 packets]	Structure: Orchard house Location: Southfield House, Horton Street, Rugby, Warwickshire Client: Miss Pennington	1907
TR MES AD1/1582	Structure: Conservatory Location: The Grove, Esher, Surrey Client: Col. C.J. Price	1887

TR MES AD1/1584	Structure: Glasshouses Location: Queens Park, Longton, Staffordshire Client: J.W. Wardel [Borough Surveyor]	1891
TR MES AD1/1585	Structure: Removing radiators Location: Imperial Hotel, Rugby, Warwickshire Client: Charles Cockerill [Builder]	1918
TR MES AD1/1585	Structure: Heating apparatus; Boiler repairs Location: Peacock Inn, Newbold Road, Rugby, Warwickshire Client: F.W. Willard [Architect]	1899; 1918
TR MES AD1/1586 [1 of 4 packets]	Structure: North house Location: Rainford Hall, St Helens, Lancashire Client: Mrs Richard Pilkington	1912
TR MES AD1/1586 [2 of 4 packets]	Structure: Rose house and rearrangement of greenhouses Location: Rainford Hall, St Helens, Lancashire Client: Mrs Richard Pilkington	1898
TR MES AD1/1586 [3 of 4 packets]	Structure: Rebuilding peach and stove house Location: Rainford Hall, St Helens, Lancashire Client: Mrs Richard Pilkington	1935
TR MES AD1/1586 [4 of 4 packets]	Structure: Heating apparatus; Lean to frames Location: Rainford Hall, St Helens, Lancashire Client: Mrs Richard Pilkington	1911; 1930
TR MES AD1/1587	Structure: Greenhouse Location: Andover Nursery, Junction Road, Andover, Buckinghamshire Client: W. Palmer	1898
TR MES AD1/1589	Structure: Conservatory roof Location: Holme Hill, Dalston, near Carlisle, Cumbria Client: Messrs Paley and Austin [Architects]	1891
TR MES AD1/1591	Structure: Heating apparatus Location: Annestown, Tramore, Waterford, Ireland Client: Mrs Palliser	1895
TR MES AD1/1593	Structure: Conservatory Location: Queens Hotel, Harrogate, North Yorkshire Client: John Thompson and Co.	1900
TR MES AD1/1595	Structure: Wall cover Location: Radford, Leamington, Warwickshire Client: J.L. Paton	1894
TR MES AD1/1596	Structure: Glasshouse Location: Ashlawn, The Inwoods, Rugby, Warwickshire Client: J. Parnell	1894
TR MES AD1/1597	Structure: Curvilinear plant house and fernery Location: Rainsbrook, Rugby, Warwickshire Client: J. Parnell	1896
TR MES AD1/1598	Structure: Glasshouse Location: Alperton Lodge, Wembley, Middlesex Client: Hon. Rupert Guinness	1903
TR MES AD1/1599 [1 of 4 packets]	Structure: Painting and repairs, Boiler Location: Belmont, 39 Honor Oak Road, Forest Hill, London Client: J.Arthur Pyne	1922
TR MES AD1/1599 [2 of 4 packets]	Structure: Plant house and stove; Painting Location: Belmont, 39 Honor Oak Road, Forest Hill, London Client: J. Arthur Pyne	1898; 1900

TR MES AD1/1599 [3 and 4 of 4 packets]	Structure: Conservatory Location: Belmont, 39 Honor Oak Road, Forest Hill, London Client: J. Arthur Pyne	1914
TR MES AD1/1601	Structure: Glasshouse Location: Highlands, Woldingham, Surrey Client: W.H. Prescott	1906
TR MES AD1/1602	Structure: Conservatory Location: Hills Lea, Guildford, Surrey Client: W. Pimm	1901
TR MES AD1/1603	Structure: Plant house Location: Walton Hall, Bletchley, Buckinghamshire Client: Miss Pinfold	1899
TR MES AD1/1604	Structure: Conservatory Location: Penrhewlyn House, Neath, Glamorgan, Wales Client: Richard Phillips	1895
TR MES AD1/1605	Structure: Greenhouse Location: Eashing Park, Godalming, Surrey Client: Lord Penzance	1888
TR MES AD1/1606	Structure: Forcing house Location: Chedington Court, Misterton, Crewkerne, Somerset Client: Sir Henry Pets	1901
TR MES AD1/1607	Structure: Heating apparatus Location: Central Hall, Holborn, London Client: W.J. Purkiss	1889
TR MES AD1/1608	Structure: Plant house Location: Glen Rosa, 60 Woodvale, Lordship Lane, London Client: A. Pemberton	1893
TR MES AD1/1609	Structure: Conservatory Location: The Woodlands, Beulah Hill, Norwood, London Client: M. Pontifex per Pontifex and Wood	1889
TR MES AD1/1610	Structure: Conservatory Location: Hartshill Hall, Stoke-on-Trent, Staffordshire Client: R. Nicholls	1899
TR MES AD1/1611	Structure: Forcing house; Greenhouse Location: Mountfield, Faversham, Kent Client: F.G. Oliver	1899; 1900
TR MES AD1/1612	Structure: Conservatory; Glasshouse Location: Tanbridge, Horsham, West Sussex Client: Thomas Oliver	1889; 1906
TR MES AD1/1613 [1 of 3 packets]	Structure: Painting; Boiler Location: The Elms, Castle Bar, Ealing, London Client: William Owen	1900; 1904
TR MES AD1/1613 [2 of 3 packets]	Structure: Peach house, tomato house, plant house and pit Location: The Elms, Castle Bar, Ealing, London Client: William Owen	1894
TR MES AD1/1613 [3 of 3 packets]	Structure: Conservatory Location: The Elms, Castle Bar, Ealing, London Client: William Owen	1890
TR MES AD1/1614	Structure: Glasshouse Location: Springhead, Bulwell, Nottinghamshire Client: Henry J. Neilson	1904

TR MES AD1/1615	Structure: Glasshouse; Vinery and peach house Location: The Knipp, Chiddingfold, Surrey Client: J.F. Ogilvy per Horace Farquharson [Architect]	1901; 1905
TR MES AD1/1616	Structure: Heating apparatus Location: Kennett Hall, Newmarket, Suffolk Client: Capt. Pering	1905
TR MES AD1/1617	Structure: Heating apparatus and repairs Location: Walcot, Lydbury North, Shropshire Client: Lord Powis	1900
TR MES AD1/1618	Structure: Conservatory Location: Dyke Road, Brighton, East Sussex Client: W. Porter	1901
TR MES AD1/1619	Structure: Plant house and stove Location: Cobden Hill, Radlett, Hertfordshire Client: R.S. Phillimore	1899
TR MES AD1/1620	Structure: Conservatory Location: Maesgwynne, Whitland, South Wales Client: Mrs C. Powell	1895
TR MES AD1/1621 [1 of 6 packets]	Structure: Plant house, stove and intermediate houses Location: Bletchingley Castle, Bletchingley, Surrey Client: A.P. Brandt	1924
TR MES AD1/1621 [2 and 3 of 6 packets]	Structure: Boiler Location: Castle Hill, Bletchingley, Surrey Client: A.P. Brandt	1919; 1923
TR MES AD1/1621 [4, 5, 6 of 6 packets]	Structure: Conservatory Location: Woolpits, Bletchingley, Surrey Client: Henry Partridge	1900
TR MES AD1/1621 [4, 5, 6 of 6 packets]	Structure: Plant houses, palm house, Vineries, forcing house, peach house Location: Castle Hill, Bletchingley, Surrey Client: Henry Partridge	1900
TR MES AD1/1622 [2 packets]	Structure: Vinery, Conservatory, and Plant houses Location: Arthur Avenue, Lenton Boulevard, Nottingham, Nottinghamshire Client: A. Orgill	1898
TR MES AD1/1623	Structure: Covered way to mortuary Location: Nottingham General Hospital, Nottinghamshire Client: Alfred Watershouse and Sons [Architects]	1902
TR MES AD1/1624	Structure: Conservatory Location: Cherry Garth, Cottingham near Hull, Yorkshire Client: W.J. Owbridge	1899
TR MES AD1/1645 [1 of 2 packets]	Structure: Boiler Location: West Court, Bray-on-Thames, Berkshire Client: W. West Neve	1924; 1925
TR MES AD1/1645 [2 of 2 packets]	Structure: Conservatory and corridor Location: Osbourne Lodge, Cranbrook, Kent Client: W. West Neve [Architect]	1902
TR MES AD1/1645 [2 of 2 packets]	Structure: Vineries and greenhouses; Conservatory Location: Fishery Estate, Maidenhead, Berkshire Client: W. West Neve	1901; 1902
TR MES AD1/1646 See also TR MES AD1/1645	Structure: Greenhouse Location: Osbourne Lodge, Cranbrook, Kent Client: Miss West Neve	1905
TR MES AD1/1647	Structure: Heating apparatus Location: Claygate, Surrey Client: Braid, Pates and Co. per J. Nicholson and Co	1904

TR MES AD1/1648	Structure: Conservatory Location: Tattenhill, Burton-on-Trent, Staffordshire Client: J.J. Newbould	1904
TR MES AD1/1649	Structure: Greenhouse Location: Delville, Reigate, Surrey Client: A.M. Ogle	1901
TR MES AD1/1650	Structure: Boiler Location: Constantinople Client: Sidney Nowill and Co.	1904
TR MES AD1/1651	Structure: Conservatory Location: Broadwater Manor, Worthing, Sussex Client: H. Nye	1904
TR MES AD1/1652	Structure: Glasshouses Location: Clayworth, Bawtry, South Yorkshire Client: R.C. Otter	1890
TR MES AD1/1653	Structure: Greenhouses Location: Berry Hill, Taplow, Buckinghamshire Client: Hon. Mrs Needham	1900
TR MES AD1/1654	Structure: Stove and cucumber house Location: Blatherwycke Park, Wansford, Northamptonshire Client: H.S. O'Brien	1901
TR MES AD1/1655	Structure: Vineries, Conservatory and greenhouses; Glasshouse Location: Annaghmore, Collooney, Co. Sligo, Ireland Client: C.K. O'Hara	1901; 1904
TR MES AD1/1656	Structure: Plant house Location: Eardiston House, West Felton, Oswestry, Shropshire Client: J.B. Oswell	1906
TR MES AD1/1657	Structure: Greenhouse; Alterations to greenhouse; Carnation House Location: The Hermitage, Hazlewood Road, Duffield, Derbyshire Client: J.R. Nayler; W.L.P. Woolley	1901; 1937; 1938
TR MES AD1/1659	Structure: Glasshouses Location: Avon House, Gordon Road, Tunbridge Wells, Kent Client: Miss Nix	1896
TR MES AD1/1660	Structure: Glasshouse Location: Bear Place, Twyford, Berkshire Client: Henry Nicholl	1896
TR MES AD1/1661	Structure: Plant house and vinery Location: Broadward Hall, Aston-on-Clun, Shropshire Client: J.S. Moreton	1911
TR MES AD1/1661	Structure: Heating apparatus Location: Broadward Hall, Leintwardine, Herefordshire Client: Marquis de Biddlecope per T. Overton and Son	1892
TR MES AD1/1662	Structure: Heating apparatus Location: Stowe House, Lichfield, Staffordshire Client: Mrs Roby Thorpe	1906
TR MES AD1/1663 [1 of 3 packets]	Structure: Rebuilding Melon house Location: Hollington House, Woolton Hill, Newbury, Berkshire Client: E.C. Cohen	1935

TR MES AD1/1663 [1, 2 and 3 of 3 packets]	Structure: Peach house; Muscat vinery, forcing house, plant house, orchid house and mushroom beds Location: Hollington House, Woolton Hill, Newbury, Berkshire Client: W.T. Taylor	1902; 1904
TR MES AD1/1664	Structure: Heating apparatus Location: Sherfield Manor, Basingstoke, Hampshire Client: J.B. Taylor	1900
TR MES AD1/1666	Structure: Greenhouses; Forcing house; Heating apparatus Location: Manor House, Barton Hartshorn, Buckinghamshire Client: Hon. Mrs Charles Trotter	1905; 1906; 1909
TR MES AD1/1668	Structure: Glasshouse; Glasshouse Location: Nowell House, Southwell, Nottinghamshire Client: Rev. Canon Henry J. Tebbutt	1905; 1908
TR MES AD1/1669	Structure: Peach house Location: Stanton Court, Weybridge, Surrey Client: T.P. Templeman	1903
TR MES AD1/1670	Structure: Fruit houses and palm house Location: Biggins, Kirkby Lonsdale, Cumbria Client: Dr Paget Tomlinson	1892
TR MES AD1/1699 [1 of 2 packets]	Structure: Forcing house Location: Tolroy, Hayle, Cornwall Client: H.H. Trevithick	1886
TR MES AD1/1699 [2 of 2 packets]	Structure: Verandah Location: Tolroy, Hayle, Cornwall Client: H.H. Trevithick	1891
TR MES AD1/1700	Structure: Conservatory Location: Penarth, Cardiff, Wales Client: E. Thomas	1887
TR MES AD1/1701 [1 and 4 of 4 packets]	Structure: Cases Location: 112 and 113 Fore Street, London Client: W.S. Thomson and Co.	1898
TR MES AD1/1701 [3 of 4 packets]	Structure: Heating apparatus Location: 112 and 113 Fore Street, London Client: W.S. Thomson and Co.	1896
TR MES AD1/1701 [2 of 4 packets]	Structure: Steam Heating apparatus Location: New factory at Homerton, London Client: W.S. Thomson and Co.	1895
TR MES AD1/1702	Structure: Stove and intermediate house Location: Rostulla, Whiteabbey, Belfast, Northern Ireland Client: John Torrens	1893
TR MES AD1/1703	Structure: Stove and intermediate house Location: Edenmore, Whiteabbey, Belfast, Northern Ireland Client: Mrs Torrens	1891
TR MES AD1/1704	Structure: Greenhouse Location: Dowdeswell, Gloucestershire Client: Henry Tovey [Ironmonger]	1899
TR MES AD1/1705 [1 of 2 packets]	Structure: Plant house Location: Grayrigg, Parkstone, Dorset Client: J.H. Taylor	1900
TR MES AD1/1705 [2 of 2 packets]	Structure: Plant house, stove and pit Location: Grayrigg, Parkstone, Dorset Client: J.H. Taylor	1898

TR MES AD1/1706 [1 of 2 packets]	Structure: Conservatory Location: Cefn Mably, South Wales Client: H.M. Kenneys-Tynte	1895
TR MES AD1/1706 [2 of 2 packets]	Structure: Conservatory and cucumber house; Forcing house Location: Cefn Mably, South Wales Client: H.M. Kenneys-Tynte	1891; 1892
TR MES AD1/1707 [1 of 4 packets]	Structure: Peach house and vinery Location: Halswell, Bridgewater, Somerset Client: C.H. Kenneys-Tynte	1903
TR MES AD1/1707 [2 of 4 packets]	Structure: Extension of fruit houses Location: Halswell, Bridgewater, Somerset Client: C.H. Kenneys-Tynte	1901
TR MES AD1/1707 [3 of 4 packets]	Structure: Greenhouse Location: Halswell, Bridgewater, Somerset Client: C.H. Kenneys-Tynte	1901
TR MES AD1/1707 [4 of 4 packets]	Structure: Heating apparatus Location: Halswell Park, Bridgewater, Somerset Client: Lord Wharton	1919
TR MES AD1/1708	Structure: Conservatory and vinery Location: Ashleigh, Monkseaton, Whitley by the Sea, Northumberland Client: George D. Thompson	1895
TR MES AD1/1709	Structure: Stove, Vinery, Plant house and Potting house Location: Belvedere, Seymour Road, Mannamead, Plymouth, Hampshire Client: H. Tucker	1896
TR MES AD1/1710	Structure: Greenhouse Location: 20 Gaolgate Street, Stafford, Staffordshire Client: Thomas Till	1893
TR MES AD1/1711	Structure: Peach and plant house Location: Heatherton, Pembury, Tunbridge Wells, Kent Client: J. Thompson and Co. [Builders]	1903
TR MES AD1/1713	Structure: Conservatory Location: Polkeris, Wood Lane, Falmouth, Cornwall Client: T. Trelease	1903
TR MES AD1/1714	Structure: Plant house and pit Location: Hillcote, Manor Road, Salisbury, Wiltshire Client: A. Tucker	1891
TR MES AD1/1715	Structure: Greenhouse Location: Bridge House, Hartshill, Atherstone, Warwickshire Client: W. Taylor	1893
TR MES AD1/1717	Structure: Greenhouse Location: Fernhill Park, Fernhill Heath, Worcestershire Client: J.C. Turner	1901
TR MES AD1/1718	Structure: Heating apparatus Location: Ringdale, Faringdon, Berkshire Client: J. Thorley	1894
TR MES AD1/1719	Structure: Cucumber and melon house Location: Rendcomb Park, Cirencester, Gloucestershire Client: James Taylor	1893
TR MES AD1/1720	Structure: Greenhouse Location: Holly House, Hetton-le-Hole, Fence Houses, Sunderland, Northumberland Client: John Todd	1890

TR MES AD1/1721	Structure: Plant house Location: Rosendale, The Brampton, Newcastle, Staffordshire Client: T. Taylor	1898
TR MES AD1/1722	Structure: Conservatory Location: Greenhill Park, New Barnet, Hertfordshire Client: Mrs Twentyman	1893
TR MES AD1/1723	Structure: Heating apparatus for house and chapel Location: Tichborne Hall, Alresford, Hampshire Client: Sir Henry Tichborne	1888
TR MES AD1/1724	Structure: Greenhouse Location: Oaklands, Alnwick, Northumberland Client: John Tate	1890
TR MES AD1/1725	Structure: Vinery Location: Old Hall, Morecambe, Lancashire Client: W. Telley	1890
TR MES AD1/1726	Structure: Conservatory Location: Duddeston, Bournemouth, Dorset Client: Miss Twells	1899
TR MES AD1/1728	Structure: Conservatory Location: Torrington House, Burton-on-Trent, Staffordshire Client: J.N. Tresise	1890
TR MES AD1/1730	Structure: Vineries; Plant house Location: Maidenhatch, Pangbourne, Berkshire Client: Capt. Thornton	1899; 1911
TR MES AD1/1733	Structure: Plant house, forcing houses, shed, conservatory; Plant house Location: Beech Hurst, Haywards Heath, West Sussex Client: S. Tyzack	1901; 1904
TR MES AD1/1734	Structure: Cucumber house Location: Eweny Prioory, Bridgend, Glamorganshire, Wales Client: Col. J. Picton Turberville	1897
TR MES AD1/1735	Structure: Conservatory Location: Crookleigh, Furness Road, Morecambe, Lancashire Client: Frederick W. Tattersall	1900
TR MES AD1/1737 See also TR MES AD1/1738/2	Structure: Carnation and forcing house Location: Penrice Castle, Reynoldstone RSO, Glamorganshire, Wales Client: Miss Talbot	1898
TR MES AD1/1738 [1 of 3 packets]	Structure: Boilers; Sky lights to squash court Location: Margam Castle, Port Talbot, South Wales Client: Capt. A.M. Talbot Fletcher	1925; 1927
TR MES AD1/1738 [2 of 3 packets] See also TR MES AD1/1737	Structure: Vinery and peach house Location: Penrice Castle, near Swansea, Glamorganshire, Wales Client: Miss Talbot	1891
TR MES AD1/1738 [2 and 3 of 3 packets]	Structure: Greenhouse; Stoves, plant house, propagating house Location: Margam Park, Port Talbot, South Wales Client: Miss Talbot	1890; 1891
TR MES AD1/1739	Structure: Heating apparatus Location: Cam, near Dursley, Gloucestershire Client: A. Ashbee per Turner and Pritchard [Plumbers]	1900

TR MES AD1/1740	Structure: Vinery Location: The Nash, Kempsey, Worcestershire Client: Sir Richard Temple, Bart.	1896
TR MES AD1/1741	Structure: Peach house, vinery and greenhouses Location: Stubbings House, Maidenhead, Berkshire Client: W.H. Tyser	1901
TR MES AD1/1742	Structure: Conservatory Location: Lillington Lodge, 56 Kenilworth Road, Leamington Spa, Warwickshire Client: F. Thorne	1897
TR MES AD1/1743	Structure: Wall cover Location: Rothwell Grange, Kettering, Northamptonshire Client: J. Borlase Tibbits	1894
TR MES AD1/1744	Structure: Conservatory Location: The Hatch, Sunninghill, Berkshire Client: Col. Giles per Robert Emerie Tyler [Architect]	1888
TR MES AD1/1744	Structure: Heating apparatus Location: Riverholme, Hampton Court, London Client: H.O. O'Hagan per Robert Emerie Tyler [Architect]	1890
TR MES AD1/1744	Structure: Heating apparatus Location: Grand Panorama des Chutes du Niagara, Avenue du Bois de Boulogne, Paris, France Client: Robert Emerie Tyler [Architect]	1889
TR MES AD1/1744	Structure: Heating apparatus Location: London Panorama, Westminster, London Client: Robert Emerie Tyler [Architect]	1890
TR MES AD1/1745	Structure: Glasshouse Location: Horton Lodge, Rudyard, Staffordshire Client: S.C. Thompson	1891
TR MES AD1/1746	Structure: Plant house Location: Helmside, Grasmere, Cumbria Client: J. Taylior	1898
TR MES AD1/1747	Structure: Vinery Location: The Manor House, Knowle, Warwickshire Client: Edward Tangye	1901
TR MES AD1/1748	Structure: Cucumber and melon house Location: Lynwood, Sunningdale, Berkshire Client: G. Rodie Thompson	1892
TR MES AD1/1749	Structure: Forcing house Location: The Laurels, Iver, near Uxbridge, Middlesex Client: T.A. Tidy	1892
TR MES AD1/1750	Structure: Glasshouses Location: Begbroke House, Begbroke, Oxfordshire Client: Charles Robinson per F. Taylor and Sons	1907
TR MES AD1/1751	Structure: Conservatory Location: Lucknow Drive, Nottingham, Nottinghamshire Client: J.W. Turner	1888
TR MES AD1/1753	Structure: Roof to smoke bar Location: 647 Beastmarket Hill, Nottingham, Nottinghamshire Client: Frederick C. Martin per Messrs Truman	1898
TR MES AD1/1754	Structure: Conservatory Location: Hasely Manor, Warwick, Warwickshire Client: Alfred Hewlett	1907

TR MES AD1/1755	Structure: Greenhouse Location: Boughton Park, Kettering, Northamptonshire Client: Duke of Buccleugh, KG	1914
TR MES AD1/1755	Structure: Heating and hot water supply to stables; Frames; Blinds Location: Cawston House, Dunchurch, Warwickshire Client: Right Hon. Duke of Buccleuch; Lord Glenapp; Lord Inchcape	1908; 1930; 1935
TR MES AD1/1756	Structure: Boiler Location: Astor House, Aldwych, London Client: British and Continental Traders Ltd per John Hart	1928
TR MES AD1/1756	Structure: Glasshouse; Painting and boilers Location: Lockinvar, Little Heath, Potters Bar, Middlesex Client: John Hart	1906; 1907
TR MES AD1/1757	Structure: Tomato house Location: The Burgage, Southwell, Nottinghamshire Client: Revd. Canon W. Glaister	1908
TR MES AD1/1758	Structure: Boiler and heating apparatus Location: Huntsland, Crawley Down, Sussex Client: E. Cayford	1907
TR MES AD1/1759	Structure: Carnation house Location: The Grange, Farnborough, Banbury, Oxfordshire Client: Ronald A. Holbech	1907
TR MES AD1/1760	Structure: Plant house Location: The Nook, Croxley Green RSO, Hertfordshire Client: C. Biegel	1907
TR MES AD1/1761	Structure: Heating apparatus Location: Romford, Essex Client: Messrs Field Mallett and Co. [Engineers]	1902
TR MES AD1/1762	Structure: Heating to factory Location: Wood Street, Ilkeston, Derbyshire Client: Samuel Fletcher and Son	1907; 1912
TR MES AD1/1763	Structure: Greenhouse Location: Whitaker Road, Derby, Derbyshire Client: P.W. Lucas	1906
TR MES AD1/1764	Structure: Greenhouse Location: Birchville, Whitehall Road, Rugby, Warwickshire Client: B. Haynes	1908
TR MES AD1/1766	Structure: Glasshouse; Stove house; Boiler Location: Portland House, Blyth Bridge, Stoke-on-Trent, Staffordshire Client: H. Aynsley	1907; 1921
TR MES AD1/1767	Structure: Glasshouses Location: St. Clere, Kemsing, Kent Client: Sir Mark Collett, Bart.	1907
TR MES AD1/1768 [1 and 2 of 2 packets]	Structure: Re-erecting glasshouse from Brookfield House at Chase Cliff; Rebuilding vinery Location: Chase Cliff, Whatstandwell, near Matlock, Derbyshire Client: Maurice Deacon [Tenant]; F.C.A. Hurt [Owner]	1909; 1921
TR MES AD1/1768 [2 of 2 packets]	Structure: Plant house Location: Whittington House, near Chesterfield, Derbyshire Client: Maurice Deacon	1907

TR MES AD1/1770	Structure: Glasshouses Location: Shirenewton Hall, Chepstow, Monmouthshire, Wales Client: C. Oswald Liddell	1906
TR MES AD1/1771	Structure: Peach house; Conservatory Location: Throstle Nest, Chellow Dene, Allerton, Bradford, Yorkshire Client: James Hill	1907; 1910
TR MES AD1/1773	Structure: Conservatory roof Location: Moore Place, Esher, Surrey Client: C.A. Moreing per Messrs Maple and Co.	1907
TR MES AD1/1775	Structure: Glasshouse Location: The Firs, Chingford, Essex Client: J. Wilcox	1906
TR MES AD1/1776	Structure: Heating apparatus; Boiler repairs Location: 48a Gillingham Street, Eccleston Square, London Client: The Krieger Electric Carriage Syndicate Ltd [later Royal Garage]	1907; 1921
TR MES AD1/1777	Structure: Painting and repairs Location: The Hoo, Sydenham Hill, London Client: Mrs R. Thornton	1906
TR MES AD1/1778	Structure: Vinery and plant house Location: Salisbury House, Cloumel, Tipperary, Ireland Client: J.W. Cleere	1906
TR MES AD1/1779	Structure: Plant house Location: Poyston, Pembroke, Wales Client: Henry Owen, DCL	1908
TR MES AD1/1780	Structure: Glasshouse Location: Phyllis Court, Rosecroft Avenue, Hampstead, London Client: H. Parker Lowe	1906
TR MES AD1/1781	Structure: Plant house and stove Location: Kneesworth Hall, Royston, Hertfordshire Client: Lady Mary Holland	1906
TR MES AD1/1782	Structure: Glasshouse; Boiler Location: Dalby Hall, Spilsby, Lincolnshire Client: B.C. Garfit; Frank Dawson	1906; 1949
TR MES AD1/1783	Structure: Peach house Location: Beacon Hill House, Hucknall Torkard, Nottinghamshire Client: Mrs Needham Ball	1906
TR MES AD1/1784	Structure: Heating apparatus Location: Biddeston House, Ludgershall, Wiltshire Client: Sir John Denison-Pender, KCMG	1908
TR MES AD1/1785	Structure: Glasshouse Location: Thorne, Doncaster, Yorkshire Client: C.W. Darley	1907
TR MES AD1/1786	Structure: Plant house Location: Coed Derw, Bettws-y-Coed, North Wales Client: E. Charles Buxton	1907
TR MES AD1/1787	Structure: Renewing lobby, vinery and peach house; Carnation house and pits Location: Witham Hall, Bourne, Lincolnshire Client: Walter Fenwick	1907; 1910

TR MES AD1/1788 [5 packets]	Structure: Heating apparatus; Alterations and additions to factory heating apparatus Location: Norfolk Street, Boston, Lincolnshire Client: Fisher Clark and Co. [Printers]	1907; 1916 to 1948
TR MES AD1/1789	Structure: Glasshouse Location: Curridge House, Hermitage, near Newbury, Berkshire Client: J. Spencer Evans	1907
TR MES AD1/1791 [1 of 2 packets]	Structure: Forcing, rose, plant and carnation houses Location: Hilfield Park, Aldenham, Hertfordshire Client: E. Guy Ridpath [Tenant] per Lord Aldenham [Landlord]	1912
TR MES AD1/1791 [2 of 2 packets]	Structure: Greenhouse Location: Hilfield Park, Aldenham, Hertfordshire Client: Sir Henry Bargrave Deane [Tenant] per Right Hon. Lord Aldenham [Landlord]	1907
TR MES AD1/1793	Structure: Peach wall cover Location: Gredington, Whitchurch, Shropshire Client: Lord Kenyon	1906
TR MES AD1/1794	Structure: Conservatory Location: 153 Banbury Road, Oxford, Oxfordshire Client: Rev. E.J. Smith	1907
TR MES AD1/1795	Structure: Greenhouse Location: Sidney Sussex College, Cambridge, Cambridgeshire Client: C. Smith	1907
TR MES AD1/1796	Structure: Conservatory Location: Milestone House, Staplehurst, Kent Client: Mr White per J.W. Wickings [Builder]	1907
TR MES AD1/1797	Structure: Pit frames; Heating apparatus Location: East Court, East Grinstead, West Sussex Client: E. Cooper	1907; 1910
TR MES AD1/1798	Structure: Plant house, peach house and pits Location: Bramston House, Oundle, Northamptonshire Client: C.A. Newman	1907
TR MES AD1/1801	Structure: Chrysanthemum house Location: Nower Hill, Pinner, Middlesex Client: Ambrose Heal	1906
TR MES AD1/1802	Structure: Glasshouses Location: Wyphurst, Cranleigh, Surrey Client: G.E. Chadwyck-Healey	1907
TR MES AD1/1803 [1 of 2 packets]	Structure: Peach house Location: Eartham House, Chichester, West Sussex Client: Sir W.B.M. Bird, Bart	1910
TR MES AD1/1803 [2 of 2 packets]	Structure: Glasshouses; Boiler; Boilers Location: Eartham House, Chichester, West Sussex Client: Sir W.B.M. Bird, Bart	1906; 1922; 1931
TR MES AD1/1804	Structure: Peach house, vinery and other glasshouses; Boiler Location: Lewins Court, Crockham Hill, Edenbridge, Kent Client: George Ing; S.D. Gladstone	1905; 1938
TR MES AD1/1805	Structure: Heating apparatus and ventilating equipment Location: Gogerddan, Bow Street RSO, Cardiganshire, Wales Client: Sir Edward Pryse	1906

TR MES AD1/1808	Structure: Peach house, plant house, fernery Location: Norway Lodge, Prenton Hill, Birkenhead, Merseyside Client: A.H. Bunney	1907
TR MES AD1/1809	Structure: Heating apparatus Location: North Lands, Streatley, Berkshire Client: R. Rees per J. Smallbone [Builder]	1906; 1908
TR MES AD1/1810	Structure: Greenhouse; Boiler Location: Chamber House, Marland near Rochdale, Lancashire Client: Charles F. Robinson	1907; 1908
TR MES AD1/1811	Structure: Glasshouses Location: New York Lodge, Bourne End, Buckinghamshire Client: [G.A. Kessler] per T.W. Heath and Son [Builders]	1907
TR MES AD1/1812	Structure: Forcing, stove, intermediate, melon, plant and cucumber houses Location: Hinwick Hall, Wellingborough, Northamptonshire Client: Gilbert Robinson	1907
TR MES AD1/1813	Structure: Heating apparatus Location: 9 Spencer Park, Wansworth Common, London Client: Thomas Hodgkinson	1907
TR MES AD1/1814	Structure: Glasshouse Location: Sylvan Lodge, Brighton, East Sussex Client: H.J. Infield, J.P.	1907
TR MES AD1/1815	Structure: Conservatory Location: Ashfield, Golcar, Huddersfield, Yorkshire Client: Edward Whitwand	1906
TR MES AD1/1816	Structure: Plant house Location: White Lodge, Cheveley, Newmarket, Suffolk Client: S.W. Graystone	1907
TR MES AD1/1819 [1 of 2 packets]	Structure: Heating and hot water apparatus for residence Location: Nantyderry House, Abergavenny, Wales Client: Miss Evans	1907
TR MES AD1/1819 [2 of 2 packets]	Structure: Conservatory Location: Nantyderry House, Abergavenny, Wales Client: Miss Evans per Edgar G.C. Down [Architect]	1899
TR MES AD1/1820	Structure: Melon and plant house Location: Dolben, St Asaph RSO, Denbighshire, Wales Client: Major R. Williams Wym	1907
TR MES AD1/1822	Structure: Conservatory; Greenhouse Location: Southland, Kingsway, Cleethorpes, Lincolnshire Client: Sir Thomas Robinson, KBE	1907; 1922
TR MES AD1/1823	Structure: Melon house and pit Location: Abbots Oak, Whitwick, Leicestershire Client: Lady Joyce	1906
TR MES AD1/1824	Structure: Greenhouse Location: Ballamoar, Isle Of Man Client: Mr Curphey per Harry Crickmay [Architect]	1906
TR MES AD1/1825	Structure: Plant house and stove Location: Boveridge Park, Cranborne, Salisbury, Wiltshire Client: G.F. Thursby	1907

TR MES AD1/1826	Structure: Peach house; Vinery, plant house and pits Location: Elmstone Court, Preston, Dover, Kent Client: C.W. Firebrace	1907; 1908
TR MES AD1/1827	Structure: Vinery Location: The Court, Ackworth, Pontefract, West Yorkshire Client: George D. Cullingworth	1906
TR MES AD1/1828	Structure: Heating apparatus Location: Englesea House, Crewe, Cheshire Client: W. McCracken	1907
TR MES AD1/1829	Structure: Greenhouse, plant house, stove and vineries Location: Braxted Park, Witham, Essex Client: W.B. Gladstone	1906
TR MES AD1/1831	Structure: Plant house Location: Colwyn, Redington Road, West Hampstead, London Client: George Traill	1907
TR MES AD1/1832	Structure: Heating apparatus Location: Cotswold Park, near Cirencester, Gloucestershire Client: Rev. J. Priestley Foster	1906
TR MES AD1/1833	Structure: Carnation house and other glasshouses Location: Bourton Hall, near Rugby, Warwickshire Client: F. Shaw	1907
TR MES AD1/1834	Structure: Plant house Location: Eccleshill, Hayes Lane, Bromley, Kent Client: C. Douglas Clark	1906
TR MES AD1/1835	Structure: Plant house and stove Location: The Glen, Newry, Co. Down, Ireland Client: D.M. Barcroft	1907
TR MES AD1/1836 [1 and 2 of 3 packets]	Structure: Orchid houses Location: Morley Manor, Morley, Derbyshire Client: Mrs Sacheverell Bateman	1906
TR MES AD1/1836 [3 of 3 packets]	Structure: Ventilating equipment and repairs; Boiler repairs Location: Morley Manor, Morley, Derbyshire Client: Mrs Lister Kaye	1913; 1925
TR MES AD1/1838	Structure: Greenhouse Location: The Hollies, Market Weighton, East Yorkshire Client: F. Proudlock	1907
TR MES AD1/1839	Structure: Conservatory Location: Hoddenfield, Bargate, Grimsby, Lincolnshire Client: Samuel Ellis	1906
TR MES AD1/1840 [1 of 2 packets]	Structure: Greenhouses Location: Manor House, Bishopstoke, Hampshire Client: R.W. Bourne	1906
TR MES AD1/1840 [2 of 2 packets]	Structure: Greenhouses [Mainly referring to court case] Location: Manor House, Bishopstoke, Hampshire Client: R.W. Bourne	1906
TR MES AD1/1841	Structure: Greenhouse Location: Derrys Wood, Wonersh, near Guildford, Surrey Client: Jill Courage	1907
TR MES AD1/1842 [1, 2 and 3 of 4 packets]	Structure: Forcing house, potting shed, conservatory and other glasshouses Location: Cransley Hall, Kettering, Northamptonshire Client: Capt. A.H. Thurburn	1905

TR MES AD1/1842 [4 of 4 packets]	Structure: Boiler Location: Cransley Hall, Kettering, Northamptonshire Client: Capt. A.H. Thurnburn	1924
TR MES AD1/1843	Structure: Conservatory, vineries, plant house and others Location: Weston Lodge, Weston-under-Penyard, Ross, Herefordshire Client: John Gabbitas	1907
TR MES AD1/1844	Structure: Greenhouse Location: Crockham Hill, Edenbridge, Kent Client: Dr. H. Philpot	1907
TR MES AD1/1846	Structure: Conservatory Location: 48 Musters Road, West Bridgford, Nottinghamshire Client: H. Gamble	1906
TR MES AD1/1847	Structure: Vinery, mushroom house, plant house and stove house Location: Grayshott Hall, Liphook, Hampshire Client: A. Ingham Whitaker	1891
TR MES AD1/1849 [1 of 2 packets]	Structure: Stove and plant house Location: Fairhill, Coventry, Warwickshire Client: John Powers	1901
TR MES AD1/1849 [2 of 2 packets]	Structure: Glasshouses Location: Mill House, Coventry, Warwickshire Client: John Powers	1892
TR MES AD1/1851	Structure: Conservatory and ventilating apparatus Location: Kinvara, Portarlinton Road, Bournemouth, Dorset Client: Mr Thompson per Frederick Hoare and Sons [Builders]	1902
TR MES AD1/1852 [1 of 7 packets]	Structure: Plant house Location: Kensington Gardens, London Client: H.M. Office of Works per W. Browne [Park Superintendent]	1893
TR MES AD1/1852 [2 of 7 packets]	Structure: Verandah for Refreshment Pavilion and Roof to Urinals Location: Kensington Gardens, London Client: H.M. Office of Works per W. Browne [Park Superintendent]	1896
TR MES AD1/1852 [3 of 7 packets]	Structure: Palm House; Roof to lavatory Location: Kensington Gardens, London Client: H.M. Office of Works per W. Browne [Park Superintendent]	1896; 1899
TR MES AD1/1852 [4 of 7 packets]	Structure: Roof over Lavatory Location: St James' Park, London Client: H.M. Office of Works per W. Browne [Park Superintendent]	1897
TR MES AD1/1852 [5 of 7 packets]	Structure: Roof over lavatory Location: Regents Park, London Client: H.M. Office of Works per E. Jordan [Park Superintendent]	1898
TR MES AD1/1852 [6 of 7 packets]	Structure: Greenhouses Location: Framing Ground, Hyde Park, London Client: H.M. Office of Works	1908

TR MES AD1/1852 [7 of 7 packets]	Structure: Twin houses and corridor Location: Framing Ground, Hyde Park, London Client: H.M. Office of Works per C. Jordan [Park Superindendant]	1905
TR MES AD1/1853	Structure: Conservatory Location: Naranhilty, Nepal, India Client: Commanding General Futtch Shum Shere Jung Rana Bahadur	1900
TR MES AD1/1854	Structure: Roof to court yard Location: Ex Railway buildings, Kast-EL-Nil Street, Cairo, Egypt Client: W. Hamilton [Engineer]	1901
TR MES AD1/1855	Structure: Heating apparatus Location: Caxton Buildings, Ripley, Derbyshire Client: G.C. Brittain	1905
TR MES AD1/1858	Structure: Stove house; Heating apparatus Location: Hurstbourne Park, near Whitchurch, Hampshire Client: Earl of Portsmouth	1901; 1907
TR MES AD1/1859 [1 of 5 packets]	Structure: Orchid house and conservatory Location: Littleover Hall, near Derby, Derbyshire Client: Edward McInnes	1901
TR MES AD1/1859 [2 of 5 packets]	Structure: Painting and propagating house Location: Littleover Hall, near Derby, Derbyshire Client: Edward McInnes	1905
TR MES AD1/1859 [3 of 5 packets]	Structure: Plant house and stove Location: Littleover Hall, near Derby, Derbyshire Client: Edward McInnes	1891
TR MES AD1/1859 [4 of 5 packets]	Structure: Boiler; Painting Location: Littleover Hall, near Derby, Derbyshire Client: Edward McInnes	1898; 1906
TR MES AD1/1859 [5 of 5 packets]	Structure: Peach house Location: Littleover Hall, near Derby, Derbyshire Client: Edward McInnes	1899
TR MES AD1/1860 [2 packets]	Structure: Moving and refixing plant house and pit Location: Shipley Hall, Shipley, Derbyshire Client: E. Miller Mundy	1902
TR MES AD1/1862 [1, 2, 4 and 5 of 5 packets]	Structure: Vineries, Peach, forcing, cucumber and plant houses, conservatory and stove Location: Overbury Court, near Tewkesbury, Gloucestershire Client: Richard B. Martin, MP	1899
TR MES AD1/1862 [3 of 5 packets]	Structure: Plant houses Location: Overbury Court, near Tewkesbury, Gloucestershire Client: Richard B. Martin, MP	1904
TR MES AD1/1863 [2 packets]	Structure: Orchid, carnation, plant, intermediate and stove houses Location: Kings Weston, Shirehampton near Bristol, Gloucestershire Client: P. Napier Miles	1903
TR MES AD1/1864	Structure: Vinery Location: Great Chesterford Mills, Saffron Walden, Essex Client: Henry King	1901

TR MES AD1/1865 [5 packets]	Structure: Conservatory Location: Atherstone House, Atkins Road, Clapham Park, London Client: Edwin Jones per J. Wallis Chapman	1899
TR MES AD1/1866	Structure: Greenhouse; Orchid houses Location: Beaulieu, Arthur Road, Wimbledon Park, London Client: F. Kirchner; Peter keary	1892; 1897
TR MES AD1/1867	Structure: Frame Location: Abbots Hill, Hemel Hempstead, Hertfordshire Client: H.E. Hooper per W. Baldwin	1901
TR MES AD1/1868 [1, 2 of 4 packets] See also TR MES AD1/1337	Structure: Heating apparatus to residence Location: Guilsborough Hall, Northampton, Northamptonshire Client: Mrs Irene Osgood	1912
TR MES AD1/1868 [3 of 4 packets]	Structure: Stokery Location: Guilsborough Hall, Northampton, Northamptonshire Client: Mrs Harborough Sherrard	1909
TR MES AD1/1868 [4 of 4 packets]	Structure: Vinery Location: Guilsborough Hall, Northampton, Northamptonshire Client: Mrs Harborough Sherrard	1909
TR MES AD1/1870	Structure: Boiler Location: Wigganthorpe, York, Yorkshire Client: Lord Holden of Alston	1921
TR MES AD1/1872	Structure: Forcing house Location: Highfield Manor, Stafford, Staffordshire Client: David Hollins	1900
TR MES AD1/1873 [1 of 5 packets]	Structure: Pit frame Location: Selwood, Rotherham, Yorkshire Client: G.D. Owen per Mark Watts	1894
TR MES AD1/1873 [2, 4, 5 of 5 packets]	Structure: Cattleya, orchid, plant, peach and forcing houses and corridor Location: Selwood, Rotherham, Yorkshire Client: G.D. Owen per Mark Watts	1891-1893
TR MES AD1/1873 [3 of 5 packets]	Structure: Vinery and heating alterations Location: Selwood, Rotherham, Yorkshire Client: G.D. Owen per Mark Watts	1892
TR MES AD1/1875 [1 of 4 packets]	Structure: Vineries; Peach house; Rebuilding conservatory Location: The Grange, Walton on Thames, Surrey Client: Dr George W. Drabble	1909; 1914; 1919
TR MES AD1/1875 [2 of 4 packets]	Structure: Roof to stable yard Location: The Grange, Walton on Thames, Surrey Client: F.H. Cook	1897
TR MES AD1/1875 [3 of 4 packets] Originally numbered 697	Structure: Glasshouses Location: The Grange, Walton on Thames, Surrey Client: F.H. Cook	1899
TR MES AD1/1875 [4 of 4 packets]	Structure: Boiler Location: The Grange, Walton on Thames, Surrey Client: Dr George W. Drabble	1923

TR MES AD1/1875 [5 of 5 packets] Originally numbered 697	Structure: Vinery; Plant house Location: The Grange, Walton on Thames, Surrey Client: F.H. Cook	1895; 1900
TR MES AD1/1876 [1 of 2 packets]	Structure: Boiler; Rebuilding plant house Location: Ham House, Richmond, Surrey Client: Right Hon. Earl of Dysart	1910, 1915, 1927 and 1929; 1928
TR MES AD1/1876 [2 of 2 packets]	Structure: Heating apparatus; Forcing houses; Boiler Location: Buckminster Park, Grantham, Lincolnshire Client: Right Hon. Earl of Dysart	1909; 1911; 1930 and 1931
TR MES AD1/1877	Structure: Glasshouse; Plant house Location: Salam Bungalow, Meliden, near Rhyl, North Wales Client: Alfred Dickenson [Engineer]	1908; 1909
TR MES AD1/1878	Structure: Heating to shop Location: 65 High Street, Swadlincote, Burton on Trent, Derbyshire Client: H.B. Dinnis [Jeweller]	1908
TR MES AD1/1879	Structure: Conservatory Location: 5 Laves Gardens, Acton, London Client: William Daley and Co [Builders]	1908
TR MES AD1/1880	Structure: Heating repairs Location: Treborth, Bangor, North Wales Client: H.R. Davies	1913
TR MES AD1/1880	Structure: Heating apparatus Location: Bodlondeb, Bangor, North Wales Client: H.R. Davies	1906
TR MES AD1/1882	Structure: Orchid house Location: 16 Norfolk Road, Harrogate, North Yorkshire Client: Richard Ward	1907
TR MES AD1/1883	Structure: Heating apparatus Location: Thurstonville, Greenodd, Ulverston, Cumbria Client: Mrs Woodburn	1908
TR MES AD1/1884	Structure: Boiler Location: Holly Lodge, Papaite, via Wanganni, New Zealand Client: per Messrs Watson Bros	1908
TR MES AD1/1885	Structure: Conservatory and forcing house; Greenhouse Location: The Holt, Barnacre, Garstang, Lancashire Client: Charles J. Winder	1908; 1919
TR MES AD1/1886	Structure: Conservatory; Carnation house Location: Wycombe Court, High Wycombe, Buckinghamshire Client: H.H. Worthington	1908; 1912
TR MES AD1/1887	Structure: Glasshouse Location: Titley Vicarage, Leominster, Herefordshire Client: Rev. W. Oswald Wait	1908
TR MES AD1/1888	Structure: Glasshouses and pits Location: The Phillipines, Brasted Chart, Kent Client: William Willis	1906
TR MES AD1/1889	Structure: Greenhouse Location: Coombe Hill, Butlers Cross, Tring, Buckinghamshire Client: Sir John Lawson Walton, KC, MP	1908

TR MES AD1/1890	Structure: Verandah and glasshouse Location: Lorne House, Uppingham, Rutlandshire Client: Rev. F.W. Welldon	1908
TR MES AD1/1891	Structure: Porch Location: Totnes, Duffield Road, Derby, Derbyshire Client: Miss Locke	1908
TR MES AD1/1892	Structure: Glasshouse Location: St Luke's Hospital, Old Street, London Client: W.H. Baird [Secretary]	1909
TR MES AD1/1893	Structure: Greenhouse Location: White's Farm, Goudhurst, Kent Client: W. Louis Lucas [Architect]	1907
TR MES AD1/1893	Structure: Vinery and forcing house Location: Oak Ash, Chaddleworth, Buckinghamshire Client: W. Louis Lucas [Architect]	1907
TR MES AD1/1895	Structure: Conservatory Location: Marshalls, Ware, Hertfordshire Client: R. McLeake	1908
TR MES AD1/1896	Structure: Plant and peach house; Rebuilding houses Location: Dunham Massey Hall, Altrincham, Cheshire Client: Right Hon. Earl of Stamford	1909; 1926
TR MES AD1/1898 [1 of 2 packets]	Structure: Boiler Location: Loddington Hall, Kettering, Northamptonshire Client: Stephen Schilizzi	1943
TR MES AD1/1898 [2 of 2 packets]	Structure: Glasshouse Location: Loddington Hall, Kettering, Northamptonshire Client: A.R. Steele	1907
TR MES AD1/1899	Structure: Greenhouse and Stages Location: The Hall, Brampton Bryan RSO, Herefordshire Client: Joseph Shaw	1908
TR MES AD1/1901	Structure: Stove, Cucumber and plant house; Boiler Location: Shuckborough Park, Daventry, Northamptonshire Client: Sir Gerald F.S. Shuckborough, Bart	1908; 1930
TR MES AD1/1902	Structure: Carnation house Location: Ranston, Blandford, Dorset Client: Sir Randolph Baker	1908
TR MES AD1/1903	Structure: Heating apparatus Location: Holly Dene, Bromley, Kent Client: Henry Kent [Builder]	1908
TR MES AD1/1904	Structure: Greenhouse; Repairs to greenhouse; Boiler Location: Chawton House, Alton, Hampshire Client: Montague G. Knight; Lt. Col. L.C.E Knight	1908; 1910; 1927
TR MES AD1/1905	Structure: Plant house and stove; Painting Location: Eagle House, Wimbledon, London Client: Mr Jackson	1907; 1913
TR MES AD1/1906	Structure: Heating apparatus Location: Ditton House, near Maidenhead, Berkshire Client: E. Garcke	1907
TR MES AD1/1908	Structure: Greenhouse Location: Branscombe, Stretton, Burton-on-Trent, Staffordshire Client: Mrs G. Greensmith	1907
TR MES AD1/1909	Structure: Conservatory Location: Highfield Park, Headington, Oxfordshire Client: Mr Moss per George Gardiner [Architect]	1908

TR MES AD1/1910	Structure: Plant house and stove Location: Sibdon Castle, Craven Arms, Shropshire Client: Mrs A. Champion	1909
TR MES AD1/1911	Structure: Conservatory and plant house Location: Warwicks Bench, Guildford, Surrey Client: Bernard Crooke	1908
TR MES AD1/1913	Structure: Greenhouse; Peach house Location: The Manor House, Notgrove, Gloucestershire Client: Cyril Cunard	1908; 1911
TR MES AD1/1914	Structure: Heating apparatus Location: Caves Oriental Café, Northdown Road, Margate, Kent Client: Ernest E. Moody [Architect]	1907
TR MES AD1/1915	Structure: Greenhouse Location: Stansted Bury, Ware, Hertfordshire Client: Spencer Trower per Ernest Clarke [Builder]	1908
TR MES AD1/1916	Structure: Glasshouse Location: Gwysaney, Mold, North Wales Client: P.T. Davies Cooke	1910
TR MES AD1/1916	Structure: Glasshouse Location: Owston Park, Doncaster, South Yorkshire Client: W.H. Matthews [Tenant] per D.P. Davies Cooke [Landlord]	1908
TR MES AD1/1917	Structure: Conservatory Location: Fons George, Taunton, Somerset Client: E.C. Boulting	1907
TR MES AD1/1918	Structure: Plant house Location: Chelford Parsonage, Chelford, Cheshire Client: Rev. Colin E.B. Bell	1907
TR MES AD1/1920	Structure: New roof to vinery; Greenhouse; Painting Location: The Elms, Twyford, Winchester, Hampshire Client: Vice Admiral J.C. Burnell	1909; 1912; 1920
TR MES AD1/1921	Structure: Greenhouse Location: Sturton-by-Stow, via Lincoln, Lincolnshire Client: Thomas Blakeborough	1908
TR MES AD1/1922	Structure: Heating apparatus Location: Eldeston Lodge, Norfolk Client: Edward Beauchamp	1908
TR MES AD1/1923 [1 of 2 packets]	Structure: Heating apparatus to residence; Greenhouse Location: Mells Park, Frome, Somerset Client: Gilbert F. Bates	1912; 1913
TR MES AD1/1923 [2 of 2 packets]	Structure: Glasshouses Location: Mells Park, Frome, Somerset Client: Gilbert F. Bates	1907
TR MES AD1/1924	Structure: Plant house and forcing house Location: Woodlands, Ewhurst, Surrey Client: C. Friswell	1909
TR MES AD1/1925	Structure: Vineries Location: Derwent Bank, Duffield Road, Derby, Derbyshire Client: William Fletcher	1908
TR MES AD1/1926	Structure: Greenhouses Location: Castle Hill, South Molton, Devon Client: Right Hon. Earl Fortescue	1908 and 1931

TR MES AD1/1927	Structure: Glasshouses Location: Red Lodge, Bassett, Hampshire Client: A.F. Fynn	1908
TR MES AD1/1928 [1 of 5 packets]	Structure: Heating apparatus; Heating to offices; Heating to warehouse Location: Moss Street Mills, Derby, Derbyshire Client: William Wild and Co	1933; 1938; 1939
TR MES AD1/1928 [2 of 5 packets]	Structure: Heating apparatus Location: Woodstock, Burton Road, Derby, Derbyshire Client: William Wild	1940
TR MES AD1/1928 [3 of 5 packets]	Structure: Heating to covered yard; Boiler Location: Moss Street Mills, Derby, Derbyshire Client: William Wild and Co	1935; 1940
TR MES AD1/1928 [4 of 5 packets]	Structure: Heating apparatus Location: Moss Street Mills, Derby, Derbyshire Client: Wild and Fell	1912; 1922
TR MES AD1/1928 [5 of 5 packets]	Structure: Heating apparatus; Heating to tape factory; Heating alterations Location: Moss Street Mills, Derby, Derbyshire Client: J.A. Wild; Wild and Fell	1905; 1908; 1931
TR MES AD1/1929	Structure: Heating apparatus; Boiler Location: Dalton Holme, Beverley, East Yorkshire Client: Lord Hotham	1906; 1948
TR MES AD1/1930 [2 packets]	Structure: Repairs Location: The Prospect, Trowbridge, Wiltshire Client: Francis Hobson	1908
TR MES AD1/1931	Structure: Glasshouse Location: Teddersley, Penkridge, Staffordshire Client: Lord Hatherton	1908
TR MES AD1/1933	Structure: Conservatory; Glasshouse Location: Beechfield, Alderley Edge, Cheshire Client: Frederick W. Holmes	1907; 1909
TR MES AD1/1934	Structure: Greenhouse Location: Limavady, Co. Derry, Ireland Client: Richard Hull [Builder]	1908
TR MES AD1/1935	Structure: Plant house and forcing house Location: Elmhurst, Rugby, Warwickshire Client: Thomas Hunter [Builder]	1908
TR MES AD1/1936	Structure: Greenhouse Location: Nether Winchenden, Aylesbury, Buckinghamshire Client: Mrs Napier Higgins	1907
TR MES AD1/1937 [1 and 2 of 3 packets]	Structure: Conservatory Location: Stamford Park, Stalybridge, Cheshire Client: Samuel Turner [Park Superintendent]	1907
TR MES AD1/1937 [3 of 3 packets]	Structure: Greenhouse Location: Stamford Park, Stalybridge, Cheshire Client: Samuel Turner [Park Superintendent]	1914
TR MES AD1/1938	Structure: Plant house Location: Harlaston Drive, Lenton Sands, Nottinghamshire Client: J.J. Spencer	1907
TR MES AD1/1939	Structure: Tomato house Location: Clifton Terrace, Uttoxeter Road, Blythe Bridge, Staffordshire Client: D.H. Stewart [Architect]	1908

TR MES AD1/1940	Structure: Conservatory Location: Surrenden, Staplehurst, Kent Client: Mrs Nicholson	1908
TR MES AD1/1941	Structure: Heating apparatus Location: Banstead Place, Banstead, Surrey Client: Sir Ralph Neville	1908
TR MES AD1/1942	Structure: Vinery Location: Boughspring House, Chepstow, Monmouthshire, Wales Client: Miss Morgan	1908
TR MES AD1/1943	Structure: Plant house Location: Scriventon, Speldhurst, Tunbridge Wells, Kent Client: J.T. Marsh	1908
TR MES AD1/1944	Structure: Glasshouse Location: Manor House, Hambledon, Henley-on-Thames, Oxfordshire Client: C.A. Scott Murray	1907
TR MES AD1/1945	Structure: Plant house Location: Beechwood, Biddenham Road, Bedford, Bedfordshire Client: W. Mitchell	1908
TR MES AD1/1947 [1 of 2 packets]	Structure: Boiler Location: Bilton Rise [Formerly Plex House], Rugby, Warwickshire Client: F. Merttens	1921
TR MES AD1/1947 [2 of 2 packets]	Structure: Conservatory; Peach house Location: Plex House, Old Bilton, Rugby, Warwickshire Client: J.C. Peache	1907; 1908
TR MES AD1/1948	Structure: Odontoglossum, Cattleya and stove houses Location: Swanston, Whitchurch, Oxfordshire Client: Frank Loughborough Pearson	1906
TR MES AD1/1950	Structure: Glasshouse Location: Manor House, Horsham, Sussex Client: Mrs Padwick	1907
TR MES AD1/1951	Structure: Conservatory Location: East Malling, Kent Client: E. Pye [Buidler]	1908
TR MES AD1/1952 [2 packets]	Structure: Conservatory and propagating houses Location: Alexandra Park, Oldham, Lancashire Client: Oldham Corporation per Borough Surveyor	1906
TR MES AD1/1953	Structure: Plant house and pit Location: Ruddington, Nottinghamshire Client: W.R. Rook	1908
TR MES AD1/1954	Structure: Greenhouse Location: Hepmangrove House, Bury, Huntingdon, Cambridgeshire Client: John Rowell	1908
TR MES AD1/1955	Structure: Greenhouse; Heating apparatus Location: Twyford Lodge, Winchester, Hampshire Client: Alexander P. Ralli	1908; 1909
TR MES AD1/1956 [1 of 3 packets]	Structure: Stoves for winter garden Location: Hawthorndene, Wynberg, Cape Town, South Africa Client: Sir J.B. Robinson	1908

TR MES AD1/1956 [2 and 3 of 3 packets]	Structure: Conservatory and skating rink Location: Hawthorndene, Wynberg, Cape Town, South Africa Client: Sir J.B. Robinson	1907
TR MES AD1/1958	Structure: Plant house, vinery and pit; Painting Location: Preshute House, Marlborough, Wiltshire Client: Rev. P.W. Taylor	1908; 1910
TR MES AD1/1962	Structure: Peach house Location: The Grange, Steeple Aston, Oxfordshire Client: Mrs Bradshaw	1908
TR MES AD1/1966	Structure: Boiler Location: Bosworth Hall Mission, Bosworth Road, North Kensington, London Client: A.W. Peters [Architect]	1927
TR MES AD1/1966	Structure: Heating apparatus Location: Bosworth Road Mission Chapel, Kensington, London Client: S. Wallis Chapman [Architect]	1903
TR MES AD1/1967	Structure: Heating apparatus Location: Board Schools, Beeston, Nottinghamshire Client: John C. Bowley [Architect]	1891
TR MES AD1/1968	Structure: Heating to founder's chapel Location: Boston Church, Boston, Lincolnshire Client: W. Samuel Weatherby [Architect]	1906
TR MES AD1/1969	Structure: Heating apparatus Location: Bracebridge Church, Lincoln, Lincolnshire Client: C. Hodgson Fowler [Architect]	1895
TR MES AD1/1970	Structure: Heating apparatus Location: The Pottery School, Belper, Derbyshire Client: Derbyshire Education Committee	1904
TR MES AD1/1971	Structure: Heating apparatus Location: Bilton Church, Bilton, Rugby, Warwickshire Client: Capt. H. Riall Sankey, RE	1901
TR MES AD1/1972	Structure: Boiler; Boiler; Heating alterations Location: St Aidan's Church, Shobnall Road, Burton-on-Trent, Staffordshire Client: Bass, Ratcliff and Cretton Ltd; Percy Stokes [Secretary]	1906; 1945; 1947
TR MES AD1/1973	Structure: Heating apparatus Location: Holy Trinity Church, Burton-on-Trent, Staffordshire Client: H.E. Mear [Church Warden]	1898
TR MES AD1/1975 [1 of 3 packets]	Structure: Boiler repairs; Boiler Location: Stretton Church, Stretton, Burton-on-Trent, Staffordshire Client: Bass, Ratcliff and Cretton Ltd; Rev. J. Edwards	1921; 1937
TR MES AD1/1975 [2 of 3 packets]	Structure: Hot water apparatus Location: Stretton Church, Stretton, Burton-on-Trent, Staffordshire Client: J.T. Micklethwaite [Architect]	1895
TR MES AD1/1975 [3 of 3 packets]	Structure: Boilers Location: St. Mary's Church, Stretton, Burton-on-Trent, Staffordshire Client: Bass, Ratcliff and Cretton Ltd	1915

TR MES AD1/1984	Structure: Heating apparatus Location: St Mary's Roman Catholic Schools, Boston, Lincolnshire Client: Canon O'Donaghue per S. Sherwin and Son [Builders]	1908
TR MES AD1/1986	Structure: Heating apparatus; Boiler Location: St Johns Church, Ask Road, Battersea, London Client: Hudson Bros [Builders]	1904; 1922
TR MES AD1/1997	Structure: Heating apparatus Location: Copt Oak Church, Leicestershire Client: T. and H. Herbert [Builders]	1889
TR MES AD1/1998	Structure: Heating apparatus Location: Cliftonville Wesleyan Chapel, Margate, Kent Client: C. Hobday [Plumber]	1896
TR MES AD1/1999	Structure: Heating apparatus Location: Burbage Church, Buxton, Derbyshire Client: H.A. Hubbersty	1892
TR MES AD1/2000	Structure: Heating apparatus Location: Brampton Church, Northampton, Northamptonshire Client: Rev. H.C. Calveley	1889

Records of Properties in Bedfordshire

TR MES AD1/141	Structure: Plant house Location: Howard Villa, Cardington, Bedfordshire Client: Mrs Gertrude Mills	1904
TR MES AD1/143	Structure: Greenhouses Location: 10 Rothsay Gardens, Bedford, Bedfordshire Client: R.H. Kinsey	1899
TR MES AD1/301	Structure: Conservatory Location: The Dene, Woburn Sands, Bedfordshire Client: H.B. Mallam per A. Hudson [Plumber]	1896
TR MES AD1/306	Structure: Heating apparatus Location: Mendip Lodge, De Parys Avenue, Bedford, Bedfordshire Client: L.A.W. Auley per W. Hagnes [Builder]	1891
TR MES AD1/311	Structure: Greenhouses Location: St Mary's Abbey, Cardington Road, Bedford, Bedfordshire Client: Hurst Hodgson	1902
TR MES AD1/454	Structure: Glass porch Location: Barholm, Bushmead Avenue, Bedford, Bedfordshire Client: Col. Grierson	1896
TR MES AD1/485	Structure: Greenhouse Location: 55 The Grove, Bedford, Bedfordshire Client: W. Gilpin	1889-1890
TR MES AD1/492	Structure: Plant house and conservatory Location: The Larches, Luton, Bedfordshire Client: J.W. Green	1902-1903
TR MES AD1/513 [3 packets]	Structure: Conservatory; Heating apparatus; Peach house Location: Woodlands, Clapham, Bedford, Bedfordshire Client: William L. Fitzpatrick	1901; 1902; 1903
TR MES AD1/531	Structure: Heating apparatus Location: Higham Bury, Ampthill, Bedfordshire Client: E. Jekyll per Samuel Foster [Contractor]	1899
TR MES AD1/699	Structure: Plant House Location: Cotefield, Leighton Buzzard, Bedfordshire Client: Major A. Cookson	1895
TR MES AD1/824	Structure: Conservatory Location: Westoning Manor, Ampthill, Bedfordshire Client: J.G.C. Campion	1898
TR MES AD1/913 [2 packets]	Structure: Greenhouse [Pot experimental station] Location: Woburn, Bedfordshire Client: Royal Agricultural Society of England	1897
TR MES AD1/954	Structure: Conservatory Location: The Lodge, The Heath, Leighton Buzzard, Bedfordshire Client: F. Bassett	1892
TR MES AD1/974 [5 packets]	Structure: Museum roof; Conservatory; Forcing house; Glass house; Potato Pits; Peach House; Glazed wall cover; Peach house; Apricot house; Glass wall cover Location: Woburn Abbey, Bedfordshire Client: Duke of Bedford, KG	1903; 1906; 1908; 1909; 1910; 1912; 1921; 1925; 1927; 1929
TR MES AD1/1143	Structure: Heating apparatus; Conservatory; Hot water apparatus Location: Ampthill House, Ampthill, Bedfordshire Client: A.H. and Mrs Wingfield	1893-1895 1898; 1908

TR MES AD1/1280	Structure: Plant house Location: Kimbolton Road, Bedford, Bedfordshire Client: Dr Sharpin	1896
TR MES AD1/1343 [2 packets]	Structure: Hot water supply and heating apparatus Location: St Georges, Ampthill, Bedfordshire Client: G.H. Rushbrooke	1895; 1904
TR MES AD1/1434	Structure: Heating apparatus Location: Melchbourne Park, Sharnbrook, Bedfordshire Client: Lord St John	1894
TR MES AD1/1486	Structure: Riding school Location: Mentmore, Leighton Buzzard, Bedfordshire Client: Right Hon. Earl of Roseberg	1887
TR MES AD1/1518	Structure: Conservatory Location: Modern School House, Bedford, Bedfordshire Client: Dr R.B. Poole	1887
TR MES AD1/1945	Structure: Plant house Location: Beechwood, Biddenham Road, Bedford, Bedfordshire Client: W. Mitchell	1908

Records of Properties in Berkshire

TR MES AD1/116	Structure: Stove and vinery Location: Englemere, Ascot, Berkshire Client: Hon. Sir Robert H. Meade	1895
TR MES AD1/230 [2 of 2 packets]	Structure: Carnation house; Extension to greenhouse Location: Faringdon House, Faringdon, Berkshire Client: Thomas Kingscote; Lord Berners	1899; 1933-1937
TR MES AD1/278	Structure: Repair work Location: Clare Court, Wokingham, Berkshire Client: Mrs Hatherill	1906
TR MES AD1/284	Structure: Vineries; Forcing house Location: Binfield Manor, Bracknell, Berkshire Client: Right Hon. Lord Arthur Hill; L.R. Erskine	1904; 1908
TR MES AD1/289	Structure: Plant house Location: Holloway Sanatorium, Virginia Water, Berkshire Client: Dr W.D. Moore	1900
TR MES AD1/300	Structure: Plant house, stove and pit Location: Clewer Lodge, Windsor, Berkshire Client: Mrs Hornby	1889
TR MES AD1/398	Structure: Greenhouse Location: Forest House, Binfield, Bracknell, Berkshire Client: Hon. Hugh Hare	1905
TR MES AD1/424	Structure: Intermediate plant house Location: South Hill Park, Bracknell, Berkshire Client: Sir Arthur Hayter	1897
TR MES AD1/428	Structure: Greenhouses Location: The Gables, Burnham, Maidenhead, Berkshire Client: F.C.D. Haggard per A.F. Nutt [Architect]	1898
TR MES AD1/512	Structure: Palm House and Orchid House Location: Dedworth Manor, Windsor, Berkshire Client: Edmund B. Foster	1897-1898
TR MES AD1/554	Structure: Greenhouse Location: Merlebank, Donnington Holt, Newbury, Berkshire Client: Mrs Fellows	1905
TR MES AD1/639	Structure: Conservatory Location: The Elms, Wokingham, Berkshire Client: T.E. Ellison	1893
TR MES AD1/682	Structure: Glasshouse Location: Summerholme, Fishery Estate, Bray, Berkshire Client: N.M. Cohen	1902
TR MES AD1/722	Structure: Iron stages for vineries and forcing house Location: West Woodhay House, Newbury, Berkshire Client: Mrs Cole	1892
TR MES AD1/740	Structure: Glass houses - Vinery and plant house Location: Shrubbs Hill House, Sunningdale, Berkshire Client: Mrs Chambers	1891-1892
TR MES AD1/827	Structure: Plant house Location: Bourton House, Shrivenham, Berkshire Client: C.K. Butler	1900
TR MES AD1/927	Structure: Conservatory Location: The Grange, Harmondsworth, Slough, Berkshire Client: John Bolders	1895

TR MES AD1/929	Structure: Greenhouse Location: Greenham, Newbury, Berkshire Client: J.H. Bowman	1902
TR MES AD1/992	Structure: Conservatory Location: Essex Lodge, Osborne Road, Windsor, Berkshire Client: E.R. Blewitt	1898
TR MES AD1/1022	Structure: Glasshouse Location: St Leonards, Windsor, Berkshire Client: Lady Brinkman	1906
TR MES AD1/1028	Structure: Greenhouse and plant house Location: Newtown House, Newbury, Berkshire Client: Sir Alexander Arbuthnot, Bart.	1891
TR MES AD1/1055	Structure: Heating apparatus Location: Faringdon, Berkshire Client: J. Thorley per T.W. Anns [Ironmonger]	1892
TR MES AD1/1055	Structure: Heating apparatus Location: Faringdon, Berkshire Client: John Heath per T.W. Anns [Ironmonger]	1892
TR MES AD1/1055	Structure: Plant house Location: Faringdon, Berkshire Client: Dr Lockwood per T.W. Anns [Ironmonger]	1898
TR MES AD1/1067	Structure: Vinery Location: Wixenford, Wokingham, Berkshire Client: E.P. Arnold per Agricultural and Horticultural Association	1902
TR MES AD1/1087	Structure: Greenhouse; Plant houses Location: Forest Park, Windsor, Berkshire Client: Arthur L. Wigan	1899; 1900
TR MES AD1/1125	Structure: Heating apparatus Location: Bearwood Estate, Wokingham, Berkshire Client: A.F. Walter	1901-1908`
TR MES AD1/1126	Structure: Peach house; Early Vineries and camellia house Location: Shrubbs Hill, Sunningdale, Ascot, Berkshire Client: E.S. Walmsley	1892; 1893
TR MES AD1/1149 [1 of 3 packets]	Structure: Conservatory Location: Hillside Cottage, Woodspeen near Newbury, Berkshire Client: A.C. Wylie	1901
TR MES AD1/1149 [2 of 3 packets]	Structure: Forcing house and potting shed Location: Hillside Cottage, Woodspeen near Newbury, Berkshire Client: A.C. Wylie	1902
TR MES AD1/1149 [3 of 3 packets]	Structure: Plant house and alterations to conservatory Location: Hillside Cottage, Woodspeen near Newbury, Berkshire Client: A.C. Wylie	1900
TR MES AD1/1238	Structure: Heating alterations Location: Scarletts, Twyford, Berkshire Client: Rev. H.M. Wells	1893
TR MES AD1/1267 [1 of 2 packets]	Structure: Plant house, ferneries, vinery, repairs and heating apparatus Location: Shottesbrooke Park, Maidenhead, Berkshire Client: Guy Oswald Smith	1897

TR MES AD1/1267 [2 of 2 packets]	Structure: Palm house roof Location: Shottesbrooke Park, Maidenhead, Berkshire Client: Guy Oswald Smith	1904
TR MES AD1/1292	Structure: Greenhouse and heating apparatus Location: Radley College, Abingdon, Berkshire Client: E.F. Simpkinson	1903
TR MES AD1/1323	Structure: Conservatory Location: Gilmuire, Ascot, Berkshire Client: E. Maxwell Stuart	1897
TR MES AD1/1547	Structure: Heating apparatus Location: Barton Court, Kintbury near Hungerford, Berkshire Client: W. Parrott	1902
TR MES AD1/1566	Structure: Exhaust steam heating apparatus Location: Adamantine Brick Works, Reading, Berkshire Client: Poulton and Son	1895
TR MES AD1/1567	Structure: Conservatory Location: The Priory, Datchet, Berkshire Client: H.L. Prior	1890
TR MES AD1/1645 [1 of 2 packets]	Structure: Boiler Location: West Court, Bray-on-Thames, Berkshire Client: W. West Neve	1924; 1925
TR MES AD1/1645 [2 of 2 packets]	Structure: Vineries and greenhouses; Conservatory Location: Fishery Estate, Maidenhead, Berkshire Client: W. West Neve	1901; 1902
TR MES AD1/1660	Structure: Glasshouse Location: Bear Place, Twyford, Berkshire Client: Henry Nicholl	1896
TR MES AD1/1663 [1 of 3 packets]	Structure: Rebuilding Melon house Location: Hollington House, Woolton Hill, Newbury, Berkshire Client: E.C. Cohen	1935
TR MES AD1/1663 [1, 2 and 3 of 3 packets]	Structure: Peach house; Muscat vinery, forcing house, plant house, orchid house and mushroom beds Location: Hollington House, Woolton Hill, Newbury, Berkshire Client: W.T. Taylor	1902; 1904
TR MES AD1/1718	Structure: Heating apparatus Location: Ringdale, Faringdon, Berkshire Client: J. Thorley	1894
TR MES AD1/1730	Structure: Vineries; Plant house Location: Maidenhatch, Pangbourne, Berkshire Client: Capt. Thornton	1899; 1911
TR MES AD1/1741	Structure: Peach house, vinery and greenhouses Location: Stubbings House, Maidenhead, Berkshire Client: W.H. Tyser	1901
TR MES AD1/1744	Structure: Conservatory Location: The Hatch, Sunninghill, Berkshire Client: Col. Giles per Robert Emerie Tyler [Architect]	1888
TR MES AD1/1748	Structure: Cucumber and melon house Location: Lynwood, Sunningdale, Berkshire Client: G. Rodie Thompson	1892
TR MES AD1/1789	Structure: Glasshouse Location: Curridge House, Hermitage, near Newbury, Berkshire Client: J. Spencer Evans	1907

TR MES AD1/1809	Structure: Heating apparatus Location: North Lands, Streatley, Berkshire Client: R. Rees per J. Smallbone [Builder]	1906; 1908
TR MES AD1/1906	Structure: Heating apparatus Location: Ditton House, near Maidenhead, Berkshire Client: E. Garcke	1907

Records of Properties in Buckinghamshire

TR MES AD1/379	Structure: Greenhouses Location: Castle House, Buckingham, Buckinghamshire Client: H. Hearn per R.C. Hadland	1897; 1903
TR MES AD1/468	Structure: Plant house Location: Butlers Court, Beaconsfield, Buckinghamshire Client: A. Grenfell	1894
TR MES AD1/730 [2 packets]	Structure: Boiler replacement; Greenhouse Location: Missenden Abbey, Great Missenden, Buckinghamshire Client: George Carrington; Miss Carrington	1903; 1921
TR MES AD1/746	Structure: Conservatory, Vinery and heating for house Location: Staple Hall, Fenny Stratford, Bletchley, Buckinghamshire Client: Thomas E. Cornwardine	1894
TR MES AD1/818	Structure: Heating apparatus Location: Chalfont Grange, Chalfont St Peter, Buckinghamshire Client: Mrs Fass	1906
TR MES AD1/833	Structure: Greenhouse Location: Ouse Bank, Newport Pagnell, Buckinghamshire Client: W. Rogers Bull	1892
TR MES AD1/870 [1 of 3 packets]	Structure: Boiler and heating apparatus Location: The Bungalow, Hedsor Gardens, Bourne End, Buckinghamshire Client: Philip Shephard	1940
TR MES AD1/870 [2 of 3 packets]	Structure: Alterations to heating; Glasshouses; Flowering house; Peach house Location: South Lodge and Hedsor Court, Hedsor, Bourne End, Buckinghamshire Client: J. Amery Parkes	1926; 1927; 1928; 1933
TR MES AD1/870 [3 of 3 packets]	Structure: Plant house; Heating apparatus Location: Hedsor House, Bourne End, Buckinghamshire Client: Right Hon. Lord Boston; D'Arcy Baker	1897; 1928
TR MES AD1/979	Structure: Greenhouse Location: Woodside House, Chenies, Buckinghamshire Client: Joseph Bates [Builder]	1893
TR MES AD1/990	Structure: Ventilating equipment for linotype room; Location: Fleet Street, London Client: Daily Telegraph	1931; 1938
TR MES AD1/1063	Structure: Heating apparatus Location: New House, Pollard Wood, Chalfont St Giles, Buckinghamshire Client: T.A. Allen	1905
TR MES AD1/1279	Structure: Heating apparatus, painting and repairs Location: Westbury Manor, near Bracknell, Buckinghamshire Client: Sir Samuel Scott, Bart.	1903
TR MES AD1/1317	Structure: Heating apparatus; Heating alterations Location: Fingest Grove, High Wycombe, Buckinghamshire Client: F. Crawford Smith	1904; 1906
TR MES AD1/1339	Structure: Greenhouse Location: Widgenton House, Beaconsfield, Buckinghamshire Client: John Rolfe	1893
TR MES AD1/1351	Structure: Greenhouses; Vinery Location: Hedgerley Park, Stoke Poges, Buckinghamshire Client: Mrs Stevenson	1893; 1895

TR MES AD1/1397	Structure: Glasshouse Location: Grendon Hall, Aylesbury, Buckinghamshire Client: A.E. Skinner	1905
TR MES AD1/1437	Structure: Conservatory Location: Little Missenden House, Little Missenden, Buckinghamshire Client: P.S. Stephens, KC	1901
TR MES AD1/1523	Structure: Plant house Location: The Gables, Wolverton, Buckinghamshire Client: C.A. Park	1898
TR MES AD1/1531	Structure: Peach house, plant house and stove; Heating apparatus Location: Lillingstone Dagnell, Buckinghamshire Client: Hon. Mrs Douglas Pennant; Capt. Roberts	1904; 1919
TR MES AD1/1558	Structure: Greenhouse Location: Woodlands, Beaconsfield, Buckinghamshire Client: Mrs Penfold	1901
TR MES AD1/1587	Structure: Greenhouse Location: Andover Nursery, Junction Road, Andover, Buckinghamshire Client: W. Palmer	1898
TR MES AD1/1603	Structure: Plant house Location: Walton Hall, Bletchley, Buckinghamshire Client: Miss Pinfold	1899
TR MES AD1/1653	Structure: Greenhouses Location: Berry Hill, Taplow, Buckinghamshire Client: Hon. Mrs Needham	1900
TR MES AD1/1666	Structure: Greenhouses; Forcing house; Heating apparatus Location: Manor House, Barton Hartshorn, Buckinghamshire Client: Hon. Mrs Charles Trotter	1905; 1906; 1909
TR MES AD1/1811	Structure: Glasshouses Location: New York Lodge, Bourne End, Buckinghamshire Client: [G.A. Kessler] per T.W. Heath and Son [Builders]	1907
TR MES AD1/1886	Structure: Conservatory; Carnation house Location: Wycombe Court, High Wycombe, Buckinghamshire Client: H.H. Worthington	1908; 1912
TR MES AD1/1889	Structure: Greenhouse Location: Coombe Hill, Butlers Cross, Tring, Buckinghamshire Client: Sir John Lawson Walton, KC, MP	1908
TR MES AD1/1893	Structure: Vinery and forcing house Location: Oak Ash, Chaddleworth, Buckinghamshire Client: W. Louis Lucas [Architect]	1907
TR MES AD1/1936	Structure: Greenhouse Location: Nether Winchenden, Aylesbury, Buckinghamshire Client: Mrs Napier Higgins	1907

Records of Properties in Cambridgeshire

TR MES AD1/307	Structure: Greenhouse Location: 17 Thornhill Road, Croydon, Cambridgeshire Client: W. Hunter	1894
TR MES AD1/455	Structure: Conservatory; Glass roof Location: Parkside, Warham Road, South Croydon, Cambridgeshire Client: P.G. Guimareans	1898; 1900
TR MES AD1/462	Structure: Conservatory Location: Cathedral Precincts, Peterborough, Cambridgeshire Client: H.P. Gates	1890
TR MES AD1/494	Structure: Vinery and Plant House Location: West Street, Godmanchester, Cambridgeshire Client: W. Gadsby	1899
TR MES AD1/536	Structure: Plant house Location: Milton Park, Peterborough, Cambridgeshire Client: G.W.C. Fitzwilliam	1893
TR MES AD1/560	Structure: Plant house Location: Christs College, Cambridge, Cambridgeshire Client: Rev. Thomas C. Fitzpatrick	1905
TR MES AD1/729	Structure: Conservatory Location: Wellesley Road, Croydon, Cambridgeshire Client: Dr Rosser [per Messrs Crickmay [architects]]	1895
TR MES AD1/737	Structure: Heating Location: United Methodist Free Church, Lincoln Road, Peterborough, Cambridgeshire Client: Mr T. Casbon	1904
TR MES AD1/922	Structure: Conservatory and stove Location: Park Road, Peterborough, Cambridgeshire Client: Perkins per Perkins and Barford, Queen Street Iron Works	1904
TR MES AD1/957	Structure: Vinery and peach cover Location: Abington Hall, Cambridgeshire Client: E. Barker	1890
TR MES AD1/1296	Structure: Vinery and peach house; Conservatory Location: Stanground Manor House, Peterborough, Cambridgeshire Client: John D. Selby	1887; 1889
TR MES AD1/1298	Structure: Glasshouse; Painting Location: Weston Colville Hall, Cambridgeshire Client: Martin Slater	1901; 1904
TR MES AD1/1322	Structure: Plant house Location: Thorpe Hall, Peterborough, Cambridgeshire Client: Lt. Col. C.J. Strong	1903
TR MES AD1/1389	Structure: Heating apparatus Location: Hinchinbrook, Huntingdon, Cambridgeshire Client: Earl of Sandwich	1897
TR MES AD1/1403	Structure: Conservatory roof and painting Location: Milton Park, Peterborough, Cambridgeshire Client: G.W.C. Fitzwilliam	1897
TR MES AD1/1562	Structure: Greenhouse Location: Ashfield, Peterborough, Cambridgeshire Client: John A. Percival	1895
TR MES AD1/1579	Structure: Plant house Location: The Palace, Peterborough, Cambridgeshire Client: Bishop of Peterborough	1897

TR MES AD1/1795	Structure: Greenhouse Location: Sidney Sussex College, Cambridge, Cambridgeshire Client: C. Smith	1907
TR MES AD1/1954	Structure: Greenhouse Location: Hepmangrove House, Bury, Huntingdon, Cambridgeshire Client: John Rowell	1908

Records of Properties in Cheshire

TR MES AD1/72	Structure: Conservatory Location: Henshall Hall, Congleton, Cheshire Client: John Lewis [Architect]	1891
TR MES AD1/82	Structure: Vinery Location: Leftwich Grange, Northwich, Cheshire Client: W.H. Moreton	1892
TR MES AD1/115	Structure: Vinery and conservatory Location: Mere House, Weaverham, Northwich, Cheshire Client: William Marshall	1896
TR MES AD1/159	Structure: Conservatory Location: House at Kenyon Junction, Cheshire Clients: W.E. and R.T. Marsh	1891
TR MES AD1/190	Structure: Glass Houses Location: Alveston Hall, Nantwich, Cheshire Client: A. Knowles	1903
TR MES AD1/214	Structure: Plant house and stove Location: The Oaklands, Preston Brook, near Warrington, Cheshire Client: W.C. Jones	1891
TR MES AD1/260	Structure: Boiler Location: Dorset House, Heaton Chapel, near Stockport, Cheshire Client: William Jennison	1893
TR MES AD1/260	Structure: Plant house Location: Derby House, Heaton Moor, Stockport, Cheshire Client: John Jennison	1892
TR MES AD1/296	Structure: Greenhouse Location: Hilderstone, Hartford, Cheshire Client: Charles Humfrey	1908
TR MES AD1/296	Structure: Conservatory Location: The Poplars, Winnington Park, Northwich, Cheshire Client: Charles Humfrey	1893
TR MES AD1/707 [2 packets]	Structure: Plant house; Greenhouse Location: Queens Park, Crewe, Cheshire Client: Crewe Corporation per Borough Surveyor	1894; 1903
TR MES AD1/707	Structure: Plant protector; Greenhouse Location: Crewe Cemetary, Cheshire Client: Crewe Corporation per Borough Surveyor	1896; 1936
TR MES AD1/849	Structure: Greenhouse Location: 16 Beswicks Road, Northwich, Cheshire Client: per Brunner, Mond and Co.	1911
TR MES AD1/849	Structure: Greenhouse Location: Winnington Hall, Northwich, Cheshire Client: Dr Ludwig Mond per Brunner, Mond and Co.	1904
TR MES AD1/849	Structure: Conservatory Location: Hillside, Sandbach, Cheshire Client: R.L. Allen per Brunner, Mond and Co.	1906
TR MES AD1/883 [1 of 3 packets]	Structure: Glasshouses Location: Greystone, Hill Top Road, Hale, Cheshire Client: Mrs H.J. Marsland	1916

TR MES AD1/996	Structure: Greenhouse Location: Adswood House, Stockport, Cheshire Client: Thomas Bell	1889
TR MES AD1/1029	Structure: Heating alterations Location: The Parsonage, Sandbach Heath, Sandbach, Cheshire Client: Rev. S.H. Armistead	1891
TR MES AD1/1059	Structure: Greenhouse Location: Ellershie, Marple, near Stockport, Cheshire Client: F.C. Aldous	1905
TR MES AD1/1075	Structure: Plant house Location: The Croft, Knutsford, Cheshire Client: R.H. Watt	1903
TR MES AD1/1101	Structure: Glasshouses Location: Wistaston Hall, Crewe, Cheshire Client: J. Baskerville Clegg per Capt. Walthall [Landlord] per Lionel C. Molesworth [Agent]	1904
TR MES AD1/1129	Structure: Heating apparatus; Orchard house; Greenhouse Location: Beech House, Helsby, Warrington, Cheshire Client: Arthur F. Wrigley	1911; 1912; 1913
TR MES AD1/1200	Structure: Plant house and stove Location: Wellbank, Sandbach, Cheshire Client: Mrs Yates	1889
TR MES AD1/1363 [1 and 2 of 3 packets]	Structure: Greenhouses and palm house Location: Vernon Park, Stockport, Cheshire Client: Stockport, Cheshire Corporation	1904
TR MES AD1/1363 [3 of 3 packets]	Structure: Plant house and pit Location: Vernon Park, Stockport, Cheshire Client: Stockport, Cheshire Corporation	1912
TR MES AD1/1565	Structure: Greenhouse Location: Calvesley Hall, Tarporley, Cheshire Client: Mrs H.R. Peel	1889
TR MES AD1/1578	Structure: Greenhouse Location: Overleigh, Hough Green, Chester, Cheshire Client: Mr Roberts per Messrs Parker Bros [Builders]	1896
TR MES AD1/1828	Structure: Heating apparatus Location: Englesea House, Crewe, Cheshire Client: W. McCracken	1907
TR MES AD1/1896	Structure: Plant and peach house; Rebuilding houses Location: Dunham Massey Hall, Altrincham, Cheshire Client: Right Hon. Earl of Stamford	1909; 1926
TR MES AD1/1918	Structure: Plant house Location: Chelford Parsonage, Chelford, Cheshire Client: Rev. Colin E.B. Bell	1907
TR MES AD1/1933	Structure: Conservatory; Glasshouse Location: Beechfield, Alderley Edge, Cheshire Client: Frederick W. Holmes	1907; 1909
TR MES AD1/1937 [1 and 2 of 3 packets]	Structure: Conservatory Location: Stamford Park, Stalybridge, Cheshire Client: Samuel Turner [Park Superintendent]	1907
TR MES AD1/1937 [3 of 3 packets]	Structure: Greenhouse Location: Stamford Park, Stalybridge, Cheshire Client: Samuel Turner [Park Superintendent]	1914

Records of Properties in Cornwall

TR MES AD1/692	Structure: Peach house Location: Polapit Tamar, Launceston, Cornwall Client: R.C. Coode	1898
TR MES AD1/816	Structure: Vinery Location: Tehidy Park, Camborne, Cornwall Client: [G.L. Bassett] per Country Gentlemens Club	1906
TR MES AD1/1699 [1 of 2 packets]	Structure: Forcing house Location: Tolroy, Hayle, Cornwall Client: H.H. Trevithick	1886
TR MES AD1/1699 [2 of 2 packets]	Structure: Verandah Location: Tolroy, Hayle, Cornwall Client: H.H. Trevithick	1891
TR MES AD1/1713	Structure: Conservatory Location: Polkeris, Wood Lane, Falmouth, Cornwall Client: T. Trelease	1903

Records of Properties in Cumbria

TR MES AD1/117 See also TR MES AD1/1396	Structure: Plant house Location: Arndene, Abbey Road, Barrow-in-Furness, Cumbria Client: J.P. Smith JP per Messrs. Mackereth Ltd	1905
TR MES AD1/168	Structure: New greenhouse roof Location: Grimeshill, Kirkby Lonsdale, Cumbria Client: W. Middleton-Moore	1894
TR MES AD1/198	Structure: Tomato house Location: Walney Island, Barrow in Furness, Cumbria Client: Isle of Walney Estates Co. Ltd [Branch of Vickers, Sons and Maxim Ltd]	1902
TR MES AD1/252	Structure: Conservatory Location: Kents Bank, via Carnforth, Cumbria Client: R. Illingworth	1896
TR MES AD1/343	Structure: Conservatory; Vinery Location: Rock Lea, Barrow-in-Furness, Cumbria Client: G.S. Heath	1899; 1901
TR MES AD1/426	Structure: Forcing house Location: Hutton John, Penrith, Cumbria Client: W.J. Hudleston	1892
TR MES AD1/443	Structure: Plant House and Vinery Location: Graythwaite Manor, Grange-over-Sands, Cumbria Client: W.M. Gray	1903
TR MES AD1/708	Structure: Vinery Location: Holker Hall, Cark-in-Cartmel, Cumbria Client: Lord Victor C.W. Cavendish, MP	1904
TR MES AD1/1271	Structure: Heating apparatus Location: Isel Church, Cockermouth, Cumbria Client: Rev. B. Hawker	1901
TR MES AD1/1321 [2 packets]	Structure: Repairs and renewals Location: Eden Hall, Langwathby RSO, Cumbria Client: Charles H. Shaw	1906
TR MES AD1/1396 See also TR MES AD1/117	Structure: Greenhouse Location: Arndene, Abbey Road, Barrow-in-Furness, Cumbria Client: J.P. Smith per Messrs Mackereths and Ulverstone	1905
TR MES AD1/1409	Structure: Vinery, plant house and pit Location: Priors Lee, Barrow-in-Furness, Cumbria Client: A.H. Strongitharm	1887
TR MES AD1/1537	Structure: Greenhouse; Stove; Vineries; Boiler Location: Rampsbeck House, Ullswater, Penrith, Cumbria Client: Mrs Pritt	1902; 1903; 1905; 1908
TR MES AD1/1589	Structure: Conservatory roof Location: Holme Hill, Dalston, near Carlisle, Cumbria Client: Messrs Paley and Austin [Architects]	1891
TR MES AD1/1670	Structure: Fruit houses and palm house Location: Biggins, Kirkby Lonsdale, Cumbria Client: Dr Paget Tomlinson	1892
TR MES AD1/1746	Structure: Plant house Location: Helmside, Grasmere, Cumbria Client: J. T aylor	1898
TR MES AD1/1883	Structure: Heating apparatus Location: Thurstonville, Greenodd, Ulverston, Cumbria Client: Mrs Woodburn	1908

Records of Properties in Derbyshire

TR MES AD1/91	Structure: Glass house Location: Chase Cliffe, Whatstandwell, Derbyshire Client: His honourable judge, H.R. Mansel-Jones	1906
TR MES AD1/97	Structure: Greenhouse; Peach House Location: Tapton House, Chesterfield, Derbyshire Client: Mrs Markham	1896; 1899
TR MES AD1/139	Structure: Orangery Location: Markeaton Hall, near Derby, Derbyshire Client: Mrs Mundy	1904
TR MES AD1/144	Structure: Greenhouse Location: Tissington Hall, Ashbourn, Derbyshire Client: Mrs Reid Martin	1892
TR MES AD1/206	Structure: Vinery Location: Walton Lodge, Chesterfield, Derbyshire Client: W. Wynne Jendwine	1902
TR MES AD1/224	Structure: Glasshouse Location: Quarndon Hill, near Derby, Derbyshire Client: Alfred Jacobson	1902
TR MES AD1/228	Structure: Mains water lines Location: Sunnyhill Vineries, Littleover, Derby, Derbyshire Client: J.M. Kitley	1900
TR MES AD1/237	Structure: Vineries Location: Horsley Woodhouse, Derby, Derbyshire Client: H. Jordan	1899
TR MES AD1/258	Structure: Greenhouse Location: Babington Lane, Elmbank, Burton Road, Derby, Derbyshire Client: John Jerram	1896
TR MES AD1/297 See also TR MES AD1/1768	Structure: Conservatory and tea room Location: Alderwasley Hall, near Wirksworth, Derbyshire Client: Lieut. Col. A.F. Hurt	1902
TR MES AD1/340	Structure: Greenhouse Location: Walton House, nr. Chesterfield, Derbyshire Client: Mansfeldt H. Humble	1893-1894
TR MES AD1/344	Structure: Conservatory at Whatstandwell Location: Crich, nr. Matlock Bath, Derbyshire Client: John Haynes	1902
TR MES AD1/373	Structure: Heating apparatus Location: The Gardens, Sawley near Derby, Derbyshire Client: Miss Burnett and Miss Page per Miss Grace Harriman	1895
TR MES AD1/401	Structure: Heating apparatus Location: Clifton House, Clifton, Derbyshire Client: Mrs C.M. Hodge	1897
TR MES AD1/509	Structure: Greenhouse Location: The College, All Saints, Derby, Derbyshire Client: T.A. Fuller	1901
TR MES AD1/510	Structure: Heating apparatus, enlarging stove Location: Haddon House, Bakewell, Derbyshire Client: Mrs Ward Fox	1890
TR MES AD1/541	Structure: Conservatory Location: Belvoir House, Sandiacre, Derbyshire Client: E.W. Field	1897

TR MES AD1/543	Structure: Conservatory; Glazing conservatory Location: Beechwood, 239 Osmaston Road, Derby, Derbyshire Client: Henry Fowke; Ernest E. Jordan	1899; 1916
TR MES AD1/621	Structure: Vinery and heating apparatus Location: The Lodge, Darley Dale, Matlock, Derbyshire Client: T. Cooper Drabble	1900
TR MES AD1/672	Structure: Painting glasshouses Location: Belfield, Long Eaton, Derbyshire Client: F.R. Claye	1903
TR MES AD1/673	Structure: Heating apparatus; Peach house Location: The Poplars, Duffield Road, Derby, Derbyshire Client: Edgar H. Claye	1894; 1897
TR MES AD1/673	Structure: Heating apparatus Location: Darleyfields, Duffield Road, Derby, Derbyshire Client: Edgar H. Claye	1898
TR MES AD1/711	Structure: Greenhouse Location: Burnaston House, Etwall, Derbyshire Client: G. D'Arcy Clark	1889
TR MES AD1/721 [3 packets]	Structure: Glasshouses and hot water; Conservatory; Painting Location: The Outwoods, Duffield, near Derby, Derbyshire Client: C.W. Catt	1900; 1901; 1905
TR MES AD1/736	Structure: Heating apparatus for ground floor stores Location: West Bars, Chesterfield, Derbyshire Client: Chesterfield, Derbyshire and District Cooperative Society	1903
TR MES AD1/750	Structure: Greenhouse Location: Brailsford Refectory, Derby, Derbyshire Client: Rev. J.G. Croker	1890
TR MES AD1/838	Structure: Plant house Location: The Pastures, Derby, Derbyshire Client: Walter Boden	1903
TR MES AD1/850	Structure: Heating apparatus; Greenhouse Location: Kingston Hall, Derby, Derbyshire Client: Right Hon. Lord Belper	1896; 1913
TR MES AD1/867 [2 packets]	Structure: Peach house; Conservatory and stove; Painting; Frames Location: Orient Lodge, Green Fairfield, Buxton, Derbyshire Client: J.S. Brittain	1892; 1896; 1897; 1899
TR MES AD1/894	Structure: Heating apparatus Location: Buxton, Derbyshire Client: Buxton Lime Firms Company Ltd.	1897
TR MES AD1/909	Structure: Smoke room Location: Buxton palace Hotel, Buxton, Derbyshire Client: W. Holland [Architect]	1900
TR MES AD1/912	Structure: Heating apparatus Location: Blue Bell, Church Street, Melbourne, Derbyshire Client: Joseph Burton [Plumber]	1904
TR MES AD1/916 [1 of 2 packets]	Structure: Heating apparatus Location: Factory in Ilkeston, Derbyshire Client: William Barton [Architect]	1904
TR MES AD1/921 [3 packets]	Structure: Plant house; Show house; Heating apparatus; Greenhouse; Greenhouses Location: Elvaston Nurseries, Borrowash, Derbyshire Client: William Barron and Son Ltd.	1903; 1906; 1921; 1936; 1939

TR MES AD1/953	Structure: Glasshouses; Boiler Location: Ashgate Lodge, Chesterfield, Derbyshire Client: A. Barnes, MP	1891; 1935
TR MES AD1/963	Structure: Repairs to vinery Location: Elmhurst, Derby, Derbyshire Client: W. Bemrose	1903
TR MES AD1/994	Structure: Forcing house Location: 51 Conway Street, Long Eaton, Derbyshire Client: Henry Broomfield	1903
TR MES AD1/995	Structure: Camelia house and vinery; Repairs Location: Tupton Hall, Chesterfield, Derbyshire Client: A.G. Barnes; Packman Estate	1893; 1917
TR MES AD1/1006	Structure: Heating apparatus Location: Men's Wing, Belper, Derbyshire Client: Belper Union Workhouse	1903
TR MES AD1/1052	Structure: Greenhouse Location: 163 Victoria Cottages, Station Road, Long Eaton, Derbyshire Client: J.V. Allen	1903
TR MES AD1/1058	Structure: Conservatory; Forcing house; Peach house Location: The Limes, Mickleover, Derbyshire Client: H.E. Ayres and Mrs Ayres	1893; 1895; 1899
TR MES AD1/1092 [2 packets]	Structure: Conservatory and glasshouse Location: Burbage House, Buxton, Derbyshire Client: T.H. Lowthran per W.R. Bryden [Architect]	1903
TR MES AD1/1098	Structure: Greenhouse; Greenhouses Location: The Grange, Butterley, Derbyshire Client: Fitzherbert Wright per Alfred M. Wright; G.F. Wright	1907; 1911
TR MES AD1/1109	Structure: Greenhouse Location: Century Nurseries, Kedleston Road, Derby, Derbyshire Client: George A. Wheeldon	1901
TR MES AD1/1109	Structure: Greenhouses and pits Location: Parkfields House, Derby, Derbyshire Client: George A. Wheeldon	1900
TR MES AD1/1136	Structure: Stove Location: Burton Closes, Bakewell, Derbyshire Client: S. Taylor Whitehead	1890
TR MES AD1/1189	Structure: Glasshouse Location: Waltham House, Wirksworth, Derbyshire Client: George H. Wheatcroft	1898
TR MES AD1/1240 [2 packets]	Structure: Glasshouses, painting and heating apparatus Location: Lea Wood, Matlock Bath, Derbyshire Client: Mrs Walker	1900
TR MES AD1/1268	Structure: Heating apparatus Location: Douglas House, Osmaston Road, Derby, Derbyshire Client: A. Swingler	1894
TR MES AD1/1297	Structure: Ante room; Plant house and stove Location: Matlock Bath, Derbyshire Client: Smedley's Hydropathic Company	1893; 1900
TR MES AD1/1341	Structure: Conservatory Location: The Limes, Kedleston Road, Derby, Derbyshire Client: A.H. Rowbotham	1896
TR MES AD1/1368	Structure: Vinery Location: 2, The Gables, Uttoxeter Road, Derby, Derbyshire Client: W.R. Smith	1887

TR MES AD1/1391	Structure: Heating apparatus Location: Hazlebrow, Duffield, Derbyshire Client: George Simpson	1894
TR MES AD1/1402 [3 packets]	Structure: Palm house, Orchid house, Cattleya house, Laelia house, heating apparatus and weather vane Location: Lea Green, near Matlock, Derbyshire Client: J.B. Marsden Smedley	1896
TR MES AD1/1417	Structure: Repairs and painting Location: Edge Hill, Duffield, Derbyshire Client: H. Swingler	1901
TR MES AD1/1446	Structure: Conservatory Location: Goldwell Bank, Ashgate Road, Chesterfield, Derbyshire Client: William Spooner	1901
TR MES AD1/1451	Structure: Ventilating and heating apparatus Location: Glossop House, Ilkeston, Derbyshire Client: E. Smith	1901
TR MES AD1/1490	Structure: Greenhouse Location: Ashbourne Road, Derby, Derbyshire Client: Railway Servants Orphanage	1896
TR MES AD1/1541	Structure: Glasshouse Location: Thurlaston Grange, Derby, Derbyshire Client: Rev. Charles H. Prodgers	1904
TR MES AD1/1572	Structure: Conservatory Location: Brampton Manor, Chesterfield, Derbyshire Client: James Pearson	1897
TR MES AD1/1657	Structure: Greenhouse; Alterations to greenhouse; Carnation House Location: The Hermitage, Hazlewood Road, Duffield, Derbyshire Client: J.R. Nayler; W.L.P. Woolley	1901; 1937; 1938
TR MES AD1/1762	Structure: Heating to factory Location: Wood Street, Ilkeston, Derbyshire Client: Samuel Fletcher and Son	1907; 1912
TR MES AD1/1763	Structure: Greenhouse Location: Whitaker Road, Derby, Derbyshire Client: P.W. Lucas	1906
TR MES AD1/1768 [1 and 2 of 2 packets]	Structure: Re-erecting glasshouse from Brookfield House at Chase Cliff; Rebuilding vinery Location: Chase Cliff, Whatstandwell, near Matlock, Derbyshire Client: Maurice Deacon [Tenant]; F.C.A. Hurt [Owner]	1909; 1921
TR MES AD1/1768 [2 of 2 packets]	Structure: Plant house Location: Whittington House, near Chesterfield, Derbyshire Client: Maurice Deacon	1907
TR MES AD1/1836 [1 and 2 of 3 packets]	Structure: Orchid houses Location: Morley Manor, Morley, Derbyshire Client: Mrs Sacheverell Bateman	1906
TR MES AD1/1836 [3 of 3 packets]	Structure: Ventilating equipment and repairs; Boiler repairs Location: Morley Manor, Morley, Derbyshire Client: Mrs Lister Kaye	1913; 1925
TR MES AD1/1855	Structure: Heating apparatus Location: Caxton Buildings, Ripley, Derbyshire Client: G.C. Brittain	1905
TR MES AD1/1859 [1 of 5 packets]	Structure: Orchid house and conservatory Location: Littleover Hall, near Derby, Derbyshire Client: Edward McInnes	1901

TR MES AD1/1859 [2 of 5 packets]	Structure: Painting and propagating house Location: Littleover Hall, near Derby, Derbyshire Client: Edward McInnes	1905
TR MES AD1/1859 [3 of 5 packets]	Structure: Plant house and stove Location: Littleover Hall, near Derby, Derbyshire Client: Edward McInnes	1891
TR MES AD1/1859 [4 of 5 packets]	Structure: Boiler; Painting Location: Littleover Hall, near Derby, Derbyshire Client: Edward McInnes	1898; 1906
TR MES AD1/1859 [5 of 5 packets]	Structure: Peach house Location: Littleover Hall, near Derby, Derbyshire Client: Edward McInnes	1899
TR MES AD1/1860 [2 packets]	Structure: Moving and refixing plant house and pit Location: Shipley Hall, Shipley, Derbyshire Client: E. Miller Mundy	1902
TR MES AD1/1878	Structure: Heating to shop Location: 65 High Street, Swadlincote, Burton on Trent, Derbyshire Client: H.B. Dinnis [Jeweller]	1908
TR MES AD1/1891	Structure: Porch Location: Totnes, Duffield Road, Derby, Derbyshire Client: Miss Locke	1908
TR MES AD1/1925	Structure: Vineries Location: Derwent Bank, Duffield Road, Derby, Derbyshire Client: William Fletcher	1908
TR MES AD1/1928 [1 of 5 packets]	Structure: Heating apparatus; Heating to offices; Heating to warehouse Location: Moss Street Mills, Derby, Derbyshire Client: William Wild and Co	1933; 1938; 1939
TR MES AD1/1928 [2 of 5 packets]	Structure: Heating apparatus Location: Woodstock, Burton Road, Derby, Derbyshire Client: William Wild	1940
TR MES AD1/1928 [3 of 5 packets]	Structure: Heating to covered yard; Boiler Location: Moss Street Mills, Derby, Derbyshire Client: William Wild and Co	1935; 1940
TR MES AD1/1928 [4 of 5 packets]	Structure: Heating apparatus Location: Moss Street Mills, Derby, Derbyshire Client: Wild and Fell	1912; 1922
TR MES AD1/1928 [5 of 5 packets]	Structure: Heating apparatus; Heating to tape factory; Heating alterations Location: Moss Street Mills, Derby, Derbyshire Client: J.A. Wild; Wild and Fell	1905; 1908; 1931
TR MES AD1/1970	Structure: Heating apparatus Location: The Pottery School, Belper, Derbyshire Client: Derbyshire Education Committee	1904
TR MES AD1/1999	Structure: Heating apparatus Location: Burbage Church, Buxton, Derbyshire Client: H.A. Hubbersty	1892

Records of Properties in Devon

TR MES AD1/149	Structure: Peach house and vinery Location: Townleigh, Lewdown, Devon Client: Mr H.B. Blackburn per G.H. Mounsdon [Nurseryman]	1893
TR MES AD1/182	Structure: Peach house Location: High Bank, Sidmouth, Devon Client: Dr A Macindor	1902
TR MES AD1/399	Structure: Orchid houses Location: Wonham, Bampton, Devon Client: Mrs John Holland	1896
TR MES AD1/427	Structure: Vinery and Stove Location: Upcott House, Barnstaple, Devon Client: Stafford Harding	1889
TR MES AD1/442	Structure: Plant House Location: Tapley, Bishops Teignton, Devon Client: Dr Galabin	1899
TR MES AD1/503	Structure: Plant house and heating apparatus Location: Abbotsfield, Tavistock, South Devon Client: F.F. Freeman	1894-1895
TR MES AD1/530	Structure: Heating apparatus Location: Warfleet, Dartmouth, Devon Client: Sir Thomas Freake	1898
TR MES AD1/889	Structure: Boiler Location: Downes, Crediton, Devon Client: General Sir Redvers Buller, VC	1932
TR MES AD1/976	Structure: Plant house Location: Gosford House, Ottery St Mary, Devon Client: S. Bennett	1892
TR MES AD1/1069	Structure: Tomato house Location: 101 High Street, Ilfracombe, Devon Client: F.M. Watkin	1903
TR MES AD1/1120	Structure: Vinery, Forcing house and greenhouse Location: Mount Sandford, Barnstaple, North Devon Client: Eustace R. Wigram	1902
TR MES AD1/1404	Structure: Conservatory Location: Hillstead, St Mary Church Road, Torquay, Devon Client: Dr Stark	1889
TR MES AD1/1429	Structure: Greenhouse Location: Glen Cottage, Buckland Brewer, Bideford, Devon Client: Capt. Saunders	1887
TR MES AD1/1926	Structure: Greenhouses Location: Castle Hill, South Molton, Devon Client: Right Hon. Earl Fortescue	1908 and 1931

Records of Properties in Dorset

TR MES AD1/78	Structure: Conservatory Location: Flaghead, Canford Cliffs, Bournemouth, Dorset Client: Col. Charles Mercier	1895
TR MES AD1/94	Structure: Boiler and fittings Location: Market Place, Blandford, Dorset Client: J. Marshall	1905
TR MES AD1/153	Structure: Conservatory Location: Smedmore, Corfe Castle, Dorset Client: Col. Marsel	1894
TR MES AD1/384	Structure: Heating apparatus Location: Winfrith House, Winfrith, Dorchester, Dorset Client: Miss Alice Hughes	1903-1904
TR MES AD1/464	Structure: Peach house Location: Gaunts House, Wimborne, Dorset Client: Sir Richard G. Glyn, Bart	1898
TR MES AD1/518	Structure: Glasshouses Location: Eastbury Park, Blandford, Dorset Client: Henry R. Farquharson	1891
TR MES AD1/712 [3 packets]	Structure: Vinery, Conservatory, Peach house; Fernery and Orchid House Location: Radipole Manor, Radipole, Weymouth, Dorset Client: Henry Cox per Messrs Crickmay [Architects]	1899; 1903
TR MES AD1/745	Structure: Conservatory Location: Queens Avenue, Victoria Park Estate, Dorchester, Dorset Client: Capt. D. Granville per Messrs Crickmay [architects]	1898
TR MES AD1/1001 [4 packets]	Structure: Stove and muscat vinery; Heating apparatus; Boiler; Painting and carnation house; Stove, vinery, plant house and melon house Location: Lytchett House, Poole, Dorset Client: Lord Eustace Cecil; Lord Evelyn Cecil, GBE, MP	1893; 1895;1917; 1925; 1928
TR MES AD1/1127	Structure: Conservatory; Plant house Location: Herrington, Dorchester, Dorset Client: Capt. Williams	1903; 1905
TR MES AD1/1181	Structure: Plant house Location: Westmead, Bridport, Dorset Client: William Colfox, JP	1891
TR MES AD1/1352	Structure: Conservatory Location: Steepleton Manor, Dorchester, Dorset Client: H. Stilwell	1896
TR MES AD1/1501 [3 of 3 packets]	Structure: Vinery and peach house Location: The Manor House, Hinton St. Mary, Sturminster Newton, Dorset Client: Capt. G.F. Pitt-Rivers	1929
TR MES AD1/1501 [2 of 3 packets]	Structure: Glasshouse Location: The Manor House, Hinton St. Mary, Sturminster Newton, Dorset Client: A. Pitt-Rivers	1903
TR MES AD1/1501 [1 of 3 packets]	Structure: Orangery roof and boiler Location: The Manor House, Hinton St. Mary, Sturminster Newton, Dorset Client: Pitt-Rivers Estate	1902

TR MES AD1/1576	Structure: Peach house Location: Rousdon, Lyme Regis, Dorset Client: Sir Cuthbert Peek, Bart.	1900
TR MES AD1/1705 [1 of 2 packets]	Structure: Plant house Location: Grayrigg, Parkstone, Dorset Client: J.H. Taylor	1900
TR MES AD1/1705 [2 of 2 packets]	Structure: Plant house, stove and pit Location: Grayrigg, Parkstone, Dorset Client: J.H. Taylor	1898
TR MES AD1/1726	Structure: Conservatory Location: Duddeston, Bournemouth, Dorset Client: Miss Twells	1899
TR MES AD1/1851	Structure: Conservatory and ventilating apparatus Location: Kinvara, Portarlinton Road, Bournemouth, Dorset Client: Mr Thompson per Fred. Hoare and Sons [Builders]	1902
TR MES AD1/1902	Structure: Carnation house Location: Ranston, Blandford, Dorset Client: Sir Randolph Baker	1908

Records of Properties in Essex

TR MES AD1/125	Structure: Vinery Location: Grove House, South Woodford, Essex Client: J. Miller	1891
TR MES AD1/142	Structure: Heating apparatus Location: Lea Court, The Lees, Westcliff-on-Sea, Essex Client: W.J. Maddison	1904
TR MES AD1/414	Structure: Rose House Location: Oak Hall, Buckhurst Hill, Essex Client: W.G. Huxley	1898
TR MES AD1/425 [2 packets]	Structure: Plant house, Stove and Forcing houses; Painting Location: Hill House, Lexdon, Colchester, Essex Client: S.F. Hurnard	1892; 1919
TR MES AD1/644	Structure: Boiler Location: Littlebury, Saffron Walden, Essex Client: E. Emson	1906
TR MES AD1/648	Structure: Vineries Location: Holmehurst, Loughton, Essex Client: F.L. Edwards	1887
TR MES AD1/735	Structure: Heating for Greenhouse Location: The Farm Buildings, Chadwell Heath Asylum, Goodmayes, Essex Client: Chadwell Heath Asylum	1903
TR MES AD1/792	Structure: Glasshouses Location: Claybury Asylum, Woodford, Essex Client: George T. Hine [Architect]	1894
TR MES AD1/861	Structure: Vinery Location: The Lawn, Southchurch, Essex Client: E.W. Barnett	1891-1892
TR MES AD1/880	Structure: Heating apparatus Location: Starling Lodge, Epping New Road, Buckhurst Hill, Essex Client: F.E. Bye	1904
TR MES AD1/918	Structure: Cucmber house, plant house and stokery Location: Southend, Essex Client: Messrs Baker and Wiseman [Builders]	1889
TR MES AD1/952 [2 packets]	Structure: Heating apparatus Location: Barking Public Offices, Barking, Essex Client: Barking Town Urban District Council	1894; 1920; 1922; 1924
TR MES AD1/960	Structure: Heating apparatus Location: Police Station, Colchester, Essex Client: Brightwen Binyon [Architect]	1895
TR MES AD1/981	Structure: Heating apparatus Location: Lynderswood, Braintree, Essex Client: Edgar Barker	1897
TR MES AD1/989	Structure: Plant house; Conservatory Location: Ravensmere, Kendal Avenue, Epping, Essex Client: George Brooke	1899; 1902
TR MES AD1/1082	Structure: Greenhouse Location: Greenhill, Evesham, Essex Client: Lewis G. Wait	1901
TR MES AD1/1082	Structure: Boiler; Twin houses Location: Chadbury Fruit Farm, Evesham, Essex Client: Lewis G. Wait	1900; 1901

TR MES AD1/1084	Structure: Orangery; Greenhouse Location: Langton, Hornchurch, Essex Client: Mr W. and Miss E. Varco Williams	1906; 1907
TR MES AD1/1138 [1 of 2 packets]	Structure: Stove; Rebuilding woodwork Location: Easton Lodge, Dunmow, Essex Client: Countess of Warwick	1894; 1896
TR MES AD1/1138 [2 of 2 packets]	Structure: Boiler; Boiler Location: Easton Lodge, Dunmow, Essex Client: Countess of Warwick	1927; 1930
TR MES AD1/1235	Structure: Glass vestibule Location: Lion Works, West Thurrock, Essex Client: Wouldham Cement Company	1902
TR MES AD1/1357	Structure: Heating apparatus Location: Ecclesbourne, The Avenue, Grove Park, Wanstead, Essex Client: William Stewart	1904
TR MES AD1/1362	Structure: Heating apparatus to house Location: Hatfield Peverel House, Witham, Essex Client: Alfred Rosling	1894
TR MES AD1/1362	Structure: Heating apparatus to house Location: Cardfields, Hatfield Peverel, Witham, Essex Client: Alfred Rosling	1895
TR MES AD1/1398	Structure: Conservatory and forcing house Location: Hillcrest, Brentwood, Essex Client: Alfred Smart	1905
TR MES AD1/1761	Structure: Heating apparatus Location: Romford, Essex Client: Messrs Field Mallett and Co. [Engineers]	1902
TR MES AD1/1775	Structure: Glasshouse Location: The Firs, Chingford, Essex Client: J. Wilcox	1906
TR MES AD1/1829	Structure: Greenhouse, plant house, stove and vineries Location: Braxted Park, Witham, Essex Client: W.B. Gladstone	1906
TR MES AD1/1864	Structure: Vinery Location: Great Chesterford Mills, Saffron Walden, Essex Client: Henry King	1901

Records of Properties in Gloucestershire

TR MES AD1/77	Structure: Glasshouse Location: Benwell House, Woodchester, Gloucestershire Client: Mrs Mostyn	1906
TR MES AD1/195	Structure: Conservatory Location: Quince Lawn, Cheltenham, Gloucestershire Client: Percy Hubert Hepburn Kenworthy	1903
TR MES AD1/196 See also TR MES AD1/230	Structure: Carnation House Location: The Abbey, Cirencester, Gloucestershire Client: Thomas Kingscote	1904
TR MES AD1/230 [1 of 2 packets] See also TR MES AD1/196	Structure: Carnation house Location: Watermoor House, Cirencester, Gloucestershire Client: Thomas Kingscote, MVO	1919
TR MES AD1/292	Structure: Greenhouses and Peach House; Heating apparatus Location: Chavenage, Tetbury, Gloucestershire Client: Col. W.W. Hoole; Major Lowsley Williams	1891-1893; 1913
TR MES AD1/321	Structure: Conservatory Location: Mangersbury Manor, Stow on the Wold, Gloucestershire Client: J.H. Hewitt	1900
TR MES AD1/356	Structure: Orchid house Location: Westonbirt House, Tetbury, Gloucestershire Client: Capt. Holford	1900
TR MES AD1/391	Structure: Stove and intermediate house Location: Oldown, Almondsbury, Gloucestershire Client: W.H. Harford	1888
TR MES AD1/404	Structure: Peach House Location: Elmestree, Tetbury, Gloucestershire Client: F. Henry	1896
TR MES AD1/410	Structure: Greenhouse Location: Cowley Manor, Cheltenham, Gloucestershire Client: James Horlick	1899
TR MES AD1/475	Structure: Greenhouse Location: Ebrington, Campden, Gloucestershire Client: A.H. Gordon Duff	1899
TR MES AD1/475	Structure: Plant house Location: Churchmead, Hatherop, Fairford, Gloucestershire Client: A.H. Gordon Duff	1907
TR MES AD1/515	Structure: Vinery Location: Riverside, Kempsford, near Fairford, Gloucestershire Client: Tom Faulkner	1903
TR MES AD1/519	Structure: Conservatory; Plant and forcing house Location: The Querns, Cirencester, Gloucestershire Client: J.P. Forsyth Forest; Capt. Hamilton Gordon	1898; 1911
TR MES AD1/714	Structure: Heating apparatus Location: Friezewood, Rudgeway, Gloucestershire Client: G.D. Crossman	1889
TR MES AD1/754	Structure: Heating for house Location: Stanley Hall, Stroud, Gloucestershire Client: Col. James C. Collier	1890
TR MES AD1/841	Structure: Greenhouse Location: Flaxley Abbey, Newnham, Gloucestershire Client: Lady Crawley Boevey	1890

TR MES AD1/917	Structure: Heating apparatus Location: Lampern House, near Dursley, Gloucestershire Client: G. Lloyd Baker	1896
TR MES AD1/917	Structure: Heating apparatus Location: Hardwicke Court, Gloucester, Gloucestershire Client: G. Lloyd Baker	1892-1893
TR MES AD1/925	Structure: Heating apparatus Location: Kencott House, Lechlade, Gloucestershire Client: Dr Pilkington per Joseph Bowley and Son [Builders]	1903
TR MES AD1/980	Structure: Heating apparatus Location: Fairford Vicarage, Fairford, Gloucestershire Client: Rev. F.R. Carbonell per George Barrett and Co. [Ironmongers]	1892
TR MES AD1/1003	Structure: Orchid, carnation and plant houses Location: Hatherop Castle, Fairford, Gloucestershire Client: Gardner S. Bazley	1903
TR MES AD1/1104	Structure: Greenhouse Location: Firwood House, near Chalford, Gloucestershire Client: Rev. C. Smyth per Wall and Hook [Builders]	1892
TR MES AD1/1130	Structure: Vinery and peach house Location: Meredith, Gloucester, Gloucestershire Client: Sir W. Wedderburn, Bart.	1903
TR MES AD1/1201	Structure: Plant house; Pit frames; Glasshouse; Violet frames Location: Forthampton Court, Tewkesbury, Gloucestershire Client: Joseph R. Yorke	1890; 1895; 1897; 1900
TR MES AD1/1408	Structure: Vinery and Forcing houses Location: Toddington Grange, Winchcomb RSO, Gloucestershire Client: Capt. Stacey	1897
TR MES AD1/1433	Structure: Heating apparatus Location: St Peters Church, Frocester, Gloucestershire Client: Rev. W Symonds	1889
TR MES AD1/1534	Structure: Forcing house Location: Tibberton Court, Tibberton SO, Gloucestershire Client: Mrs W.E. Price	1904
TR MES AD1/1704	Structure: Greenhouse Location: Dowdeswell, Gloucestershire Client: Henry Tovey [Ironmonger]	1899
TR MES AD1/1719	Structure: Cucumber and melon house Location: Rendcomb Park, Cirencester, Gloucestershire Client: James Taylor	1893
TR MES AD1/1739	Structure: Heating apparatus Location: Cam, near Dursley, Gloucestershire Client: A. Ashbee per Turner and Pritchard [Plumbers]	1900
TR MES AD1/1832	Structure: Heating apparatus Location: Cotswold Park, near Cirencester, Gloucestershire Client: Rev. J. Priestley Foster	1906
TR MES AD1/1862 [1, 2, 4 and 5 of 5 packets]	Structure: Vineries, Peach, forcing, cucumber and plant houses, conservatory and stove Location: Overbury Court, near Tewkesbury, Gloucestershire Client: Richard B. Martin, MP	1899
TR MES AD1/1862 [3 of 5 packets]	Structure: Plant houses Location: Overbury Court, near Tewkesbury, Gloucestershire Client: Richard B. Martin, MP	1904

TR MES AD1/1863
[2 packets]

Structure: Orchid, carnation, plant, intermediate and stove
houses
Location: Kings Weston, Shirehampton near Bristol,
Gloucestershire
Client: P. Napier Miles

1903

TR MES AD1/1913

Structure: Greenhouse; Peach house
Location: The Manor House, Notgrove, Gloucestershire
Client: Cyril Cunard

1908; 1911

Records of Properties in Hampshire

TR MES AD1/71	Structure: Peach house; Plant house Location: Westbury House, Petersfield, Hampshire Client: Col. H. Le Roy Lewis, DSO	1900; 1908
TR MES AD1/129	Structure: Greenhouse Location: Palace House, Beaulieu, Southampton, Hampshire Client: Lord Montague	1894
TR MES AD1/133	Structure: Orchid House and boiler shed Location: Richmond House, Hayling Island, Hampshire Client: Charles H. McEuen	1897
TR MES AD1/169	Structure: Boiler Location: Down Grange, Basingstoke, Hampshire Client: W. R. Mitchell	1893
TR MES AD1/175	Structure: Peach house Location: South Stoneham House, Swaythling, Southampton, Hampshire Client: Sir Samuel Montagu	1901
TR MES AD1/180	Structure: Peach house Location: Woolmer, Liphook, Hampshire Client: Sir Archibald Macdonald	1902
TR MES AD1/202	Structure: Peach house; Conservatory; Fernery Location: Northgate Place, Winchester, Hampshire Client: H.E. Johnson	1897; 1899; 1906
TR MES AD1/286	Structure: Plant house Location: The Merrie Thought, Fordingbridge, Hampshire Client: Miss Hulse	1901
TR MES AD1/308	Structure: Conservatory Location: Pinehurst, Headley, Hampshire Client: E.F. Hubbuck	1900
TR MES AD1/314	Structure: Greenhouses Location: Brambridge House, near Bishopstoke, Hampshire Client: Major Powney per Hampton and Sons [Builders]	1901
TR MES AD1/320	Structure: Peach house; Greenhouses Location: Manor House, Alton, Hampshire Client: Henry Hall; Goodwyn Hall	1899; 1908- 1914
TR MES AD1/400	Structure: Conservatory Location: Barton Mark, Winchester, Hampshire Client: James Harris	1898
TR MES AD1/436	Structure: Conservatory Location: Swanmore Cottage, Bishops Waltham, Hampshire Client: Charles R. Gunner	1898
TR MES AD1/476	Structure: Vinery Location: 6 Wingfield Villas, Mannamead, Plymouth, Hampshire Client: Mr Goulding	1896
TR MES AD1/484	Structure: Heating apparatus Location: The Hundred, Romsey, Hampshire Client: Mr Short per Messr. Golding and Son [Builders]	1892
TR MES AD1/488	Structure: Rose house Location: Tothill Nurseries, Plymouth, Hampshire Client: Amos Groombridge	1904

TR MES AD1/502	Structure: Conservatory Location: Keverstone Court, Manor Road, Bournemouth, Hampshire Client: W.E. Gibb per Samuel S. Dottridge [Architect]	1902
TR MES AD1/505	Structure: Conservatory Location: The Friary, Southgate Road, Winchester, Hampshire Client: Rev. Canon Furneaux	1900
TR MES AD1/506	Structure: Heating apparatus Location: 2 St Peters Terrace, Bournemouth, Hampshire Client: J.F. Fogerty	1900
TR MES AD1/624	Structure: Greenhouse Location: Blackbridge House, Winchester, Hampshire Client: Col. F.A. Dickens	1899
TR MES AD1/667	Structure: Glasshouse Location: Dodwell Lodge, Bursledon, Southampton, Hampshire Client: Lieut. C.D. Eden, R.N.	1892
TR MES AD1/739	Structure: Greenhouse Location: Nately Hill, Hook, Hampshire Client: Mrs Frederica Cahen	1904
TR MES AD1/763	Structure: Peach houses; Vinery and melon house; Carnation and plant house Location: Embley Park, Romsey, Hampshire Client: Major Spencer Chichester	1897; 1900; 1914
TR MES AD1/864	Structure: Glasshouse Location: Botley, Hampshire Client: William J.C. Bailey [Builder]	1895
TR MES AD1/866	Structure: Conservatory and greenhouse Location: Mannamead, Plymouth, Hampshire Client: J.A. Bellamy	1899
TR MES AD1/869	Structure: Vinery Location: 5 Fairfield Terrace, Denville Estate, Havant, Southampton, Hampshire Client: Mrs Barnes	1892
TR MES AD1/872	Structure: Conservatory and boiler house Location: Amberwood, Christchurch, Hampshire Client: Mrs Braddyll	1889
TR MES AD1/873	Structure: Stove and vinery; Fruit house; Plant house Location: Fairthorne, Botley, Hampshire Client: Miss Burrell	1894; 1895; 1896
TR MES AD1/901	Structure: Greenhouse; Greenhouse; Plant house Location: The College, Winchester, Hampshire Client: Rev. Dr Hubert Burge and Mrs Burge	1901; 1906; 1910
TR MES AD1/919	Structure: Conservatory; Greenhouse Location: Fyfyde, Winchester, Hampshire Client: Frederick Bowker	1900; 1925
TR MES AD1/970	Structure: Conservatory Location: Snakemoor, Botley, Hampshire Client: Edward B. Bernard	1891
TR MES AD1/977	Structure: Heating apparatus Location: Red Rice, Andover, Hampshire Client: Thomas Best	1903

TR MES AD1/1051 [2 of 4 packets]	Structure: Boiler Location: H.M. Dockyard, Portsmouth, Hampshire Client: H.M. Admiralty	1915
TR MES AD1/1051 [4 of 4 packets]	Structure: Conservatory Location: Whale Island, Portsmouth, Hampshire Client: H.M. Admiralty	1897
TR MES AD1/1096	Structure: Greenhouse; Wall cover Location: Hurstbourne Priors, near Whitchurch, Hampshire Client: Peter Williams	1903; 1905
TR MES AD1/1108	Structure: Glasshouse Location: Priestlands, near Lymington, Hampshire Client: Major Blunt per Wilfred T. Wire [Architect]	1906
TR MES AD1/1150	Structure: Reglazing roof Location: Winchester, Hampshire Corn Exchange, Winchester, Hampshire Client: Walter Bailey [Solicitor]	1902
TR MES AD1/1204	Structure: Roof house; Greenhouse Location: Grayshott Court, Liphook, Hampshire Client: Charles Erskine Vertue; Miss Vertue	1894; 1907
TR MES AD1/1236	Structure: Conservatory Location: Oakcroft, Fareham, Hampshire Client: W.J. Wilson, MD	1894
TR MES AD1/1272	Structure: Glasshouse Location: Whin-hurst, Hayling Island, Havant, Hampshire Client: John Glas Sanderman	1902
TR MES AD1/1335	Structure: Stove house Location: The Wakes, Selbourne, Hampshire Client: F.M. Read	1892
TR MES AD1/1354	Structure: Plant house Location: Weyhill, Andover, Hampshire Client: Capt. W. Smith	1901
TR MES AD1/1381	Structure: Vineries and plant house Location: Belmont Park, Havant, Hampshire Client: Mrs R.J. Snell	1905
TR MES AD1/1448	Structure: Conservatory Location: Solent Cottage, near Southampton, Hampshire Client: Lord Scarborough	1895
TR MES AD1/1455	Structure: Vinery, Cucumber house, and greenhouses Location: The Lodge, Cosham, Hampshire Client: Col. C.L. Reynolds	1889
TR MES AD1/1470	Structure: Plant house; Greenhouse Location: Holmesland, Botley, Hampshire Client: Admiral Rowley	1898; 1899
TR MES AD1/1472	Structure: Heating apparatus Location: The Orchard, Crofton, Lee-on-Solent, Hampshire Client: Matthew William Rowles [Builder]	1896
TR MES AD1/1563	Structure: Vinery Location: Wainsford, Lymington, Hampshire Client: E. Powell King per W. Parton	1900
TR MES AD1/1580	Structure: Forcing house Location: Anthony House, Devonport, Hampshire Client: Col. Reginald Pole Carew, CB	1897

TR MES AD1/1664	Structure: Heating apparatus Location: Sherfield Manor, Basingstoke, Hampshire Client: J.B. Taylor	1900
TR MES AD1/1709	Structure: Stove, Vinery, Plant house and Potting house Location: Belvedere, Seymour Road, Mannamead, Plymouth, Hampshire Client: H. Tucker	1896
TR MES AD1/1723	Structure: Heating apparatus for house and chapel Location: Tichborne Hall, Alresford, Hampshire Client: Sir Henry Tichborne	1888
TR MES AD1/1840 [1 of 2 packets]	Structure: Greenhouses Location: Manor House, Bishopstoke, Hampshire Client: R.W. Bourne	1906
TR MES AD1/1840 [2 of 2 packets]	Structure: Greenhouses [Mainly referring to court case] Location: Manor House, Bishopstoke, Hampshire Client: R.W. Bourne	1906
TR MES AD1/1847	Structure: Vinery, mushroom house, plant house and stove house Location: Grayshott Hall, Liphook, Hampshire Client: A. Ingham Whitaker	1891
TR MES AD1/1858	Structure: Stove house; Heating apparatus Location: Hurstbourne Park, near Whitchurch, Hampshire Client: Earl of Portsmouth	1901; 1907
TR MES AD1/1904	Structure: Greenhouse; Repairs to greenhouse; Boiler Location: Chawton House, Alton, Hampshire Client: Montague G. Knight; Lt. Col. L.C.E Knight	1908; 1910; 1927
TR MES AD1/1920	Structure: New roof to vinery; Greenhouse; Painting Location: The Elms, Twyford, Winchester, Hampshire Client: Vice Admiral J.C. Burnell	1909; 1912; 1920
TR MES AD1/1927	Structure: Glasshouses Location: Red Lodge, Bassett, Hampshire Client: A.F. Fynn	1908
TR MES AD1/1955	Structure: Greenhouse; Heating apparatus Location: Twyford Lodge, Winchester, Hampshire Client: Alexander P. Ralli	1908; 1909

Records of Properties in Herefordshire

TR MES AD1/375	Structure: Pit and heating apparatus Location: Haffield, Ledbury, Herefordshire Client: Dr W.C. Henry	1891
TR MES AD1/804	Structure: Range Location: Garnons, Hereford, Herefordshire Client: Capt. Sir John Cotterell	1898
TR MES AD1/947 See also TR MES AD1/1529	Structure: Greenhouses Location: Bishopswood, Ross, Herefordshire Client: James Murray Bannerman	1896
TR MES AD1/1007	Structure: Greenhouse Location: Ridgebourne, Kington, Herefordshire Client: Mrs Banks	1902
TR MES AD1/1008 [3 packets]	Structure: Conservatory; Repairs Location: Hergest Croft, Kington, Herefordshire Client: W.H. Banks	1899; 1911
TR MES AD1/1293	Structure: Plant house and vinery Location: Kentchurch Court, Pontrilas, Herefordshire Client: G. Lee Morris	1890
TR MES AD1/1395	Structure: Conservatory Location: Kynaston House, Ross, Herefordshire Client: H.L. Lutwyche per W.H. Smith [Builder]	1890
TR MES AD1/1529	Structure: Conservatory Location: The Coppice, Ross, Herefordshire Client: Capt. W. Partridge	1897
TR MES AD1/1529 See also TR MES AD1/947	Structure: Vineries, stove, peach house and pits Location: Bishops Wood, Ross-on-Wye, Herefordshire Client: Capt. W. Partridge	1895
TR MES AD1/1557	Structure: Vinery Location: Rocklands, Goodrich, Ross-on-Wye, Herefordshire Client: Admiral Pearson	1901
TR MES AD1/1568	Structure: Stove Location: West Hill, Ledbury, Herefordshire Client: L.H. Palairt	1891
TR MES AD1/1661	Structure: Heating apparatus Location: Broadward Hall, Leintwardine, Herefordshire Client: Marquis de Biddlecope per T. Overton and Son	1892
TR MES AD1/1843	Structure: Conservatory, vineries, plant house and others Location: Weston Lodge, Weston-under-Penyard, Ross, Herefordshire Client: John Gabbittas	1907
TR MES AD1/1887	Structure: Glasshouse Location: Titley Vicarage, Leominster, Herefordshire Client: Rev. W. Oswald Wait	1908
TR MES AD1/1899	Structure: Greenhouse and Stages Location: The Hall, Brampton Bryan RSO, Herefordshire Client: Joseph Shaw	1908

Records of Properties in Hertfordshire

TR MES AD1/99	Structure: Greenhouse Location: Sunnyside, Potters Bar, Hertfordshire Client: A. Marshall	1893
TR MES AD1/275	Structure: Conservatory Location: The Manor, Little Berkhamstead, Hertfordshire Client: C. Hanbury	1903
TR MES AD1/282	Structure: Conservatory Location: Oakdene, New Barnet, Hertfordshire Client: C. Honeywill	1912
TR MES AD1/282	Structure: Conservatory Location: Cedardale, Richmond Road, New Barnet, Hertfordshire Client: C. Honeywill	1903
TR MES AD1/318	Structure: Greenhouse Location: Ware, Hertfordshire Client: Thomas Hunt	1895
TR MES AD1/350	Structure: Heating apparatus; Vineries Location: Stagenhoe Park, Welwyn, Hertfordshire Client: W. Bailey Hawkins	1895; 1906
TR MES AD1/378	Structure: Conservatory Location: Goddington, Chelsfield, Orpington, Hertfordshire Client: A. Miller Hallett	1892-1894
TR MES AD1/396	Structure: Conservatory Location: The Hoo, Welwyn, Hertfordshire Client: Viscount Hampden	1894
TR MES AD1/447	Structure: Heating apparatus Location: Beaumont Manor, Cheshunt, Hertfordshire Client: G.F.H. Grant [Formerly T.J. Fisher]	1900
TR MES AD1/616	Structure: Plant house Location: The Priory, Royston, Hertfordshire Client: Lady Dacre	1891
TR MES AD1/662	Structure: Glasshouse Location: Frogmore, Rickmansworth, Hertfordshire Client: Allan Edwards	1897-1898
TR MES AD1/704	Structure: Painting and heating of greenhouses and vinery Location: Chipperfield House, Kings Langley, Hertfordshire Client: Sands Clayton	1890
TR MES AD1/733	Structure: Heating apparatus for stables/Coach House Location: Ponsbourne Park, Hertfordshire Client: J.W. Carlisle	1897
TR MES AD1/791	Structure: Plant house Location: Bushey House, Bushey, Hertfordshire Client: E.H. Cuthbertson	1900
TR MES AD1/812	Structure: Heating apparatus Location: Watford, Hertfordshire Client: Clifford and Gough [Contractors]	1894
TR MES AD1/857 [1, 3 and 6 of 6 packets]	Structure: Refitting of house including heating Location: Wilcroft, Hertford, Hertfordshire Client: A.W.N. Burder	1901-1903
TR MES AD1/903	Structure: Heating apparatus Location: Brent Pelham Hall, Buntingford, Hertfordshire Client: Edward E. Barclay	1904

TR MES AD1/1060	Structure: Plant house Location: Willow Grange, Church Road, Watford, Hertfordshire Client: F. Armstrong	1901
TR MES AD1/1133	Structure: Painting, plant house Location: Laurel Lodge, Dancers Hill, Barnet, Hertfordshire Client: H.A. Whateley	1898
TR MES AD1/1379	Structure: Glasshouse Location: Walton Lodge, Broxbourne, Hertfordshire Client: C. Simpson	1905
TR MES AD1/1382	Structure: Tomato house Location: Sparrows Herve Hall, Bushey Heath, Hertfordshire Client: J. Walter Smith	1906
TR MES AD1/1495	Structure: Conservatory and plant house Location: Lynwood, Totteridge Lane, Totteridge, Hertfordshire Client: F.R. Reeves	1901
TR MES AD1/1519	Structure: Conservatory Location: Highfield, Stevenage, Hertfordshire Client: C. Poston	1899
TR MES AD1/1619	Structure: Plant house and stove Location: Cobden Hill, Radlett, Hertfordshire Client: R.S. Phillimore	1899
TR MES AD1/1722	Structure: Conservatory Location: Greenhill Park, New Barnet, Hertfordshire Client: Mrs Twentyman	1893
TR MES AD1/1760	Structure: Plant house Location: The Nook, Croxley Green RSO, Hertfordshire Client: C. Biegel	1907
TR MES AD1/1781	Structure: Plant house and stove Location: Kneesworth Hall, Royston, Hertfordshire Client: Lady Mary Holland	1906
TR MES AD1/1791 [1 of 2 packets]	Structure: Forcing, rose, plant and carnation houses Location: Hilfield Park, Aldenham, Hertfordshire Client: E. Guy Ridpath [Tenant] per Lord Aldenham [Landlord]	1912
TR MES AD1/1791 [2 of 2 packets]	Structure: Greenhouse Location: Hilfield Park, Aldenham, Hertfordshire Client: Sir Henry Bargrave Deane [Tenant] per Right Hon. Lord Aldenham [Landlord]	1907
TR MES AD1/1867	Structure: Frame Location: Abbots Hill, Hemel Hempstead, Hertfordshire Client: H.E. Hooper per W. Baldwin	1901
TR MES AD1/1895	Structure: Conservatory Location: Marshalls, Ware, Hertfordshire Client: R. McLeake	1908
TR MES AD1/1915	Structure: Greenhouse Location: Stansted Bury, Ware, Hertfordshire Client: Spencer Trower per Ernest Clarke [Builder]	1908

Records of Properties on the Isles of Wight and Man

TR MES AD1/246	Structure: Conservatory and heating apparatus Location: Windcliffe, Niton, Isle of Wight Client: R.Temple G. Kirkpatrick	1901
TR MES AD1/1320	Structure: Vinery; Greenhouse; Repairs Location: Thorncliffe, Niton-under-Cliff, Isle Of Wight Client: S.H. Schmitz; Theodore John Hubert Schmitz	1896; 1923; 1924
TR MES AD1/1824	Structure: Greenhouse Location: Ballamoar, Isle Of Man Client: Mr Curphey per Harry Crickmay [Architect]	1906

Records of Properties in Kent

TR MES AD1/81	Structure: Heating apparatus Location: The Hut, Birchington-on-sea, Kent Client: W. Macnamara	1898
TR MES AD1/86	Structure: Orchid house Location: 10 Radnor Park West, Folkestone, Kent Client: E. Sutcliffe per J.A. Mitchell [Florist]	1904
TR MES AD1/124	Structure: Cucumber and Melon houses Location: Wickham Hall, West Wickham, Beckenham, Kent Client: G. Mellin	1897
TR MES AD1/134	Structure: Glass house Location: The Willows, Wickhambreaux near Dover, Kent Client: John G. Meiggs	1891
TR MES AD1/217	Structure: Greenhouse Location: "Invergloy", Grasmere Road, Bromley, Kent Client: G/C.H. Kenning	1894
TR MES AD1/234	Structure: Vineries and repainting greenhouses Location: Shoreham Place, Shoreham, Sevenoaks, Kent Client: Sir Henry James	1894
TR MES AD1/261	Structure: Stove and porch; Plant house Location: Broomsleigh, Seal Chart, Sevenoaks, Kent Client: Thomas Johnson	1886; 1894
TR MES AD1/264	Structure: Conservatory Location: Mountains, Tonbridge, Kent Client: J.H. Johnson	1889
TR MES AD1/285 See also TR MES AD1/261	Structure: Heating apparatus Location: Broomsleigh, Seal Chart, Sevenoaks, Kent Client: H.A. Hooker	1902; 1909
TR MES AD1/315	Structure: Plant house; Orchid house Location: Oakfield Cottage, Dartford Heath, Kent Client: J.G. Hepburn	1899; 1903
TR MES AD1/382	Structure: Plant house Location: Margate Cemetary, Kent Client: R.A. Harris [Architect]	1903-1904
TR MES AD1/431	Structure: Porch Location: Bridgewater Villa, Margate, Kent Client: Robert A. Harris	1898
TR MES AD1/549	Structure: Plant house Location: Broomfield, Yalding, Maidstone, Kent Client: Charles E. Fletcher	1905
TR MES AD1/613	Structure: Glasshouses Location: Swaylands, Tonbridge, Kent Client: G.J. Drummond per Hope Constable [Builder]	1898
TR MES AD1/620	Structure: Forcing house and vineries Location: Cramore Place, Chislehurst, Kent Client: J. Dewrance	1901
TR MES AD1/638	Structure: Conservatory Location: Heather Bank, Carlton Road, Tunbridge Wells, Kent Client: George Evans	1889
TR MES AD1/645	Structure: Greenhouse Location: Woodlands, Sevenoaks, Kent Client: Mrs Ellerton	1889

TR MES AD1/690	Structure: Plant house Location: Avey South Hill, Bromley, Kent Client: Kenneth E. Chalmers	1899-1900
TR MES AD1/691	Structure: Heating apparatus for cells Location: Chislehurst Police Station, Kent Client: Wiltshire and Son [Builders]	1893
TR MES AD1/698 [See also TR MES AD1/613]	Structure: Vinery Location: Penshurst, Tonbridge, Kent Client: Mr Hope Constable [Builder]	1902-1903
TR MES AD1/703 [2 packets]	Structure: Plant House Location: Highfield, Shoreham, Sevenoaks, Kent Client: Benjamin L. Cohen, MP and Louisa E. Cohen	1898
TR MES AD1/705	Structure: Conservatory Location: Kent Lodge, Sidcup, Kent Client: W. T. Crossweller	1898
TR MES AD1/761	Structure:Camelia House, improvements to vinery and pits Location: Ospringe House, Faversham, Kent Client: Mrs Carter	1893
TR MES AD1/798	Structure: Alterations to verandah Location: Hackwood, Widmore Road, Bromley, Kent Client: E. Clark	1898
TR MES AD1/843	Structure: Greenhouse Location: Lindfield Lodge, Folkestone, Kent Client: Col. R.A. Blane	1889
TR MES AD1/844	Structure: Greenhouse Location: Borstal Road, Rochester, Kent Client: C. Willis per F. Braby and Co	1888
TR MES AD1/933	Structure: Greenhouses Location: Brook Fever Hospital, Shooters Hill, Kent Client: Metropolitan Asylums Board	1896
TR MES AD1/993	Structure: Conservatory Location: Garth, Broadstairs, Kent Client: B. Beech	1896
TR MES AD1/1010	Structure: Conservatory Location: Powerscourt, Beckenham, Kent Client: L.E.G. Bryan	1904
TR MES AD1/1050	Structure: Glasshouses Location: Malling Place, West Malling, Kent Client: James Adams	1902
TR MES AD1/1051 [2 of 4 packets]	Structure: Huts Location: H.M. Dockyard, Chatham, Kent Client: H.M. Admiralty	1914
TR MES AD1/1051 [1 and 3 of 4 packets]	Structure: Garage; Hut Location: R.N. Aviation Depot, Kingsnorth, Kent Client: H.M. Admiralty	1915
TR MES AD1/1051 [4 of 4 packets]	Structure: Vinery, plant house and pits Location: Commander-in-chief's residence, H.M. Docks, Chatham, Kent Client: H.M. Admiralty	1906
TR MES AD1/1054	Structure: Heating apparatus Location:Melrose, Knockholt, Kent Client: J. Airey	1899

TR MES AD1/1122	Structure: Covered way from billiard room to conservatory Location: Etherton Hall, Speldhurst, Tunbridge Wells, Kent Client: E.W. Winter	1896
TR MES AD1/1139	Structure: Peach cover Location: Hurstled, Sevenoaks, Kent Client: Mr Humphreys per Wiltshire and Sons [Builders]	1900
TR MES AD1/1188	Structure: Palm house, plant house, potting shed and vinery; Heating apparatus Location: The Cedars, Chislehurst Common, Kent Client: W. Willett	1897
TR MES AD1/1190	Structure: Forcing house Location: Holcombe, Chatham, Kent Client: George Wrinch	1896
TR MES AD1/1316 [2 packets]	Structure: Plant house; Carnation houses and repairs; Summer house Location: Woodside, South Hill Park, Bromley, Kent Client: H.W. Symondson	1906; 1916-1923; 1924
TR MES AD1/1326	Structure: Plant house Location: Seabrook Hotel, Hythe, Kent Client: South Eastern Railway Company	1899
TR MES AD1/1340	Structure: Stove house, muscat vinery, peach hosue and vinery Location: The Friars, Matfield Green, Paddock Wood, Kent Client: D'Arcy Reeve	1895
TR MES AD1/1457 [2 of 6 packets]	Structure: Vinery and orchid house Location: Camden Holt, Chislehurst, Kent Client: F.A. Robinson	1897
TR MES AD1/1457 [1, 3 and 4 of 6 packets]	Structure: Conservatory and verandah Location: Camden Holt, Chislehurst, Kent Client: F.A. Robinson	1896
TR MES AD1/1457 [5 and 6 of 6 packets]	Structure: Rebuilding glasshouses Location: Camden Holt, Chislehurst, Kent Client: Evan Spicer	1930
TR MES AD1/1458	Structure: Conservatory Location: St Peters Vicarage, Tunbridge Wells, Kent Client: Rev. Joseph Rogers	1887
TR MES AD1/1492	Structure: Melon, Cucumber and plant houses Location: 24 Darnley Road, Gravesend, Kent Client: W. Russell	1898
TR MES AD1/1540	Structure: Plant and forcing house Location: Lynton, Vine Road, Sevenoaks, Kent Client: George S. Pinchin	1903
TR MES AD1/1550	Structure: Stove house Location: Oakwood, Chislehurst, Kent Client: R. de Q. Quincey	1901
TR MES AD1/1551 [1 of 2 packets]	Structure: Greenhouse Location: Inglewood, Chislehurst, Kent Client: Richard De Q. Quincey	1899
TR MES AD1/1560	Structure: Conservatory and verandah Location: 7 Elderslie Road, Eltham, Kent Client: A. Parker	1902
TR MES AD1/1611	Structure: Forcing house; Greenhouse Location: Mountfield, Faversham, Kent Client: F.G. Oliver	1899; 1900

TR MES AD1/1645 [2 of 2 packets]	Structure: Conservatory and corridor Location: Osbourne Lodge, Cranbrook, Kent Client: W. West Neve [Architect]	1902
TR MES AD1/1646 See also TR MES AD1/1645	Structure: Greenhouse Location: Osbourne Lodge, Cranbrook, Kent Client: Miss West Neve	1905
TR MES AD1/1659	Structure: Glasshouses Location: Avon House, Gordon Road, Tunbridge Wells, Kent Client: Miss Nix	1896
TR MES AD1/1711	Structure: Peach and plant house Location: Heatherton, Pembury, Tunbridge Wells, Kent Client: J. Thompson and Co. [Builders]	1903
TR MES AD1/1767	Structure: Glasshouses Location: St. Clere, Kemsing, Kent Client: Sir Mark Collett, Bart.	1907
TR MES AD1/1796	Structure: Conservatory Location: Milestone House, Staplehurst, Kent Client: Mr White per J.W. Wickings [Builder]	1907
TR MES AD1/1804	Structure: Peach house, vinery and other glasshouses; Boiler Location: Lewins Court, Crockham Hill, Edenbridge, Kent Client: George Ing; S.D. Gladstone	1905; 1938
TR MES AD1/1826	Structure: Peach house; Vinery, plant house and pits Location: Elmstone Court, Preston, Dover, Kent Client: C.W. Firebrace	1907; 1908
TR MES AD1/1834	Structure: Plant house Location: Eccleshill, Hayes Lane, Bromley, Kent Client: C. Douglas Clark	1906
TR MES AD1/1844	Structure: Greenhouse Location: Crockham Hill, Edenbridge, Kent Client: Dr. H. Philpot	1907
TR MES AD1/1888	Structure: Glasshouses and pits Location: The Phillipines, Brasted Chart, Kent Client: William Willis	1906
TR MES AD1/1893	Structure: Greenhouse Location: White's Farm, Goudhurst, Kent Client: W. Louis Lucas [Architect]	1907
TR MES AD1/1903	Structure: Heating apparatus Location: Holly Dene, Bromley, Kent Client: Henry Kent [Builder]	1908
TR MES AD1/1914	Structure: Heating apparatus Location: Caves Oriental Café, Northdown Road, Margate, Kent Client: Ernest E. Moody [Architect]	1907
TR MES AD1/1940	Structure: Conservatory Location: Surrenden, Staplehurst, Kent Client: Mrs Nicholson	1908
TR MES AD1/1943	Structure: Plant house Location: Scriventon, Speldhurst, Tunbridge Wells, Kent Client: J.T. Marsh	1908
TR MES AD1/1951	Structure: Conservatory Location: East Malling, Kent Client: E. Pye [Buidler]	1908

TR MES AD1/1998

Structure: Heating apparatus
Location: Cliftonville Wesleyan Chapel, Margate, Kent
Client: C. Hobday [Plumber]

1896

Records of Properties in Lancashire

TR MES AD1/212	Structure: Painting Vinery and other buildings, and fitting ventilator Location: "Fern Bank", 32 Palatine Road, Withington, Manchester, Lancashire Client: George King	1902
TR MES AD1/390	Structure: Greenhouse Location: Mayfield, West Park Road, Blackburn, Lancashire Client: Miss Hoyle	1889
TR MES AD1/397	Structure: Conservatory Location: Holm Lea, Rainhill, Lancashire Client: Douglas Herman	1903
TR MES AD1/415	Structure: Heating apparatus Location: 17 Palatine Square, Burnley, Lancashire Client: W.M. Holmes	1888
TR MES AD1/440	Structure: Conservatory Location: Briars Hey, Rainhill, Lancashire Client: William Gamble	1900
TR MES AD1/461	Structure: Conservatory Location: Stoneywood, Victoria Park, Manchester, Lancashire Client: W. Gaddum	1889
TR MES AD1/469	Structure: Forcing house and stove house Location: Brydekirk, Parbold, near Southport, Lancashire Client: G. Graham	1902
TR MES AD1/486	Structure: Conservatory Location: Reedley Grove, near Burnley, Lancashire Client: J.R. Grimshaw	1889
TR MES AD1/539	Structure: Fernery Location: The Uplands, Whitefield, near Manchester, Lancashire Client: J.R. Fletcher	1897
TR MES AD1/657	Structure: Pit framed lights and heating apparatus Location: Standish Hall, Wigan, Lancashire Client: N. Eckersley	1890-1891
TR MES AD1/660	Structure: Boiler Location: Farington House, Preston, Lancashire Client: John Eccles	1900
TR MES AD1/756	Structure: Conservatory Location: Llangroyd, Colne, Lancashire Client: Miss Carr	1899
TR MES AD1/782	Structure: Boiler Location: 36 Corporation Street, Manchester, Lancashire Client: C.T. Chivers	1886
TR MES AD1/802	Structure: Conservatory Location: Egerton Road, Ashton on Ribble, Lancashire Client: Henry Curwen per Robert Curwen [Architect]	1892
TR MES AD1/805	Structure: Plant house and melon house; Boiler Location: Skerton, Lancaster, Lancashire Client: Miss Coulston per Messrs. Coulston and Co.	1898
TR MES AD1/845	Structure: Heating apparatus Location: Manchester, Lancashire Client: Bells Asbestos Company	1889
TR MES AD1/883 [2 and 3 of 3 packets]	Structure: Glasshouses; Conservatory Location: Eaves Hall, Clitheroe, Lancashire Client: Edward Burton; Mrs H.J. Marsland	1890; 1906

TR MES AD1/916 [2 of 2 packets]	Structure: Conservatory Location: St Mary's Gate, Lancaster, Lancashire Client: Miss Burton	1894
TR MES AD1/951	Structure: Plant house and Stove Location: Castle House, Lancaster, Lancashire Client: Thomas Barton	1891
TR MES AD1/955 [2 of 3 packets]	Structure: Glasshouses Location: Cemetary, Blackburn, Lancashire Client: Blackburn Corporation	1913
TR MES AD1/955 [2 of 3 packets]	Structure: Greenhouses Location: Queens Park, Blackburn, Lancashire Client: Blackburn Corporation	1889
TR MES AD1/955 [1 and 3 of 3 packets]	Structure: Greenhouse; Stove house; Greenhouse Location: Corporation Park, Blackburn, Lancashire Client: Blackburn Corporation	1907; 1920; 1925
TR MES AD1/955 [3 of 3 packets]	Structure: Plant drawing class room Location: Municipal Technical School, Blackburn, Lancashire Client: Blackburn Corporation	1903
TR MES AD1/1032	Structure: Glasshouses and heating apparatus; Glass porch Location: Lostock Dene, Lostock, Bolton, Lancashire Client: Frank Ainsworth	1893; 1894
TR MES AD1/1034	Structure: Rose and azalea house Location: Holcombe Hall, Ramsbottom, near Manchester, Lancashire Client: Thomas Aitken	1896
TR MES AD1/1088 [1 of 2 packets]	Structure: Peach house; Plant house; Heating apparatus Location: The Elms, Whitefield, Lancashire Client: Walter Wild	1903; 1905; 1908
TR MES AD1/1088 [2 of 2 packets]	Structure: Stove and cool house Location: The Elms, Whitefield, Lancashire Client: Walter Wild	1912
TR MES AD1/1160	Structure: Stove and greenhouse Location: Brooklands, Broughton near Preston, Lancashire Client: A. Westworth	1902
TR MES AD1/1161 [1 of 2 packets]	Structure: Rebuilding stove house; Ventilation and conservatory roof repairs Location: Chesham, Bury, Lancashire Client: The Misses Walker	1927; 1940
TR MES AD1/1161 [2 of 2 packets]	Structure: Plant house; Conservatory; Vinery; Glasshouse Location: Chesham, Bury, Lancashire Client: Col. O. Ormrod Walker	1899; 1901; 1904; 1910
TR MES AD1/1174	Structure: Greenhouse Location: Moss Field, Pleasington, Blackburn, Lancashire Client: John F. Wilding	1886
TR MES AD1/1191	Structure: Greenhouse Location: Victoria Road, Morecambe, Lancashire Client: G. Willson	1887
TR MES AD1/1327	Structure: Forcing house Location: Priors Lea, Broughton near Preston, Lancashire Client: B. Sykes	1899
TR MES AD1/1345	Structure: Conservatory, stove, porch and orchid house Location: Beardwood, Blackburn, Lancashire Client: John Rutherford, MP	1896
TR MES AD1/1366	Structure: Heating apparatus Location: John O'Gaunts Gate, Lancaster, Lancashire Client: Shrigley and Hunt	1896

TR MES AD1/1386	Structure: Greenhouse Location: Entwistle, Bolton, Lancashire Client: William Simpson per Simpson and Godlee	1892
TR MES AD1/1411	Structure: Vinery, forcing house, conservatory Location: Turfcote, Helmshore, Haslingden, Lancashire Client: W.H. Smith	1894
TR MES AD1/1443	Structure: Greenhouse Location: Church Works, Church, Lancashire Client: F. Steiner and Co	1902
TR MES AD1/1480	Structure: Glasshouses Location: Quarry Glen, Blackburn, Lancashire Client: T.P. Ritzema, JP	1899
TR MES AD1/1491	Structure: Winter garden Location: Longford Hall, Manchester, Lancashire Client: Mrs Rylands	1892
TR MES AD1/1514	Structure: Conservatory, vinery and potting house Location: Rivington, Eccles, Manchester, Lancashire Client: Alfred Pilkington	1890
TR MES AD1/1554	Structure: Glasshouses Location: Winston Hall, East Park Road, Blackburn, Lancashire Client: Rev. James Pickop	1903
TR MES AD1/1586 [1 of 4 packets]	Structure: North house Location: Rainford Hall, St Helens, Lancashire Client: Mrs Richard Pilkington	1912
TR MES AD1/1586 [2 of 4 packets]	Structure: Rose house and rearrangement of greenhouses Location: Rainford Hall, St Helens, Lancashire Client: Mrs Richard Pilkington	1898
TR MES AD1/1586 [3 of 4 packets]	Structure: Rebuilding peach and stove house Location: Rainford Hall, St Helens, Lancashire Client: Mrs Richard Pilkington	1935
TR MES AD1/1586 [4 of 4 packets]	Structure: Heating apparatus; Lean to frames Location: Rainford Hall, St Helens, Lancashire Client: Mrs Richard Pilkington	1911; 1930
TR MES AD1/1725	Structure: Vinery Location: Old Hall, Morecambe, Lancashire Client: W. Telley	1890
TR MES AD1/1735	Structure: Conservatory Location: Crookleigh, Furness Road, Morecambe, Lancashire Client: Frederick W. Tattersall	1900
TR MES AD1/1810	Structure: Greenhouse; Boiler Location: Chamber House, Marland near Rochdale, Lancashire Client: Charles F. Robinson	1907; 1908
TR MES AD1/1885	Structure: Conservatory and forcing house; Greenhouse Location: The Holt, Barnacre, Garstang, Lancashire Client: Charles J. Winder	1908; 1919
TR MES AD1/1952 [2 packets]	Structure: Conservatory and propagating houses Location: Alexandra Park, Oldham, Lancashire Client: Oldham Corporation per Borough Surveyor	1906

Records of Properties in Leicestershire

TR MES AD1/267	Structure: Greenhouse Location: The Old Hall, Rearsby, Leicestershire Client: Major Campbell Johnson	1905
TR MES AD1/294	Structure: Plant house; Additions to greenhouse Location: Manor House, Overseal, Ashby de la Zouch, Leicestershire Client: John Hall	1894; 1902
TR MES AD1/394	Structure: Renewing glasshouses Location: Finney Spring, Shepshed, Leicestershire Client: S. Tebbutt per Reginald J. Hill	1898
TR MES AD1/421	Structure: Conservatory Location: The Elms, Thorpe Satchville, near Melton Mowbray, Leicestershire Client: G.W. Hillyard	1899
TR MES AD1/438	Structure: Boiler Location: Victoria Works, Syston near Leicester, Leicestershire Client: H. Garner and Sons	1916
TR MES AD1/501	Structure: Heating apparatus Location: Forest House, Shepshed, Loughborough, Leicestershire Client: H.H. Gibbs	1904
TR MES AD1/517	Structure: Greenhouse Location: Catthorpe Hall, Catthorpe near Rugby, Leicestershire Client: W. Foster per Foster and Dicksie [Contractors]	1901
TR MES AD1/544	Structure: Re-heating Vineries Location: The Coplow, Billesdon, Leicestershire Client: Rev. C.R. Fowke	1898
TR MES AD1/743	Structure: Glasshouse Location: Westcotes Lodge, Ashleigh Road, Leicester, Leicestershire Client: J.G. Chattaway	1896-1897
TR MES AD1/803	Structure: Conservatory Location: The Old House, Queniborough, Syston, Leicestershire Client: Thomas Cawdell	1901
TR MES AD1/865 [1 of 2 packets]	Structure: Heating apparatus Location: Barkby Hall, near Syston, Leicestershire Client: Thomas Brooks	1888
TR MES AD1/865 [2 of 2 packets]	Structure: Plant house Location: Barkby Hall, near Syston, Leicestershire Client: Thomas Brooks	1899

TR MES AD1/956	Structure: Heating apparatus Location: Barrow on Soar Liberal [and Labour and Institute] Club, Melton Road, Barrow on Soar, Leicestershire Client: Mr Bennett and H. Jacques[Club Secretaries]	1904; 1929
TR MES AD1/1078 [1 of 2 packets]	Structure: Greenhouse; Cold frames Location: One Ash, Woodthorpe, near Loughborough, Leicestershire Client: A.C. Faire	1931; 1934
TR MES AD1/1078 [2 of 2 packets]	Structure: Stove and plant house; Boiler Location: One Ash, Woodthorpe, near Loughborough, Leicestershire Client: William Wright	1899; 1918
TR MES AD1/1094	Structure: Heating residence Location: The Manor House, Cossington, Leicestershire Client: G.H. Woolley	1903
TR MES AD1/1112	Structure: Conservatory; Glazed stoker Location: Highlands, Stoneygate Avenue, Knighton, Leicestershire Client: E.G. Ward	1901; 1907
TR MES AD1/1144	Structure: Heating apparatus Location: Garage on Derby Road, Loughborough, Leicestershire Client: Midland Brewery Company	1924
TR MES AD1/1144	Structure: Glass roof to passage Location: Greyhound Hotel [Midland Brewery], Nottingham Road, Loughborough, Leicestershire Client: E.H. Warner	1897
TR MES AD1/1270	Structure: Hot house;Boiler; Heating apparatus Location: Burton Hall, Loughborough, Leicestershire Client: Lord Seymour; Duke of Somerset; Right Hon. Earl of Huntingdon	1892; 1921; 1928
TR MES AD1/1301	Structure: Plant house Location: Ivy Dene, Wanlip Road, Syston, Leicestershire Client: J.W. Smith	1904
TR MES AD1/1310	Structure: Heating apparatus Location: Shepshed, near Loughborough, Leicestershire Client: Shepshed Conservative Club	1904
TR MES AD1/1311	Structure: Conservatory Location: Hoton, Loughborough, Leicestershire Client: Frederick Clarke per Mr Spencer	1893
TR MES AD1/1347	Structure: Plant house Location: Barrow on Soar, Leicestershire Client: Montagu Stone	1901
TR MES AD1/1384	Structure: Conservatory and plant house Location: Springfield Road, Leicester, Leicestershire Client: W.H. Stevens	1890

TR MES AD1/1384	Structure: Greenhouses; Peach house Location: Nether Close, Stoughton Drive, Oadby Road, Leicester, Leicestershire Client: W.H. Stevens	1902; 1907
TR MES AD1/1469	Structure: Conservatory Location: Queniborough Hall, Syston, Leicestershire Client: Herbert W. Reynolds	1902
TR MES AD1/1539	Structure: Greenhouse Location: Oadby Road, Leicester, Leicestershire Client: M.H. Pearson	1903
TR MES AD1/1574	Structure: Plant house Location: Humberstone Hall, Leicester, Leicestershire Client: Mrs Thompson [Tenant] per Mrs Guy Paget	1898
TR MES AD1/1823	Structure: Melon house and pit Location: Abbots Oak, Whitwick, Leicestershire Client: Lady Joyce	1906
TR MES AD1/1997	Structure: Heating apparatus Location: Copt Oak Church, Leicestershire Client: T. and H. Herbert [Builders]	1889

Records of Properties in Lincolnshire

TR MES AD1/193	Structure: Greenhouse boiler Location: The White House, Barrowby, Grantham, Lincolnshire Client: T.G. Jackson	1919
TR MES AD1/193	Structure: Conservatory; Plant house Location: Welby, Grantham, Lincolnshire Client: T.G. Jackson	1905; 1909
TR MES AD1/197	Structure: Heating apparatus for greenhouse Location: 17 Spring Gardens, Spalding, Lincolnshire Client: W. Jepson	1904
TR MES AD1/231	Structure: Heating apparatus Location: Westgate, Sleaford, Lincolnshire Client: Gerald Knight	1895
TR MES AD1/244	Structure: Heating apparatus Location: Rauceby Asylum, M.S. House, Lincolnshire Client: Kirk, Knight and Co., Sleaford	1901
TR MES AD1/329	Structure: Conservatory Location: Laxton Park, Stamford, Lincolnshire Client: James Hornsby	1896
TR MES AD1/331	Structure: Greenhouse Location: Tumby Lawn, Boston, Lincolnshire Client: Sir H.M. Hawley, Bart	1900
TR MES AD1/380	Structure: Conservatory Location: Sunnyside, Grimsby Road, Cleethorpes, Lincolnshire Client: Mrs Hill	1903
TR MES AD1/647	Structure: Stove and plant house Location: Deeping St James Manor, Market Deeping, Lincolnshire Client: Lady Exeter	1901
TR MES AD1/809	Structure: Heating apparatus Location: Tixover Grange, Stamford, Lincolnshire Client: Lord John Pakenham Cecil	1899
TR MES AD1/855 [11 packets]	Structure: Heating apparatus and hot water supply Location: Ale Stores, Tablet Room and Joiners Shop, Kings Road, St Pancras : Dixie Ale Stores, Burton-on-Trent, Staffordshire : Shobnall Ale Stores, Staffordshire : Nags Head, Swadlincote, Staffordshire : Commercial Inn, Sleaford, Lincolnshire : Stores at Wellington Street, Hull, Yorkshire : St Chads Church, Hunter Street, Burton-on-Trent, Staffordshire : Hawkins Lane Stores, Burton-on-Trent, Staffordshire : Old Brewery, High Street, Burton-on-Trent, Staffordshire : General Offices, Kings Road, Pancras Road, London : New Loco Shed Client: Bass, Ratcliff and Gretton Ltd, Burton-on-Trent, Staffordshire	1893-1909
TR MES AD1/915	Structure: Heating apparatus Location: New Farmstead, Scartho, near Grimsby, Lincolnshire Client: Thomas Baskcomb	1903
TR MES AD1/972	Structure: Greenhouse Location: Standish House, Spilsby Road, Boston, Lincolnshire Client: John Beaulah	1893

TR MES AD1/1064	Structure: Plant house Location: 9 Barn Hill, Stamford, Lincolnshire Client: J.E. Ather	1887
TR MES AD1/1073	Structure: Vinery Location: Bainton, Stamford, Lincolnshire Client: W.C. Welby	1889
TR MES AD1/1105	Structure: Plant house Location: Thurlby Hall, Newark, Lincolnshire Client: Cecil H. Wray	1891
TR MES AD1/1131	Structure: Plant house Location: The Nuns, Stamford, Lincolnshire Client: Lieut. Col. F.A. White	1902
TR MES AD1/1177	Structure: Greenhouse and potting shed Location: Fulbeck Rectory, Grantham, Lincolnshire Client: Rev. T. Vere Willson	1894
TR MES AD1/1187	Structure: Heating apparatus Location: Trustees Primitive Methodist Chapel, West Stockwith, Gainsborough, Lincolnshire Client: James Wood	1890
TR MES AD1/1262	Structure: Plant house Location: The Elms, Sleaford Road, Boston, Lincolnshire Client: J.B. Wood	1902
TR MES AD1/1283	Structure: Conservatory Location: Manor House, Reepham, Lincolnshire Client: Mrs Wilson per Messrs Thomas Simpson and Sons	1893
TR MES AD1/1361	Structure: Tomato houses Location: Croft House, Weeby, Lincolnshire Client: F.W. Stephenson	1892
TR MES AD1/1376	Structure: Stoves and earl Vinery Location: Dudley Street, Grimsby, Lincolnshire Client: Jack Sutcliffe	1890
TR MES AD1/1390	Structure: Heating apparatus Location: Corn Exchange, Sleaford, Lincolnshire Client: F.F. Bellamy [Secretary]	1902
TR MES AD1/1431	Structure: Wall cover Location: Waltham Hall, Grimsby, Lincolnshire Client: Arthur Soames	1887
TR MES AD1/1504	Structure: Conservatory Location: Boothly Hall, Grantham, Lincolnshire Client: Rev. R.A. Walts per J.W. Rimington [Plumber]	1905
TR MES AD1/1521	Structure: Greenhouse Location: St Andrews, Stamford, Lincolnshire Client: J.H. Phillips	1889
TR MES AD1/1535	Structure: Greenhouses Location: Pier Gardens, Cleethorpes, Lincolnshire Client: Great Central Railway Co. per G.A. Pillatt	1905
TR MES AD1/1559	Structure: Heating apparatus and hot water supply Location: Westholme, Sleaford, Lincolnshire Client: H.A. Peake	1902
TR MES AD1/1782	Structure: Glasshouse; Boiler Location: Dalby Hall, Spilsby, Lincolnshire Client: B.C. Garfit; Frank Dawson	1906; 1949
TR MES AD1/1787	Structure: Renewing lobby, vinery and peach house; Carnation house and pits Location: Witham Hall, Bourne, Lincolnshire Client: Walter Fenwick	1907; 1910

TR MES AD1/1788 [5 packets]	Structure: Heating apparatus; Alterations and additions to factory heating apparatus Location: Norfolk Street, Boston, Lincolnshire Client: Fisher Clark and Co. [Printers]	1907; 1916 to 1948
TR MES AD1/1822	Structure: Conservatory; Greenhouse Location: Southland, Kingsway, Cleethorpes, Lincolnshire Client: Sir Thomas Robinson, KBE	1907; 1922
TR MES AD1/1839	Structure: Conservatory Location: Hoddenfield, Bargate, Grimsby, Lincolnshire Client: Samuel Ellis	1906
TR MES AD1/1876 [2 of 2 packets]	Structure: Heating apparatus; Forcing houses; Boiler Location: Buckminster Park, Grantham, Lincolnshire Client: Right Hon. Earl of Dysart	1909; 1911; 1930 and 1931
TR MES AD1/1921	Structure: Greenhouse Location: Sturton-by-Stow, via Lincoln, Lincolnshire Client: Thomas Blakeborough	1908
TR MES AD1/1968	Structure: Heating to founder's chapel Location: Boston Church, Boston, Lincolnshire Client: W. Samuel Weatherby [Architect]	1906
TR MES AD1/1969	Structure: Heating apparatus Location: Bracebridge Church, Lincoln, Lincolnshire Client: C. Hodgson Fowler [Architect]	1895
TR MES AD1/1984	Structure: Heating apparatus Location: St Mary's Roman Catholic Schools, Boston, Lincolnshire Client: Canon O'Donaghue per S. Sherwin and Son [Builders]	1908

Records of Properties in London

TR MES AD1/70	Structure: Plant house Location: Hartfield, Roehampton Lane, London Client: W. Austin Leigh	1900
TR MES AD1/114	Structure: Conservatory Location: Glenn, 69 Crystal Palace Park Road, London Client: M. Michaelson	1895
TR MES AD1/119	Structure: Glass House Location: 1 Green Street, Park Lane, London Client: Mathews and Rogers	1894-1900
TR MES AD1/151	Structure: Conservatory and porch Location: Northwood Lodge, Finsbury Park, London Client: J.W. Maltby	1902
TR MES AD1/156	Structure: Plant house Location: 'Gladswood', Wimbledon Common, London Client: W.E. Martyn	1898
TR MES AD1/167	Structure: Boiler Location: Bangors Park, Uxbridge Client: Tonmon Mosley	1898
TR MES AD1/176	Structure: Conservatory Location: Atterslie, 39 Lancaster Road, West Norwood, London Client: H. R. Mumford	1901
TR MES AD1/183	Structure: Conservatory Location: The Elms, Stanmore, London Client: Mr J. McDiarmid	1901
TR MES AD1/210	Structure: Greenhouse Location: Vancouver House, Forest Hill, London Client: Walter King	1906
TR MES AD1/213	Structure: Conservatory Location: Spring Lodge, Richmond Road, Twickenham, London Client: Capt. Leonard O. Kelly	1901
TR MES AD1/223	Structure: Heating apparatus Location: Albert Court Works and Wood Lane Works, London Client: Kensington and Knightsbridge Electric Lighting Company/Notting Hill Electric Company	1900
TR MES AD1/251	Structure: Conservatory Location: 5 Chartfield Road, Putney, London Client: Mrs Jackson	1901
TR MES AD1/324	Structure: Greenhouse Location: Shepherds Hill, Highgate, London Client: Frederick Hindley	1892
TR MES AD1/338	Structure: Conservatory heating apparatus Location: Ingleside, Edge Hill Road, Castle Bar, Ealing, London Client: M. Hulbert	1894-1895
TR MES AD1/339	Structure: Ventilation and lighting Location: 100a Queen Victoria Street, London Client: James Hill	1889-1890
TR MES AD1/348	Structure: Conservatory Location: Burleigh House, Belsize Lane, London Client: D.R. Harvest	1891

TR MES AD1/352	Structure: Conservatory Location: The Wilderness, Blagdons Lane, Old Southgate, London Client: P.P. Hasluck	1896
TR MES AD1/355 [4 packets]	Structure: Greenhouse; Painting of greenhouse Location: South Heath, East Heath Road, Hampstead, London Client: H. Haines	1906; 1908-1933
TR MES AD1/360	Structure: Heating apparatus Location: Hounslow Town Hall, London Client: H.G. Cresswell [Architect], T. Hiscock [Builder]	1889-1890
TR MES AD1/384	Structure: Heating apparatus Location: 52 Gower Street, Bedford Square, London Client: Miss Alice Hughes	1903-1904
TR MES AD1/388	Structure: Vinery, plant house and store Location: "Avalon", Green Lanes, Finsbury Park, London Client: G. Hand	1892-1893
TR MES AD1/409	Structure: Plant house and propagating house Location: Birnam, Castle Hill Park, Ealing, London Client: J. Henderson	1887
TR MES AD1/419 [3 Packets]	Structure: Plant house; Painting greenhouse; Repairs Location: Grove Lodge, Highgate Hill, London Client: Percival Hart	1899; 1923; 1928
TR MES AD1/422	Structure: Plant house and stove Location: Oaklands, Plumstead Common, Woolwich, London Client: E. Hughes	1898
TR MES AD1/434	Structure: Vinery and Orchid house Location: The Acorns, Oakleigh Park, London Client: J.M. Holt	1898
TR MES AD1/437	Structure: Heating apparatus Location: St Johns College, Battersea, London Client: Messrs Gregory and Co. [Builders]	1898
TR MES AD1/446	Structure: Conservatory Location: The Towers, Hillingdon, Uxbridge, London Client: Dr H.Gervis	1902
TR MES AD1/479	Structure: Greenhouses Location: 5 The Grove, Highgate, London Client: R. Gaskell	1901; 1910
TR MES AD1/482 [2 packets]	Structure: Conservatory Location: Grosvenor House, 32 Harvard Road, Gunnersbury, London Client: Robert C. Gaverick	1902
TR MES AD1/490	Structure: Conservatory Location: Redington Road, West Heath, Hampstead, London Client: Dr William Garnett	1902
TR MES AD1/500	Structure: Greenhouse Location: Aubrey House, Riverside, Twickenham, London Client: Col. Gardener	1894
TR MES AD1/525	Structure: Heating of premises Location: 78 Upper Thames Street, London Client: Robert Fletcher and sons	1896
TR MES AD1/526	Structure: Heating apparatus Location: Rifle Street, Poplar, London Client: Far Famed Cake Company	1895

TR MES AD1/535	Structure: Greenhouse Location: The Parade, White Hart Lane, Tottenham, London Client: J.B. Ferreira	1891
TR MES AD1/542	Structure: Palm house Location: Sutton Court Nursery, Chiswick, London Client: W. Fromow and Son	1894
TR MES AD1/547	Structure: Heating apparatus Location: St Marys Parish Hall, Kilburn, London Client: E.H. Francis and Son	1890
TR MES AD1/552	Structure: Greenhouse Location: Egerton, Mount Park, Harrow, London Client: Miss Forbes	1890
TR MES AD1/561	Structure: Conservatory Location: Kirkconnel, Ealing Common, London Client: Mrs Forbes per Robert Griggs [Architect]	1906
TR MES AD1/561	Structure: Fernery Location: Hazeldean, Putney Hill, London Client: Mrs J. Forbes per Robert Griggs [Architect]	1901
TR MES AD1/564	Structure: Greenhouse Location: Fountain Hospital, Grove Road, Lower Tooting, London Client: Messrs Wilson, Son & Aldwinckle [Architects]	1894
TR MES AD1/627	Structure: Heating apparatus Location: 66 Victoria Street, Westminster, London Client: Drake & Gorham	1894
TR MES AD1/674	Structure: Conservatory; Replacing roof of conservatory; Painting of greenhouses Location: Conifer Crest, Montpelier Road, Ealing, London Client: Ralph Callard	1899; 1903; 1911
TR MES AD1/674	Structure: Greenhouse Location: Lyncombe, 2 Aston Road, Ealing, London Client: Ralph Callard	1893
TR MES AD1/717	Structure: Heating apparatus Location: Town Hall and Vestry Hall, Rosebery Avenue, Clerkenwell, London Client: C. Evans-Vaughan [Architect]	1895
TR MES AD1/728	Structure: Heating apparatus Location: 76 Southwark Street, London Client: Celvicol Co.	1902
TR MES AD1/741	Structure: Greenhouse Location: Furze Bank, Queens Ride, Barnes Common, London Client: W.J. Cundall	1902-1903
TR MES AD1/764	Structure: Greenhouse Location: 6 Keswick Road, Putney, London Client: G.R. Crickmay	1891
TR MES AD1/775	Structure: Porch Location: Glaslyn, Plum Lane, Plumstead, London Client: W. Coles	1894
TR MES AD1/780	Structure: Greenhouse Location: Woodruff, 14 Corfton Road, Ealing, London Client: Charles L. Cribb	1912

TR MES AD1/780	Structure: Greenhouse Location: Savernake, Ashton Road, Ealing, London Client: Charles L. Cribb	1905
TR MES AD1/781	Structure: Conservatory Location: 21 Bedford Square, London Client: Mrs Campbell per George Clegg and Son	1899
TR MES AD1/783	Structure: Heating apparatus Location: 41 Stepney Green, London Client: Mr Charrington per W. Catmur [Plumber]	1895
TR MES AD1/787	Structure: Plant house Location: Corran, Mount Park Road, Harrow, London Client: Mrs Cater	1905
TR MES AD1/796	Structure: Glasshouse Location: Ingarsby, Edge Hill, Wimbledon, London Client: Edward Carver	1891
TR MES AD1/806	Structure: Portable Greenhouse Location: 40 Victoria Road, Kensington, London Client: Cooper and Taylor	1906
TR MES AD1/815	Structure: Glasshouses and pits Location: Moray Lodge, Campden Hill, London Client: [D.J. Pullinger] per Creaton and Co.	1903
TR MES AD1/823	Structure: Glasshouse Location: Old Mill House, Cowley, Uxbridge, London Client: Percy Caldecott	1906
TR MES AD1/825 [1 of 7 packets]	Structure: Boiler house and twin houses Location: Newton Road Nurseries, near Westbourne Grove, London Client: William Whiteley per A.M. Ridge [Architect]	1897
TR MES AD1/825 [3 to 7 of 7 packets]	Structure: Vineries, peach houses, pineries, orchid houses, plant houses, cucumber and melon houses, strawberry houses, camellia houses, carnation house and rose house; Forcing house and pits; Peach houses and vinery Location: The Nurseries, Hillingdon Heath near Uxbridge, London Client: William Whiteley per J.F. Collinson [Builder]	1890; 1890; 1895
TR MES AD1/834 [4 packets]	Structure: Vinery; Glasshouses; Orchard and peach houses; Range; Roof Location: Tewkesbury Lodge, Forest Hill, London Client: Charles Bayer	1891; 1892; 1897; 1899 1900
TR MES AD1/834 See also TR MES AD1/836	Structure: Roof; Painting roof Location: Victoria Buildings, Golden Lane, London Client: Charles Bayer per Lewis Solomon [Architect]	1898; 1899
TR MES AD1/835 [5 packets] See also TR MES AD1/834	Structure: Conservatory; Boiler; Repairs to conservatory Location: Tewkesbury Lodge/Hamilton Lodge, Honor Oak Road, Forest Hill, London Client: Herbert C. Bayer; E. Scala	1899; 1915; 1953
TR MES AD1/836 See also TR MES AD1/834	Structure: Replacing and fixing glass roof Location: Golden Lane, London Client: C. Bayer and Co	1905

TR MES AD1/855 [11 packets]	Structure: Heating apparatus and hot water supply Location: Ale Stores, Tablet Room and Joiners Shop, Kings Road, St Pancras : Dixie Ale Stores, Burton-on-Trent, Staffordshire : Shobnall Ale Stores, Staffordshire : Nags Head, Swadlincote, Staffordshire : Commercial Inn, Sleaford, Lincolnshire : Stores at Wellington Street, Hull, Yorkshire : St Chads Church, Hunter Street, Burton-on-Trent, Staffordshire : Hawkins Lane Stores, Burton-on-Trent, Staffordshire : Old Brewery, High Street, Burton-on-Trent, Staffordshire : General Offices, Kings Road, Pancras Road, London : New Loco Shed Client: Bass, Ratcliff and Gretton Ltd, Burton-on-Trent, Staffordshire	1893-1909
TR MES AD1/858	Structure: Greenhouses Location: Elm Croft, Hornsey Lane, Highgate, London Client: H.H. Barratt	1894
TR MES AD1/860	Structure: Heating for workshop Location: Hythe Road, Willesden Junction, London Client: The British Incandescent Electric Lamp Company	1898-1901
TR MES AD1/884	Structure: Greenhouse Location: Cannon Hill, Old Southgate, London Client: H.M. Bourne	1900
TR MES AD1/906	Structure: Boiler Location: Tudor House, West Hill Road, Wandsworth, London Client: R.L. Burrows	1891
TR MES AD1/907	Structure: Greenhouse Location: 168 Claremont Road, Forest Gate, London Client: E. Bluemel	1900
TR MES AD1/924	Structure: Glasshouse Location: Duncross, Shepherds Hill, Highgate, London Client: W. Balden	1906
TR MES AD1/931	Structure: Greenhouses Location: Roundhill House, Sydenham, London Client: A.H.J. Boass	1894
TR MES AD1/966	Structure: Glasshouse Location: Stambourne, 147 Auckland Road, Upper Norwood, London Client: J. Beddow	1893
TR MES AD1/975	Structure: Heating apparatus Location: 20 Red Lion Street, Clerkenwell, London Client: S. Betts	1896
TR MES AD1/990	Structure: Ventilating equipment for linotype room; Location: Fleet Street, London Client: Daily Telegraph	1931; 1938
TR MES AD1/1016	Structure: Conservatory Location: 29 Abercorn Place, Maida Vale, London Client: Major Blumenthal	1900

TR MES AD1/1024	Structure: Painting and repairs to glasshouses Location: 17 Sydenham Hill, London Client: Mrs Barry	1907
TR MES AD1/1042	Structure: Glasshouse Location: West Field, Nether Street, Finchley, London Client: C.H. Attrears	1902
TR MES AD1/1081	Structure: Conservatory; Conservatory Location: Essex House, Ballards Lane, Finchley, London Client: Ludwig Wagner	1896; 1902
TR MES AD1/1086	Structure: Steam heating apparatus Location: Hythe Road, Cumberland Road, Willesden Junction, London Client: Wicks Rotary Type Company Ltd	1897
TR MES AD1/1111	Structure: Painting; Boiler Location: Wood House, North Finchley, London Client: C.W. Wright Ingle	1899; 1903
TR MES AD1/1141	Structure: Forcing house Location: 285 Upper Richmond Road, Putney, London Client: T. Blanco White	1903
TR MES AD1/1171	Structure: Conservatory Location: Broughton, Fountain Road, Upper Norwood, London Client: Mrs Wolff	1899
TR MES AD1/1183	Structure: Plant house Location: Russettings, Streatham Hill, London Client: A.S. Cochrane	1893
TR MES AD1/1198	Structure: Roof for Eastern Aviary Location: Zoological Gardens, Regents Park, London Client: Zoological Society of London	1903
TR MES AD1/1230	Structure: Greenhouse Location: Russell House, 15 Cann Hall Road, Leytonstone, London Client: P.W. Withers	1897
TR MES AD1/1277	Structure: Boiler Location: The Cottage, 44 Streatham Hill, London Client: F. Stokes	1902
TR MES AD1/1281	Structure: Plant house and vinery Location: D'Urban Lodge, Woodchurch Road, West Hampstead, London Client: Martin Short	1898
TR MES AD1/1284	Structure: Heating apparatus Location: Broadfields, Winchmore Hill, London Client: W.T. Pauler, JP per Messers F. Smith and Co	1905
TR MES AD1/1295 [1 of 2 packets]	Structure: Painting; Boiler Location: Fairfield, 65 Upper Richmond Road, Putney, London Client: J. Bridson Seadle	1901; 1926
TR MES AD1/1295 [2 of 2 packets]	Structure: Glasshouse Location: Fairfield, 65 Upper Richmond Road, Putney, London Client: J. Bridson Seadle	1906
TR MES AD1/1304	Structure: Pit Location: Broomhall, Mount Park, Harrow, London Client: J.W. Stuart	1900

TR MES AD1/1334 [1 of 3 packets]	Structure: Plant house Location: 20 Denmark Avenue, Wimbledon, London Client: Ferdinand Rosing	1899
TR MES AD1/1334 [2 of 3 packets]	Structure: Alterations and additions to greenhouses Location: 20 Denmark Avenue, Wimbledon, London Client: Ferdinand Rosing	1900
TR MES AD1/1334 [3 of 3 packets]	Structure: Glasshouse Location: Iddesleigh, Kingston Vale, Putney, London Client: Ferdinand Rosing	1896
TR MES AD1/1359	Structure: Conservatory Location: Whitefriars, Chislett Road, Hampstead, London Client: N.M. Shimberg	1905
TR MES AD1/1367	Structure: Conservatory Location: Sherborne, Thurlow Park Road, West Dulwich, London Client: Henry Smith	1894
TR MES AD1/1375	Structure: Greenhouse Location: Paper Staining Works, Chiswick, London Client: Arthur Sanderson and Son	1894
TR MES AD1/1380	Structure: Glasshouse; Winter garden Location: Glenthorne, Bishops Avenue, East Finchley, London Client: G. Sainsbury	1903; 1910
TR MES AD1/1382	Structure: Peach house, plant house and stove; Heating to house; Location: Ivy House, North End, Hampstead, London Client: J. Walter Smith	1898; 1900
TR MES AD1/1401 [2 packets]	Structure: Plant house and vineries Location: Albert Cottage, Leigham Court Road, Streatham, London Client: P. Summers	1888
TR MES AD1/1407	Structure: Greenhouses Location: 6 The Grove, Highgate, London Client: A. Pye Smith	1898
TR MES AD1/1415 [2 packets]	Structure: Conservatory, plant house, pits, heating apparatus and painting Location: The Red House, Streatham, London Client: H. Stevenson	1902
TR MES AD1/1460	Structure: Heating apparatus Location: Sudbury Priory, near Harrow, London Client: M.C. Robinson [Architect]	1895
TR MES AD1/1497	Structure: Greenhouses Location: 4 Devonshire Road, Forest Hill, London Client: T.R. Roberts and Co. [Builders]	1902
TR MES AD1/1509	Structure: Conservatory Location: Rosslyn, 70 Castlenau, Barnes, London Client: H.C. Roberts	1904
TR MES AD1/1512	Structure: Glasshouse Location: East Sheen, London Client: R.H. Leycester Penryhn	1894
TR MES AD1/1520	Structure: Repairing vinery Location: Bushey Park, Teddington, Richmond-upon-Thames, London Client: Lady Cecilia Paget	1887
TR MES AD1/1532	Structure: Boilers Location: Central London Railway, London Client: T. Potter and Sons [Engineers]	1906

TR MES AD1/1542	Structure: Propogating house Location: Keswick Lodge, East Putney, London Client: A.J. Picketts	1902
TR MES AD1/1543 [2 packets]	Structure: Plant house; Rebuilding greenhouse; Greenhouse; Painting Location: Poplar Recreation Ground, East India Dock Road, Poplar, London Client: Poplar Borough Council	1903; 1932 and 1951; 1937 1949
TR MES AD1/1549 [2 packets]	Structure: Glasshouses; Heating apparatus Location: The Logs, East Heath Road, Hampstead Heath, London Client: F. Pusinelli	1898
TR MES AD1/1599 [1 of 4 packets]	Structure: Painting and repairs, Boiler Location: Belmont, 39 Honor Oak Road, Forest Hill, London Client: J.Arthur Pyne	1922
TR MES AD1/1599 [2 of 4 packets]	Structure: Plant house and stove; Painting Location: Belmont, 39 Honor Oak Road, Forest Hill, London Client: J. Arthur Pyne	1898; 1900
TR MES AD1/1599 [3 and 4 of 4 packets]	Structure: Conservatory Location: Belmont, 39 Honor Oak Road, Forest Hill, London Client: J. Arthur Pyne	1914
TR MES AD1/1607	Structure: Heating apparatus Location: Central Hall, Holborn, London Client: W.J. Purkiss	1889
TR MES AD1/1608	Structure: Plant house Location: Glen Rosa, 60 Woodvale, Lordship Lane, London Client: A. Pemberton	1893
TR MES AD1/1609	Structure: Conservatory Location: The Woodlands, Beulah Hill, Norwood, London Client: M. Pontifex per Pontifex and Wood	1889
TR MES AD1/1613 [1 of 3 packets]	Structure: Painting; Boiler Location: The Elms, Castle Bar, Ealing, London Client: William Owen	1900; 1904
TR MES AD1/1613 [2 of 3 packets]	Structure: Peach house, tomato house, plant house and pit Location: The Elms, Castle Bar, Ealing, London Client: William Owen	1894
TR MES AD1/1613 [3 of 3 packets]	Structure: Conservatory Location: The Elms, Castle Bar, Ealing, London Client: William Owen	1890
TR MES AD1/1701 [1 and 4 of 4 packets]	Structure: Cases Location: 112 and 113 Fore Street, London Client: W.S. Thomson and Co.	1898
TR MES AD1/1701 [3 of 4 packets]	Structure: Heating apparatus Location: 112 and 113 Fore Street, London Client: W.S. Thomson and Co.	1896
TR MES AD1/1701 [2 of 4 packets]	Structure: Steam Heating apparatus Location: New factory at Homerton, London Client: W.S. Thomson and Co.	1895
TR MES AD1/1744	Structure: Heating apparatus Location: Riverholme, Hampton Court, London Client: H.O. O'Hagan per Robert Emerie Tyler [Architect]	1890
TR MES AD1/1744	Structure: Heating apparatus Location: London Panorama, Westminster, London Client: Robert Emerie Tyler [Architect]	1890

TR MES AD1/1756	Structure: Boiler Location: Astor House, Aldwych, London Client: British and Continental Traders Ltd per John Hart	1928
TR MES AD1/1776	Structure: Heating apparatus; Boiler repairs Location: 48a Gillingham Street, Eccleston Square, London Client: The Krieger Electric Carriage Syndicate Ltd [later Royal Garage]	1907; 1921
TR MES AD1/1777	Structure: Painting and repairs Location: The Hoo, Sydenham Hill, London Client: Mrs R. Thornton	1906
TR MES AD1/1780	Structure: Glasshouse Location: Phyllis Court, Rosecroft Avenue, Hampstead, London Client: H. Parker Lowe	1906
TR MES AD1/1813	Structure: Heating apparatus Location: 9 Spencer Park, Wansworth Common, London Client: Thomas Hodgkinson	1907
TR MES AD1/1831	Structure: Plant house Location: Colwyn, Redington Road, West Hampstead, London Client: George Traill	1907
TR MES AD1/1852 [1 of 7 packets]	Structure: Plant house Location: Kensington Gardens, London Client: H.M. Office of Works per W. Browne [Park Superintendent]	1893
TR MES AD1/1852 [2 of 7 packets]	Structure: Verandah for Refreshment Pavilion and Roof to Urinals Location: Kensington Gardens, London Client: H.M. Office of Works per W. Browne [Park Superintendent]	1896
TR MES AD1/1852 [3 of 7 packets]	Structure: Palm House; Roof to lavatory Location: Kensington Gardens, London Client: H.M. Office of Works per W. Browne [Park Superintendent]	1896; 1899
TR MES AD1/1852 [4 of 7 packets]	Structure: Roof over Lavatory Location: St James' Park, London Client: H.M. Office of Works per W. Browne [Park Superintendent]	1897
TR MES AD1/1852 [5 of 7 packets]	Structure: Roof over lavatory Location: Regents Park, London Client: H.M. Office of Works per E. Jordan [Park Superintendent]	1898
TR MES AD1/1852 [6 of 7 packets]	Structure: Greenhouses Location: Framing Ground, Hyde Park, London Client: H.M. Office of Works	1908
TR MES AD1/1852 [7 of 7 packets]	Structure: Twin houses and corridor Location: Framing Ground, Hyde Park, London Client: H.M. Office of Works per C. Jordan [Park Superintendent]	1905
TR MES AD1/1865 [5 packets]	Structure: Conservatory Location: Atherstone House, Atkins Road, Clapham Park, London Client: Edwin Jones per J. Wallis Chapman	1899

TR MES AD1/1866	Structure: Greenhouse; Orchid houses Location: Beaulieu, Arthur Road, Wimbledon Park, London Client: F. Kirchner; Peter keary	1892; 1897
TR MES AD1/1879	Structure: Conservatory Location: 5 Laves Gardens, Acton, London Client: William Daley and Co [Builders]	1908
TR MES AD1/1892	Structure: Glasshouse Location: St Luke's Hospital, Old Street, London Client: W.H. Baird [Secretary]	1909
TR MES AD1/1905	Structure: Plant house and stove; Painting Location: Eagle House, Wimbledon, London Client: Mr Jackson	1907; 1913
TR MES AD1/1966	Structure: Boiler Location: Bosworth Hall Mission, Bosworth Road, North Kensington, London Client: A.W. Peters [Architect]	1927
TR MES AD1/1966	Structure: Heating apparatus Location: Bosworth Road Mission Chapel, Kensington, London Client: S. Wallis Chapman [Architect]	1903
TR MES AD1/1986	Structure: Heating apparatus; Boiler Location: St Johns Church, Ask Road, Battersea, London Client: Hudson Bros [Builders]	1904; 1922

Records of Properties in Merseyside

TR MES AD1/302	Structure: Greenhouses and conservatory Location: The Rookery, Southport [Estate Office at The Grove, Roe Lane, Southport], Merseyside Client: Charles H.B. Hesketh	1904; 1912
TR MES AD1/630	Structure: Range of glasshouses Location: Childwell Lodge, Wavertree, Liverpool, Merseyside Client: A. Earle	1892
TR MES AD1/968	Structure: Conservatory; Fernery Location: 62 Dale Street, Liverpool, Merseyside Client: E. Berry	1892; 1893
TR MES AD1/1035	Structure: Vineries Location: Manhattan, Gateacre, Liverpool, Merseyside Client: J.B. Atherton	1899
TR MES AD1/1454	Structure: Exhaust steam heating Location: Southend Works, Bridgewater Street, Liverpool, Merseyside Client: Read Bros.	1898; 1900
TR MES AD1/1808	Structure: Peach house, plant house, fernery Location: Norway Lodge, Prenton Hill, Birkenhead, Merseyside Client: A.H. Bunney	1907

Records of Properties in Middlesex

TR MES AD1/136	Structure: Conservatory Location: Pinner, Middlesex Client: F.H. Mabbett per Baker and Turrill [Architects]	1895
TR MES AD1/211	Structure: Greenhouse Location: Dundee House, Mill Plat, Isleworth, Middlesex Client: G.M. Gerality per R. Knight	1898
TR MES AD1/266	Structure: Palm house; Boiler Location: Osterley Park, Isleworth, Middlesex Client: Right Hon. Earl of Jersey	1898; 1932
TR MES AD1/322	Structure: Greenhouse Location: Fraysbrook, West Drayton, Middlesex Client: E. Humbert	1892
TR MES AD1/387	Structure: Greenhouse and stove; Boiler Location: The Gardens, Mower Hill, Pinner, Middlesex Client: Ambrose Heal; Mrs Heal	1898-1899; 1926
TR MES AD1/944	Structure: Heating apparatus Location: St Martins Church, Ruislip near Pinner, Middlesex Client: L. Ingham Baker	1893
TR MES AD1/969	Structure: Conservatory Location: Holly Grove House, Staines Road, Hounslow, Middlesex Client: J.R. Berry	1893
TR MES AD1/1072	Structure: Heating apparatus Location: Roc Steel Foundry, West Drayton, Middlesex Client: Edmund Trevor Lloyd Williams	1903
TR MES AD1/1090 [1 of 2 packets]	Structure: Painting; Glasshouse; Boiler Location: Bedfont House, East Bedfont, Middlesex Client: D.H. Rhiner Waring; Miss Rowe-Waring	1900; 1904; 1938
TR MES AD1/1090 [2 of 2 packets]	Structure: Winter Garden Location: Bedfont House, East Bedfont, Middlesex Client: D.H. Rhiner Waring	1899
TR MES AD1/1269	Structure: Heating apparatus; Boiler repairs Location: Leggatts, Potters Bar, Middlesex Client: Mrs J. Gurney Sheppard; W.F. Jackson	1897; 1915
TR MES AD1/1382	Structure: Refixing peach house, plant house, stove and forcing houses Location: Eastcote, Pinner, Middlesex Client: J. Walter Smith	1906
TR MES AD1/1479	Structure: Plant house; Painting Location: Barra Hall, Hayes, Middlesex Client: Robert Reid	1892; 1902
TR MES AD1/1488	Structure: Glasshouses Location: Greenford Hall, Southall, Middlesex Client: J.R. Roy	1891
TR MES AD1/1536	Structure: Glasshouse Location: Hadley Dene, Hadley Wood, Middlesex Client: Alan Potter	1906
TR MES AD1/1544	Structure: Boiler Location: Feltham, Middlesex Client: Pritchetts and Gold	1902
TR MES AD1/1546 [1 of 2 packets]	Structure: Glasshouse Location: Uplands, Feltham, Middlesex Client: Theodore W. Pritchett	1905

TR MES AD1/1553	Structure: Conservatory Location: Powiscourt, Potters Bar, Middlesex Client: Alfred Parker	1900
TR MES AD1/1598	Structure: Glasshouse Location: Alperton Lodge, Wembley, Middlesex Client: Hon. Rupert Guinness	1903
TR MES AD1/1749	Structure: Forcing house Location: The Laurels, Iver, near Uxbridge, Middlesex Client: T.A. Tidy	1892
TR MES AD1/1756	Structure: Glasshouse; Painting and boilers Location: Lockinvar, Little Heath, Potters Bar, Middlesex Client: John Hart	1906; 1907
TR MES AD1/1801	Structure: Chrysanthemum house Location: Nower Hill, Pinner, Middlesex Client: Ambrose Heal	1906

Records of Properties in Norfolk

TR MES AD1/75	Structure: Plant House Location: Loddon Vicarage, Norfolk Client: Rev. C.B. Mayhew	1889
TR MES AD1/80	Structure: Plant house Location: Lynford Hall, Mundford, Norfolk Client: F.J.C. Montague	1905
TR MES AD1/164	Structure: Heating apparatus Location: Kenninghall, Norfolk Client: Murton & Turner Engineers	1889
TR MES AD1/253	Structure: Heating apparatus Location: Bayfield Hall, Holt, Norfolk Client: Sir Alfred Jodrell, Bart	1894
TR MES AD1/558	Structure: Plant House Location: Mon Plaisir, Sherringham, Norfolk Client: C. Foster	1901
TR MES AD1/628	Structure: Heating apparatus Location: Broome Place, Bungay, Norfolk Client: Edmund de Poix	1888
TR MES AD1/631	Structure: Heating apparatus Location: Syleham Nurseries, Scole, Norfolk Client: Evans and Co.	1906
TR MES AD1/689	Structure: Vinery and plant protector; Replacement boiler Location: Letheringsett Hall, Holt, Norfolk Client: Right Hon. Lord Edward H. Cozens-Hardy [Justice]	1899; 1917
TR MES AD1/1922	Structure: Heating apparatus Location: Eldeston Lodge, Norfolk Client: Edward Beauchamp	1908

Records of Properties in Northamptonshire

TR MES AD1/247	Structure: Boiler Location: Fawsley Park, Daventry, Northamptonshire Client: Lady Knightley	1902
TR MES AD1/471	Structure: Range and Orchid House Location: East Haddon Hall, near Northampton, Northamptonshire Client: Mrs Guthrie	1892
TR MES AD1/533	Structure: Greenhouse Location: Moreton Pinkney Manor, Byfield RSO, Northamptonshire Client: Miss Grey	1905
TR MES AD1/930	Structure: Glasshouses Location: Laddington Hall, Kettering, Northamptonshire Client: Capt. A.W. de Capel Brooke	1892
TR MES AD1/946	Structure: Plant house and vinery Location: Sarnia House, Kettering, Northamptonshire Client: Thomas Bird	1900
TR MES AD1/971	Structure: Greenhouse Location: Islip, Thrapston, Northamptonshire Client: Miss Beauford	1896
TR MES AD1/1004 [2 packets]	Structure: Glasshouses Location: The Rookery, Brixworth, Northamptonshire Client: Percy E. Bucknall	1905; 1925
TR MES AD1/1113	Structure: Plant house and forcing house Location: Courteenhall, Northamptonshire Client: Sir Herewald Wake, Bart	1901
TR MES AD1/1116	Structure: Heating apparatus and plant house Location: Burton Latimer, Kettering, Northamptonshire Client: T. and J. Wallis	1889
TR MES AD1/1203	Structure: Glasshouses Location: Stoke Bruerne park, Towcester, Northamptonshire Client: B.W. Vernon	1895
TR MES AD1/1299	Structure: Heating apparatus Location: Drayton House, Thrapston, Northamptonshire Client: Mrs Stopford Sackville	1894
TR MES AD1/1337 See also TR MES AD1/1868	Structure: Conservatory, plant house and pit Location: Guilsborough House, Northampton, Northamptonshire Client: Capt. W.G. Renton	1897
TR MES AD1/1413	Structure: Conservatory Location: The Hollies, Thrapston, Northamptonshire Client: G. Smith	1901
TR MES AD1/1426	Structure: Vinery Location: The Rectory, Oundle, Northamptonshire Client: J.W. Smith	1887
TR MES AD1/1468	Structure: Conservatory Location: The Hollies, Sutton Bassett, Northamptonshire Client: Mrs W. Rowlatt	1900
TR MES AD1/1654	Structure: Stove and cucumber house Location: Blatherwycke Park, Wansford, Northamptonshire Client: H.S. O'Brien	1901
TR MES AD1/1743	Structure: Wall cover Location: Rothwell Grange, Kettering, Northamptonshire Client: J. Borlase Tibbits	1894

TR MES AD1/1755	Structure: Greenhouse Location: Boughton Park, Kettering, Northamptonshire Client: Duke of Buccleugh, KG	1914
TR MES AD1/1798	Structure: Plant house, peach house and pits Location: Bramston House, Oundle, Northamptonshire Client: C.A. Newman	1907
TR MES AD1/1812	Structure: Forcing, stove, intermediate, melon, plant and cucumber houses Location: Hinwick Hall, Wellingborough, Northamptonshire Client: Gilbert Robinson	1907
TR MES AD1/1842 [1, 2 and 3 of 4 packets]	Structure: Forcing house, potting shed, conservatory and other glasshouses Location: Cransley Hall, Kettering, Northamptonshire Client: Capt. A.H. Thurburn	1905
TR MES AD1/1842 [4 of 4 packets]	Structure: Boiler Location: Cransley Hall, Kettering, Northamptonshire Client: Capt. A.H. Thurburn	1924
TR MES AD1/1868 [1, 2 of 4 packets] See also TR MES AD1/1337	Structure: Heating apparatus to residence Location: Guilsborough Hall, Northampton, Northamptonshire Client: Mrs Irene Osgood	1912
TR MES AD1/1868 [3 of 4 packets]	Structure: Stokery Location: Guilsborough Hall, Northampton, Northamptonshire Client: Mrs Harborough Sherrard	1909
TR MES AD1/1868 [4 of 4 packets]	Structure: Vinery Location: Guilsborough Hall, Northampton, Northamptonshire Client: Mrs Harborough Sherrard	1909
TR MES AD1/1898 [1 of 2 packets]	Structure: Boiler Location: Loddington Hall, Kettering, Northamptonshire Client: Stephen Schilizzi	1943
TR MES AD1/1898 [2 of 2 packets]	Structure: Glasshouse Location: Loddington Hall, Kettering, Northamptonshire Client: A.R. Steele	1907
TR MES AD1/1901	Structure: Stove, Cucumber and plant house; Boiler Location: Shuckborough Park, Daventry, Northamptonshire Client: Sir Gerald F.S. Shuckborough, Bart	1908; 1930
TR MES AD1/2000	Structure: Heating apparatus Location: Brampton Church, Northampton, Northamptonshire Client: Rev. H.C. Calveley	1889

Records of Properties in Northumberland and County Durham

TR MES AD1/386	Structure: Greenhouse Location: Fern Dene, Ryton on Tyne, Northumberland Client: H.C. Harvey	1892-1893
TR MES AD1/453	Structure: Orchid House; Peach house and cool Orchid House; Orchid House Location: Lesbury House, Lesbury RSO, Northumberland Client: T.G. Gibson	1893; 1894; 1897
TR MES AD1/1043	Structure: Conservatory Location: Linden, Morpeth, Northumberland Client: Louis Ames	1890
TR MES AD1/1100	Structure: Conservatory Location: Shotley Grove, South Boldon, County Durham Client: Mrs J. Whitlock	1901
TR MES AD1/1360	Structure: Glasshouses; Plant house Location: 9 South Bailey, Durham, Co. Durham Client: C. Duncombe Shafts	1906; 1910
TR MES AD1/1708	Structure: Conservatory and vinery Location: Ashleigh, Monkseaton, Whitley by the Sea, Northumberland Client: George D. Thompson	1895
TR MES AD1/1720	Structure: Greenhouse Location: Holly House, Hetton-le-Hole, Fence Houses, Sunderland, Northumberland Client: John Todd	1890
TR MES AD1/1724	Structure: Greenhouse Location: Oaklands, Alnwick, Northumberland Client: John Tate	1890

Records of Properties in Nottinghamshire

TR MES AD1/92	Structure: Boiler Location: Bloomsgrrove Works, Nottingham, Nottinghamshire Client: Manlove, Alliott and Co., LTD	1891
TR MES AD1/93	Structure: Greenhouse/Conservatory Location: Clarence Lodge, Lucknow Road, Nottingham, Nottinghamshire Client: T. Moody	1904
TR MES AD1/100	Structure: Peach House; Heating apparatus Location: Ruddington Hall, Nottingham, Nottinghamshire Client: Philo and Mills	1903; 1905
TR MES AD1/108	Structure: Heating apparatus Location: Catholic Church, Hucknall Torkard, Nottinghamshire Client: Rev. John R. McDonnell	1892
TR MES AD1/109	Structure: Heating apparatus alterations Location: Raddington House, Nottingham, Nottinghamshire Client: W. Forster Mills	1901
TR MES AD1/112	Structure: Conservatory Location: Sherwood Hall, Mansfield, Nottinghamshire Client: H.W. Mills	1899
TR MES AD1/118	Structure: Glasshouse Location: Thoresby Park, Ollerton, Nottinghamshire Client: Earl Manvers	1899
TR MES AD1/189	Structure: Plant House Location: Park Nurseries, Barrack Lane, Lenton, Nottinghamshire Client: Mr Kingdon per Mr Butters	1903
TR MES AD1/270	Structure: Conservatory Location: Sherwood Rise, Nottingham, Nottinghamshire Client: C. Hibbert	1890
TR MES AD1/310	Structure: Plant house Location: Rock Hill, Sherwood Rise, Nottingham, Nottinghamshire Client: H. Hopkinson	1897
TR MES AD1/328	Structure: Stove and plant house Location: Cyprus Road, Nottingham, Nottinghamshire Client: Charles Hill	1892
TR MES AD1/374	Structure: Heating apparatus for fruit houses Location: Berry Hill, Mansfield, Nottinghamshire Client: Mrs Hollins	1897-1898
TR MES AD1/429	Structure: Heating apparatus Location: Bulwell Hall, Nottingham, Nottinghamshire Client: Thomas Hardy	1894
TR MES AD1/538	Structure: Plant House Location: Nettleworth Manor, Mansfield, Nottinghamshire Client: Lady Fitzherbert	1896
TR MES AD1/626	Structure: Conservatory Location: Wilford Lane, West Bridgford, Nottinghamshire Client: H. Daubrey	1902
TR MES AD1/635	Structure: Peach house, Vinery and plant house Location: Sparken House, Worksop, Nottinghamshire Client: J.D. Ellis	1894
TR MES AD1/646	Structure: Conservatory Location: Blantyre, 5 Cavendish Crescent, The Park, Nottingham, Nottinghamshire Client: Francis M. Ellis	1901

TR MES AD1/668	Structure: Conservatory Location: Bramcote, Nottingham, Nottinghamshire [house occupied by R. Enfield, but owned by Mrs Sherwin Gregory, sister to Capt. Holden] Client: Richard Enfield	1891
TR MES AD1/800	Structure: Greenhouse Location: Terham House, Clumber Crescent, Nottingham, Nottinghamshire Client: Mrs Cafferata	1893
TR MES AD1/811	Structure: Heating apparatus Location: Forest Hill, Worksop, Nottinghamshire Client: Peter Cadman	1896
TR MES AD1/821	Structure: Boiler; Heating apparatus; Boiler repairs; Rebuilding greenhouse Location: Bunney Park, Nottingham, Nottinghamshire Client: Mrs E. Cordeux (formerly Mrs Wilkinson Smith)	1904; 1918; 1927; 1928
TR MES AD1/821	Structure: Heating apparatus for Miss Hawksley, Bunney Park; Heating apparatus for Bunney Vicarage Location: Bunney Vicarage, Nottingham, Nottinghamshire Client: Rev. H. Cooper	1895; 1895- 1896
TR MES AD1/829	Structure: Vinery Location: Sandiacre, near Nottingham, Nottinghamshire Client: George Bastable	1898
TR MES AD1/831	Structure: Plant house; Blinds and painting Location: 55 Musters Road, West Bridgford, Nottinghamshire Client: A. Brotherton	1900; 1903
TR MES AD1/863	Structure: Boiler and heating apparatus Location: London Road, Newark, Nottinghamshire Client: Messrs G. Brown and son	1904
TR MES AD1/914	Structure: Five glasshouses Location: Sutton on Trent near Newark, Nottinghamshire Client: James Blackburn	1894
TR MES AD1/964	Structure: Greenhouse Location: Sherwood Street, Nottingham, Nottinghamshire Client: Bell and Sons [Builders]	1891
TR MES AD1/967	Structure: Conservatory Location: Grove House, Worksop, Nottinghamshire Client: E.R. Berry	1895
TR MES AD1/1074 [1 of 2 packets]	Structure: Conservatory Location: South Collingham, Newark, Nottinghamshire Client: John Wigram	1893
TR MES AD1/1074 [2 of 2 packets]	Structure: Glass porch Location: The Manor, Collingham, Newark, Nottinghamshire Client: John Wigram	1903
TR MES AD1/1099	Structure: Plant house; Rose house; Extension to glasshouse Location: Whitemore Lodge, Bobbers Mill, Nottingham, Nottinghamshire Client: J. White	1905; 1906; 1907
TR MES AD1/1194	Structure: Conservatory Location: 401 Mansfield Road, Carrington, Nottinghamshire Client: John Woollatt	1895

TR MES AD1/1196	Structure: Conservatory Location: Ruddington, near Nottingham, Nottinghamshire Client: George Wadsley	1902
TR MES AD1/1266 [1 of 6 packets]	Structure: Heating apparatus Location: Ramsdale Park, near Arnold, Nottinghamshire Client: Sir Charles Secley, Bart.	1912
TR MES AD1/1266 [2 of 6 packets]	Structure: Peach houses, muscat vinery, Carnation house, tomato houses, plant houses Location: Sherwood Lodge, Nottinghamshire Client: Sir Charles Secley, Bart.	1916
TR MES AD1/1266 [3 of 6 packets]	Structure: Boiler and heating apparatus Location: Ramsdale Park, near Arnold, Nottinghamshire Client: Sir Charles Secley, Bart.	1911
TR MES AD1/1266 [4 of 6 packets]	Structure: Heating apparatus and boiler repairs Location: Sherwood Lodge, Nottinghamshire Client: Sir Charles Secley, Bart.	1924
TR MES AD1/1266 [5 of 6 packets]	Structure: Heating apparatus for residence Location: Ramsdale Park, near Arnold, Nottinghamshire Client: Sir Charles Secley, Bart.	1910
TR MES AD1/1266 [6 of 6 packets]	Structure: Boiler; Heating apparatus Location: Ramsdale Park, near Arnold, Nottinghamshire [Includes two letters regarding East Leake Church, near Loughborough] Client: Col. F.E. Secley	1916; 1922
TR MES AD1/1300	Structure: Steam heating Location: Netherfield, Nottinghamshire Client: Stafford and Co [Printers]	1901
TR MES AD1/1328	Structure: Heating apparatus Location: 59 Pierrepont Road, Trent Boulevard, West Bridgford, Nottinghamshire Client: R. Simpson	1895
TR MES AD1/1328	Structure: Greenhouse Location: 39 Greyfriars Gate, Nottingham, Nottinghamshire Client: R. Simpson	1895
TR MES AD1/1329	Structure: Conservatory Location: Highfield, Radcliffe-on-Trent, Nottinghamshire Client: J. Selby	1903
TR MES AD1/1333	Structure: Greenhouse Location: Bestwood, Arnold, Nottinghamshire Client: Duke of St Albans	1889
TR MES AD1/1350	Structure: Greenhouse Location: Ravensdene, Magdala Road, Nottingham, Nottinghamshire Client: A. Stafford	1897
TR MES AD1/1365	Structure: Plant house and conservatory Location: North Clifton Hall, Newark, Nottinghamshire Client: Capt S. Hutton Riddell per Smith, Woolley and Wigram	1896
TR MES AD1/1387	Structure: Heating apparatus; Heating to house Location: Dunstead House, Langley Mills, Nottinghamshire Client: William Smith; Lady Smith	1892; 1927
TR MES AD1/1410	Structure: Vinery; Boiler Location: Thurgarton Vicarage, Nottinghamshire Client: Rev. A.M.Y. Bailey per Messrs Smith, Woolley and Wigram	1892; 1914

TR MES AD1/1418	Structure: Greenhouse Location: Glenholme, Gregory Boulevard, Nottingham, Nottinghamshire Client: James B. Snook	1894
TR MES AD1/1430	Structure: Camellia house and vinery Location: Gleadthorpe, Cavendish Crescent, The Park, Nottingham, Nottinghamshire Client: R. Steele	1889
TR MES AD1/1442	Structure: Greenhouse Location: Hazledene, Sherwood, Nottinghamshire Client: Percy James Smith	1903
TR MES AD1/1450	Structure: Heating apparatus Location: Bennet Street, Long Eaton, Nottinghamshire Client: H.B. Sketchley	1904
TR MES AD1/1473	Structure: Conservatory Location: The Gables, Collingham, Newark, Nottinghamshire Client: R.L. Rice	1894
TR MES AD1/1496	Structure: Glasshouses Location: Lucknow Drive, Nottingham, Nottinghamshire Client: John Robinson	1887
TR MES AD1/1525	Structure: Glasshouse Location: Pelham Road, Sherwood Rise, Nottingham, Nottinghamshire Client: A.F. Payne	1899
TR MES AD1/1614	Structure: Glasshouse Location: Springhead, Bulwell, Nottinghamshire Client: Henry J. Neilson	1904
TR MES AD1/1622 [2 packets]	Structure: Vinery, Conservatory, and Plant houses Location: Arthur Avenue, Lenton Boulevard, Nottingham, Nottinghamshire Client: A. Orgill	1898
TR MES AD1/1623	Structure: Covered way to mortuary Location: Nottingham General Hospital, Nottinghamshire Client: Alfred Watershouse and Sons [Architects]	1902
TR MES AD1/1668	Structure: Glasshouse; Glasshouse Location: Nowell House, Southwell, Nottinghamshire Client: Rev. Canon Henry J. Tebbutt	1905; 1908
TR MES AD1/1751	Structure: Conservatory Location: Lucknow Drive, Nottingham, Nottinghamshire Client: J.W. Turner	1888
TR MES AD1/1753	Structure: Roof to smoke bar Location: 647 Beastmarket Hill, Nottingham, Nottinghamshire Client: Frederick C. Martin per Messrs Truman	1898
TR MES AD1/1757	Structure: Tomato house Location: The Burgage, Southwell, Nottinghamshire Client: Revd. Canon W. Glaister	1908
TR MES AD1/1783	Structure: Peach house Location: Beacon Hill House, Hucknall Torkard, Nottinghamshire Client: Mrs Needham Ball	1906
TR MES AD1/1846	Structure: Conservatory Location: 48 Musters Road, West Bridgford, Nottinghamshire Client: H. Gamble	1906
TR MES AD1/1938	Structure: Plant house Location: Harlaston Drive, Lenton Sands, Nottinghamshire Client: J.J. Spencer	1907

TR MES AD1/1953	Structure: Plant house and pit Location: Ruddington, Nottinghamshire Client: W.R. Rook	1908
TR MES AD1/1967	Structure: Heating apparatus Location: Board Schools, Beeston, Nottinghamshire Client: John C. Bowley [Architect]	1891

Records of Properties in Oxfordshire

TR MES AD1/101	Structure: Greenhouse/Conservatory Location: Balliol College, Oxford, Oxfordshire Client: Sir W. Markby	1893
TR MES AD1/110	Structure: Conservatory Location: Rectory Farm, Streatley, Goring-on-Thames, Oxfordshire Client: Capt. C.L. Marks DSO	1903
TR MES AD1/148	Structure: Greenhouse Location: The Red House, Bodicote, Banbury, Oxfordshire Client: Lt. Col. Hon. C.C. Molyneux	1906
TR MES AD1/266	Structure: Boiler; Greenhouse Location: Middleton Park, Bicester, Oxfordshire Client: Right Hon. Earl of Jersey	1903; 1920
TR MES AD1/335	Structure: Greenhouse and Vinery Location: The Grove, Henley on Thames, Oxfordshire Client: F.C. Hill	1895-1896
TR MES AD1/449	Structure: Conservatory Location: Summertown, Oxford, Oxfordshire Client: O. Grimby	1891
TR MES AD1/470	Structure: Peach House Location: Stratton Audley Park, Bicester, Oxfordshire Client: Col. Gosling	1900
TR MES AD1/553	Structure: Glasshouses Location: Enstone, Oxfordshire Client: J. Faulkner	1889
TR MES AD1/622	Structure: Glasshouse Location: 2 St Margarets Road, Oxford, Oxfordshire Client: H.A. Dickson	1896
TR MES AD1/643 [2 packets]	Structure: Greenhouse; Stove house, heating and ventilating apparatus; Peach houses Location: Youlbury, Boars Hill, near Oxford, Oxfordshire Client: Sir Arthur J. Evans	1893; 1911; 1914
TR MES AD1/651	Structure: Forcing house Location: Eversley, Westwood Park, Forest Hill, Oxfordshire Client: E.H.P Eason	1893
TR MES AD1/771	Structure: Plant house and stove Location: Headington Hill, Oxford, Oxfordshire Client: G.M. Child	1894
TR MES AD1/820	Structure: Glasshouse Location: Homestead, Banbury, Oxfordshire Client: Mrs Aubrey Cartwright	1905
TR MES AD1/842 See also TR MES AD1/958 and 959	Structure: Heating apparatus Location: Wallingford, Oxfordshire Client: A.L. Morphew per Brasher and Co.	1900
TR MES AD1/875 [5 packets]	Structure: Vinery; Conservatory and corridor; Painting; Boiler; Boiler; Location: Tiddington House, Wheatley SO, Oxfordshire Client: G.W. Bennett; Mrs Adrian Corbett	1891; 1900; 1893-1916; 1923; 1938
TR MES AD1/878	Structure: Glasshouse Location: Draycott House, Bodicote, Banbury, Oxfordshire Client: F.B. Judge Baldwin	1903
TR MES AD1/898	Structure: Boiler Location: 1 Broad Street, Oxford, Oxfordshire Client: W. Baker and Co.	1903

TR MES AD1/941	Structure: Heating apparatus Location: Heythrop Park, Chipping Norton, Oxfordshire Client: Albert Brassey	1899
TR MES AD1/958	Structure: Vinery Location: Wallingford, Oxfordshire Client: Brasher and Sons	1903
TR MES AD1/959	Structure: Plant house and stove; Glasshouses; Pits Location: East Lodge, Strathbraan, Shillingford, Wallingford, Oxfordshire Client: F.W. Mortimer per Messrs Brasher and Sons [Builders]	1898; 1899; 1900
TR MES AD1/999	Structure: Plant house Location: Cleveland, Kidlington, Oxfordshire Client: J.A. Baines	1902
TR MES AD1/1154	Structure: Glasshouse Location: Barrington Park, Burford, Oxfordshire Client: E.G.R. Wingfield	1905
TR MES AD1/1270	Structure: Renewing forcing house Location: Burton Hall, Banbury, Oxfordshire Client: Lord Ernest St Maur	1910
TR MES AD1/1276	Structure: Glasshouse; Glasshouse Location: Thames Bank, Goring, Oxfordshire Client: F. Shoolbred	1891; 1894
TR MES AD1/1285	Structure: Heating apparatus Location: Woodlands, Remenham Hill, Henley, Oxfordshire Client: Rawlins per W.F. Sargeant [Builder]	1896
TR MES AD1/1373	Structure: Conservatory Location: Bodicote House, Banbury, Oxfordshire Client: J.F. Starkey	1898
TR MES AD1/1392 [1 of 2 packets]	Structure: Greenhouses; Glasshouse Location: Caversfield House, Bicester, Oxfordshire Client: Mrs Phillips per Messrs Thomas Smith and Sons	1893; 1907
TR MES AD1/1392 [2 of 2 packets]	Structure: Peach hosue and vinery Location: Caversfield House, Bicester, Oxfordshire Client: Major the Hon. E.H. Wyndham, MC	1924
TR MES AD1/1425	Structure: Heating apparatus Location: Remenham Hill, Henley on Thames, Oxfordshire Client: F. Sargeant [Builder]	1893
TR MES AD1/1750	Structure: Glasshouses Location: Begbroke House, Begbroke, Oxfordshire Client: Charles Robinson per F. Taylor and Sons	1907
TR MES AD1/1759	Structure: Carnation house Location: The Grange, Farnborough, Banbury, Oxfordshire Client: Ronald A. Holbech	1907
TR MES AD1/1794	Structure: Conservatory Location: 153 Banbury Road, Oxford, Oxfordshire Client: Rev. E.J. Smith	1907
TR MES AD1/1909	Structure: Conservatory Location: Highfield Park, Headington, Oxfordshire Client: Mr Moss per George Gardiner [Architect]	1908
TR MES AD1/1944	Structure: Glasshouse Location: Manor House, Hambleton, Henley-on-Thames, Oxfordshire Client: C.A. Scott Murray	1907
TR MES AD1/1948	Structure: Odontoglossum, Cattleya and stove houses Location: Swanston, Whitchurch, Oxfordshire Client: Frank Loughborough Pearson	1906

TR MES AD1/1962 Structure: Peach house
Location: The Grange, Steeple Aston, Oxfordshire
Client: Mrs Bradshaw

1908

Records of Properties in Rutlandshire

TR MES AD1/349	Structure: Greenhouse Location: Ketton Hall, Rutland, Rutlandshire Client: R.R. Hollins per T. Hare and Son	1902
TR MES AD1/1106	Structure: Conservatory; Heating apparatus Location: Wing, Oakham, Rutlandshire Client: E. Worrall	1892; 1895
TR MES AD1/1890	Structure: Verandah and glasshouse Location: Lorne House, Uppingham, Rutlandshire Client: Rev. F.W. Welldon	1908

Records of Properties in Shropshire

TR MES AD1/145	Structure: Greenhouse Location: Culmington House, Bromfield, Shropshire Client: Capt. Money DSO	1906
TR MES AD1/229	Structure: Verandah Location: Leighton Hall, Ironbridge, Shropshire Client: J.T. Kynnersley	1888-1890
TR MES AD1/333	Structure: Plant house Location: Highfield, Shrewsbury, Shropshire Client: T.M. Howells	1898
TR MES AD1/407	Structure: Conservatory Location: 1 Claremont Buildings, Shrewsbury, Shropshire Client: Samuel Heighway	1898
TR MES AD1/497	Structure: Conservatory Location: The Grove, Craven Arms, Shropshire Client: H.D. Greene, MP	1901
TR MES AD1/498	Structure: Conservatory Location: Mytton Hall, Shrewsbury, Shropshire Client: J.R. Greatorix	1901
TR MES AD1/540	Structure: Conservatory Location: Ightfield Rectory, Whitchurch, Shropshire Client: Rev. R.B. Faulkner	1892
TR MES AD1/713	Structure: Glasshouses Location: Combermere Abbey, Whitchurch, Shropshire Client: Lord Combermere	1899-1902
TR MES AD1/727	Structure: Heating apparatus; Boiler; Heating apparatus Location: Bryn-y-pys, Overton, Ellesmere, Shropshire Client: A.J.P. Child; Edmund Peel	1905; 1908; 1912
TR MES AD1/734	Structure: Greenhouse Location: Pimley Manor, Shrewsbury, Shropshire Client: Mrs Corbett [Formerly Mrs Piggott]	1903
TR MES AD1/734	Structure: Greenhouse Location: Upton Magna Rectory, Shrewsbury, Shropshire Client: Mrs Piggott	1890
TR MES AD1/846	Structure: Plant house Location: The Derwyn, Gobowen, Oswestry, Shropshire Client: F. Boughey	1895
TR MES AD1/854	Structure: Conservatory Location: Hillside, Church Stretton, Shropshire Client: W.L. Browne	1899
TR MES AD1/942	Structure: Rose and carnation house Location: Weston Park, Weston-under-Lizard, near Shifnal, Shropshire Client: Earl of Bradford	1901
TR MES AD1/1119	Structure: Greenhouse; Rebuilding vinery; Peach house; Vinery Location: Shakenhurst, Cleobury Mortimer, Shropshire Client: C.W. Wickstead; Hugh Gurney	1892; 1900; 1908; 1909
TR MES AD1/1124	Structure: Greenhouse Location: The Pyms, Wem, Shropshire Client: Samuel Hudson per George T. Whitfield [Timber merchant]	1895

TR MES AD1/1157	Structure: Glasshouse; Plant house Location: Cantreyn, Bridgnorth, Shropshire Client: Alfred P. Welch	1894; 1898
TR MES AD1/1158	Structure: Greenhouse Location: Hopton Court, Cleobury Mortimer, Shropshire Client: Rear Admiral K. Woodward	1897
TR MES AD1/1192	Structure: Conservatory and fernery roof; Moving and re-erecting conservatory Location: Culmington Manor, Craven Arms, Shropshire Client: Edward Wood; Capt. Wood	1894; 1908
TR MES AD1/1231	Structure: Vinery; Forcing houses Location: Onslow, Shrewsbury, Shropshire Client: Mrs M. Wingfield	1896; 1901
TR MES AD1/1617	Structure: Heating apparatus and repairs Location: Walcot, Lydbury North, Shropshire Client: Lord Powis	1900
TR MES AD1/1656	Structure: Plant house Location: Eardiston House, West Felton, Oswestry, Shropshire Client: J.B. Oswell	1906
TR MES AD1/1661	Structure: Plant house and vinery Location: Broadward Hall, Aston-on-Clun, Shropshire Client: J.S. Moreton	1911
TR MES AD1/1793	Structure: Peach wall cover Location: Gredington, Whitchurch, Shropshire Client: Lord Kenyon	1906
TR MES AD1/1910	Structure: Plant house and stove Location: Sibdon Castle, Craven Arms, Shropshire Client: Mrs A. Champion	1909

Records of Properties in Somerset

TR MES AD1/147	Structure: Conservatory Location: The Manor House, Limpley Stoke, Bath, Somerset Client: H.M. Marshall	1904
TR MES AD1/280	Structure: Vinery and pits Location: Rock House, Lansdowne Road, Bath, Somerset Client: Miss Hope	1904
TR MES AD1/686	Structure: Conservatory Location: St Georges Lodge, Oldfield Road, Bath, Somerset Client: John J.S. Collins	1904
TR MES AD1/778	Structure: Plant house and stove Location: 44 London Road, Clapton, Somerset Client: J.R. Cordall	1892
TR MES AD1/877	Structure: Glasshouses Location: Boyton Manor, Codford, Bath, Somerset Client: G.R. Bryant	1889
TR MES AD1/1118	Structure: Stove and conservatory Location: Warleigh Lodge, Bathford, Bath, Somerset Client: J. Onslow Watts	1893
TR MES AD1/1308	Structure: Heating apparatus; Vinery Location: Chipley Park, Wellington, Somerset Client: Capt. H.W. Carleton Smith	1895; 1896
TR MES AD1/1432	Structure: Heating apparatus Location: Clandown Church, Radstock, Bath, Somerset Client: Rev. W. Symonds	1886
TR MES AD1/1436	Structure: Heating apparatus Location: Somerset Wheel and Wagon Works, Martock, Somerset Client: William Sparrow	1899
TR MES AD1/1606	Structure: Forcing house Location: Chedington Court, Misterton, Crewkerne, Somerset Client: Sir Henry Pets	1901
TR MES AD1/1707 [1 of 4 packets]	Structure: Peach house and vinery Location: Halswell, Bridgewater, Somerset Client: C.H. Kenneys-Tynte	1903
TR MES AD1/1707 [2 of 4 packets]	Structure: Extension of fruit houses Location: Halswell, Bridgewater, Somerset Client: C.H. Kenneys-Tynte	1901
TR MES AD1/1707 [3 of 4 packets]	Structure: Greenhouse Location: Halswell, Bridgewater, Somerset Client: C.H. Kenneys-Tynte	1901
TR MES AD1/1707 [4 of 4 packets]	Structure: Heating apparatus Location: Halswell Park, Bridgewater, Somerset Client: Lord Wharton	1919
TR MES AD1/1917	Structure: Conservatory Location: Fons George, Taunton, Somerset Client: E.C. Boulting	1907
TR MES AD1/1923 [1 of 2 packets]	Structure: Heating apparatus to residence; Greenhouse Location: Mells Park, Frome, Somerset Client: Gilbert F. Bates	1912; 1913
TR MES AD1/1923 [2 of 2 packets]	Structure: Glasshouses Location: Mells Park, Frome, Somerset Client: Gilbert F. Bates	1907

Records of Properties in Staffordshire

TR MES AD1/158	Structure: Conservatory, Heating Apparatus Location: Bolehall Manor house, Tamworth, Staffordshire Client: W. McGregor	1890
TR MES AD1/161 [2 packets]	Structure: Conservatory; Greenhouse and heating Location: The Brooms, Stone, Staffordshire Client: C. McIlroy	1899; 1924
TR MES AD1/188	Structure: Conservatory Location: Oulton Rocks, Stone, Staffordshire Client: H. J. Johnson	1897; 1906
TR MES AD1/204	Structure: Extension to Greenhouse Location: Rotherwood, Stafford, Staffordshire Client: Nicolas Joyce	1902
TR MES AD1/204	Structure: Plant house and stove Location: The Smallthornes, Stafford, Staffordshire Client: Nicolas Joyce	1895
TR MES AD1/205	Structure: Plant house and stove Location: Oulton Old Hall, Stone, Staffordshire Client: F.G. Kitchener	1898
TR MES AD1/240 [2 packets]	Structure: Plant houses, heating to mushroom house Location: Thorpe Hall, Tamworth, Staffordshire Client: W.F. Inge	1890-1900
TR MES AD1/248	Structure: Plant house and stove Location: Gladwyn, Stoke-on-Trent, Staffordshire Client: H. Gwynne Kirkham	1902
TR MES AD1/313	Structure: Peach House; Vinery Location: Branstone House, near Burton-on-Trent, Staffordshire Client: Charles Harrison	1894; 1900
TR MES AD1/381	Structure: Vinery and potting house Location: The Rifleman Inn, Derby Street, Burton-on-Trent, Staffordshire Client: R.A. Haines	1903
TR MES AD1/473	Structure: "Live" steam heating apparatus for offices Location: Swadlincote near Burton-on-Trent, Staffordshire Client: Granville Colliery Company	1899
TR MES AD1/520	Structure: Heating apparatus Location: Bohemia, Lichfield Road, Stafford, Staffordshire Client: Mrs Follows	1899
TR MES AD1/546	Structure: Peach House Location: Hanbury, Burton-on-Trent, Staffordshire Client: Rev. J.R. Foot	1891
TR MES AD1/650	Structure: Conservatory Location: Fenton Hall, Fenton, Staffordshire Client: J. Linday per H.P. Embrey and Co. [Builders]	1901
TR MES AD1/658	Structure: Greenhouses Location: Hollydene, Longton, Staffordshire Client: C.J. Edwards	1897-1898
TR MES AD1/663	Structure: Conservatory Location: Knivedon, Leek, Staffordshire Client: C.C. Ellis	1902
TR MES AD1/664	Structure: Forcing House and heating apparatus Location: Weston House, Swadlincote, near Burton-on-Trent, Staffordshire Client: A.H. and W.E. Eley [Nurserymen]	1903

TR MES AD1/664	Structure: Forcing House and heating apparatus Location: Seal Wood Nurseries, Linton, near Burton-on-Trent, Staffordshire Client: A.H. and W.E. Eley [Nurserymen]	1903
TR MES AD1/851	Structure: Plant house Location: Langdale, Stafford, Staffordshire Client: Thomas Bostock	1901
TR MES AD1/855 [11 packets]	Structure: Heating apparatus and hot water supply Location: Ale Stores, Tablet Room and Joiners Shop, Kings Road, St Pancras : Dixie Ale Stores, Burton-on-Trent, Staffordshire : Shobnall Ale Stores, Staffordshire : Nags Head, Swadlincote, Staffordshire : Commercial Inn, Sleaford, Lincolnshire : Stores at Wellington Street, Hull, Yorkshire : St Chads Church, Hunter Street, Burton-on-Trent, Staffordshire : Hawkins Lane Stores, Burton-on-Trent, Staffordshire : Old Brewery, High Street, Burton-on-Trent, Staffordshire : General Offices, Kings Road, Pancras Road, London : New Loco Shed Client: Bass, Ratcliff and Gretton Ltd, Burton-on-Trent, Staffordshire	1893-1909
TR MES AD1/882 [2 packets]	Structure: Stove and fernery; Heating apparatus; Repairs to vinery; Boiler Location: Foremark Hall, Repton, near Burton-on-Trent, Staffordshire Client: Sir Francis Burdett, Bart.	1892; 1911; 1924; 1928
TR MES AD1/890	Structure: Greenhouse Location: Walton on the Hill, Staffordshire Client: Joseph S. Burton [Builder]	1905
TR MES AD1/900	Structure: Conservatory and vinery Location: Broadfield House, Branston Road, Burton-on-Trent, Staffordshire Client: Mrs Brooks	1904
TR MES AD1/932	Structure: Stove and pit Location: Loxley Hall, Uttoxeter, Staffordshire Client: Stephen Blount	1903
TR MES AD1/961 See also TR MES AD1/962	Structure: Glasshouse; Boiler Location: The Rowans, Ashby Road, Burton-on-Trent, Staffordshire Client: S. Briggs	1906; 1924
TR MES AD1/962 See also TR MES AD1/961	Structure: Propagating house Location: Rowans, Ashby Road, Burton-on-Trent, Staffordshire Client: S. Briggs	1905
TR MES AD1/962	Structure: Plant and forcing house Location: The Burton Copper Mills, Burton-on-Trent, Staffordshire Client: Briggs and Co.	1892
TR MES AD1/1019	Structure: Heating apparatus Location: The Manor House, Linton, Burton-on-Trent, Staffordshire Client: Mrs J. Beard	1904

TR MES AD1/1025 [2 packets]	Structure: Conservatory and verandah; Plant house Location: The Oaklands, Rowley Avenue, Stafford, Staffordshire Client: H. Bostock	1903; 1906
TR MES AD1/1033	Structure: Heating apparatus Location: Lightwood Rocks, Longton, Staffordshire Client: W.A. Adderley	1894
TR MES AD1/1061	Structure: Conservatory Location: Rowley Park, Stafford, Staffordshire Client: F. Amies	1902
TR MES AD1/1083	Structure: Glasshouses including vinery; Fernery roof; Conservatory Location: Eureka Lodge, Swadlincote, Burton-on-Trent, Staffordshire Client: John D. Wragg	1892; 1896; 1901
TR MES AD1/1089	Structure: Vinery; Vinery; Ventilation; Greenhouse Location: 67 Branstone Road, Burton-on-Trent, Staffordshire Client: John A. Walker	1894; 1897; 1904; 1906
TR MES AD1/1123	Structure: Plant house Location: Crescent Brewery, Burton-on-Trent, Staffordshire Client: E. Wright	1889
TR MES AD1/1178	Structure: Glasshouse Location: Idle Rocks, Stone, Staffordshire Client: Mrs Godfrey Wedgwood	1905
TR MES AD1/1239	Structure: Heating apparatus and glasshouses Location: Meece House, near Stone, Staffordshire Client: E.J.W. Wood	1901
TR MES AD1/1494	Structure: Glasshouses; Forcing house Location: Beechfield, Penkhull, Stoke-on-Trent, Staffordshire Client: H.M. Robinson	1893; 1896
TR MES AD1/1507	Structure: Heating apparatus Location: Great Northern Wharf, Wetmore Road, Burton-on-Trent, Staffordshire Client: Redfern and Mason	1905
TR MES AD1/1517	Structure: Orchid house Location: Trentham Vicarage, Stoke-on-Trent, Staffordshire Client: Rev. Edmund V. Piggott	1888
TR MES AD1/1561	Structure: Heating apparatus Location: Tramway Depot, Stoke-on-Trent, Staffordshire Client: Potteries Electric Traction Company	1901; 1907
TR MES AD1/1584	Structure: Glasshouses Location: Queens Park, Longton, Staffordshire Client: J.W. Wardel [Borough Surveyor]	1891
TR MES AD1/1610	Structure: Conservatory Location: Hartshill Hall, Stoke-on-Trent, Staffordshire Client: R. Nicholls	1899
TR MES AD1/1648	Structure: Conservatory Location: Tattenhill, Burton-on-Trent, Staffordshire Client: J.J. Newbould	1904
TR MES AD1/1662	Structure: Heating apparatus Location: Stowe House, Lichfield, Staffordshire Client: Mrs Roby Thorpe	1906
TR MES AD1/1710	Structure: Greenhouse Location: 20 Gaolgate Street, Stafford, Staffordshire Client: Thomas Till	1893

TR MES AD1/1721	Structure: Plant house Location: Rosendale, The Brampton, Newcastle, Staffordshire Client: T. Taylor	1898
TR MES AD1/1728	Structure: Conservatory Location: Torrington House, Burton-on-Trent, Staffordshire Client: J.N. Tresise	1890
TR MES AD1/1745	Structure: Glasshouse Location: Horton Lodge, Rudyard, Staffordshire Client: S.C. Thompson	1891
TR MES AD1/1766	Structure: Glasshouse; Stove house; Boiler Location: Portland House, Blyth Bridge, Stoke-on-Trent, Staffordshire Client: H. Aynsley	1907; 1921
TR MES AD1/1872	Structure: Forcing house Location: Highfield Manor, Stafford, Staffordshire Client: David Hollins	1900
TR MES AD1/1908	Structure: Greenhouse Location: Branscombe, Stretton, Burton-on-Trent, Staffordshire Client: Mrs G. Greensmith	1907
TR MES AD1/1931	Structure: Glasshouse Location: Teddersley, Penkridge, Staffordshire Client: Lord Hatherton	1908
TR MES AD1/1939	Structure: Tomato house Location: Clifton Terrace, Uttoxeter Road, Blythe Bridge, Staffordshire Client: D.H. Stewart [Architect]	1908
TR MES AD1/1972	Structure: Boiler; Boiler; Heating alterations Location: St Aidan's Church, Shobnall Road, Burton-on-Trent, Staffordshire Client: Bass, Ratcliff and Cretton Ltd; Percy Stokes [Secretary]	1906; 1945; 1947
TR MES AD1/1973	Structure: Heating apparatus Location: Holy Trinity Church, Burton-on-Trent, Staffordshire Client: H.E. Mear [Church Warden]	1898
TR MES AD1/1975 [1 of 3 packets]	Structure: Boiler repairs; Boiler Location: Stretton Church, Stretton, Burton-on-Trent, Staffordshire Client: Bass, Ratcliff and Cretton Ltd; Rev. J. Edwards	1921; 1937
TR MES AD1/1975 [2 of 3 packets]	Structure: Hot water apparatus Location: Stretton Church, Stretton, Burton-on-Trent, Staffordshire Client: J.T. Micklethwaite [Architect]	1895
TR MES AD1/1975 [3 of 3 packets]	Structure: Boilers Location: St. Mary's Church, Stretton, Burton-on-Trent, Staffordshire Client: Bass, Ratcliff and Cretton Ltd	1915

Records of Properties in Suffolk

TR MES AD1/157	Structure: Conservatory Location: Barnadistron Hall, Haverhill, Suffolk Client: Lady Malcolm of Poltallock	1903
TR MES AD1/545	Structure: Vinery Location: Statton Hall, Ipswich, Suffolk Client: J.O. Fison	1895
TR MES AD1/767	Structure: Heating apparatus for warehouse Location: Beccles, Suffolk Client: Messrs Clowes and Son [Printers]	1893
TR MES AD1/807	Structure: Heating apparatus Location: Baptists Sunday School, Lewes, East Suffolk Client: H. Curtis Card [Architect]	1899
TR MES AD1/895	Structure: Conservatory Location: Park Gate Mansion, Normanhurst, Battle, Suffolk Client: Right Hon. Lord Brassey, KCB	1889
TR MES AD1/1077	Structure: Plant house and pit Location: Blackheath, Saxmundham, Suffolk Client: Commander Vernon Wentworth	1902
TR MES AD1/1079	Structure: Conservatory Location: Little Beville, Bures, Suffolk Client: F. Welsted	1899
TR MES AD1/1193	Structure: Conservatory Location: Hamilton House, Newmarket, Suffolk Client: John Watts	1892
TR MES AD1/1405	Structure: Conservatory Location: Heathside, Newmarket, Suffolk Client: W.B. Sheppard	1890
TR MES AD1/1440	Structure: Plant house Location: Side Hill Stud, Newmarket, Suffolk Client: Mrs Sherwood	1900
TR MES AD1/1616	Structure: Heating apparatus Location: Kennett Hall, Newmarket, Suffolk Client: Capt. Pering	1905
TR MES AD1/1816	Structure: Plant house Location: White Lodge, Cheveley, Newmarket, Suffolk Client: S.W. Graystone	1907

Records of Properties in Surrey

TR MES AD1/83	Structure: Heating to shop and office Location: Post Office, Worcester Park, Surrey Client: Millward and Son	1895
TR MES AD1/106	Structure: Conservatory Location: Oxted, Surrey Client: Mr Money Marsland per Ellis Marsland [Architect]	1893
TR MES AD1/113	Structure: Conservatory Location: The Dormers, Langley Avenue, Surbiton, Surrey Client: Mr Mazetti per Hampton and Sons [Builders]	1905
TR MES AD1/146	Structure: Greenhouse Location: Westfield, Catherine Road, Surbiton, Surrey Client: Dr H.A. Martin	1900
TR MES AD1/169	Structure: Plant house Location: Bryony Hill, Hambledon, Surrey Client: Mr Muir	1891, 1894
TR MES AD1/170	Structure: Conservatory Location: The Laurels, Chiddingfold, Godalming, Surrey Client: J. F. Milner	1889-1890
TR MES AD1/179	Structure: Conservatory Location: Tangle Hill, Chilworth, Guildford, Surrey Client: Sir Philip Magnus	1901
TR MES AD1/186	Structure: Plant house Location: Elm House, West Clandon, Guildford, Surrey Client: H. Mott	1898
TR MES AD1/195	Structure: Glasshouses Location: Fir Croft, Withdean, Brighton Client: Daniel Hack	1900
TR MES AD1/221	Structure: Conservatory Location: Lovelace Gardens, Surbiton, Surrey Client: J. Jenkins	1890
TR MES AD1/269	Structure: Greenhouse Location: High View, Oatlands, Walton-on-Thames, Surrey Client: Ernest Hill	1904
TR MES AD1/347	Structure: Plant house Location: Sutton Place, Guildford, Surrey Client: Sydney Harrison	1889
TR MES AD1/411	Structure: Conservatory Location: Oakdale, Ockley, Surrey Client: E.A. Hamlyn	1902
TR MES AD1/412	Structure: Orchid house Location: Elm House, Leatherhead, Surrey Client: Frank G. Howell	1891
TR MES AD1/460 [3 packets]	Structure: Greenhouse; Conservatory Location: Shamrock, Matham Road, East Molesey, Surrey Client: A.J. Gillott	1891-1895
TR MES AD1/477	Structure: Plant house and stove Location: Hazelhurst, Worcester Park, Surrey Client: Charles Garton	1891
TR MES AD1/527	Structure: Forcing House Location: Broome Park, Betchworth, Surrey Client: Lady Louisa Fielding	1905
TR MES AD1/548	Structure: Vinery, stove and pits Location: The Grange, Sutton, Surrey Client: R.C. Forster	1903

TR MES AD1/565	Structure: Greenhouse Location: Lodge Hill, Farnham, Surrey Client: Miss J. Fildes	1901
TR MES AD1/615	Structure: Greenhouse Location: Tanfield, West Clandon, Guildford, Surrey Client: Mrs Du Buisson	1898
TR MES AD1/623	Structure: Greenhouse Location: Avenue House, Sunbury-on-Thames, Surrey Client: Horace Dove	1899
TR MES AD1/632	Structure: Conservatory Location: Warren Road, Guildford, Surrey Client: Stanley Ellis [Builder]	1903
TR MES AD1/632	Structure: Greenhouse Location: 29 Chertsey Street, Guildford, Surrey Client: Stanley Ellis [Builder]	1933
TR MES AD1/634	Structure: Greenhouse Location: The Cottage, Lyne, Chartsey, Surrey Client: Wallace Elliot	1904
TR MES AD1/637	Structure: Stove and repair work Location: Woodlands, Cobham, Surrey Client: C.W. Earle	1889
TR MES AD1/641	Structure: Greenhouse Location: Kingston Estate, Beaufort Road, near Surbiton, Surrey Client: Messrs Edmeston and Gabriel [Architects]	1896
TR MES AD1/666	Structure: Conservatory Location: Wootton House, Dorking, Surrey Client: W.E. Evelyn per Pulman and Son	1901
TR MES AD1/679	Structure: Heating apparatus; Glasshouse Location: Tyrells, Leatherhead, Surrey Client: L.D. Cunliffe	1891; 1896
TR MES AD1/680	Structure: Plant house Location: The Lodge, Thames Ditton, Kingston-on-Thames, Surrey Client: Sir Guy Campbell	1900
TR MES AD1/681	Structure: Conservatory; Painting glasshouse Location: Streatham Ladge, Lower Streatham, Surrey Client: E. Coulthurst	1888; 1895
TR MES AD1/700	Structure: Plant house Location: Gatton Cottage, Reigate, Surrey Client: Mrs Crawford	1895
TR MES AD1/706	Structure: Heating apparatus Location: Torthorwald, Holmwood, Dorking, Surrey Client: Rev. W Carlile	1895
TR MES AD1/710	Structure: Heating apparatus Location: Brookside Hill, Sandhurst, Camberley, Surrey Client: W. Napier Church	1904
TR MES AD1/716 [2 packets]	Structure: Glass houses; Vinery and cool peach house Location: Hedley Court, Epsom, Surrey Client: Walter Cunliffe	1894; 1901
TR MES AD1/718	Structure: Conservatory and lobby Location: Greenhayes, Doods Park Road, Reigate, Surrey Client: Miss Rosa E. Cooper	1902
TR MES AD1/724 [2 packets]	Structure: Range and pit; Plant house; Boiler Location: Worplesdon St Mary, near Guildford, Surrey Client: Miss Cunliffe	1893; 1900; 1908

TR MES AD1/732	Structure: Heating apparatus Location: Chessington Lodge, Chessington, Surrey Client: D.R. Cameron	1908
TR MES AD1/738	Structure: Boiler installation and replacement in greenhouse Location: "Chaleshurst", Chiddingfold, Surrey Client: Rev. S. Cooper	1904-1912
TR MES AD1/742 [8 packets]	Structure: Conservatory, greenhouse, pits, Vineries Location: "Birtley", Bramley, Guildford, Surrey Client: Hon. Henry Cubitt	1891-1896
TR MES AD1/742	Structure: Conservatory/Vinery/fruit houses heating apparatus repairs Location: "The Denbies", Dorking, Surrey Client: Hon. Henry Cubitt	1904-1917
TR MES AD1/742	Structure: Heating to St Barnabas Church Location: Ranmore, Dorking, Surrey Client: Hon. Henry Cubitt	1907-1908
TR MES AD1/742	Structure: Vineries and Church boiler repairs Location: "The Denbies", Dorking, Surrey and St Barnabas Church, Ranmore Client: Rt. Hon. Lord Ashcombe [Hon. Henry Cubitt]	1924-1944
TR MES AD1/749	Structure: Plant House Location: Norfolk House, Kew Road, Richmond, Surrey Client: A. Chancellor	1899
TR MES AD1/752	Structure: Conservatory Location: Paines Hill, Limpsfield, Surrey Client: E. Cooper per G.E. Streatfield [Architect]	1902
TR MES AD1/757 [3 packets]	Structure: Conservatory and painting Location: Thorncote, Staines, Surrey Client: Sir E. Clarke, KC	1901
TR MES AD1/768	Structure: Conservatory Location: Surrey Lodge, Hersham, Walton on Thames, Surrey Client: Mr Capon per Messrs Crickmay [Architects]	1900
TR MES AD1/795	Structure: Plant house Location: Kilmarnock Lodge, Caterham Valley, Surrey Client: Edmund Chalk	1896
TR MES AD1/825 [2 of 7 packets]	Structure: Ventilating equipment for stables Location: Kingston Road, Raynes Park, Surrey Client: William Whiteley per A.M. Ridge [Architect]	1898
TR MES AD1/839	Structure: Conservatory and Fernery Location: Marlyns House, Guildford, Surrey Client: W.H. Burbidge	1888
TR MES AD1/852	Structure: Greenhouse Location: The Pines, Englefield Green, Surrey Client: Henry Bishop	1903
TR MES AD1/853	Structure: Greenhouse Location: Dickhurst, near Haslemere, Surrey Client: J.H. Baker	1902
TR MES AD1/862	Structure: Conservatory Location: Beech Hill, Mayford, Woking, Surrey Client: Samuel Bircham	

TR MES AD1/868	Structure: Repairs to greenhouses; Painting; Location: Beech Hollow, Oatlands Park, Weybridge, Surrey Client: Alfred F. Bloxam	1893; 1898-1899
TR MES AD1/871	Structure: Peach house Location: Quarry House, Bletchingley, Surrey Client: Harrington E. Broad	1904
TR MES AD1/886	Structure: Greenhouse Location: Colley Manor, Reigate Heath, Surrey Client: F.N. Horne per Buckland and Waters [Builders]	1904
TR MES AD1/891	Structure: Conservatory, Plant house and stove Location: The Woodlands, Reigate, Surrey Client: J.J. Brown	1893
TR MES AD1/920	Structure: Heating apparatus Location: Gosbury Hall, Hook, Surbiton, Surrey Client: A. Barnett	1896
TR MES AD1/945	Structure: Vinery and peach house; Plant house Location: Ashtead Grange, Leatherhead, Surrey Client: W.T. Birts	1895; 1902
TR MES AD1/965	Structure: Vinery; Vinery Location: Upper Gatton Park, Merstham, Surrey Client: Alex D. Druce; A. Benson	1893; 1900
TR MES AD1/1036 [2 packets]	Structure: Orchid houses; Vinery; Conservatory; Glasshouse; Boiler Location: Pippbrook, Dorking, Surrey Client: H. Gurney Aggs	1891; 1892; 1913; 1914; 1915
TR MES AD1/1039	Structure: Plant house, stove, fernery and passageway Location: Heathersett, Reigate, Surrey Client: Julius Auerback	1904
TR MES AD1/1066	Structure: Conservatory Location: Eastfield Lodge, Guildford, Surrey Client: Rev. F. Ashpital	1894
TR MES AD1/1076 [2 packets]	Structure: Heating apparatus; Boiler; Heating apparatus Location: Bartholomew Press, South Street, Dorking, Surrey Client: Adland and Son [Printers]	1906; 1927; 1949
TR MES AD1/1086	Structure: Boiler Location: Halfway Lodge, Esher, Surrey Client: Frederick Wicks	1897
TR MES AD1/1095 [2 packets]	Structure: Repairs and painting Location: Sanderstead Court, Sanderstead, near Croyden, Surrey Client: L.A. Wallace; E.D. Morton	1905; 1915
TR MES AD1/1148	Structure: Conservatory Location: Frolbury Manor, Dorking, Surrey Client: G.F.S. Warne	1898
TR MES AD1/1151	Structure: Greenhouse Location: Merstham House, Merstham, Surrey Client: Andrew Walker	1903
TR MES AD1/1162	Structure: Fernery Location: Mansion House Farm, Crowhurst, Lingfield, Surrey Client: John T. Williams	1902
TR MES AD1/1168	Structure: Conservatory Location: The Old House, Shalford, Guildford, Surrey Client: Miss Warburton	1891
TR MES AD1/1173	Structure: Greenhouse Location: Banstead, Surrey Client: W.J. Wells [Builder]	1891

TR MES AD1/1179	Structure: Glasshouse Location: The Cedars, Epsom, Surrey Client: A.J. Warren	1905
TR MES AD1/1185	Structure: Glasshouse Location: Dormans, Surrey Client: Dr James Watson MD	1901
TR MES AD1/1278	Structure: Conservatory; Vinery and peach house Location: Cross Lanes, London Road, Guildford, Surrey Client: Ferdinand F. Smallpiece	1892; 1902
TR MES AD1/1319	Structure: Plant house Location: Kenwolde Court, Virginia Water, Surrey Client: G. Stevens	1898
TR MES AD1/1338	Structure: Peach houses Location: Bradstone Brook, Shalford, Guildford, Surrey Client: J.F. Renton	1890
TR MES AD1/1358	Structure: Greenhouses; Painting Location: Shalimar, Ewell, Surrey Client: C. Chaloner Smith	1898; 1902
TR MES AD1/1388	Structure: Peach houses; Painting Location: The Priory, Reigate, Surrey Client: Lady Henry Somerset	1896; 1900
TR MES AD1/1406 [1 of 4 packets]	Structure: Plant houses Location: Harestone, Caterham Valley, Surrey Client: W. Garland Soper	1901
TR MES AD1/1406 [2 of 4 packets]	Structure: Peach house, vinery, fernery and heating apparatus Location: Harestone, Caterham Valley, Surrey Client: W. Garland Soper	1893
TR MES AD1/1406 [3 of 4 packets]	Structure: Vineries and peach house Location: Harestone, Caterham Valley, Surrey Client: W. Garland Soper	1898
TR MES AD1/1406 [4 of 4 packets]	Structure: Painting Location: Harestone, Caterham Valley, Surrey Client: W. Garland Soper	1904
TR MES AD1/1461	Structure: Forcing house and plant house Location: Stone Lodge, Cheam, Surrey Client: J.M. Ryrie	1898
TR MES AD1/1478	Structure: Conservatory Location: Medfa, Gloucester Road, Kingston Hill, Surrey Client: W.J. Russell	1896
TR MES AD1/1481	Structure: Greenhouse Location: Highfield, Englefield Green, Surrey Client: Miss Ridge	1894
TR MES AD1/1482	Structure: Greenhouse; Boiler Location: Coopers Hill, Englefield Green, Surrey Client: Royal Indian Engineering College	1901; 1902
TR MES AD1/1489	Structure: Glasshouses Location: Normanswood, Farnham, Surrey Client: Thomas Russell, CMG	1900
TR MES AD1/1493	Structure: Heating alterations; Glasshouses Location: Hall Place, Cranleigh, Surrey Client: E.L. Rowcliffe	1899; 1902
TR MES AD1/1511	Structure: Glasshouse; Boiler Location: Soloms Court, Banstead, Surrey Client: H.K. Rutherford	1906; 1940

TR MES AD1/1515	Structure: Mushroom house, plant house, vinery, stove, potting house, conservatory, and orchid house Location: Stoke Hill, Guildford, Surrey Client: Rev. F. Paynter	1893
TR MES AD1/1545	Structure: Glasshouse Location: Clark's Farm, Capel, Dorking, Surrey Client: George E.B. Pritchett	1909
TR MES AD1/1551 [2 of 2 packets]	Structure: Pit with ridge box Location: Fairholme, Langley Avenue, Surbiton, Surrey Client: H.D. De Quincey	1897
TR MES AD1/1582	Structure: Conservatory Location: The Grove, Esher, Surrey Client: Col. C.J. Price	1887
TR MES AD1/1601	Structure: Glasshouse Location: Highlands, Woldingham, Surrey Client: W.H. Prescott	1906
TR MES AD1/1602	Structure: Conservatory Location: Hills Lea, Guildford, Surrey Client: W. Pimm	1901
TR MES AD1/1605	Structure: Greenhouse Location: Eashing Park, Godalming, Surrey Client: Lord Penzance	1888
TR MES AD1/1615	Structure: Glasshouse; Vinery and peach house Location: The Knipp, Chiddingfold, Surrey Client: J.F. Ogilvy per Horace Farquharson [Architect]	1901; 1905
TR MES AD1/1621 [1 of 6 packets]	Structure: Plant house, stove and intermediate houses Location: Bletchingley Castle, Bletchingley, Surrey Client: A.P. Brandt	1924
TR MES AD1/1621 [2 and 3 of 6 packets]	Structure: Boiler Location: Castle Hill, Bletchingley, Surrey Client: A.P. Brandt	1919; 1923
TR MES AD1/1621 [4, 5, 6 of 6 packets]	Structure: Conservatory Location: Woolpits, Bletchingley, Surrey Client: Henry Partridge	1900
TR MES AD1/1621 [4, 5, 6 of 6 packets]	Structure: Plant houses, palm house, Vineries, forcing house, peach house Location: Castle Hill, Bletchingley, Surrey Client: Henry Partridge	1900
TR MES AD1/1647	Structure: Heating apparatus Location: Claygate, Surrey Client: Braid, Pates and Co. per J. Nicholson and Co	1904
TR MES AD1/1649	Structure: Greenhouse Location: Delville, Reigate, Surrey Client: A.M. Ogle	1901
TR MES AD1/1669	Structure: Peach house Location: Stanton Court, Weybridge, Surrey Client: T.P. Templeman	1903
TR MES AD1/1773	Structure: Conservatory roof Location: Moore Place, Esher, Surrey Client: C.A. Moreing per Messrs Maple and Co.	1907
TR MES AD1/1802	Structure: Glasshouses Location: Wyphurst, Cranleigh, Surrey Client: G.E. Chadwyck-Healey	1907
TR MES AD1/1841	Structure: Greenhouse Location: Derrys Wood, Wonersh, near Guildford, Surrey Client: Jill Courage	1907

TR MES AD1/1875 [1 of 4 packets]	Structure: Vineries; Peach house; Rebuilding conservatory Location: The Grange, Walton on Thames, Surrey Client: Dr George W. Drabble	1909; 1914; 1919
TR MES AD1/1875 [2 of 4 packets]	Structure: Roof to stable yard Location: The Grange, Walton on Thames, Surrey Client: F.H. Cook	1897
TR MES AD1/1875 [3 of 4 packets] Originally numbered 697	Structure: Glasshouses Location: The Grange, Walton on Thames, Surrey Client: F.H. Cook	1899
TR MES AD1/1875 [4 of 4 packets]	Structure: Boiler Location: The Grange, Walton on Thames, Surrey Client: Dr George W. Drabble	1923
TR MES AD1/1875 [5 of 5 packets] Originally numbered 697	Structure: Vinery; Plant house Location: The Grange, Walton on Thames, Surrey Client: F.H. Cook	1895; 1900
TR MES AD1/1876 [1 of 2 packets]	Structure: Boiler; Rebuilding plant house Location: Ham House, Richmond, Surrey Client: Right Hon. Earl of Dysart	1910, 1915, 1927 and 1929; 1928
TR MES AD1/1911	Structure: Conservatory and plant house Location: Warwicks Bench, Guildford, Surrey Client: Bernard Crooke	1908
TR MES AD1/1924	Structure: Plant house and forcing house Location: Woodlands, Ewhurst, Surrey Client: C. Friswell	1909
TR MES AD1/1941	Structure: Heating apparatus Location: Banstead Place, Banstead, Surrey Client: Sir Ralph Neville	1908

Records of Properties in Sussex

TR MES AD1/67	Structure: Vinery Location: 10 The Village, Meads, Eastbourne, Sussex Client: Latter Parsons and Co.	1892
TR MES AD1/105	Structure: Heating apparatus Location: Drill Hall, Seaford, Sussex Client: B.A. Miller [Civil Engineer]	1896
TR MES AD1/216	Structure: Vineries Location: Pevensey, Hastings, East Sussex Client: W.J. Kelsey	1894
TR MES AD1/226	Structure: Heating apparatus for house and conservatory Location: Rotherhill, Midhurst, West Sussex Client: Rev. H.R. Keene	1889
TR MES AD1/249	Structure: Conservatory Location: Hailsham, Sussex Client: Alfred Kent	1898
TR MES AD1/277	Structure: Glasshouse Location: Hylands, Arlington, near Hailsham, Sussex Client: G.S. Harris	1902
TR MES AD1/326	Structure: Vineries Location: Hailsham Vicarage, Hailsham, Sussex Client: Rev. F. Clyde Harvey	1892
TR MES AD1/351	Structure: Heating in greenhouse Location: Hapstead Gardens, Ardingley, Sussex Client: H.H. Hett	1901
TR MES AD1/353	Structure: Conservatory Location: Slindon House, Arundel, West Sussex Client: Major Leslie per Hampton and Sons	1905
TR MES AD1/448	Structure: Conservatory Location: 1 Dorset Mansions, Bexhill on Sea, East Sussex Client: Mrs Gibson	1901
TR MES AD1/625	Structure: Plant house Location: Bexhill-on-Sea, East Sussex Client: Earl de la Warr	1899
TR MES AD1/627	Structure: Greenhouse Location: Copyhold, Cuckfield, Sussex Client: Bernard L. Drake	1913
TR MES AD1/653	Structure: Greenhouse Location: Diamond House, Burgess Hill, Sussex Client: Ellis, Drew and Co.	1892
TR MES AD1/784	Structure: Plant house Location: Coghurst Hall, Ore, Hastings, East Sussex Client: H. Coghill	1897
TR MES AD1/876	Structure: Heating apparatus Location: Fir Grove, East Hoathly, Sussex Client: Capt. George Bryan	1889
TR MES AD1/881 [2 packets]	Structure: Conservatory; Glasshouses Location: 8 Hanover Crescent, Brighton, East Sussex Client: G.H. Attree; E.M. Marx	1893; 1907
TR MES AD1/893	Structure: Heating apparatus Location: Arundel Police Station, Arundel, West Sussex Client: Arthur Burrell [Builder]	1901
TR MES AD1/923	Structure: Vinery, Forcing, Tomato, Peach and Plant houses Location: Oaklands, Haywards Heath, Sussex Client: James Bradford	1906

TR MES AD1/926	Structure: Heating apparatus and repair work Location: Wakehurst Place, Haywards Heath, Sussex Client: T.W. Boord	1894
TR MES AD1/1009	Structure: Conservatory Location: Robson House, Surrenden Road, Preston Park, Brighton, Sussex Client: H.R. Blackburn	1898
TR MES AD1/1017	Structure: Plant house Location: St Leonards Lodge, Maze Hill, St Leonards-on-sea, East Sussex Client: A.H. Burton	1900
TR MES AD1/1062	Structure: Forcing house Location: Shernfold Park, Frant, Tunbridge Wells, East Sussex Client: Hon. J. Ashburnham	1895
TR MES AD1/1132	Structure: Glasshouses including vinery Location: Sunnyside, Upper Lewes Road, Brighton, Sussex Client: A. Wallis	1900
TR MES AD1/1159	Structure: Conservatory Location: Ferndale Bank, Tunbridge Wells, East Sussex Client: J.S. Weare	1887
TR MES AD1/1167	Structure: Early vinery; Plant house and vinery Location: Hartfield Grove, Colemans Hatch, Sussex Client: Sir Spencer Walpole KCB	1905; 1906
TR MES AD1/1290	Structure: Hot water heating Location: Sussex County Lunatic Asylum, Haywards Heath, Sussex Client: Henry Card [Architect]	1899
TR MES AD1/1346	Structure: Greenhouse Location: Lavant, Chichester, West Sussex Client: Rev. G. Riadore	1888
TR MES AD1/1374	Structure: Conservatory Location: Wadhurst Place, Sussex Client: W.D. Watson Smyth	1886
TR MES AD1/1393 [4 packets]	Structure: Greenhouses, conservatory, forcing house, intermediate house, pit, installing running water and heating apparatus, painting; Firebars Location: Stonehurst, Ardingley, Sussex Client: J. Stuart	1894-1899; 1909
TR MES AD1/1399 [1 of 2 packets]	Structure: Greenhouse Location: Lydhurst, Haywards Heath, Sussex Client: E. Steinkopff	1901
TR MES AD1/1399 [2 of 2 packets]	Structure: Plant and forcing houses Location: Lydhurst, Haywards Heath, Sussex Client: Mrs Stewart Mackenzie	1907
TR MES AD1/1423	Structure: Conservatory Location: Tivoli House, Withdean, Brighton, East Sussex Client: James Savage	1902
TR MES AD1/1427	Structure: Greenhouse Location: Slaugham, near Crawley, Sussex Client: Capt. Sergison	1900
TR MES AD1/1476 [2 packets]	Structure: Conservatory, corridor, stove, intermediate house, plant house, potting shed and fernery Location: Broadhill, Keymer, Hassocks RSO, Sussex Client: G.W. Ryder	1901

TR MES AD1/1546 [2 of 2 packets]	Structure: Glasshouse Location: Bilbury, Mill Gap Road, Eastbourne, Sussex Client: Theodore W. Pritchett	1925
TR MES AD1/1564	Structure: Vineries; Vinery; Painting Location: Stonelands, East Grinstead, West Sussex Client: F. Godwin King per W. Parton	1899; 1900; 1901
TR MES AD1/1612	Structure: Conservatory; Glasshouse Location: Tanbridge, Horsham, West Sussex Client: Thomas Oliver	1889; 1906
TR MES AD1/1618	Structure: Conservatory Location: Dyke Road, Brighton, East Sussex Client: W. Porter	1901
TR MES AD1/1651	Structure: Conservatory Location: Broadwater Manor, Worthing, Sussex Client: H. Nye	1904
TR MES AD1/1733	Structure: Plant house, forcing houses, shed, conservatory; Plant house Location: Beech Hurst, Haywards Heath, West Sussex Client: S. Tyzack	1901; 1904
TR MES AD1/1758	Structure: Boiler and heating apparatus Location: Huntsland, Crawley Down, Sussex Client: E. Cayford	1907
TR MES AD1/1797	Structure: Pit frames; Heating apparatus Location: East Court, East Grinstead, West Sussex Client: E. Cooper	1907; 1910
TR MES AD1/1803 [1 of 2 packets]	Structure: Peach house Location: Eartham House, Chichester, West Sussex Client: Sir W.B.M. Bird, Bart	1910
TR MES AD1/1803 [2 of 2 packets]	Structure: Glasshouses; Boiler; Boilers Location: Eartham House, Chichester, West Sussex Client: Sir W.B.M. Bird, Bart	1906; 1922; 1931
TR MES AD1/1814	Structure: Glasshouse Location: Sylvan Lodge, Brighton, East Sussex Client: H.J. Infield, J.P.	1907
TR MES AD1/1950	Structure: Glasshouse Location: Manor House, Horsham, Sussex Client: Mrs Padwick	1907

Records of Properties in Warwickshire

TR MES AD1/103	Structure: Greenhouse Location: The Gate House, Mere Vale, Atherstone, Warwickshire Client: P.H. Parry Mitchell	1896
TR MES AD1/104 [2 packets]	Structure: Painting to greenhouses Location: Sulby Hall near Rugby, Warwickshire Client: Major Guy Paget	1930
TR MES AD1/104	Structure: Vinery, Azalea house and other glasshouses Location: Sulby Hall, Rugby, Warwickshire Client: Miss Mansell, Major E.D. Mansell	1899-1902
TR MES AD1/165	Structure: Conservatory Location: The Manor House, Nelford, Rugby, Warwickshire Client: Ernest Mansell	1900
TR MES AD1/185	Structure: Conservatory Location: Palton House, Rugby, Warwickshire Client: F. A. Morris	1902
TR MES AD1/199	Structure: Vinery and peach house; Greenhouse Location: Fawley House, Hillmorton Road, Rugby, Warwickshire Client: J.H. Ivens	1903; 1913
TR MES AD1/272	Structure: Greenhouse Location: Grendon Rectory, Grendon, Atherstone, Warwickshire Client: Rev. H. Hanmer	1906
TR MES AD1/293	Structure: Conservatory; Heating apparatus Location: Oaklands, Kenilworth Road, Leamington, Warwickshire Client: A. Holt	1901; 1909
TR MES AD1/346	Structure: Potting shed, plus heating apparatus Location: Twycross, Atherstone, Warwickshire Client: Harrington Hulton	1891
TR MES AD1/377	Structure: Plant house Location: Hasley Manor, Warwick, Warwickshire Client: Alfred Hawlett	1896
TR MES AD1/385	Structure: Fernery Location: Gospel Oak, Lapworth, Warwickshire Client: John Hildick	1905
TR MES AD1/441	Structure: Conservatories Location: Four Elms/The Court, Ullesthorpe, Rugby, Warwickshire Client: H.G. Goodacre per Robert Cooke [Builder]	1902
TR MES AD1/441	Structure: Conservatories Location: Claybrook Grange near Rugby, Warwickshire Client: H.G. Goodacre per Robert Cooke [Builder]	1902
TR MES AD1/534	Structure: Plant House Location: Fox Hill, West Haddon, Rugby, Warwickshire Client: Hon. E.A. Fitzroy	1899
TR MES AD1/537 [2 packets]	Structure: Heating apparatus and greenhouse; Boiler Location: The Croft, Hillmorton, Rugby, Warwickshire Client: George A. Fenwick; Alice K. Fenwick	1893; 1927
TR MES AD1/566	Structure: Plant house Location: Halford Manor, Ettington, Warwickshire Client: F.M. Freake	1903

TR MES AD1/619	Structure: Glass range Location: Wappenbury, Leamington Spa, Warwickshire Client: George Darlinson	1897
TR MES AD1/655	Structure: Peach house Location: Lindley Hall, Nuneaton, Warwickshire Client: Capt. Vincent T. Eyre	1889-1891
TR MES AD1/694	Structure: Plant house Location: Clayhook Grange, Rugby, Warwickshire Client: George Beale	1924
TR MES AD1/702	Structure: Glass house Location: Eastfield, Rugby, Warwickshire Client: J. Cumming	1894
TR MES AD1/753	Structure: Hot water supply Location: Coventry, Warwickshire Client: Coventry and Warwickshire Hospital per Ellis G. Crisp	1901-1902
TR MES AD1/762	Structure: Heating apparatus Location: Coventry Public Bath, Warwickshire Client: Coventry Corporation	1897
TR MES AD1/786 See also TR MES AD1/1474	Structure: Vinery Location: Grendon Hall, Atherstone, Warwickshire Client: Sir Guy Chetwynd, Bart	1906
TR MES AD1/814	Structure: Stove and cucumber house Location: Shottery Hall, Stratford-upon-Avon, Warwickshire Client: H.F. Carter	1906
TR MES AD1/1027	Structure: Peach cover Location: Measham Hall, Atherstone, Warwickshire Client: Sir William Abney	1901
TR MES AD1/1031	Structure: Greenhouses Location: 43 Hillmorton Road, Rugby, Warwickshire Client: Mrs Arundel	1895; 1897
TR MES AD1/1146	Structure: Conservatory; Painting; Painting Location: The Elms, Southam, Warwickshire Client: William Wood	1895; 1910; 1918
TR MES AD1/1186	Structure: Heating apparatus Location: Earlsdon, Coventry, Warwickshire Client: R.J. Pike per J. Worwood [Builder]	1889
TR MES AD1/1307	Structure: Conservatory Location: Horton Street West, Rugby, Warwickshire Client: G. Stallard	1893
TR MES AD1/1369	Structure: Glasshouses Location: Newbold Revel, Rugby, Warwickshire Client: Rev. Richard Wood	1887
TR MES AD1/1372	Structure: Boiler Location: Newbold Revel, Rugby, Warwickshire Client: A.H.E. Wood	1896
TR MES AD1/1383 [2 packets]	Structure: Heating apparatus, steam cooking apparatus and hot water supply Location: Gate Hotel, Nuneaton, Warwickshire Client: R. Stanley	1896
TR MES AD1/1421 [1 of 2 packets]	Structure: Conservatory and heating apparatus Location: Bawnmore, Bilton, Rugby, Warwickshire Client: Capt. H. Riall Sankey	1902

TR MES AD1/1421 [2 of 2 packets]	Structure: Heating apparatus; Stove, plant house and pit Location: Bawnmore, Bilton, Rugby, Warwickshire Client: Capt. H. Riall Sankey	1897; 1898
TR MES AD1/1422	Structure: Plant and peach houses Location: Idlicote, Shipston on Stour, Warwickshire Client: Right Hon. Lord Southampton	1899
TR MES AD1/1456	Structure: Heating apparatus Location: Rugby Conservative Club, Rugby, Warwickshire Client: T.W. Willard [Architect]	1899
TR MES AD1/1459	Structure: Conservatory and forcing house Location: The Cottage, Coundon, Coventry, Warwickshire Client: William Ratcliff	1897
TR MES AD1/1471	Structure: Conservatory; Greenhouse Location: The Elms, Coventry, Warwickshire Client: W.L. Robinson	1890; 1899
TR MES AD1/1485	Structure: Heating apparatus and conservatory Location: Overslade, Rugby, Warwickshire Client: Mark Robinson	1897
TR MES AD1/1498	Structure: Peach house Location: Keresley Grange, Coventry, Warwickshire Client: John Rotherham	1902
TR MES AD1/1516	Structure: Conservatory; Heating Location: Higham Grange, Nuneaton, Warwickshire Client: Hon. E.H. Pierrepont	1887; 1901
TR MES AD1/1575	Structure: Peach house Location: Brooklyn, Coventry, Warwickshire Client: G.A. Pridmore	1892
TR MES AD1/1581 [1 of 3 packets]	Structure: Plant house Location: Southfield House, Horton Street, Rugby, Warwickshire Client: Miss Pennington	1899
TR MES AD1/1581 [2 of 3 packets]	Structure: Painting and heating apparatus Location: Southfield House, Horton Street, Rugby, Warwickshire Client: Miss Pennington	1900
TR MES AD1/1581 [3 of 3 packets]	Structure: Orchard house Location: Southfield House, Horton Street, Rugby, Warwickshire Client: Miss Pennington	1907
TR MES AD1/1585	Structure: Removing radiators Location: Imperial Hotel, Rugby, Warwickshire Client: Charles Cockerill [Builder]	1918
TR MES AD1/1585	Structure: Heating apparatus; Boiler repairs Location: Peacock Inn, Newbold Road, Rugby, Warwickshire Client: F.W. Willard [Architect]	1899; 1918
TR MES AD1/1595	Structure: Wall cover Location: Radford, Leamington, Warwickshire Client: J.L. Paton	1894
TR MES AD1/1596	Structure: Glasshouse Location: Ashlawn, The Inwoods, Rugby, Warwickshire Client: J. Parnell	1894
TR MES AD1/1597	Structure: Curvilinear plant house and fernery Location: Rainsbrook, Rugby, Warwickshire Client: J. Parnell	1896

TR MES AD1/1715	Structure: Greenhouse Location: Bridge House, Hartshill, Atherstone, Warwickshire Client: W. Taylor	1893
TR MES AD1/1742	Structure: Conservatory Location: Lillington Lodge, 56 Kenilworth Road, Leamington Spa, Warwickshire Client: F. Thorne	1897
TR MES AD1/1747	Structure: Vinery Location: The Manor House, Knowle, Warwickshire Client: Edward Tangye	1901
TR MES AD1/1754	Structure: Conservatory Location: Hasely Manor, Warwick, Warwickshire Client: Alfred Hewlett	1907
TR MES AD1/1755	Structure: Heating and hot water supply to stables; Frames; Blinds Location: Cawston House, Dunchurch, Warwickshire Client: Right Hon. Duke of Buccleuch; Lord Glenapp; Lord Inchcape	1908; 1930; 1935
TR MES AD1/1764	Structure: Greenhouse Location: Birchville, Whitehall Road, Rugby, Warwickshire Client: B. Haynes	1908
TR MES AD1/1833	Structure: Carnation house and other glasshouses Location: Bourton Hall, near Rugby, Warwickshire Client: F. Shaw	1907
TR MES AD1/1849 [1 of 2 packets]	Structure: Stove and plant house Location: Fairhill, Coventry, Warwickshire Client: John Powers	1901
TR MES AD1/1849 [2 of 2 packets]	Structure: Glasshouses Location: Mill House, Coventry, Warwickshire Client: John Powers	1892
TR MES AD1/1935	Structure: Plant house and forcing house Location: Elmhurst, Rugby, Warwickshire Client: Thomas Hunter [Builder]	1908
TR MES AD1/1947 [1 of 2 packets]	Structure: Boiler Location: Bilton Rise [Formerly Plex House], Rugby, Warwickshire Client: F. Merttens	1921
TR MES AD1/1947 [2 of 2 packets]	Structure: Conservatory; Peach house Location: Plex House, Old Bilton, Rugby, Warwickshire Client: J.C. Peache	1907; 1908
TR MES AD1/1971	Structure: Heating apparatus Location: Bilton Church, Bilton, Rugby, Warwickshire Client: Capt. H. Riall Sankey, RE	1901

Records of Properties in the West Midlands

TR MES AD1/220	Structure: Boiler Location: Stourbridge, West Midlands Client: Jones and Attwood [Engineers]	1891
TR MES AD1/408	Structure: Conservatory Location: Olton Court, Olton, Birmingham, West Midlands Client: D.C. Hasluck	1891
TR MES AD1/677	Structure: Glasshouses Location: Bella Vista, Hartopp Road, Sutton Coldfield, West Midlands Client: Job Coley	1897-1898
TR MES AD1/725	Structure: Conservatory and forcing house Location: 3 Westbourne Road, Edgbaston, Birmingham, West Midlands Client: E.M. Carter	1905
TR MES AD1/949	Structure: Greenhouse Location: Newlyn, Driffold Road, Sutton Coldfield, West Midlands Client: Charles H. Brampton	1891
TR MES AD1/1047 [1 of 2 packets]	Structure: Extension to ballroom, stable roof and windows; Conservatory Location: Normanhurst, Boldmere, Wylde Green, West Midlands Client: Joseph Appleby	1897; 1899
TR MES AD1/1047 [2 of 2 packets]	Structure: Heating apparatus; Heating apparatus; Boiler; Boiler Location: New works, Tower Road, Aston, Birmingham, West Midlands Client: Joseph Appleby Ltd	1915; 1920; 1931; 1945
TR MES AD1/1166 [1 of 2 packets]	Structure: Vinery; Cool house Location: Uplands, Selly Hill, Birmingham, West Midlands Client: Charles Winn	1906; 1910
TR MES AD1/1166 [2 of 2 packets]	Structure: Vinery; Rebuilding vineries Location: Uplands, Selly Hill, Birmingham, West Midlands Client: Charles Winn	1905; 1914
TR MES AD1/1170	Structure: Plant house Location: West Park, Wolverhampton, West Midlands Client: Wolverhampton Corporation per borough surveyor	1897
TR MES AD1/1414	Structure: Plant and forcing house Location: Tettenhall, Wolverhampton, West Midlands Client: C.E. Shaw, MP	1902
TR MES AD1/1445	Structure: Plant house Location: The Knoll, Sutton Coldfield, West Midlands Client: John Charles Skelton	1889
TR MES AD1/1466	Structure: Conservatory; Forcing house Location: The Pines, Penn Road, Wolverhampton, West Midlands Client: J. Rollings	1895; 1897

Records of Properties in Wiltshire

TR MES AD1/90	Structure: Conservatory; Greenhouse Location: Marlborough College, Marlborough, Wiltshire Client: Mr J. Gibson Bulmer	1904; 1913
TR MES AD1/107	Structure: Greenhouse Location: Bassett Down House, near Swindon, Wiltshire Client: Mrs Maskelyne	1889
TR MES AD1/127	Structure: Heating apparatus Location: Hampworth Lodge, Downton, Salisbury, Wiltshire Client: Mrs Morrison	1896
TR MES AD1/140	Structure: Glass verandah Location: Savernake Hospital, near Marlborough, Wiltshire Client: Marlborough Cottage Hospital	1904
TR MES AD1/166	Structure: Greenhouse Location: Polebarn House, Trowbridge, Wiltshire Client: William Mackay	1899
TR MES AD1/332	Structure: Greenhouse Location: Sandle Manor, Fording Bridge, Salisbury, Wiltshire Client: Sir Edward Hulse, Bart	1900
TR MES AD1/405	Structure: Heating apparatus Location: Stourton, Gillingham, Wiltshire Client: Sir Henry Ainslie Hoare	1895
TR MES AD1/715	Structure: Conservatory Location: 8 Clarendon Gardens, Trowbridge, Wiltshire Client: J. P Cogswell	1892
TR MES AD1/726	Structure: Plant house; Glasshouse Location: Wingfield House, Trowbridge, Wiltshire Client: Sir Vincent Caillard, Bart	1898; 1905
TR MES AD1/794	Structure: Forcing house and pits Location: Donhead House, Donhead St Andrew, Salisbury, Wiltshire Client: Horace G. Chapman	1899
TR MES AD1/828	Structure: Conservatory; heating apparatus; Greenhouse Location: Downton, Salisbury, Wiltshire Client: John Bailey [Builder]	1898; 1900; 1902
TR MES AD1/856	Structure: Conservatory Location: Elmhurst, Trowbridge, Wiltshire Client: Henry Blake	1893-1894
TR MES AD1/857 [3 and 4 of 6 packets]	Structure: Heating; Plant house and Vinery Location: Belcombe Court, Bradford-on-Avon, Wiltshire Client: Alfred W.N. Burder	1906; 1914
TR MES AD1/1049	Structure: Vineries Location: Beechcroft, Kingsdown, Swindon, Wiltshire Client: Thomas Arkell	1898; 1900
TR MES AD1/1501 [2 of 3 packets]	Structure: Loggia Location: Rushmore, Wiltshire Client: A.E.L.F. Pitt-Rivers	1910
TR MES AD1/1538	Structure: Conservatory Location: The Cranhams, Trowbridge, Wiltshire Client: J.R. Philpott	1892
TR MES AD1/1714	Structure: Plant house and pit Location: Hillcote, Manor Road, Salisbury, Wiltshire Client: A. Tucker	1891

TR MES AD1/1784	Structure: Heating apparatus Location: Biddeston House, Ludgershall, Wiltshire Client: Sir John Denison-Pender, KCMG	1908
TR MES AD1/1825	Structure: Plant house and stove Location: Boveridge Park, Cranborne, Salisbury, Wiltshire Client: G.F. Thursby	1907
TR MES AD1/1930 [2 packets]	Structure: Repairs Location: The Prospect, Trowbridge, Wiltshire Client: Francis Hobson	1908
TR MES AD1/1958	Structure: Plant house, vinery and pit; Painting Location: Preshute House, Marlborough, Wiltshire Client: Rev. P.W. Taylor	1908; 1910

Records of Properties in Worcestershire

TR MES AD1/178	Structure: Tomato house Location: Hanley Castle, Worcestershire Client: G. F. Mann	1903
TR MES AD1/227	Structure: Greenhouse; Vinery Location: Heron Lodge, Red Hill, Worcester, Worcestershire Client: W.Kilbourne Kay	1897-1898; 1903
TR MES AD1/371	Structure: Forcing house Location: Froxmer Court, Worcester, Worcestershire Client: T.W. Hill	1893
TR MES AD1/478	Structure: Conservatory Location: The Gables, Whittington, near Worcester, Worcestershire Client: S. Bromley Garrard	1892
TR MES AD1/480	Structure: Vineries and peach houses Location: Hadzor, Droitwich, Worcestershire Client: H. Gough [Market Gardener]	1891
TR MES AD1/516	Structure: Glasshouses Location: Charlton House, Charlton, Pershore, Worcestershire Client: J. Faulkner	1899
TR MES AD1/614	Structure: Greenhouse Location: Railway Signal Works, Worcester, Worcestershire Client: Messrs. Dutton and Co.	1896
TR MES AD1/649	Structure: Greenhouse Location: Ewe and Lamb Inn, The Butts, Worcester, Worcestershire Client: Yeates and Jones [Architects] per Lewis Clarke and Co.	1901
TR MES AD1/819	Structure: Greenhouse Location: Homestead, Welland, Malvern Wells, Worcestershire Client: Mrs Farthing	1900
TR MES AD1/857 [2 and 5 of 6 packets]	Structure: Motor Garage; Heating to house Location: Powyke Court, Worcester, Worcestershire Client: A.W.N. Burder	1923-1924; 1927-1933
TR MES AD1/1011 [2 packets]	Structure: Camellia, intermediate and stokery houses; Forcing houses Location: Spring Grove, Bewdley, Worcestershire Client: T.W. Binyon; Major W. Harcourt Webb	1905
TR MES AD1/1153	Structure: Heating apparatus Location: Arley Cottage, Bewdley, Worcestershire Client: Charles J. Woodward	1897
TR MES AD1/1717	Structure: Greenhouse Location: Fernhill Park, Fernhill Heath, Worcestershire Client: J.C. Turner	1901
TR MES AD1/1740	Structure: Vinery Location: The Nash, Kempsey, Worcestershire Client: Sir Richard Temple, Bart.	1896

Records of Properties in Yorkshire

TR MES AD1/68	Structure: Plant house Location: Seacroft, Leeds, West Yorkshire Client: Leeds City Hospital	1904
TR MES AD1/96	Structure: Greenhouse Location: Park Villa, Bolton, Yorkshire Client: R. Maisland	1904
TR MES AD1/121	Structure: Plant house and intermediate house; Peach House Location: Melton Park, Doncaster, South Yorkshire Client: Mrs Montague	1896; 1904
TR MES AD1/128	Structure: Plant house Location: Queens Park, Kilburn, North Yorkshire Client: Alex McKenzie	1890
TR MES AD1/132	Structure: Conservatory Location: Heworth Hyrst, York, Yorkshire Client: Mrs Middlewood	1899
TR MES AD1/162	Structure: Plant house Location: Lake View, 25 North Parks Road, Bradford, Yorkshire Client: J. Murgatroyd	1901
TR MES AD1/209	Structure: Greenhouses Location: Treeton Grange, Treeton, near Rotherham, South Yorkshire Client: F.J. Jones	1893; 1901
TR MES AD1/225	Structure: Greenhouse/Conservatory Location: Badsworth Grange, Pontefract, West Yorkshire Client: Mrs Heywood Jones	1889-1891
TR MES AD1/232	Structure: Vinery and plant house Location: Hawthorne Villa, Huddersfield Road, Barnsley, South Yorkshire Client: H. Johnson	1896
TR MES AD1/241	Structure: Glasshouse Location: Holmesfield, Kimberworth, Rotherham, South Yorkshire Client: J.B. Jenkinson	1902
TR MES AD1/257	Structure: Boilers Location: Rotherham, South Yorkshire Client: Messrs. Robert Jenkins and Co, boiler makers	1894-1898
TR MES AD1/273	Structure: Plant house Location: Dunnington Hall, York, Yorkshire Client: John Hildyard	1906
TR MES AD1/287	Structure: Bridge passageway Location: Southfield House, Cottingham, East Yorkshire Client: Joseph H. Horsley	1896
TR MES AD1/341	Structure: Conservatory Location: "The Hollies", Norton Lees, Sheffield, South Yorkshire Client: J. Hall	1902
TR MES AD1/342	Structure: Conservatory Location: Thorpe House, Norton Lees, Sheffield, South Yorkshire Client: G. Hall	1893
TR MES AD1/345	Structure: Conservatory at "New Close" Location: "Holm-Leigh", Cottingley Grange, Nab Wood, Shipley, Bradford, West Yorkshire Client: G. Holmes	1902
TR MES AD1/361	Structure: Conservatory Location: Molescroft, Beverley, East Yorkshire Client: Richard Hodgson	1900

TR MES AD1/370	Structure: Greenhouse Location: National School, Darfield, Barnsley, South Yorkshire Client: George Hoyle	1894
TR MES AD1/403	Structure: Peach house, Cucumber house and potting shed Location: Abbeydale Park, Dore near Sheffield, South Yorkshire Client: E. Hall	1891
TR MES AD1/417	Structure: Plant house Location: Woodhouse Moor, Leeds, West Yorkshire Client: Thomas Hewson	1891
TR MES AD1/466	Structure: Forcing house Location: Garswood Hall, Newton le Willows, North Yorkshire Client: Lady Gerard	1889
TR MES AD1/474	Structure: Conservatory and stove Location: The Hollies, Bramley, near Leeds, West Yorkshire Client: Edwin Gaunt	1895
TR MES AD1/514	Structure: Greenhouse Location: Long Royds, Skelmanthorpe near Huddersfield, South Yorkshire Client: John F. Field	1906
TR MES AD1/523	Structure: Conservatory Location: Cathedine, Burley-in-Wharfedale near Leeds, West Yorkshire Client: E.P. Arnold Foster	1901
TR MES AD1/556	Structure: Iron stage for greenhouse Location: Campsall Hall, Doncaster, South Yorkshire Client: F.B. Frank	1905
TR MES AD1/563 [2 packets]	Structure: Heating apparatus; Vinery and plant houses Location: Holme House, Lightcliffe near Halifax, West Yorkshire Client: Sir Algernon Firth	1902; 1913
TR MES AD1/675	Structure: Conservatory Location: The Gables, Beverley, East Yorkshire Client: Mrs Crust	1894
TR MES AD1/701	Structure: Heating Location: King James' Grammar School, Knaresborough, North Yorkshire Client: Messrs. Barrowcliff and Allcock [Architects]	1900
TR MES AD1/709	Structure: Glass houses Location: Hessele near Hull, Yorkshire Client: F. Costello	1904
TR MES AD1/720	Structure: Heating apparatus Location: Gargrave House, Gargrave, Leeds, West Yorkshire Client: J.W. Coulthurst	1904
TR MES AD1/723	Structure: Orchid Houses Location: Rawdon Hill, Arthington, Leeds, West Yorkshire Client: W. Johnson Cheetham	1889
TR MES AD1/758	Structure: Glass corridor Location: Convent of our Lady of Mercy, Clifford, Boston Spa RSO, Yorkshire Client: Sisters of Mercy	1900
TR MES AD1/760	Structure: Conservatory Location: The Old Hall, Hornsea, Hull, Yorkshire Client: Mrs Strickland Constable	1899
TR MES AD1/774	Structure: Plant house, Conservatory Location: Todwick Grange, Kiveton Park, Sheffield, South Yorkshire Client: J. Staveley Coulton-Fox	1896

TR MES AD1/779	Structure: Glasshouses Location: Boyle House, West Ardsley, Wakefield, South Yorkshire Client: S. Colbeck	1893
TR MES AD1/799	Structure: Alterations to glasshouses Location: Selwood, Rotherham, South Yorkshire Client: C.E. Chrimes	1896
TR MES AD1/817	Structure: Glasshouses Location: Walcot, Frodingham, Doncaster, South Yorkshire Client: J. Goulton Constable	1900
TR MES AD1/830	Structure: Heating apparatus Location: Stairfoot, Barnsley, South Yorkshire Client: Wilton Brook	1894
TR MES AD1/840 [5 packets]	Structure: Greenhouses and conservatories Location: Bradford Moor, Bowling, Harold, Wibsey, Lister and Horton Public Parks, Bradford, Yorkshire Client: Bradford Corporation	1889-1950
TR MES AD1/847	Structure: Glass range Location: Pollard Hall, Gomersal, Cleckheaton, Kirklees, West Yorkshire Client: T.W. Burnley	1897
TR MES AD1/848	Structure: Plant house Location: Tingley Mills, Morley, West Yorkshire Client: H.A. Bradley per W.L. Skinner	1896
TR MES AD1/855 [11 packets]	Structure: Heating apparatus and hot water supply Location: Ale Stores, Tablet Room and Joiners Shop, Kings Road, St Pancras : Dixie Ale Stores, Burton-on-Trent, Staffordshire : Shobnall Ale Stores, Staffordshire : Nags Head, Swadlincote, Staffordshire : Commercial Inn, Sleaford, Lincolnshire : Stores at Wellington Street, Hull, Yorkshire : St Chads Church, Hunter Street, Burton-on-Trent, Staffordshire : Hawkins Lane Stores, Burton-on-Trent, Staffordshire : Old Brewery, High Street, Burton-on-Trent, Staffordshire : General Offices, Kings Road, Pancras Road, London : New Loco Shed Client: Bass, Ratcliff and Gretton Ltd, Burton-on-Trent, Staffordshire	1893-1909
TR MES AD1/859	Structure: Orchid House; Boiler Location: The West Hill, Hessle RSO, near Hull, Yorkshire Client: W.P. Burkinshaw	1897; 1916
TR MES AD1/888	Structure: Vineries Location: Hessle Mount, near Hull, East Yorkshire Client: Col. J.H. Burstall	1897
TR MES AD1/902	Structure: Painting Location: Pollard Hall, Gomersal, near Leeds, West Yorkshire Client: Thomas W. Burnley	1903
TR MES AD1/910	Structure: Heating apparatus Location: Norton Stone and Concrete Company, Norton near Stockton on Tees, Cleveland, Yorkshire Client: John Burn [Builder]	1900

TR MES AD1/928	Structure: Heating apparatus; Plant house; Carnation house Location: Middleton Hall, Middleton on the Wolds, Driffeld, Yorkshire Client: Capt. A.H. Brooksbank	1904; 1905; 1908
TR MES AD1/934	Structure: Conservatory Location: Rolston House, Hornsea, North Yorkshire Client: Capt. H. Booth	1900
TR MES AD1/991	Structure: Conservatory Location: Bents Green, Sheffield, South Yorkshire Client: Mr Blakelock	1899
TR MES AD1/1000	Structure: Conservatory Location: Tyringham, Duchy Road, Harrogate, Yorkshire Client: A.H. Briggs	1906
TR MES AD1/1021	Structure: Conservatory Location: Reinwood, Lindley, Huddersfield, West Yorkshire Client: F.W. Bentley	1900
TR MES AD1/1065	Structure: Stove Location: Cliffe Hill, Lightcliffe, Halifax, West Yorkshire Client: W.H. Aykroyd	1900
TR MES AD1/1091 [1, 2 and 3 of 8 packets]	Structure: Repairs to greenhouses Location: Bishop Burton Hall, Beverley, East Yorkshire Client: Owen S. Hellyer	1937-1938
TR MES AD1/1091 [4, 5, 6 and 8 of 8 packets]	Structure: Greenhouses, vineries, conservatory and verandah; Plant houses Location: Bishop Burton Hall, Beverley, East Yorkshire Client: Ernest Hall Watt	1890-1891; 1895
TR MES AD1/1091 [7 of 8 packets]	Structure: Boilers Location: Bishop Burton Hall, Beverley, East Yorkshire Client: Ernest Hall Watt	1904
TR MES AD1/1103	Structure: Carnation house Location: Warter Priory, Pocklington, Yorkshire Client: Mrs C.H. Wilson	1894
TR MES AD1/1114	Structure: Heating apparatus Location: Coverham Abbey, Middleham, Yorkshire Client: Mrs A. Wright per J.G. Wright [Solicitor]	1903
TR MES AD1/1117	Structure: Glass passage Location: Farnley Tyas Parsonage, near Huddersfield, Yorkshire Client: Rev. C.W. Wardroper	1889
TR MES AD1/1135	Structure: Glasshouses including vinery Location: Fernbank, Heaton, Bradford, West Yorkshire Client: J. Whittingham	1898
TR MES AD1/1155	Structure: Plant house Location: The Banks, Honley near Huddersfield, Yorkshire Client: Charles Holdroyd per Harris Wood [Contractor]	1900
TR MES AD1/1176	Structure: Greenhouse Location: Bedford House, Roundhay, Leeds, West Yorkshire Client: J.W.H. White	1895
TR MES AD1/1232	Structure: Vinery, peach house and glasshouses; Plant house and vinery Location: Oakwood Grange, Roundhay, Leeds, West Yorkshire Client: Thomas Walker; H.S. Walker	1893; 1907
TR MES AD1/1233	Structure: Heating apparatus Location: Ravensthorpe Manor, Thirsk, North Yorkshire Client: F.E. Walker	1900
TR MES AD1/1265	Structure: Range Location: Whitcliffe, Cleckheaton, West Yorkshire Client: Thomas Walker	1896

TR MES AD1/1287	Structure: Conservatory Location: Castle Avenue, Conisborough, Doncaster, South Yorkshire Client: Mr Sharp	1901
TR MES AD1/1305	Structure: Heating apparatus Location: Rock Pottery, Mexborough, South Yorkshire Client: George H. Smith [Builder]	1900
TR MES AD1/1324	Structure: Glazing, painting and ventilating Location: Esholt Hall, Shipley, Yorkshire Client: Miss Crompton Stanfield	1892
TR MES AD1/1330	Structure: Conservatory Location: Lyndhurst, Wadsley, Sheffield, Yorkshire Client: John Henry Swift	1899
TR MES AD1/1331	Structure: Conservatory Location: Egerton House, 450 Glossop Road, Sheffield, Yorkshire Client: Samuel Smith	1897
TR MES AD1/1342	Structure: Greenhouse Location: Paddock, near Huddersfield, Yorkshire Client: Messrs Ramsden and Marsden [Builders]	1893
TR MES AD1/1355	Structure: Plant house Location: Wickersley, Brough RSO, East Yorkshire Client: George L. Shackles	1907
TR MES AD1/1355	Structure: Stove and intermediate house Location: Southfield, Hessle, near Hull, Yorkshire Client: George L. Shackles	1903
TR MES AD1/1370	Structure: Vinery and greenhouses Location: The Waylands, Hessle, Hull, Yorkshire Client: A. Spring	1902
TR MES AD1/1419	Structure: Greenhouse Location: The Cliffe, Wakefield, Yorkshire Client: A.W. Stanfield	1900
TR MES AD1/1441	Structure: Glasshouses Location: Hollins Lane, Keighley, Bradford, West Yorkshire Client: Prince Smith Jnr	1899
TR MES AD1/1447	Structure: Greenhouses Location: Meersbrook Park, Sheffield, Yorkshire Client: Sheffield Corporation	1902
TR MES AD1/1449	Structure: Plant house Location: 6 Bond Street, Wakefield, Yorkshire Client: Miss Scott	1895
TR MES AD1/1464	Structure: Porch Location: Newholm, Whitby, North Yorkshire Client: Mr Pyman per David Richardson	1889
TR MES AD1/1467	Structure: Forcing house; Greenhouse Location: Cliff Lodge, Hyde Park, Leeds, Yorkshire Client: Richard Reynolds	1891; 1899
TR MES AD1/1487	Structure: Conservatory Location: Holgate, York, Yorkshire Client: A.A. Russell	1891
TR MES AD1/1502	Structure: Plant house and stove Location: Rogerthorpe Manor, Pontefract, West Yorkshire Client: Mrs Ramsden	1890
TR MES AD1/1530	Structure: New house Location: Skellow, Doncaster, South Yorkshire Client: D'Arcy S. Preston	1890

TR MES AD1/1555	Structure: Glasshouse Location: Fairstowe, Ilkley, Yorkshire Client: F.W. Pearce	1899
TR MES AD1/1593	Structure: Conservatory Location: Queens Hotel, Harrogate, North Yorkshire Client: John Thompson and Co.	1900
TR MES AD1/1624	Structure: Conservatory Location: Cherry Garth, Cottingham near Hull, Yorkshire Client: W.J. Owbridge	1899
TR MES AD1/1652	Structure: Glasshouses Location: Clayworth, Bawtry, South Yorkshire Client: R.C. Otter	1890
TR MES AD1/1771	Structure: Peach house; Conservatory Location: Throstle Nest, Chellow Dene, Allerton, Bradford, Yorkshire Client: James Hill	1907; 1910
TR MES AD1/1785	Structure: Glasshouse Location: Thorne, Doncaster, Yorkshire Client: C.W. Darley	1907
TR MES AD1/1815	Structure: Conservatory Location: Ashfield, Golcar, Huddersfield, Yorkshire Client: Edward Whitwand	1906
TR MES AD1/1827	Structure: Vinery Location: The Court, Ackworth, Pontefract, West Yorkshire Client: George D. Cullingworth	1906
TR MES AD1/1838	Structure: Greenhouse Location: The Hollies, Market Weighton, East Yorkshire Client: F. Proudlock	1907
TR MES AD1/1870	Structure: Boiler Location: Wigganthurpe, York, Yorkshire Client: Lord Holden of Alston	1921
TR MES AD1/1873 [1 of 5 packets]	Structure: Pit frame Location: Selwood, Rotherham, Yorkshire Client: G.D. Owen per Mark Watts	1894
TR MES AD1/1873 [2, 4, 5 of 5 packets]	Structure: Cattleya, orchid, plant, peach and forcing houses and corridor Location: Selwood, Rotherham, Yorkshire Client: G.D. Owen per Mark Watts	1891-1893
TR MES AD1/1873 [3 of 5 packets]	Structure: Vinery and heating alterations Location: Selwood, Rotherham, Yorkshire Client: G.D. Owen per Mark Watts	1892
TR MES AD1/1882	Structure: Orchid house Location: 16 Norfolk Road, Harrogate, North Yorkshire Client: Richard Ward	1907
TR MES AD1/1916	Structure: Glasshouse Location: Owston Park, Doncaster, South Yorkshire Client: W.H. Matthews [Tenant] per D.P. Davies Cooke [Landlord]	1908
TR MES AD1/1929	Structure: Heating apparatus; Boiler Location: Dalton Holme, Beverley, East Yorkshire Client: Lord Hotham	1906; 1948

Records of Properties in Scotland

TR MES AD1/89	Structure: Conservatory Location: Drissaig, Kilchrenan, Argyll, Scotland Client: Dr McDougall per James Wilding [Architect]	1905
TR MES AD1/218	Structure: Guttering and pipes Location: Keppoch Iron Works, Glasgow, Scotland Client: David King and Sons	1891
TR MES AD1/250	Structure: Glasshouse Location: The Orphanage, Aberlour, Strathspey, Scotland Client: Rev. Charles Jupp	1894
TR MES AD1/283	Structure: Glasshouse Location: Morington, Dunscore, Dumfries-shire, Scotland Client: T. Hope-Bell	1903
TR MES AD1/504 [2 packets]	Structure: Boiler replacement and repairs Location: Springkell, Ecclefechan, Eaglesfield, Dumfrieshire, Scotland Client: Sir J.E. Johnson-Ferguson, Bart	1917-1923
TR MES AD1/557	Structure: Skylights and opening apparatus Location: Parkneuk Works, Motherwell, North Lanarkshire, Scotland Client: Alex Findlay and Co	1903
TR MES AD1/640	Structure: Stove, intermediate house and plant house Location: Creag Mhor, Onich, Highland, Scotland Client: Lady Alice Ewing	1890
TR MES AD1/1147	Structure: Greenhouse Location: Beech hurst, Hawick NB, Roxburghshire, Scotland Client: Edward Wilson	1901

Records of Properties in Ireland

TR MES AD1/122	Structure: Peach House/Glass Houses Location: Dawson Street, Dublin, Ireland Client: Maguire and Catchell LTD	1898
TR MES AD1/131	Structure: Extension to greenhouse Location: Ardnaveigh, Birch Hill, Antrim, Ireland Client: Henry B. Murray	1890
TR MES AD1/235	Structure: Conservatory Location: Lisselan, Clonakilty, Ireland Client: Reginald Bence Jones	1896
TR MES AD1/254	Structure: Glasshouses Location: Delvin Lodge, Balbriggan, Ireland Client: R.D. Jameson	1892
TR MES AD1/524	Structure: Forcing house Location: Valencia Island, Ireland Client: Sir Maurice Fitzgerald, Bt, Knight of Kerry	1897
TR MES AD1/532	Structure: Conservatory Location: Youghal, Co. Cork, Ireland Client: S.J. Merrick	1900
TR MES AD1/684	Structure: Fernery Location: Sunville House, Limerick, Ireland Client: Thomas H. Cleere, J.P.	1900
TR MES AD1/696	Structure: Glass house; Vinery Location: Newbridge House, Donabate, Co. Dublin, Ireland Client: Mrs Cobbe	1892; 1894
TR MES AD1/747	Structure: Conservatory Location: O'Harabrook, Ballymorey, Co. Antrim, Ireland Client: Capt. J.S. Cramsie	1901
TR MES AD1/810	Structure: Greenhouse Location: Tanaralla, Listowel, Co. Kerry, Ireland Client: Mrs M.G. Cooke	1890
TR MES AD1/897	Structure: Heating apparatus Location: Ballintaggart House, Colbinstown, Co. Kildare, Ireland Client: Col. Bonham	1894
TR MES AD1/1038	Structure: Glasshouses Location: Milford House, Milford, Co. Carlow, Ireland Client: Major Alexander	1903
TR MES AD1/1085	Structure: Peach house; Peach house; Palm house roof Location: Curraghmore, Portlaw, Ireland Client: Right Hon. Lord Waterford, Marquis of Waterford	1890; 1895; 1901
TR MES AD1/1294 [1 of 2 packets]	Structure: Vinery and plant house; Peach house; Wall cover Location: Danby, Ballyshannon, Donegal, Ireland Client: Alfred Stubbs	1890; 1893; 1906
TR MES AD1/1294 [2 of 2 packets]	Structure: Peach house and vinery; Verandah Location: St Erman's, Donegal, Ireland Client: H. Stubbs	1905; 1906
TR MES AD1/1306	Structure: Heating apparatus Location: Dromana, Cappoquin, Co. Waterford, Ireland Client: G.F. Villiers Stuart	1900
TR MES AD1/1371	Structure: Heating apparatus Location: Loughananna, Mitchelstown, Co. Cork, Ireland Client: W. Summers	1900

TR MES AD1/1506	Structure: Glasshouse Location: Glandore House, Glandore, Co. Cork, Ireland Client: Very Rev. J.M. Reeves, Dean of Ross	1893
TR MES AD1/1552	Structure: Heating apparatus Location: Glencairn Abbey, Lismore, Co. Waterford, Ireland Client: A.W.B. Power	1900
TR MES AD1/1591	Structure: Heating apparatus Location: Annestown, Tramore, Waterford, Ireland Client: Mrs Palliser	1895
TR MES AD1/1655	Structure: Vineries, Conservatory and greenhouses; Glasshouse Location: Annaghmore, Collooney, Co. Sligo, Ireland Client: C.K. O'Hara	1901; 1904
TR MES AD1/1702	Structure: Stove and intermediate house Location: Rostulla, Whiteabbey, Belfast, Northern Ireland Client: John Torrens	1893
TR MES AD1/1703	Structure: Stove and intermediate house Location: Edenmore, Whiteabbey, Belfast, Northern Ireland Client: Mrs Torrens	1891
TR MES AD1/1778	Structure: Vinery and plant house Location: Salisbury House, Cloumel, Tipperary, Ireland Client: J.W. Cleere	1906
TR MES AD1/1835	Structure: Plant house and stove Location: The Glen, Newry, Co. Down, Ireland Client: D.M. Barcroft	1907
TR MES AD1/1934	Structure: Greenhouse Location: Limavady, Co. Derry, Ireland Client: Richard Hull [Builder]	1908

Records of Properties in Wales

TR MES AD1/69	Structure: Greenhouses Location: Kilvrough, Park Mill RSO, Glamorganshire, Wales Client: Admiral Sir Algernon Lyons	1902
TR MES AD1/111	Structure: Heating apparatus, greenhouse Location: Maesyrcrugiau Manor RSO, Carmarthenshire, Wales Client: C. Mansel	1906
TR MES AD1/123	Structure: Plant house Location: Ivy House, Churchstoke, Montgomeryshire, Wales Client: A.G. Montford	1888
TR MES AD1/150	Structure: Heating apparatus Location: The Hall, Angle, Pembrokeshire, Wales Client: Col. R. Mirehouse	1906
TR MES AD1/154	Structure: Greenhouse and Vinery Location: Brecon, Powys, Mid Wales Client: Col. J. Morgan, Mayor of Brecon	1890
TR MES AD1/155	Structure: Vinery Location: Mostyn Hall, Mostyn, Flintshire, North Wales Client: Lord Mostyn	1903-1951
TR MES AD1/201	Structure: Vinery Location: Snatchwood Park, Pontypool, Gwent, Wales Client: P.H. Jones	1905
TR MES AD1/236	Structure: Conservatory Location: Brynteg, Merthyr Tydfil, South Wales Client: C.H. James	1890
TR MES AD1/243	Structure: Heating apparatus Location: The Mount, Chepstow, Monmouthshire, Wales Client: M. Pegler per W. Jones and Son [Builders]	1901
TR MES AD1/262	Structure: Vinery Location: Mount Alyn, Rossett RSO, Denbysshire, Wales Client: W.T. Jolliffe	1901
TR MES AD1/265	Structure: Conservatory Location: Snatchwood House, Pontypool, Gwent, Wales Client: Edward Jones	1900
TR MES AD1/276	Structure: Peach house and Vinery; Boiler Location: Coed Helen, Caernarvon, North Wales Client: Lloyd W.J. Hughes; Major Trevor Hughes	1904; 1931
TR MES AD1/290	Structure: Greenhouse Location: Glascoed, Llanrug RSO, Caernarvonshire, Wales Client: Trevor Hughes	1904
TR MES AD1/319	Structure: Greenhouse Location: Moel Llys, Penmaenmawr, Conwy, South Wales Client: T.E. Horton	1892
TR MES AD1/358	Structure: Vinery, new boiler Location: The Brewery, Ewaunfarren, Myrthyr Tydful, South Wales Client: Richard Harrop	1894
TR MES AD1/383	Structure: Glass house Location: 55 North Road, Carnarvon, South Wales Client: Mr W.G.S. Hynde	1903-1904
TR MES AD1/467	Structure: Plant house and stove Location: Derwydd, Llandebie RSO, Carmarthenshire, Wales Client: Alan Stepney-Gulston	1894

TR MES AD1/483	Structure: Conservatory Location: Ivy Tower, near Tenby, Pembrokeshire, North Wales Client: Col. H.H. Goodeve	1892
TR MES AD1/499	Structure: Conservatory Location: 50 Plymouth Road, Penarth, Glamorganshire, Wales Client Henry Green	1898
TR MES AD1/559	Structure: Heating apparatus Location: Bottling Stores, 121 Mostyn Street, Llandudno, Wales Client: T.H. Fitzsimmons	1905
TR MES AD1/665	Structure: Plant house Location: Penrhiantyn House, Neath, Port Talbot, Wales Client: H. Eccles	1902
TR MES AD1/769 [3 packets]	Structure: Heating apparatus for house; Forcing house; Boiler; Rebuilding Palm house and fernery Location: Duffryn House, Duffryn near Cardiff, Wales Client: John Cory; Reginald and Florence Cory	1900; 1913; 1922; 1931
TR MES AD1/769	Structure: Vineries; Fernery, Plant house, Vinery Location: Porthkerry, Barry, near Cardiff, Wales Client: John Cory	1892; 1895
TR MES AD1/773	Structure: Vinery, stove and orchid house Location: Bodrhyddan, Rhyddlan RSO, Cardiff, Wales Client: Capt. Colway	1892
TR MES AD1/801	Structure: Conservatory Location: Lady Foresters Charity Convalescent Home, Llandudno, Wales Client: E.B. L'Anson [Architect]	1904
TR MES AD1/885	Structure: Plant house Location: Minera Hall, Wrexham, Flintshire, North Wales Client: John R. Burton	1896
TR MES AD1/908	Structure: Vineries and peach house; Conservatory Location: Bryn Parsonage, Pen-y-lan, Rhuabon, Denbighshire, North Wales Client: Rev. T Bunscombe per Capt. Peter Ormrod	1890; 1891
TR MES AD1/947	Structure: Heating alterations Location: Wyaston Leys, near Monmouth, Wales Client: James Murray Bannerman	1891
TR MES AD1/948	Structure: Plant house Location: Broadlands, Bridgend, South Wales Client: Miss Blandy	1891
TR MES AD1/978	Structure: Greenhouse Location: San Remo, The Walk, Merthyr Tydvil, South Wales Client: J.C. Bernascone	1904
TR MES AD1/998 [2 packets]	Structure: Conservatory; Vinery; Peach house; Repairs; Painting Location: Cadoxten House, Neath, Glamorganshire, South Wales Client: Evan Evans Bevan	1903; 1905; 1907; 1908; 1909
TR MES AD1/1071	Structure: Conservatory Location: Nantymoel, Glamorganshire, Wales Client: David Walters [Builder]	1903

TR MES AD1/1097 [2 of 2 packets]	Structure: Vinery and plant house Location: Hafod, Ystrad Meurig, Aberystwyth, Wales Client: Mrs Waddingham	1892
TR MES AD1/1097 [1 and 2 of 2 packets]	Structure: Heating apparatus and vinery; Boiler Location: Hafod, Devils Bridge RSO, Cardiganshire, South Wales Client: T.J. Waddingham	1902; 1919
TR MES AD1/1129	Structure: Conservatory and orchard house Location: Bryn, Beaumaris, Anglesey, North Wales Client: Arthur F. Wrigley	1903
TR MES AD1/1156	Structure: Vinery; Forcing house Location: Rûg, Corwen, North Wales Client: P.W Wynn and the Hon. C.H. Wynn	1890
TR MES AD1/1291	Structure: Vinery; Painting Location: Derwydd, Llandebie RSO, Carmathenshire, Wales Client: Alan Stepney-Gulston	1897; 1911
TR MES AD1/1314	Structure: Conservatory Location: Hawthorn Villa, Merthyr Tydfil, South Wales Client: John Sibbering	1889
TR MES AD1/1364	Structure: Greenhouse; Rebuilding tomato and melon house, frames and painting Location: Glandare, Aberdare, Glamorgan, South Wales Client: Robert T. Rees; Miss A.G. Rees	1895; 1935
TR MES AD1/1424	Structure: Conservatory Location: Craigisla, Penylan, Cardiff, Wales Client: T. Strachan	1898
TR MES AD1/1475	Structure: Greenhouses Location: Regent Villa, Colwyn Bay, North Wales Client: William Rothwell	1890
TR MES AD1/1505	Structure: Greenhouse Location: Haven House, Conway, North Wales Client: A. Rice	1906
TR MES AD1/1513	Structure: Fernery Location: Picton Castle, Haverford West, Pembrokeshire, Wales Client: Sir Charles E.G. Phillips, Bart.	1890
TR MES AD1/1527	Structure: Melon pit; Plant house Location: Cefn Park, Wrexham, Wales Client: Sir Roger Parker, Bart. per W. Shore	1901; 1904
TR MES AD1/1533	Structure: Boilers Location: Gorddinog, Llanfairfechan, North Wales Client: Col. Platt	1905
TR MES AD1/1534	Structure: Glasshouse Location: Pen Moel, Chepstow, Monmouthshire, Wales Client: Mrs W.E. Price	1905
TR MES AD1/1569	Structure: Greenhouse Location: 2 St Helens Crescent, Swansea, Wales Client: Dr J.L. Pritchard	1890
TR MES AD1/1604	Structure: Conservatory Location: Penrhewlyn House, Neath, Glamorgan, Wales Client: Richard Phillips	1895
TR MES AD1/1620	Structure: Conservatory Location: Maesgwynne, Whitland, South Wales Client: Mrs C. Powell	1895

TR MES AD1/1700	Structure: Conservatory Location: Penarth, Cardiff, Wales Client: E. Thomas	1887
TR MES AD1/1706 [1 of 2 packets]	Structure: Conservatory Location: Cefn Mably, South Wales Client: H.M. Kenneys-Tynte	1895
TR MES AD1/1706 [2 of 2 packets]	Structure: Conservatory and cucumber house; Forcing house Location: Cefn Mably, South Wales Client: H.M. Kenneys-Tynte	1891; 1892
TR MES AD1/1734	Structure: Cucumber house Location: Ewenny Priory, Bridgend, Glamorganshire, Wales Client: Col. J. Picton Turberville	1897
TR MES AD1/1737 See also TR MES AD1/1738/2	Structure: Carnation and forcing house Location: Penrice Castle, Reynoldstone RSO, Glamorganshire, Wales Client: Miss Talbot	1898
TR MES AD1/1738 [1 of 3 packets]	Structure: Boilers; Sky lights to squash court Location: Margam Castle, Port Talbot, South Wales Client: Capt. A.M. Talbot Fletcher	1925; 1927
TR MES AD1/1738 [2 of 3 packets] See also TR MES AD1/1737	Structure: Vinery and peach house Location: Penrice Castle, near Swansea, Glamorganshire, Wales Client: Miss Talbot	1891
TR MES AD1/1738 [2 and 3 of 3 packets]	Structure: Greenhouse; Stoves, plant house, propagating house Location: Margam Park, Port Talbot, South Wales Client: Miss Talbot	1890; 1891
TR MES AD1/1770	Structure: Glasshouses Location: Shirenewton Hall, Chepstow, Monmouthshire, Wales Client: C. Oswald Liddell	1906
TR MES AD1/1779	Structure: Plant house Location: Poyston, Pembroke, Wales Client: Henry Owen, DCL	1908
TR MES AD1/1786	Structure: Plant house Location: Coed Derw, Bettws-y-Coed, North Wales Client: E. Charles Buxton	1907
TR MES AD1/1805	Structure: Heating apparatus and ventilating equipment Location: Gogerddan, Bow Street RSO, Cardiganshire, Wales Client: Sir Edward Pryse	1906
TR MES AD1/1819 [1 of 2 packets]	Structure: Heating and hot water apparatus for residence Location: Nantyderry House, Abergavenny, Wales Client: Miss Evans	1907
TR MES AD1/1819 [2 of 2 packets]	Structure: Conservatory Location: Nantyderry House, Abergavenny, Wales Client: Miss Evans per Edgar G.C. Down [Architect]	1899
TR MES AD1/1820	Structure: Melon and plant house Location: Dolben, St Asaph RSO, Denbighshire, Wales Client: Major R. Williams Wym	1907
TR MES AD1/1877	Structure: Glasshouse; Plant house Location: Salam Bungalow, Meliden, near Rhyl, North Wales Client: Alfred Dickenson [Engineer]	1908; 1909
TR MES AD1/1880	Structure: Heating repairs Location: Treborth, Bangor, North Wales Client: H.R. Davies	1913

TR MES AD1/1880	Structure: Heating apparatus Location: Bodlondeb, Bangor, North Wales Client: H.R. Davies	1906
TR MES AD1/1916	Structure: Glasshouse Location: Gwysaney, Mold, North Wales Client: P.T. Davies Cooke	1910
TR MES AD1/1942	Structure: Vinery Location: Boughspring House, Chepstow, Monmouthshire, Wales Client: Miss Morgan	1908

Records of Properties Overseas

TR MES AD1/163	Structure: Greenhouse Location: Raconnell House, Monaghan, Republic of Ireland Client: H. B. Murray	1886
TR MES AD1/181	Structure: Greenhouse and Stove Location: Richmond House, Cork, Republic of Ireland Client: Miss Mayne	1899
TR MES AD1/187	Structure: Plant house and stove Location: [Crawley, Perth, Western Australia] Client: [Agents Messrs. Manning & Co]	1901
TR MES AD1/191	Structure: Conservatory Location: Coolnafranky, Cookstown, Co. Tyrone, Republic of Ireland Client: J. B. Gunning Moore	1900
TR MES AD1/194	Structure: Boiler Location: To be shipped to Calcutta, India Client: Indian Government, India Office, Whitehall	1903
TR MES AD1/661	Structure: Photographic Studio Location: Alexandria, Egypt Client: Egyptian Government per C.W. Burton [engineer]	1897
TR MES AD1/719	Structure: Greenhouse Location: British Embassy, Constantinople Client: Sir Henry Tanner [Government architect]	1904
TR MES AD1/887	Structure: Heating apparatus Location: Tipahi Street, Nelson, New Zealand Client: Henry B. Bolton	1903
TR MES AD1/1046	Structure: Greenhouse Location: Mount Nelson Hotel, Cape Town, South Africa Client: African Lands and Hotels Ltd	1899
TR MES AD1/1145	Structure: Palm house Location: Palermo, Sicily Client: Joshua Whitaker per J. Henry Christian	1897
TR MES AD1/1353	Structure: Boilers Location: Beunos Aires, Argentina Client: J.R. Sutton	1897
TR MES AD1/1463	Structure: Conservatory and heating apparatus Location: Fernwood, Cape Town, South Africa Client: C.D. Rudd	1891
TR MES AD1/1548	Structure: Conservatory Location: Varana, Hobart, Tasmania, Australia Client: R.C. Patterson	1902
TR MES AD1/1650	Structure: Boiler Location: Constantinople Client: Sidney Nowill and Co.	1904
TR MES AD1/1744	Structure: Heating apparatus Location: Grand Panorama des Chutes du Niagara, Avenue du Bois de Boulogne, Paris, France Client: Robert Emerie Tyler [Architect]	1889
TR MES AD1/1853	Structure: Conservatory Location: Naranhilty, Nepal, India Client: Commanding General Futtch Shum Shere Jung Rana Bahadur	1900
TR MES AD1/1854	Structure: Roof to court yard Location: Ex Railway buildings, Kast-EL-Nil Street, Cairo, Egypt Client: W. Hamilton [Engineer]	1901

TR MES AD1/1884	Structure: Boiler Location: Holly Lodge, Papaite, via Wanganni, New Zealand Client: per Messrs Watson Bros	1908
TR MES AD1/1956 [1 of 3 packets]	Structure: Stoves for winter garden Location: Hawthorndene, Wynberg, Cape Town, South Africa Client: Sir J.B. Robinson	1908
TR MES AD1/1956 [2 and 3 of 3 packets]	Structure: Conservatory and skating rink Location: Hawthorndene, Wynberg, Cape Town, South Africa Client: Sir J.B. Robinson	1907